

✓

**PRE-SHIFT
BELTS**

2MSHA03998

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-5-07

SECTION/AREA BELTS

Time of Examination Start 3:00 AM/PM End 4:40 AM/PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	Acc. Head Roll to exit #1	SENT MEN TO CLEAN DOME
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO SENSORS				1962 Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 9599

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA03999

SIGNATURE _____

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5507

SECTION/AREA BELTS

Time of Examination Start 11 AM PM

End 130 AM PM

Examiners Initials LD

Time of Examination Start 11:00 AM PM

End 12:25 AM PM

Examiners Initials LD

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	None observed	
#7	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
CO sensors	Visual Exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 Belt Some areas	Floot Dust in some areas	Running Rock Dusters
#2 Belt	1-floot Dust	Running Rock Duster
#7 Dump pit	Drippan plugged up	Cleaned

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Pre-Shift/Mine Examiner **Signature** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6622
 Certificate # 9660
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 7480

2MSHA04000

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-5-07 SECTION/AREA Belts

Time of Examination Start 7:15 AM/PM AM End 9:15 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM PM End 9:05 AM/PM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
No sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04001 Certificate # _____

Counter Signature **SIGNATURE** Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-6-07

SECTION/AREA BELTS

Time of Examination Start 3:40 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 4:00 AM PM End 5:35 AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	none observed	
#2	20.9	0.0	0.0	OK	ACC Tailpiece Area	BEING CLEANED DONE ✓
#3	20.9	0.0	0.0	OK	none observed	
#4	20.9	0.0	0.0	OK	none observed	
#5	20.9	0.0	0.0	OK	none observed	
#6	20.9	0.0	0.0	OK	none observed	
#7	20.9	0.0	0.0	OK	none observed	
Kitchen	20.9	0.0	0.0	OK	none observed	
Transformer	20.9	0.0	0.0	OK	none observed	
CO SENSORS				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above all AREAS SAFE at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9599
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA04002

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-6-07

SECTION/AREA Belts

Time of Examination Start 11:05 AM PM

End 1:15 AM PM

Examiners Initials JD

Time of Examination Start 11 AM PM

End 12:45 AM PM

Examiners Initials dy

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	ACC Tail	SENT MEN TO CLEAN DONE JT
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	ACC XC2-7 Dump	SENT MEN TO CLEAN DONE JT
#7	20.9	0	0	ok	none observed	
#8 Pitcher	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
CO SenSers	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

SIGNATURE


Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 8622

Pre-Shift/Mine Examiner _____

2MSHA04003

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE


Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-6-07 SECTION/AREA Belts

Time of Examination Start 7:05 AM/PM AM End 9:25 AM/PM PM Examiners Initials RP

Time of Examination Start 7:30 AM/PM AM End 9:15 AM/PM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **Signature** _____ Certificate # 9899

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04004

Counter Signature **SIGNATURE** _____ Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-7-07

SECTION/AREA Belts

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN	
#1								
#2								
#3								
#4								
#5								
#6								
#7								
Belt Kitcher					<div style="font-size: 2em; font-family: cursive;"> All Belts Toller </div>			
Trans.								
C.O. monitor usual								

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04005

Counter Signature _____

Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-7-07

SECTION/AREA Belts

Time of Examination Start 2:15 AM/PM AM PM End 4:25 AM/PM AM PM Examiners Initials AK/LK

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	accum tail	sent men to work on Done 5-8-07
#2	20.9	0	0	OK	accum tail	sent men to work on Done 5-8-07
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	Acc. At Drive	sent men to work on Done 5-8-07
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
trans	20.9	0	0	OK	none obs.	
Belt Ketcher	20.9	0	0	OK	none obs.	
C.O. Monitors				OK	exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift.

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 4325
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA04006

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-7-07 SECTION/AREA Belts.

Time of Examination Start 7:00 AM/PM AM End 9:25 AM/PM PM Examiners Initials BH/TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acc. Tail	working on Cleaned 5-8-07
#2	20.9	0	0	OK	Acc. Tail	working on Cleaned 5-8-07
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Acc. tail at drive	working on Cleaned 5-8-07
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
C.O. monitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Except as noted above all areas appeared reasonably safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

SIGNATURE _____ 2MSHA04007

Counter Signature _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-8-07

SECTION/AREA Belts

Time of Examination Start 300 AM PM End 545 AM PM Examiners Initials DDPC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1 belt	20.9	0	0	ok	acc. at tail, acc. cut 18 oil acc at drive.	Cleaned 5-8-07
#2 belt	20.9	0	0	ok	none obs.	
#3 belt	20.9	0	0	ok	COAL ACC. @ TAIL	Cleaned 5-8-07
#4 belt	20.9	0	0	ok	Roller piles Head roller to drive acc. in take-up	Cleaned 5-8-07
#5 belt	20.9	0	0	ok	None obs. ACC. COAL in Drive	Cleaned 5-8-07
#6 belt	20.9	0	0	ok	none obs.	
#7 belt	20.9	0	0	ok	none obs.	
Transformers	20.9	0	0	ok	none obs.	
belt kitchen	20.9	0	0	ok	none obs.	
C.O. Manifolds			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE
Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA04008

Certificate # _____

SIGNATURE
Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-8-07

SECTION/AREA Belts

Time of Examination Start 11:05 AM/PM End 1:15 AM/PM Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs.	
#2	21.0	0	0	OK	None obs.	
#3	21.0	0	0	OK	None obs.	
#4	21.0	0	0	OK	Deep Water #73 xc	Working on Pumped out 5-8-07
#5	21.0	0	0	OK	None obs.	
#6		0	0	OK	None obs.	
#7		0	0	OK	None obs.	
Trans.		0	0	OK	None obs.	
Belt Ketcher		0	0	OK	None obs.	
C.O. Monitors		VISUAL EXAM		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
Silo Belt	Tail Roller Cover missing	replaced cover 5-8-07

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 7934
 Certificate # _____
 Certificate # _____

SIGNATURE
 Counter Signature _____

2MSHA04009

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-8-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM PM End 940 AM/PM PM Examiners Initials DD

Time of Examination Start 7:00 AM/PM PM End 8:50 AM/PM PM Examiners Initials TK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	Acc. @ Tail	working on Done 5-9-07
#3	20.9	0	0	ok	Acc. off walkway side Tail piece	working on Done 5-9-07
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Trans	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CD Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04010

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-9-07 SECTION/AREA Belts

Time of Examination Start 3:05 AM PM End 5:05 AM PM Examiners Initials TC

Time of Examination Start 300 AM PM End 500 AM PM Examiners Initials DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs	
#2	20.9	0	0	OK	Needs Dusted / No rollers to l	Dusted 5-9-07
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs	
#5	20.9	0	0	OK	None obs	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
TRANS.	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Cp sensors				VISUAL EXAM		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above ALL AREAS SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9562

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 8058

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # 4735

2MSHA04011

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-9-07 SECTION/AREA Belts

Time of Examination Start 11:05 AM PM End 1:20 AM PM Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs	
#2	21.0	0	0	OK	None obs.	
#3	21.0	0	0	OK	None obs.	
#4	21.0	0	0	OK	None obs.	
#5	21.0	0	0	OK	None obs.	
#6	21.0	0	0	OK	None obs	
#7	21.0	0	0	OK	None obs	
Tunnels	21.0	0	0	OK	None obs.	
Kitchen	21.0	0	0	OK	None obs.	
CO Sensors	4.5 level Exam OK			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1/6ad	accum.	Cleaned 5-9-07

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 4325

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 7954

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04012

Counter Signature **SIGNATURE** _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-9-07 6:00 PM SECTION/AREA Belts

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Belts						
false						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04013

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Counter Signatu

Signature

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-10-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:00 AM PM Examiners Initials TC

Time of Examination Start 300 AM PM End 505 AM PM Examiners Initials DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
No sensors		Visual exam				

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 8058
 Certificate # _____
 Certificate # _____

SIGNATURE
 Counter Signature _____

2MSHA04015

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-10-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:10 AM PM Examiners Initials LR/KR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#17	20.9	0	0		OK	Drive Area Needs dusted	Working on
Belt Kitcher	20.9	0	0		OK	None obs.	
Trans.	20.9	0	0		OK	None obs.	
C.O. Monitor	visual Exam						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe. except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 7954

Pre-Shift/Mine Examiner _____

Certificate # 4375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04016

Counter Signature _____

Certificate # 8162

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-10-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM End 945 AM/PM Examiners Initials DD PC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	oil Acc. AT Drive	working on Cleared 5-11-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	coal Acc. AT Drive	Cleared 5-10-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	needs dust @ Drive none obs.	
Belt Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Certificate # 8462

Certificate # _____

Certificate # _____

SIGNATURE _____

Counter Signature _____

2MSHA04017

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-11-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~PM End 535 ~~AM~~PM Examiners Initials DD PL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	needs dust from 121 to tail - needs dust @ Drive Done 5/11/07 CA	sent people to dust
Traps	20.9	0	0	ok	none obs.	
Belt Ketcher	20.9	0	0	ok	none obs.	
C.O. Monitor manual				ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 8462

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04018

SIGNATURE

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-11-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:30 AM/PM

Examiners Initials BJ

Time of Examination Start 11:00 AM/PM

End 1:15 AM/PM

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Trans	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
Co monitors	Visual			exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE _____

2MSHA04019

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 7-11-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM PM End 9:10 AM/PM AM PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	Acc cross under	SENT MEN TO CLEAN Done 7-11-07
#7	20.9	0	0	ok	Acc 113-114	SENT MEN TO CLEAN Done 7-11-07
transformers	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
C/O Sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7 tail	need 5 bags past fire extinguisher	Plast 5 bags past fire ext at tail

PRE-SHIFT REMARKS all Areas Apperd Safe at the time of exam except those noted above

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04020

SIGNATURE _____

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5/12/07 SECTION/AREA Belts

Time of Examination Start 3 AM/PM End 5:20 AM/PM Examiners Initials dy

Time of Examination Start 3:00 AM/PM End 4:25 AM/PM Examiners Initials JD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Acc Head and 3 tail Front Back	Sent people to clean Done
#5	20.9	0	0	ok	Coal accumulations Dump point spill	Sent people to clean Done CA
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
Belts Kitchen	20.9	0	0	ok	none observed	
CO sensors	Visual Exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

#7 Belt

LOCATION	HAZARDS	ACTION
Dump point Drip pan	Drippen plugged	cleaned

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift except what is noted above

SIGNATURE [Redacted]

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6627
 Certificate # 9660
 Certificate # _____
 Certificate # _____

SIGNATURE [Redacted]

Counter Signature _____

2MSHA04021

Certificate # 03992

PRE-SHIFT BELTS

DATE OF EXAMINATION: 5-12-07 SECTION/AREA: Belts

Time of Examination Start 11:00 AM/PM AM PM End 1:15 AM/PM AM PM Examiners Initials BP

Time of Examination Start 11:00 AM/PM AM PM End 1:25 AM/PM AM PM Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0.0	0.0	OK	none observed	
#2	20	0.0	0.0	OK	none observed	
#3	20	0.0	0.0	OK	none observed	
#4	20	0.0	0.0	OK	Acc at Head Roller	sent people to clean it
#5	20	0.0	0.0	OK	none observed	
#6	20	0.0	0.0	OK	none observed	
#7	20	0.0	0.0	OK	none observed	
Kitchen	20	0.0	0.0	OK	none observed	
Transformers	20	0.0	0.0	OK	none observed	
CO Sensors					Visual Exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS: All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner: _____ **SIGNATURE** _____ Certificate # 9582

Pre-Shift/Mine Examiner: _____ **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner: _____ **SIGNATURE** _____ Certificate # _____

Pre-Shift/Mine Examiner: _____ **SIGNATURE** _____ Certificate # _____

Counter Signature: _____ **SIGNATURE** _____ Certificate # 03892

2MSHA04022

PRE-SHIFT BELTS

DATE OF EXAMINATION 5/12/07

SECTION/AREA BELTS

Time of Examination Start 7 AM/PM

End 9:20 AM/PM

Examiners Initials dy

Time of Examination Start 7:00 AM/PM

End 9:25 AM/PM

Examiners Initials JD

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	None observed	
#2	20.9	0	0		ok	None observed	
#3	20.9	0	0		ok	None observed	
#4	20.9	0	0		ok	None observed	
#5	20.9	0	0		ok	None observed	
#6	20.9	0	0		ok	coal accumulation Dump point needs dust	SENTRY MEN TO CLEAN DUST DONE IS
#7	20.9	0	0		ok	None observed	
Kitchen	20.9	0	0		ok	None observed	
Transformers	20.9	0	0		ok	None observed	
CO sensors	Visual exam ok						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at Time of pre-shift
except what is noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

Certificate # 6602
Certificate # 9660
Certificate # _____
Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04023

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-13-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 5:10 AM/PM

Examiners Initials LD

Time of Examination Start 3 AM/PM

End 4:45 AM/PM

Examiners Initials LD

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	ACC tail	Sent people to clean down 5-13-07
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.8	0	0	ok	none observed	
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	None observed	
C/O Sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7 Belt	Blue Reflectors when Back 2 XE	Advanced Reflectors

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 632

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04024

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-13-07

SECTION/AREA Belts

Time of Examination Start 12:07 ~~AM~~ PM End 1:50 AM ~~PM~~ Examiners Initials BP

Time of Examination Start 11:05 ~~AM~~ PM End 1:35 AM ~~PM~~ Examiners Initials TC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0		ok	none observed	
#2	20	0	0		ok	none observed	
#3	20	0	0		ok	none observed	
#4	20	0	0		ok	none observed	
#5	20	0	0		ok	none observed	
#6	20	0	0		ok	none observed	
#7	20	0	0		ok	none observed	
Kitchen	22	0	0		ok	none observed	
Transformers	20	0	0		ok	none observed	
CO monitors					Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner SIGNATURE

Certificate # 2599

Pre-Shift/Mine Examiner _____

Certificate # 9362

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04025

Counter Signature SIGNATURE

Certificate # 03992

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-13-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (M) End 9:25 AM/PM (M) Examiners Initials JL

Time of Examination Start 7 AM/PM (M) End 8:30 AM/PM (M) Examiners Initials JG

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	None observed	
#7	20.9	0	0	ok	Rib Rotted on top KC120 Bolts to far from Rib	SENT MEN TO SET TIMBER DONE JG
Kitchen	20.9	0	0	ok	None observed	
transformer	20.9	0	0	ok	None observed	
C/O SENSORS	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift except what is noted above

Pre-Shift/Mine Examiner SIGNATURE _____
 Pre-Shift/Mine Examiner SIGNATURE _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9660
 Certificate # 6622
 Certificate # _____
 Certificate # _____

Counter Signature SIGNATURE _____ 2MSHA04026

Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-14-07

SECTION/AREA BELTS

Time of Examination Start 3:10 AM/PM

End 4:40 AM/PM

Examiners Initials JG

Time of Examination Start 3:00 AM/PM

End 5:00 AM/PM

Examiners Initials LD

Time of Examination Start 4:20 AM/PM

End 5 AM/PM

Examiners Initials dy

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	None observed	
# 2	20.9	0	0	OK	NONE OBSERVED	
# 3	20.9	0	0	OK	NONE OBSERVED	
# 4	20.9	0	0	OK	ACCUMULATIONS AT HEAD ROLLER	Sent men to work on Done 5-14-07
# 5	20.9	0	0	OK	ACC XC 103-Head	Sent men to work on Done 5-14-07
# 6	20.9	0	0	OK	none observed	
# 7	20.9	0	0	OK	none observed	
KITCHEN	20.9	0	0	OK	NONE OBSERVED	
TRANSFORMER	20.9	0	0	OK	NONE OBSERVED	
CO. SENSORS	VISUAL EXAM			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at time of exam except those noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 7485

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04027

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-14-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials MSAP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	need dust 0 to 20	Dusted 5-14-07
#3	20.9	0	0	OK	Accum FAI piece	cleaned 5.24.07
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
at gas kit check	20.9	0	0	OK	none observed	
CO monitors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS Appeared Reasonably safe
AT time of pre-shift

SIGNATURE

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

Certificate # 2375
Certificate # 8058
Certificate # _____
Certificate # _____

2MSHA04028

SIGNATURE

Counter Signature _____

Certificate # 4785

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-14-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:20 AM/PM PM Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs	
#2	21.0	0	0	OK	None obs.	
#3	21.0	0	0	OK	None obs	
#4	21.0	0	0	OK	Deep Water #173 re Roller Piles Headrolls to drive	Working on Pumped/Sealed 5/14/07
#5	21.0	0	0	OK	None obs.	
#6	21.0	0	0	OK	None obs	
#7	21.0	0	0	OK	None obs	
Turns Formers	21.0	0	0	OK	None obs.	
Kitchen	21.0	0	0	OK	None obs.	
CD Monitors	V's used Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 7959
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04029

Counter Signature _____

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-15-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM) PM End 5:28 (AM) PM Examiners Initials KK/LR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	Headroller to Brake Needs dusted	Sent man to dust DONE 4-15-07
#5	20.9	0	0	OK	roller piles from x-cut 104 to drive	Sent man to shovel DONE 4-15-07
#6	20.9	0	0	OK	None obs	
#7	20.9	0	0	OK	Drive to Headroller Needs dusted	Sent man to dust DONE 4-15-07
trans	20.9	0	0	OK	none obs	
Belt kitchen	20.9	0	0	OK	none obs	
C.O. monitor	visual					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 Tailpiece	COAL Acc.	cleaned
#4 belt 78 to 70	Roller Piles	cleaned
#1 drive	O.H. Acc.	cleaned

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM except as noted above

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7959
 Certificate # 4375
 Certificate # _____
 Certificate # _____

2MSHA04030

SIGNATURE
 Counter Signature _____

Certificate # 8468

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-15-07

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 115 AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	COAL Acc. @ Tail	Done 5-15-07
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	Deep water x-73	Pumped 5-15-07
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	COAL Acc. @ Drive	cleaned 5-15-07
#7	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
Belt Kitchen	20.9	0	0	ok	none obs.	
CO monitors				visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04031

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-15-07 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 900 AM/PM PM Examiners Initials KK/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Belt Kitchens	20.9	0	0	OK	none	
CO. Sensor	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 6401

Certificate # 7954

Certificate # _____

Certificate # _____

2MSHA04032

SIGNATURE

Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-16-07 SECTION/AREA Belts

Time of Examination Start 300 AM End 540 AM Examiners Initials RL

Time of Examination Start 300 AM End 525 AM Examiners Initials TR/TK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	0	none observed	
#2	20.9	0	0	0	none obs	
#3	20.9	0	0	0	none obs	
#4	20.9	0	0	0	none obs	
#5	20.9	0	0	0	none obs	
#6	20.9	0	0	0	none obs	
#7	20.9	0	0	0	none obs	
Tramway	20.9	0	0	0	none obs	
Belt Kitchens	20.9	0	0	0	none obs	
CO-Sensors used even 0						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at end of pre-shift.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 7954
 Certificate # 4325
 Certificate # _____

SIGNATURE

Counter Signature

2MSHA04033

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-16-07

SECTION/AREA BELTS

Time of Examination Start 11:00 ~~AM~~/PM End 1:15 AM/~~PM~~ Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	needs dusted	working on Dusted from 62-49
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO MONITORS				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7375

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE

2MSHA04034

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-16-07

SECTION/AREA Belts

Time of Examination Start 7:10 AM/PM AM PM End 9:10 AM/PM AM PM Examiners Initials LR/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0		OK	None obs.	
#2	21.0	0	0		OK	None obs.	
#3	21.0	0	0		OK	None obs.	
#4	21.0	0	0		OK	None obs.	
#5	21.0	0	0		OK	None obs.	
#6	21.0	0	0		OK	None obs.	
#7	21.0	0	0		OK	None obs.	
Belt Kitchen	21.0	0	0		OK	None obs.	
Trens.	21.0	0	0		OK	None obs.	
C.O. Monitor							

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4375
 Certificate # 6401
 Certificate # _____
 Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04035

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-17-07

SECTION/AREA Belts

Time of Examination Start 3:10 AM PM End 5:15 AM PM Examiners Initials RL/DR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	Handrollor to #2 Needs dust	Sent men to dust tested 5-17-07
#7	20.9	0	0	OK	None obs.	
Belt Ketcher	20.9	0	0	OK	None obs.	
Tram	20.9	0	0	OK	None obs.	
C.O. Monitor	Visual Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#119 7 Belt	BR 2" Valve on Fire Valve	Repaired 5-17-07

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE


Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 4325
 Certificate # 6401
 Certificate # _____
 Certificate # _____

SIGNATURE


2MSHA04036

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-17-07

SECTION/AREA Belts

Time of Examination Start 1100 ~~AM~~/PM End 115 AM/~~PM~~ Examiners Initials DD mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	none obs.	
#2	20.9	0	0		ok	coal acc. @ Tail	Done 5-17-07
#3	20.9	0	0		ok	none obs.	
#4	20.9	0	0		ok	none obs.	
#5	20.9	0	0		ok	none obs.	
#6	20.9	0	0		ok	none obs.	
#7	20.9	0	0		ok	acc. @ Tail	cleaned 5-17-07
Belt Kitchen	20.9	0	0		ok	none obs.	
TRANS.	20.9	0	0		ok	none obs.	
CO monitors					visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of pre-shift exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04037

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-17-07

SECTION/AREA Belt

Time of Examination Start 710 AM/PM AM End 925 AM/PM PM Examiners Initials RL/LK

Time of Examination Start _____ AM/PM _____ End _____ AM/PM _____ Examiners Initials _____

Time of Examination Start _____ AM/PM _____ End _____ AM/PM _____ Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	ACC. AT TRIL	working on cleanup 5/18-07
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Ketcher	20.9	0	0	OK	None obs.	
Trans.	20.9	0	0	OK	None obs.	
C.O. Monitors					normal	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

SIGNATURE

Certificate # 4373
 Certificate # 6401
 Certificate # _____
 Certificate # _____

2MSHA04038

Counter Signature _____

SIGNATURE

Certificate # 9385

PRE-SHIFT BELTS

DATE OF EXAMINATION 5/18/07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 527 AM/PM Examiners Initials LR/RC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	None dust 123 to 125 and 125 stopping backside need to be done	sent people to take care of. Done
Belt Kitchen	20.9	0	0	OK	none observed	
Belt trans	20.9	0	0	OK	none	
C.O. Monitor	Visual					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS from approval safe at time of exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 4375
 Certificate # _____
 Certificate # _____

2MSHA04039

SIGNATURE

Counter Signature _____

Certificate # 03992

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-18-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM

End 12:37 AM PM

Examiners Initials BP

Time of Examination Start 11:07 AM PM

End 12:58 AM PM

Examiners Initials TC

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9599

Certificate # 9362

Certificate # _____

Certificate # _____

2MSHA04040

Counter Signature **SIGNATURE**

Certificate # 05892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-18-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM PM End 9:15 AM/PM AM PM Examiners Initials LD

Time of Examination Start 7 AM/PM AM PM End 830 AM/PM AM PM Examiners Initials dy

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	float Dust acc. #3X	SENT MEN TO CLEAN Done 5-18-07 Dust
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	R:b rolled, Bolts for R:b XC 125-126, 122, 119, R:b	SENT MEN TO TIMBER Done 5-18-07
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Senses	via exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift except what is noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04041

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5/19/07 SECTION/AREA BELTS

Time of Examination Start 3 AM/PM End 5:25 AM/PM Examiners Initials EG

Time of Examination Start 3:05 AM/PM End 4:20 AM/PM Examiners Initials LD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	Deepwater 73%	Sent people to pump Done at 5/19/07
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	None observed	
#7	20.9	0	0	ok	Dump point plugged with pieces of tires stopping 125%	Sent people to clean Done at 5/19/07
Kitchen						
Transformers	20.9	0	0	ok	None observed	
CO SENSORS	Visual	exam		ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift except what is noted above

SIGNATURE _____ Certificate # 6622

Pre-Shift/Mine Examiner _____ Certificate # 9660

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04042

SIGNATURE _____ Certificate # 03892

Counter Signature _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-19-07

SECTION/AREA BELTS

Time of Examination Start 11:20 AM PM End 1:35 AM PM Examiners Initials BD

Time of Examination Start 11:10 AM PM End 1:36 AM PM Examiners Initials TR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE**
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9599
 Certificate # 9362
 Certificate # _____
 Certificate # _____

2MSHA04043

Counter Signature **SIGNATURE**

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5/19/07

SECTION/AREA BELTS

Time of Examination Start 7 AM/PM AM End 9:20 AM/PM PM Examiners Initials dy

Time of Examination Start 7:00 AM/PM AM End 8:25 AM/PM PM Examiners Initials JD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Rib blown out by log need to set 3 timber	SENT MEN TO TIMBER DONE JTG
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0.2		ok	Coal accumulations Dump point & Take-up	SENT MEN TO CLEAN DONE JTG
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO Sensors	Visual Exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 tail	Coal ACC	Cleaned
#5 HEAD SNUB ROLLER	BAD BEARING ON SNUB ROLLER	REPLACED BEARING

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift except what is noted above

Pre-Shift/Mine Examiner SIGNATURE
 Pre-Shift/Mine Examiner SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6602
 Certificate # 9660
 Certificate # _____
 Certificate # _____

Counter Signature SIGNATURE

Certificate # 7485

2MSHA04044

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-20-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials LP

Time of Examination Start 3:35 AM/PM End 5:10 AM/PM Examiners Initials dy

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	coal accumulations ^{1 Tail}	Sent people to clean ^{of} None ^{of} 52007
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	No yellow reflector XC 114	sent reflector in ^{of} None ^{of} 52007
Kitchen	20.9	0	0	OK	None observed	
transformers	20.9	0	0	OK	None observed	
C/O Sensors	Visual exam			OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all areas examined appears safe at time of pre-shift
except what is noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04045

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-20-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:20 AM/PM Examiners Initials RP

Time of Examination Start 11:00 AM/PM End 1:35 AM/PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Belt Kitchen	20.9	0	0	OK	None obs.	
Belt Transformers	20.9	0	0	OK	None obs.	
CO monitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Safe at Time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____ 2MSHA04046

Certificate # 9599
 Certificate # 9362
 Certificate # _____
 Certificate # _____

Counter Signature **SIGNATURE** _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-20-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:25 AM/PM PM Examiners Initials LD

Time of Examination Start 7 AM/PM AM End 8:45 AM/PM PM Examiners Initials JG

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	roller piles XC 2-7 Head	SENT MEN TO CLEAN DONE JG
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	none observed	
Belt transformers	20.9	0	0	ok	none observed	
C/O Monitors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at the time of exam except those noted above.

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9660

Certificate # 6622

Certificate # _____

Certificate # _____

2MSHA04047

SIGNATURE _____

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-21-07

SECTION/AREA BELTS

Time of Examination Start 3:15 AM/PM

End 5:00 AM/PM

Examiners Initials JE

Time of Examination Start 3:00 AM/PM

End 5:00 AM/PM

Examiners Initials LD

Time of Examination Start 4:15 AM/PM

End 5:10 AM/PM

Examiners Initials dy

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	none observed	
# 2	20.9	0	0	OK	NONE OBSERVED	
# 3	20.9	0	0	OK	NONE OBSERVED	
# 4	20.9	0	0	OK	NONE OBSERVED	
# 5	20.9	0	0	OK	None observed	
# 6	20.9	0	0	OK	none observed	
# 7	20.9	0	0	OK	Roller Piles 116-119	Done 5-21-07 mc
Belt kitchen	20.9	0	0	OK	none observed	
Belt transfer	20.9	0	0	OK	none observed	
C/O Monitors	Visual exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all Areas Appear Safe at the time of exam except those noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7485
 Certificate # 9660
 Certificate # 6622
 Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04048

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-21-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:15 AM PM Examiners Initials MC

Time of Examination Start 1100 AM PM End 1:15 AM PM Examiners Initials DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum drive	^{Cleaned} working on 5-21-07
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Commutors				USUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7385
 Certificate # 8058
 Certificate # _____
 Certificate # _____

2MSHA04049

SIGNATURE

Counter Signature _____

Certificate # 4975

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-21-07

SECTION/AREA Belts

Time of Examination Start 7.25 AM/PM (M) End 9.45 AM/PM (M) Examiners Initials PK/RL

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	roller pits from 70-78	overed up pits and cleaned 5/21/07
#5	20.9	0	0	OK	accum head roller	7214 m/c/y cleaned 5/21/07
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs.	
Belts Kitchen	20.9	0	0	OK	none obs	
Trans.	20.9	0	0	OK	none obs	
C.O. Monitor	visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe except as noted above.

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 6401
 Certificate # _____
 Certificate # _____

2MSHA04050

SIGNATURE
 Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-22-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 500 AM/PM Examiners Initials R/KK
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	roller pulley x 32 1/2	sent man to shove cleaned 5-22-07
#2	20.9	0	0	OK	roller pulley x 1	sent man to shove cleaned 5-22-07
#3	20.9	0	0	OK	acc x 67 3/4	sent man to shove Done 5-22-07
#4	20.9	0	0	OK	roller pulley 33.76	sent man to shove Done 5-22-07
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Belt Katcher	20.9	0	0	OK	none observed	
Trans	20.9	0	0	OK	none observed	
C.O. Monitors	normal					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS except as noted other areas appeared safe at time of exam.

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 7854
 Certificate # _____
 Certificate # _____

SIGNATURE
 Counter Signature _____

2MSHA04051

Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-22-07

SECTION/AREA Belts

Time of Examination Start 1100 AM PM End 130 AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	Acc. @ Tail And x-cut 40	sent men to shovel DONE 5-22-07
#4	20.9	0	0	ok	Acc. 73 to 76 + 67	sent men to shovel #67 Done 5-22-07 ALL
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	COAL Acc. in walkway 125 1/2	sent men to shovel DONE 5-22-07
Kitchen	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
CD monitors				Usual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04052

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-22-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 934 AM/PM PM Examiners Initials LR/RL
 Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	Acc. At drive	sent men to clean Cherwood 5-22-07
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none obs.	
Trans	20.9	0	0	OK	none obs.	
C.O. Monitor <u>normal</u>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above.

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6401
 Certificate # 4375
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04053

Counter Signature _____

Certificate # 4755

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-23-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials LR/JWK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs.	
#2	21.0	0	0	OK	Acc. AT TAIL	sent men to shovel Done 5-23-07
#3	21.0	0	0	OK	None obs	
#4	21.0	0	0	OK	90 to 96 Needs dust	sent men to dust Done 5-23-07
#5	21.0	0	0	OK	None obs.	
#6	21.0	0	0	OK	None obs.	
#7	21.0	0	0	OK	None obs	
Kitchen	21.0	0	0	OK	None obs	
Transformers	21.0	0	0	OK	None obs	
CO Monitors	6:15	SUM EXAM OK				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7 Headroll	Acc of coal	cleaned 5-23-07

PRE-SHIFT REMARKS Prems approved Safe at time of Exam except as noted above

Pre-Shift/Mine Examiner [Signature] Certificate # 4375

Pre-Shift/Mine Examiner [Signature] Certificate # 7954

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04054

Counter Signature [Signature] Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-23-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM End 1:15 AM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0		OK	none observed	
#2	20.9	0.0	0.0		OK	none observed	
#3	20.9	0.0	0.0		OK	none observed	
#4	20.9	0.0	0.0		OK	none observed	
#5	20.9	0.0	0.0		OK	none observed	
#6	20.9	0.0	0.0		OK	none observed	
#7	20.9	0.0	0.0		OK	none observed	
TB Transformers	20.9	0.0	0.0		OK	none observed	
Kitchen	20.9	0.0	0.0		OK	none observed	
CO monitors					VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE
AT TIME OF PRE-SHIFT

SIGNATURE
[Redacted Signature]

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

2MSHA04055

Certificate # 2375
Certificate # 8058
Certificate # _____
Certificate # _____

SIGNATURE
[Redacted Signature]

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-23-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM AM Examiners Initials LR/KR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	accepting air hand roller N5665 chut for good next floor	up with hood & painted cleaned
Belt Ketchen	20.9	0	0	OK	None obs.	
Trans.	20.9	0	0	OK	None obs.	
C.O. Monitor visual						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner  _____

Pre-Shift/Mine Examiner  _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7954

Certificate # 4325

Certificate # _____

Certificate # _____

2MSHA04056

Counter Signature  _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-24-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 530 AM/PM Examiners Initials KK/ER

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	α	α	α	air accum at drive	sent men to wash cleaned 5-24-07
#2	20.9	α	α	α	none obs.	
#3	20.9	α	α	α	none obs.	
#4	20.9	α	α	α	air accum at drive	sent men to wash cleaned 5-24-07
#5	20.9	α	α	α	None obs	
#6	20.9	α	α	α	none obs	
#7	20.9	α	α	α	none obs	
Belt Kitchens	20.8	α	α	α	none obs	
Trucks	20.9	α	α	α	none obs	
Ed. Lenses	visual					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at end of exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7954
 Certificate # 4325
 Certificate # _____
 Certificate # _____

2MSHA04057

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-24-07

SECTION/AREA Belts

Time of Examination Start 1100 ~~AM~~/PM End 120 AM/~~PM~~ Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Roller Piles Drive to 105 Cleared 5-24-07	Dave 5-24-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	Bad Top X-cut 123	Set timbers 5-24-07
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7376

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04058

SIGNATURE

Counter Signature _____

Certificate # 4235

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-24-07 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 915 AM/PM PM Examiners Initials IR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	None obs.	
#2	21.0	0	0	OK	None obs.	
#3	21.0	0	0	OK	None obs.	
#4	21.0	0	0	OK	None obs.	
#5	21.0	0	0	OK	105 to 108 Roller piles	Suitments cleared done 5-25-07
#6	21.0	0	0	OK	None obs.	
#7	21.0	0	0	OK	None obs.	
TRANS.	21.0	0	0	OK	None obs.	
Vitchow	21.0	0	0	OK	None obs.	
CD SENSORS	VISUAL EXAM OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7 Hauler	COAL Acc.	Cleared.

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 4375

Certificate # 7954

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04059

Certificate # 4935

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-25-07 SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 505 AM/PM Examiners Initials LR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	30 to 74.1L Needs Just	SENT MAN TO DIRT DONE OK
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	#173xc Deep water	BEING PUMPED pumped 5-25-07
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs	
#7	20.9	0	0	OK	None obs	
Trucks-	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
CO Sensors	U.S. MTS	Exam	OK			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 drive	Cont. Acc.	Cleaned
108xc	Hot Roller	Dropped

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner [Signature] Certificate # 4375

Pre-Shift/Mine Examiner [Signature] Certificate # 7954

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04060

Counter Signature [Signature] Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-25-07

SECTION/AREA 132/Hs

Time of Examination Start 12:00 AM/PM PM

End 1:00 AM/PM PM

Examiners Initials SLJ

Time of Examination Start 11 AM/PM PM

End 110 AM/PM PM

Examiners Initials dy

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	30 to tail wind dust	SENT MEN TO DUST DONE ✓
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	3 Drive float dust acc	BEING DUSTED DONE ✓
#4	20.9	0	0	OK	4 Tail piece ^{Small} spill	SENT MEN TO CLEAN DONE ✓
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	Coal acc & float dust	BEING DUSTED DONE ✓
#7	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors	USUAL (OK)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift except what is noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 6602
 Certificate # _____
 Certificate # _____

2MSHA04061

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-25-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:32 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs	
#2	20.9	0	0		OK	None obs	
#3	20.9	0	0		OK	ACC AT 3 Tail	sent men to work on it Done BA
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#7	20.9	0	0		OK	None obs.	
Transformers	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
Co sensors				Visual Exam			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above ALL AREAS
SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9362

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04062 Certificate # _____

Counter Signature **SIGNATURE** _____ Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-26-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:00 AM PM Examiners Initials TC

Time of Examination Start 3:20 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
CO sensor			Visual	ETA		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of ETA

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9562

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04063

Counter Signature SIGNATURE Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-26-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 12:55 AM/PM Examiners Initials SW

Time of Examination Start 11:50 AM/PM End 12:50 AM/PM Examiners Initials dy

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	OK	none observed	
#2	21.0	0	0	OK	none observed	
#3	21.0	0	0	OK	none observed	
#4	21.0	0	0	OK	none observed	
#5	21.0	0	0	OK	none observed	
#6	21.0	0	0	OK	none observed	
#7	21.0	0	0	OK	take-up needs dusting	BEING DUSTED Done dy
Transformers	21.0	0	0	OK	none observed	
kitchen	21.0	0	0	OK	none observed	
CO Monitors	(visual check)			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#7-TAKEUP	ACCUMULATION	CLEANED <u>dy</u>

PRE-SHIFT REMARKS All Areas appeared safe to work at time of exam exam except noted above.

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9548
 Certificate # 6622
 Certificate # _____
 Certificate # _____

2MSHA04064

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-26-07 SECTION/AREA Belts.

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials BP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.5	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Comonitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas seemed safe AT TIME
of EXAM

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 9362

Certificate # 9599

Certificate # _____

Certificate # _____

2MSHA04065

SIGNATURE

Counter Signature _____

Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-27-07 SECTION/AREA BELTS

Time of Examination Start 3:00 AM PM End 5:30 AM PM Examiners Initials BP

Time of Examination Start 3:00 AM PM End 5:15 AM PM Examiners Initials TR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	Needs Dusted 127-129 Stopping 129 needs Forward	SEND MEN TO DUST DOME IV REPAIRED STOPPING
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#6 Belt	Hot Bottom Roller	Removed Roller FROM SERVICE

PRE-SHIFT REMARKS Other than listed above all area safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 9599

Pre-Shift/Mine Examiner _____ Certificate # 9362

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04066

SIGNATURE _____

Counter Signature _____ Certificate # 7488

PRE-SHIFT BELTS

DATE OF EXAMINATION 50707 SECTION/AREA Belts

Time of Examination Start 11 AM/PM End 1:30 AM/PM Examiners Initials dg

Time of Examination Start 12:20 AM/PM End 1:10 AM/PM Examiners Initials SW

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO Sensors	0.15	0.9	0.00	ok		

ON-SHIFT HAZARDS IDENTIFIED

#5 Drive

LOCATION	HAZARDS	ACTION
5 Belt	Dump Bin plugged ^{on reflowing}	Cleaned

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6622
 Certificate # 9548
 Certificate # _____
 Certificate # _____

2MSHA04067

SIGNATURE
 Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-27-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM ~~AM~~

End 9:03 AM/PM ~~AM~~

Examiners Initials JK

Time of Examination Start 7:00 AM/PM ~~AM~~

End 9:00 AM/PM ~~AM~~

Examiners Initials BP

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	ACC AT Tail Piece	SENT men to Clean Done TC508
#3	20.9	0	0	OK	ACC AT Tail Piece	SENT men to Clean Done TC508
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Clo sensor				Visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted above ALL AREAS
Safe at Time of Exam

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 9362
 Certificate # 9399
 Certificate # _____
 Certificate # _____

2MSHA04068

SIGNATURE

Counter Signature _____

Certificate # 9279

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-28-07 SECTION/AREA Belts

Time of Examination Start 3:30 AM PM End 5:17 AM PM Examiners Initials JC

Time of Examination Start 4:35 AM PM End 5:17 AM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

Called Out By _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#3	20.9	0	0	OK	None Obs.	
Transformer	20.0	0	0	OK	None Obs.	
Kitchen	20.9	0	0	OK	None Obs.	
Clo Sensors				Visited Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 9562

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 8395

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** 2MSHA04069 Certificate # 8925

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-29-07 SECTION/AREA Belts

Time of Examination Start 3:05 AM/PM End 5:30 AM/PM Examiners Initials KR/LR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	Acc. #7 tail	Done 5-29-07
#5	20.9	0	0	OK	Acc not Drive	sent men to clean Done 5-29-07
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Timos Senses	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CD Senses	VI	Su	EX	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appraised safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 4325

Pre-Shift/Mine Examiner _____

Certificate # 7954

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04070

SIGNATURE

Counter Signature _____

Certificate # 4135

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-29-07 SECTION/AREA Belts
 Time of Examination Start 11:10 AM/PM End 1:55 AM/PM Examiners Initials LR/KK
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	Stepping damaged #54	done 5-29-07 DLG
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	Need timber between 106 to 107	done 5-29-07 DLG
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO SENSORS	Visual Exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner [Signature]
 Pre-Shift/Mine Examiner [Signature]

Certificate # 4325
 Certificate # 7954
 Certificate # _____
 Certificate # _____

Counter Signature [Signature] 2MSHA04071

Certificate # 4235

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-29-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (PM) End 9:00 AM/PM (PM) Examiners Initials mo/DP

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	stopping damaged vcut 54	working on Done 5-29-07
#4	20.9	0	0	OK	oil accumulator roller piled by accumulator	working on Done 5-29-07
#5	20.9	0	0	OK	need Timber 106-107	working on Done 5-29-07
#6	20.9	0	0	OK	Accum drive	working on Done 5-29-07
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				W/SHA Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE EXCEPT AS NOTED

Pre-Shift/Mine Examiner **Signature**

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner **SIGNATURE**

Counter Signature _____

Certificate # 2375

Certificate # 8058

Certificate # _____

Certificate # _____

Certificate # _____

Certificate # 8462

2MSHA04072

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-30-07

SECTION/AREA Belts

Time of Examination Start ~~535~~ AM/PM End ~~727~~ AM/PM Examiners Initials _____
 Time of Examination Start 300 AM/PM End 535 AM/PM Examiners Initials DD mc
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	needs dust from x-20 to tail piece	sent men to clean
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	coal acc. @ Tail piece	Assessment clean done 5/30/07
#4	21	0	0	ok	Deep water x-73	Assessment to pump
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
TRANS.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO monitors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04073

SIGNATURE
 Counter Signature _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-30-07 SECTION/AREA Belts

Time of Examination Start 11:10 AM/PM End 1:40 AM/PM Examiners Initials CR/KK

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Need dust 20 to Thru	Working on Done 5-30-07
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	Deep water 73	Working on Done 5-30-07
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
TRANSFORMERS	20.9	0	0	OK	None observed	
CO SENSORS	4:50	OK	EXAM	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner [Signature] Certificate # 4375

Pre-Shift/Mine Examiner [Signature] Certificate # 7954

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature [Signature] Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-30-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM PM End 935 AM/PM AM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	CO/acc. @ Tailpiece	Sent men to work on Dowl 5-31-07
#4	20.9	0	0	ok	Deepwater X-73	Sent men to work on Dowl 5-31-07
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
CO Sensors	Visual ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE _____

2MSHA04075

Counter Signature _____

Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-31-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM PM End 5:20 AM PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	Accum drive	Sent Minn to clear Done
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	need dust 126 To Tail Pulver pits headroom to drive	Sent Minn to clear Done 5-31-07 Sent Minn to clear
TRANS.	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
CO Sensors				Visual OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe AT
Time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7325
 Certificate # 8058
 Certificate # _____
 Certificate # _____

2MSHA04076

Counter Signature **SIGNATURE** _____

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-31-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 12:31 AM/PM

Examiners Initials RK/LR

Time of Examination Start 11:00 AM/PM

End 11:33 AM/PM

Examiners Initials FM

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	None obs	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	none obs	
#5	20.9	0	0	OK	acc. pt. down	still cleaning Done 5:31-07
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	piles seen head to drive	still cleaning Done 5:31-07
Belt Kitchen	20.9	0	0	OK	none obs	
Trans	20.9	0	0	OK	none obs	
C.O. Monitor				OK	visual exam OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

SIGNATURE

Certificate # 784
 Certificate # 4375
 Certificate # 4135
 Certificate # 8227

Counter Signature _____

SIGNATURE

2MSHA04077

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 5-31-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 918 AM/PM PM Examiners Initials DDM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	COAL ACC @ TAIL Deep water X-3	Dave 6-1-07
#3	20.9	0	0	ok	COAL ACC @ TAIL	Dave 6-1-07
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	COAL ACC @ TAIL	Dave 6-1-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS,	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 8058
 Pre-Shift/Mine Examiner **SIGNATURE** _____ Certificate # 7376
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature **SIGNATURE** _____ 2MSHA04078 Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-1-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials MC/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	NONE OBSERVED	
#2	20.9	0	0	OK	NONE OBSERVED	
#3	20.9	0	0	OK	NONE OBSERVED	
#4	20.9	0	0	OK	NONE OBSERVED	
#5	20.9	0	0	OK	NONE OBSERVED	
#6	20.9	0	0	OK	NONE OBSERVED	
#7	20.9	0	0	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	OK	NONE OBSERVED	
CONDUITS K: Khen	20.9	0	0	OK	NONE OBSERVED	
CD MONITORS				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7325

Certificate # 8058

Certificate # _____

Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04079

Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-1-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM PM End 1:30 AM PM Examiners Initials LR/HR

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		α	none observed	
#2	20.9	0	0		α	none observed	
#3	20.9	0	0		α	none observed	
#4	20.9	0	0		α	accum head roller to x-cut 68 - Deep water 73	Cleaned HR to 68
#5	20.9	0	0		α	none observed	
#6	20.9	0	0		α	none observed	
#7	20.9	0	0		α	none observed	
Belt Kitchen	20.9	0	0		α	none observed	
Trans.	20.9	0	0		α	none observed	
C.O. Monitors visual exam							

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 7951
 Certificate # 4325
 Certificate # _____
 Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04080

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-1-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM

End 9:10 AM/PM PM

Examiners Initials mc

Time of Examination Start 700 AM/PM AM

End 915 AM/PM PM

Examiners Initials DD

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	0.1 Accum drive	working on Done 6-2-07
#2	20.9	0	0	OK	NONE OBSERVED	
#3	20.9	0	0	OK	NONE OBSERVED	
#4	20.9	0	0	OK	Roller Piles 70-73 Deep water 73	working on Done 6-2-07
#5	20.9	0	0	OK	Accum drive	working on Done 6-2-07
#6	20.9	0	0	OK	NONE OBSERVED	
#7	20.9	0	0	OK	Roller Piles Takeup to 114	working on Done 6-2-07
Truss Formers	20.9	0	0	OK	NONE OBSERVED	
Kitchen	20.9	0	0	OK	NONE OBSERVED	
CO monitors						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas Appeared Reasonably safe except
As noted above

SIGNATURE

Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____
Pre-Shift/Mine Examiner _____

Certificate # 7375
Certificate # 8058
Certificate # _____
Certificate # _____

SIGNATURE

Counter Signature _____

2MSHA04081

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-2-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~ PM End 520 ~~AM~~ PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.7	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	X-129-130 Acc. coal walkway & under belt	Ass. man to clean cleaned 6-2-07
Trans	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe
at time of exam

SIGNATURE
Pre-Shift/Mine Examiner _____

Certificate # 8058

Pre-Shift/Mine Examiner _____

Certificate # 7375

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE
Counter Signature _____

2MSHA04082

Certificate # _____

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-2-07 SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 200 AM/PM Examiners Initials KN/RC

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Belt Kitchen	20.9	0	0	OK	none observed	
Trans.	20.9	0	0	OK	none	
C.O. Monitors	rechecked			OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time before

Pre-Shift/Mine Examiner SIGNATURE Certificate # 640

Pre-Shift/Mine Examiner SIGNATURE Certificate # 7954

Pre-Shift/Mine Examiner Certificate #

Pre-Shift/Mine Examiner Certificate #

Counter Signature SIGNATURE 2MSHA04083 Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-2-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 925 AM/PM PM Examiners Initials DD/mc

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	cont acc under belt x-5 to x-8	working on cleaned 6-2-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Transformers	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO sensors	Visual		ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

SIGNATURE _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

2MSHA04084

Certificate # 8058

Certificate # 7375

Certificate # _____

Certificate # _____

SIGNATURE _____

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-3-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:17 AM/PM Examiners Initials ME/DD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Workshop	20.9	0	0	OK	none observed	
COMPARATORS				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE
AT TIME OF EXAM

Pre-Shift/Mine Examiner **Signature** Certificate # 7875

Pre-Shift/Mine Examiner **Signature** Certificate # 8056

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04085

Counter Signature **SIGNATURE** Certificate # 4735

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-3-07

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM AM PM End 110 AM/PM AM PM Examiners Initials R1/PR

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Time of Examination Start _____ AM/PM AM PM End _____ AM/PM AM PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none	
Kilbuck	20.9	0	0	OK	none	
CO Sensor	Visual check			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 6401

Certificate # 4875

Certificate # _____

Certificate # _____

2MSHA04086

SIGNATURE

Counter Signature _____

Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-3-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:15 AM/PM PM Examiners Initials MC/DRD

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	need dust 56 to 40	sent men to dust Dusted 6-3-07
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	Roller pikes Head to Tail	sent men to shovel shoveled 106 to tail 6-4-07
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	Accum x cut 123	sent men to shovel Pile 6-4-07
TRANSFORMERS	20.9	0	0	OK	Roller pikes none observed	
DRY KITCHEN	20.9	0	0	OK	none observed	
CO MONITORS				visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe BT
Time of pre-shift

SIGNATURE _____

Pre-Shift/Mine Examiner _____ Certificate # 7375

Pre-Shift/Mine Examiner _____ Certificate # 8058

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

SIGNATURE _____ 2MSHA04087

Counter Signature _____ Certificate # 8462

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-4-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM End 530 AM/PM Examiners Initials DD ml

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CR/M/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	none obs.	
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	none obs.	
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Trans.	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
CO Sensors		Visual ok				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner **SIGNATURE** _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 8058
 Certificate # 7375
 Certificate # _____
 Certificate # _____

2MSHA04088

Counter Signature **SIGNATURE** _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6 4 0 7 SECTION/AREA Belts

Time of Examination Start 11 AM/PM End 12:5 PM AM/PM Examiners Initials JG

Time of Examination Start 11:00 AM/PM End 1:20 AM/PM Examiners Initials FM

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____ Report Received by _____

Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	None observed	
#7	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
CO sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Pre-Shift/Mine Examiner [Signature] Certificate # 6622

Pre-Shift/Mine Examiner [Signature] Certificate # 8297

Pre-Shift/Mine Examiner _____ Certificate # _____

Pre-Shift/Mine Examiner _____ Certificate # _____

Counter Signature [Signature] Certificate # 7485

2MSHA04089

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-4-07

SECTION/AREA Belts

Time of Examination Start 7:20 AM PM End 9:50 AM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	Needs dust 7 to portal	Dusting Done GA 6507
#2	20.9	0	0		OK	None Observed	
#3	20.9	0	0		OK	None Observed	
#4	20.9	0	0		OK	None Observed	
#5	20.9	0	0		OK	None Observed	
#6	20.9	0	0		OK	None Observed	
#7	20.9	0	0		OK	None Observed	
Belt Kitchen	20.9	0	0		OK	None Observed	
Belt transformer	20.9	0	0		OK	None Observed	
CO monitors					Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Except as noted above all areas appeared reasonably safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04090

Counter Signature _____

Certificate # 03992

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-5-07 SECTION/AREA Belts
 Time of Examination Start 3:23 (AM/PM) End 5:37 (AM/PM) Examiners Initials BH
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____
 Exam. Called Out - Yes No

Called Out By _____
 Called Out By _____ Report Received by _____
 Called Out By _____ Signature _____

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
CO monitors	Visual			exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE Certificate # 8395
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____
 Pre-Shift/Mine Examiner _____ Certificate # _____

2MSHA04091

Counter Signature SIGNATURE Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-5-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM End 1:00 AM Examiners Initials z.d

Time of Examination Start 11 AM End 1:15 AM Examiners Initials clj

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	coal acc from ^{103X} to 107X	SENT MEN TO CLEAN DONE JG
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Belt kitchen	20.9	0	0	ok	None observed	
transformers	20.9	0	0	ok	None observed	
CO Sensors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#4-BELT	HOT ROLLER	REMOVED & REPLACED ROLLER

PRE-SHIFT REMARKS

all areas examined appear safe at time of pre-shift except what is noted above?

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6623

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04092

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-5-07

SECTION/AREA Belts

Time of Examination Start 7:18 AM/PM AM End 7:50 AM/PM PM Examiners Initials CP

Time of Examination Start 7:30 AM/PM AM End 9:46 AM/PM PM Examiners Initials BH

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	α	None Observed	
#2	20.9	0	0	α	None Observed	
#3	20.9	0	0	α	None Observed	
#4	20.9	0	0	α	None Observed	
#5	20.9	0	0	α	None Observed	
#6 Belt	20.9	0	0	α	None observed	
#7 Belt	20.9	0	0	α	None observed	
Kitchen	20.9	0	0	α	None Observed	
Transformers	20.9	0	0	α	None Observed	
CO monitors				Visual exam	α	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all area's appeared reasonably safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 6908

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

SIGNATURE

2MSHA04093

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-6-07

SECTION/AREA Belts

Time of Examination Start 3:04 AM/PM

End 4:45 AM/PM

Examiners Initials LP

Time of Examination Start 3:25 AM/PM

End 5:33 AM/PM

Examiners Initials BY

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6 Belt	20.9	0	0	OK	None observed	
#7 Belt	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
① Kitchen	20.9	0	0	OK	None observed	
CO monitors		Visual		exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All ~~the~~ areas appeared reasonably safe at
Time of exam

SIGNATURE
 Pre-Shift/Mine Examiner _____

Certificate # 6908

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

2MSHA04094

Certificate # _____

SIGNATURE
 Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-6-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 12:50 AM/PM Examiners Initials LP

Time of Examination Start 11 AM/PM End 1 AM/PM Examiners Initials dy

Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	Float Dust ^{96X TO Tail} acc	BEING DUSTED DONE JG
#5	20.9	0	0	ok	Float Dust ^{X96 TO 109X} acc	BEING DUSTED DONE JG
#6	20.9	0	0	ok	Needs Dust	
#7	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	None observed	
Belt kitchen	20.9	0	0	ok	none observed	
CO Monitors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
5 Drive	Coal accumulations ^{Fines}	cleaned dy

PRE-SHIFT REMARKS All areas examined appear safe at time of pre-shift except what is noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 9660

Pre-Shift/Mine Examiner _____

Certificate # 6622

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____ 2MSHA04095

Certificate # _____

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-6-07

SECTION/AREA Belts

Time of Examination Start 2:36 AM/PM (M) End 8:00 AM/PM (M) Examiners Initials LP
 Time of Examination Start 7:30 AM/PM (M) End 9:48 AM/PM (M) Examiners Initials BH
 Time of Examination Start _____ AM/PM End _____ AM/PM Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Belt Kitchen	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
CO monitors				Unusual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____
 Pre-Shift/Mine Examiner _____

Certificate # 6908
 Certificate # 8395
 Certificate # _____
 Certificate # _____

SIGNATURE

2MSHA04096

Counter Signature _____

Certificate # 03892

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-7-07

SECTION/AREA Belts

Time of Examination Start 3:28 AM/PM

End 3:50 AM/PM

Examiners Initials LP

Time of Examination Start 3:33 AM/PM

End 5:30 AM/PM

Examiners Initials BH

Time of Examination Start _____ AM/PM

End _____ AM/PM

Examiners Initials _____

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Report Received by _____

Called Out By _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	Needs dust offside w/air head to pickup	SENT MEN TO DUST DONE - TG
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Belt kitchen	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
CO monitors				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner _____

Certificate # 6908

Pre-Shift/Mine Examiner _____

Certificate # 8395

Pre-Shift/Mine Examiner _____

Certificate # _____

Pre-Shift/Mine Examiner _____

Certificate # _____

2MSHA04097

SIGNATURE

Counter Signature _____

Certificate # 7485

PRE-SHIFT BELTS

DATE OF EXAMINATION 6-7-07

SECTION/AREA BELTS

Time of Examination Start 11:10 AM/PM

End 12:05 AM/PM

Examiners Initials JG

Time of Examination Start 11:00 AM/PM

End 12:50 AM/PM

Examiners Initials LD

Time of Examination Start 11 AM/PM

End 1 AM/PM

Examiners Initials LD

Exam. Called Out - Yes No

Called Out By _____

Called Out By _____

Called Out By _____

Report Received by _____

Signature

LOCATION	O ₂	CH ₄ %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1 - BELT	20.9	0	0	OK	NONE OBSERVED	
# 2	20.9	0	0	OK		
# 3	20.9	0	0	OK		
# 4	20.9	0	0	OK		
# 5	20.9	0	0	OK		
# 6	20.9	0	0	OK		
# 7	20.9	0	0	OK		
Belt kitchen	20.9	0	0	OK		
transformers	20.9	0	0	OK	none observed	
CO monitors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all areas examined appear safe at time of pre-shift

SIGNATURE

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Pre-Shift/Mine Examiner _____

Certificate # 7485

Certificate # 9660

Certificate # 6632

Certificate # _____

SIGNATURE

2MSHA04098

Counter Signature _____

Certificate # 7485

