



**PRE-SHIFT  
BELTS**

2MSHA04100

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-31-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 910 AM/PM PM Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	oil acc. at Drive	working on Cleaned 3-31-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	acc. at tail	Cleaned 4-1-07 mc
#5	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
CO sensors		Visual ok				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04101

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-1-07

SECTION/AREA BELTS

Time of Examination Start 3:00  AM  PM

End 5:05  AM  PM

Examiners Initials MC

Time of Examination Start 300  AM  PM

End 500  AM  PM

Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	need dust Headroller to x cut 22	Dusted 4-1-07
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CD monitors					#3 belt xcut 54 CD monitor don't work	Corrected 4-1-07

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe AT  
Time of pre-shift

**SIGNATURE**  
[Redacted Signature]

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**  
[Redacted Signature]

Counter Signature \_\_\_\_\_

2MSHA04102

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-1-07 SECTION/AREA Belt

Time of Examination Start 11:00  AM  PM End 1:15  AM  PM Examiners Initials RL/LR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs	
#2	20.9	0	0	OK	None obs	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs	
#5	20.9	0	0	OK	Acc. At Drive	Working on done 4-1-07
Belt Kitcher	20.9	0	0	OK	None obs	
Trans.	20.9	0	0	OK	None obs	
G.O. Mombot						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 4375

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 6901

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_ 2MSHA04103

Counter Signature \_\_\_\_\_ Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-1-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials Mr. [Signature]

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	need dust headrope to brake	Done 4-1-07 mc
#5	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF PRESHIFT

Pre-Shift/Mine Examiner [Signature]  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 2375  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature [Signature]

2MSHA04104

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-2-07 SECTION/AREA BELTS

Time of Examination Start 3:00  AM/PM End 4:55  AM/PM Examiners Initials mcd

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out --  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Drive	Coal accumulations	cleaned

PRE-SHIFT REMARKS Area appeared reasonably safe AT  
Time of exam

Pre-Shift/Mine Examiner Signature Certificate # 2375

Pre-Shift/Mine Examiner Signature Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04105

Counter Signature SIGNATURE Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-2-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:10 AM/PM Examiners Initials L.R./W.K.

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#Transformers	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
CO Monitor	Visual Exam OK						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Henderoller	Coal Acc.	Cleaned 4-2-07

PRE-SHIFT REMARKS Areas appened Safe at time of Exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4325  
 Certificate # 7954  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04106

Counter Signatur **Signature** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-2-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM  AM  PM End 900 AM/PM  AM  PM Examiners Initials DD/mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	ok	none obs.	
#2	20.9	0.0	0.0	ok	none obs.	
#3	20.9	0.0	0.0	ok	none obs.	
#4	20.9	0.0	0.0	ok	none obs.	
#5	20.9	0.0	0.0	ok	none obs.	
Transformers	20.9	0.0	0.0	ok	none obs.	
Kitchen	20.9	0.0	0.0	ok	none obs.	
CO monitors			Visual ok			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04107

Certificate # 8058

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-3-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM End 5:00  AM  PM Examiners Initials ML/DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum xcut &	SENT MEN TO CLEAN cleared by
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Drive	Accum coal	cleaned
#3 belt	needs dusted	Dusted Bolt

PRE-SHIFT REMARKS Areas appeared reasonably safe AT  
Time of pre-shift

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04108

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4/30/7 SECTION/AREA Belts

Time of Examination Start 11:05 (AM/PM) End 12:45 (AM/PM) Examiners Initials dy

Time of Examination Start 11:05 (AM/PM) End 12:45 (AM/PM) Examiners Initials LD

Time of Examination Start \_\_\_\_\_ (AM/PM) End \_\_\_\_\_ (AM/PM) Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	ACC XC35 on top overcast	BEING CLEANED DONE <u>IG</u>
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO MONITORS	Visual Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

Pre-Shift/Mine Examiner SIGNATURE Certificate # 6622

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature SIGNATURE 2MSHA04109 Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-3-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:15 AM/PM PM Examiners Initials JR

Time of Examination Start 7:05 AM/PM AM End 8:30 AM/PM PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By Brian Pritt

Called Out By \_\_\_\_\_ Report Received by Brent Hard

Called Out By \_\_\_\_\_ Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.5	0	0	OK	None obs.	
#2	20.7	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transferrances	20.9	0	0	OK	None obs.	
Clo sensor				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe

at time of exam

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9362

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature SIGNATURE Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-4-07

SECTION/AREA BELTS

Time of Examination Start 3:00 (AM/PM)

End 5:30 (AM/PM)

Examiners Initials BP

Time of Examination Start 3:00 (AM/PM)

End 4:56 (AM/PM)

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO SCANNERS				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner \_\_\_\_\_

**SIGNATURE** [Redacted]

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature \_\_\_\_\_

**SIGNATURE** [Redacted]

2MSHA04111

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-4-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials JD

Time of Examination Start 11 AM/PM End 1245 AM/PM Examiners Initials JD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Acc under Belt 100-7ait	SENT MEN TO CLEAN Done JD
#5	20.9	0	0	ok	Roller piles had total Acc under Hand Roller	BEING CLEANED Done JD
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam			ok		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#5 Belt	Acc on both sides of the feeder	Cleaned JD
#1 Belt	Bad Bottom Roller, Hot	Dropped From Structure

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above.

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04112

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-4-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:45 AM/PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 8:40 AM/PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	ok	none observed	
# 2	20	0	0	ok	none observed	
# 3	20	0	0	ok	none observed	
# 4	20	0	0	ok	none observed	
# 5	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_ 2MSHA04113

Counter Signature \_\_\_\_\_ Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-5-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM

End 5:12  AM  PM

Examiners Initials TR

Time of Examination Start 3:00  AM  PM

End 5:16  AM  PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM  PM

End \_\_\_\_\_ AM  PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
K. J. J. J.	20.9	0	0		OK	None obs.	
Transformers	20.9	0	0		OK	None obs.	
Chlorinator	Visual Exam						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All Areas appeared safe at time

of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Certificate # 9599

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04114

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4 5 07 SECTION/AREA Belts

Time of Examination Start 11 AM End 1245 AM Examiners Initials Jy

Time of Examination Start 11:00 AM End 1:00 AM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.	0	0	ok	none obs	
#2	21.	0	0	ok	none obs	
#3	21.	0	0	ok	none obs	
#4	21.	0	0	ok	Belts running in fire	SENT MEN TO CLEAN Done LD
#5	20.9	0	0	ok	none obs	
Kitchen	20.9	0	0	ok	none obs	
transformers	20.9	0	0	ok	none obs	
C/O SENSORS				Visual exam		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
SIX CUT	Back Bottom <sup>HOT</sup> roller	Dropped roller <sup>FROM</sup> STRUT

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04115

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-5-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM End 8:50 AM/PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM End 9:05 AM/PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	ok	none observed	
# 2	20	0	0	ok	none observed	
# 3	20	0	0	ok	none observed	
# 4	20	0	0	ok	none observed	
# 5	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04116  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-6-07 SECTION/AREA Belts

Time of Examination Start 3:02 AM/PM End 5:10 AM/PM Examiners Initials TC

Time of Examination Start 3:00 AM/PM End 5:16 AM/PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	none obs.	
#2	20.9	0	0		OK	ACC. AT Tail PICKLE	SENT MEN TO CLEAR DONE
#3	20.9	0	0		OK	none obs.	
#4	20.9	0	0		OK	none obs.	
#5	20.9	0	0		OK	none obs.	
Kitchen	20.9	0	0		OK	none obs.	
Transformer	20.9	0	0		OK	none obs.	
CO sensor					Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 Belt	Hot Roller AT Tail	Turned Belt off and Removed Roller From Service TC 46-07

PRE-SHIFT REMARKS Other than listed ABOVE All AREAS safe  
AT Time of Exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362  
 Certificate # 9599  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04117

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4607 SECTION/AREA Belts

Time of Examination Start 11 AM/PM End 1245 AM/PM Examiners Initials dy

Time of Examination Start 11:00 AM/PM End 1:12 AM/PM Examiners Initials JW

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Tailpiece spill	SENT MEN TO CLEAN Done dy
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Tail piece coal accumulation	SENT MEN TO CLEAN None dy
#5	20.9	0	0	ok	Drive area coal accu.	SENT MEN TO CLEAN Done dy
kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO Monitors	(visual exam)			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe to work at time of exam except above notes

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 6622

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 9548

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04118

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-6-07 SECTION/AREA Belts

Time of Examination Start 7:00 ~~AM~~ PM End 8:45 AM/PM Examiners Initials BP

Time of Examination Start 7:20 AM/PM End 9:00 AM/PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	ok	none observed	
# 2	20	0	0	ok	none observed	
# 3	20	0	0	ok	none observed	
# 4	20	0	0	ok	none observed	
# 5	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO Sensors	Visual			exam	ok	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All crews appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 9599

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 8395

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04119

Counter Signature **SIGNATURE** Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-7-06

SECTION/AREA Belts

Time of Examination Start 7:20 AM/PM End 5:10 AM/PM Examiners Initials BP

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	Roller Piles Handrattled	SENT MEN TO CLEAN DOWN - TB
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO sensors				VIGAVI Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared

Safe at time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8395

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04120

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-7-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:00 AM/PM

Examiners Initials LD

Time of Examination Start 11 AM/PM

End 12:45 AM/PM

Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	ACC at tail	BEING CLEANED DONE JD
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
transformers	20.9	0	0	ok	None observed	
C/O Sensors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#1 xc8	ACC coat	Cleaned JD

PRE-SHIFT REMARKS all Areas appeared safe at time of exam except those noted above

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

SIGNATURE

Counter Signature \_\_\_\_\_

2MSHA04121

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-7-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials BP

Time of Examination Start 7:22 AM/PM AM End 8:55 AM/PM PM Examiners Initials BA

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CV Sensors				W/Scuff Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 8395  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04122

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-9-07 SECTION/AREA Belts

Time of Examination Start 3:47 AM/PM End 4:25 AM/PM Examiners Initials KM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	ACC XC 8	Corrected 4-9-07
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	ACC head roller to drive	Corrected 4-9-07
#4	20.9	0	0	OK	ACC XC 68	Corrected 4-9-07
#5	20.9	0	0	OK	None observed.	
Kitchen	20.9	0	0	OK	None obs.	
Transformers	20.9	0	0	OK	None obs.	
CO Sensors	Visual Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Atlas appeared safe at the time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 9379

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ 2MSHA04123 Certificate # 9385

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-9-07 SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 12:45 AM  PM Examiners Initials LR/KM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None obs.	
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
Transformer	20.9	0	0		OK	None obs.	
CO SOWORS	V. S	Sub	Exam	OK			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4325  
 Certificate # 9379  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04124

Certificate # 9385

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-9-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:55 AM/PM PM Examiners Initials MC/KK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	none observed	
#2	20.9	0.0	0.0	OK	none observed	
#3	20.9	0.0	0.0	OK	none observed	
#4	20.9	0.0	0.0	OK	none observed	
#5	20.9	0.0	0.0	OK	Accum Heddroller	cleaned 4-9-07 KK
Kitchen	20.9	0.0	0.0	OK	none observed	
Transformers	20.9	0.0	0.0	OK	none observed	
CO Sensors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe  
AT Time of Pre-shift

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7325

Certificate # 7954

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04125

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-10-07

SECTION/AREA Belts

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
BELTS Idle						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04126

Counter Signature SIGNATURE

Certificate # 9385



# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-11-07

SECTION/AREA Belts

Time of Examination Start 300  AM  PM End 520  AM  PM Examiners Initials DD KK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	none obs.	
#2	20.9	0	0		ok	none obs.	
#3	20.9	0	0		ok	none obs.	
#4	20.9	0	0		ok	none obs.	
#5	20.9	0	0		ok	none obs.	
Trans.	20.9	0	0		ok	none obs.	
Kitchen	20.9	0	0		ok	none obs.	
CO Sensors					Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe At time of exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04128

Certificate # 8058  
 Certificate # 7959  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-11-07

SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~/PM End 1:15 AM/~~PM~~ Examiners Initials KM/LR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	need dust from tail to 108	Working on same 4-11-07
#6	20.9	0	0	OK	needs dusted	Working on same 4-11-07
Kitchen	20.9	0	0	OK	none obs.	
TRANS	20.9	0	0	OK	none obs.	
CO sensors visual exam OK						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Signature

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9329

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04129

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 9385

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-11-07

SECTION/AREA Belt

Time of Examination Start 7:00 AM/PM (P)

End 8:45 AM/PM (P) Examiners Initials MC/DIS

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum Tail piece	cleaned 4-11-07
#2	20.9	0	0	OK	NONE OBSERVED	
#3	20.9	0	0	OK	NONE OBSERVED	
#4	20.9	0	0	OK	NONE OBSERVED	
#5	20.9	0	0	OK	NONE OBSERVED	
#6	20.9	0	0	OK	NONE OBSERVED	
Trams	20.9	0	0	OK	NONE OBSERVED	
Kitchen	20.9	0	0	OK	NONE OBSERVED	
C.O. Monitor				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 2325  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04130

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-12-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:00 AM/PM Examiners Initials MC/RR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Ritchon	20.9	0	0	OK	none observed	
CO monitors				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **Signature** Certificate # 7325

Pre-Shift/Mine Examiner **Signature** Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04131

Counter Signature **SIGNATURE** Certificate # 9385

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-12-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials KM LR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	needs dust xc96 to 91	Working on done 4-12-07
#5	20.9	0	0	OK	acc drive	Working on done 4-12-07
#6	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Trans	20.9	0	0	OK	none obs.	
CO monitors	<del>20.9</del>	<del>0</del>	<del>0</del>	visual OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Certificate # 4375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04132

Certificate # 9385

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-12-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM  AM  PM End 915 AM/PM  AM  PM Examiners Initials DD mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	oil accumulations @ Drive	sent men to work on <u>Done</u>
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	COAL ACC. @ Drive	sent men to work on <u>Done PC</u>
#6	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
CO monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 7375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

2MSHA04133

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-13-07

SECTION/AREA Belt

Time of Examination Start 3:00 AM/PM End 5:00 AM/PM Examiners Initials ML/DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	Tail piece AREA needs dusted	Sent people to dust. Ct
#6	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO monitors				USUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF PRE-SHIFT

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04134

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-13-07

SECTION/AREA BELTS

Time of Examination Start 11:00  AM  PM End 12:54 AM  PM Examiners Initials BP

Time of Examination Start 11:00  AM  PM End 1:12 AM  PM Examiners Initials TR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO Sensors				W/ Suel Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
7X Cut A/belt	Damaged Fire valve	repaired. CT 4/13/07

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9899

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04135

Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Certificate # 02992

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-13-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:50 AM/PM PM Examiners Initials LD

Time of Examination Start 7 AM/PM AM End 745 AM/PM PM Examiners Initials alg

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	Acc Head Roller Acc tail	cleaned by
transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO Sensors	Visual exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at the time of exam except those noted above.

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

SIGNATURE

Counter Signature \_\_\_\_\_

2MSHA04136

Certificate # 7483

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-14-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM/PM) End 5:00 (AM/PM) Examiners Initials LD

Time of Examination Start 3 (AM/PM) End 443 (AM/PM) Examiners Initials g

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
kitchen	20.9	0	0	ok	none observed	
C/O Sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared to be safe at the time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04137

Certificate # 05892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-14-07

SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~ PM

End 1:04 ~~AM~~ PM

Examiners Initials BP

Time of Examination Start 11:00 ~~AM~~ PM

End 1:10 ~~AM~~ PM

Examiners Initials TR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	OK	none observed	
# 2	20	0	0	OK	none obs.	
# 3	20	0	0	OK	none observed	
# 4	20	0	0	OK	none observed	
# 5	20	0	0	OK	none obs.	
# 6	20	0	0	OK	Needs Dusted Head to Tail	working on Dusted 4-14-07 BY
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than listed Above All Areas  
Safe At Time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04138

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-14-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM (M)

End 9:55 AM/PM (M)

Examiners Initials SD

Time of Examination Start 7 AM/PM (M)

End 8:30 AM/PM (M)

Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	ACC tail	BEING CLEANED Done SD
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
c/o Sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all Areas appeared safe at time of exam except those noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04139

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-15-07

SECTION/AREA Belts

Time of Examination Start 3:05 (AM) PM

End 5:05 (AM) PM

Examiners Initials LD

Time of Examination Start 3:05 (AM) PM

End 4:45 (AM) PM

Examiners Initials edg

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	Acc at tail mostly Back side	Sent people to clean at Done 4-15-07
#3	20.9	0	0	OK	Acc at Drive to XC 104	Sent people to clean at Done 4-15-07
#6	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
C/O Sensors	Visual exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at the time of exam except those noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04140

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-13-07 SECTION/AREA Belt 3

Time of Examination Start 11:00  AM  PM End 12:50 AM  PM Examiners Initials BP

Time of Examination Start 11:00  AM  PM End 1:16 AM  PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	ok	none observed	
# 2	20	0	0	ok	none observed	
# 3	20	0	0	ok	none observed	
# 4	20	0	0	ok	none observed	
# 5	20	0	0	ok	none observed	
# 6	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO SENSORS				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Certificate # 9362

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature SIGNATURE \_\_\_\_\_

2MSHA04141

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-15-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:55 AM/PM PM Examiners Initials JG

Time of Examination Start 8:10 AM/PM AM End 9 AM/PM AM Examiners Initials JG

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	Dust 35-tail	BEING DUSTED DONE JG
#3	20.9	0	0	ok	Acc 47-48	BEING CLEANED DONE JG
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	Acc 109-tria heds dusted	BEING CLEANED & DUSTED DONE JG
#6	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
C/O Sensors					Visual exam ok	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above

Pre-Shift/Mine Examiner [Signature]  
 Pre-Shift/Mine Examiner [Signature]  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04142

Counter Signature [Signature]

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-16-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM)/PM

End 5:12 (AM)/PM

Examiners Initials ZD

Time of Examination Start 345 (AM)/PM

End 515 (AM)/PM

Examiners Initials Zg

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04143

Certificate # \_\_\_\_\_

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-16-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials KM/MC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Acc drive	Cleaned 4-16-07
#6	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Trans	20.9	0	0	OK	none obs.	
CO monitors	vis	vis	vis	ex am		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04144

Certificate # 9379

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-16-07

SECTION/AREA Belts

Time of Examination Start 8:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials LR/KK

Time of Examination Start 9:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials LD

Time of Examination Start 8 AM/PM AM End 850 AM/PM PM Examiners Initials LD

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs	
#2	20.9	0	0	OK	Acc. At Tail	Sent man to clean cleaned 4-16-07
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	Acc at Drive - 2011 by	Sent man to clean cleaned 4-16-07
#6	20.9	0	0	OK	None obs	
Kitchen	20.9	0	0	OK	None observed	
Turns.	20.9	0	0	OK	None observed	
CO Monitors	Visual Exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above.

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Certificate # 9660

Certificate # 7954

Certificate # 6672

Counter Signature \_\_\_\_\_

2MSHA04145

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-17-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM)/PM End 5:30 (AM)/PM Examiners Initials KR/RL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs	
#3	20.9	0	0	OK	accum tool	sent men to work on PONE 4-17-07 ml
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	accum head roller	sent men to work on PONE 4-17-07 ml
#6	20.9	0	0	OK	none obs	
Kitchen	20.9	0	0	OK	none obs	
Trams	20.9	0	0	OK	none obs	
C.D. Monitor	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe except as noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7959

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 0401

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04146

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-17-07 SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 12:30 AM  PM Examiners Initials MC/DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	none observed	
# 2	20.9	0	0	OK	none observed	
# 3	20.9	0	0	OK	none observed	
# 4	20.9	0	0	OK	none observed	
# 5	20.9	0	0	OK	Roller Piles 103 to 108 Accum Drive	Shovelled 105 to 106 <sup>4/17/07</sup> <sub>103</sub> <sub>106</sub> <sub>108</sub> <sub>Roll</sub>
# 6	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Trans.	20.9	0	0	OK	none observed	
C.O. monitors				Visual Exam OK		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared reasonably safe  
at time of pre-shift

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 7375

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_ 2MSHA04147

Counter Signature \_\_\_\_\_ Certificate # 4135





# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-18-07

SECTION/AREA BELTS

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
BELTS FDI						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9875

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04150

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8925

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-18-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM (AM) End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
all BELTS IDLE						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04151

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8925

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-19-07 SECTION/AREA Belts

Time of Examination Start 3:00  AM/PM End 5:10  AM/PM Examiners Initials AK/KR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0.0	0.0	OK	None obs.	
#2	21.0	0.0	0.0	OK	None obs.	
#3	21.0	0.0	0.0	OK	64 to Tailpiece Roller piles	sent men to court
#4	21.0	0.0	0.0	OK	Deep water #73 etc.	sent men to work on pumped 4-19-07 m/c
#5	21.0	0.0	0.0	OK	None obs.	
#6	21.0	0.0	0.0	OK	None obs.	
#7	21.0	0.0	0.0	OK	None obs.	
Kitchen	21.0	0.0	0.0	OK	None obs.	
TRANSFORMERS	21.0	0.0	0.0	OK	None obs.	
CO Monitors	VISUAL EXAM OK					

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **Signature** Certificate # 4375

Pre-Shift/Mine Examiner **Signature** Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04152

Counter Signature **SIGNATURE** Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-19-07

SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 12:45 AM  PM Examiners Initials Km/DO

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	Acc in walkway around tail	working on Cleaned 4-19-07
#7	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
CO monitors	Visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04153

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-19-07

SECTION/AREA Belt

Time of Examination Start 700 AM/PM  End \_\_\_\_\_ AM/PM Examiners Initials AKA

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0		OK	none observed	
#2	20.8	0	0		OK	none observed	
#3	20.9	0	0		OK	none	
#4	20.9	0	0		OK	none observed	
#5	20.9	0	0		OK	none	
#6	20.9	0	0		OK	none	
#7	20.9	0	0		OK	none	
Trans.	20.9	0	0		OK	none	
Kitchen							
C.O. Monitors normal exam						OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954  
 Certificate # 6406  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_  
 \_\_\_\_\_

2MSHA04154

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-20-07

SECTION/AREA Belts  
 Examiners Initials KK/PL

Time of Examination Start 3:00 (AM) PM End 5:20 (AM) PM  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.5	0	0	OK	none observed	
#2	20.9	0	0	OK	NEEDS dust from new 29-55	sent people to dust done 4/20/07 GA
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	none obs	
#5	20.8	0	0	OK	acc. hoodgaler.	sent people to clean
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	sub surface just in by	sent people to clean
Beef Kitchen	20.9	0	0	OK	none obs	
Truss	20.9	0	0	OK	none obs	
C.O. Menders				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM  
Except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954  
 Certificate # 6401  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04155

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-20-07 SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 1:05  AM  PM Examiners Initials TC

Time of Examination Start 11:00  AM  PM End 1:10  AM  PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.5	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.5	0	0	OK	none obs.	
#5	20.9	0	0	OK	ACC AT HEADROLLER	Done at 4:20
#6	20.9	0	0	OK	none obs.	
#7	20.5	0	0	OK	Rib Sluffage just #34 DRIVE	Working on it DNV
Kitchen	20.9	0	0	OK	none obs.	
Transformer	20.0	0	0	OK	none obs.	
CO sensors				Visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than listed Above All Areas  
Safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9362

Pre-Shift/Mine Examiner SIGNATURE Certificate # 8395

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04156

Counter Signature SIGNATURE Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 7/20/07 SECTION/AREA BELTS

Time of Examination Start 7:06 AM/PM (M) End 9:30 AM/PM (M) Examiners Initials JG

Time of Examination Start 7:10 AM/PM (M) End 9:00 AM/PM (M) Examiners Initials JG

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Tail piece area <sup>coal</sup> acc	WORKING ON DONE JG
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	Rib shuffleg <sup>brive</sup> area	WORKING ON DONE JG
Kitchen	20.9	0	0	ok	none observed	
Transboms	20.9	0	0	ok	none observed	
Clo Senses	Visual Exam			ok		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#1 tail	ACC of Coal	cleaned
#5 HEAD	ACC. of COAL	CLEANED

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift except what is noted above

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_ 2MSHA04157

Counter Signature \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-21-07

SECTION/AREA B-115

Time of Examination Start 3:00 AM/PM End 5:15 AM/PM Examiners Initials LD

Time of Examination Start 3:08 AM/PM End 4:50 AM/PM Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	none observed	
#2	20.9	0	0		ok	Acc at tail	Sent people to clean
#3	20.9	0	0		ok	none observed	
#4	20.9	0	0		ok	none observed	
#5	20.9	0	0		ok	none observed	
#6	20.9	0	0		ok	none observed	
#7	20.9	0	0		ok	none observed	
Kitchen	20.9	0	0		ok	none observed	
transformers	20.9	0	0		ok	none observed	
C/O Sensors	visual exam ok						

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#6 tail	ACC	cleaned

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

2MSHA04158

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-21-07

SECTION/AREA BELTS

Time of Examination Start 11:00 AM/PM

End 12:57 AM/PM

Examiners Initials BP

Time of Examination Start 11:00 AM/PM

End 1:24 AM/PM

Examiners Initials TR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors	Visual Exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04159

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4/21/07

SECTION/AREA Belts

Time of Examination Start 7:20 AM/PM PM End 9:30 AM/PM PM Examiners Initials dy

Time of Examination Start 7:20 AM/PM PM End 9:40 AM/PM PM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	ok	none observed	
#2	21.0	0	0	ok	none observed	
#3	21.0	0	0	ok	none observed	
#4	21.0	0	0	ok	none observed	
#5	21.0	0	0	ok	none observed	
#6	21.0	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
clo. sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622  
 Certificate # 9660  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04160

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-22-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM/PM) End 5:10 (AM/PM) Examiners Initials LD

Time of Examination Start 305 (AM/PM) End 445 (AM/PM) Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	In sufficient Rock dust tail to #7 transfer	Sent people to dust Ct Done Ct 4/22/07
#7	20.9	0	0	ok	In sufficient Rock dust head - tail	Sent people to dust Ct Done Ct 4/22/07
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
C/O Sensors	Via exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam except those noted above.

**SIGNATURE** [Redacted]

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE** [Redacted]

Counter Signature \_\_\_\_\_

2MSHA04161

Certificate # 03992

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4/22/07

SECTION/AREA Belts

Time of Examination Start 1240 AM/PM AM/PM End 1258 AM/PM AM/PM Examiners Initials CA

Time of Examination Start 11:04 AM/PM AM/PM End 1:20 AM/PM AM/PM Examiners Initials TR

Time of Examination Start 11:00 AM/PM AM/PM End 1:14 AM/PM AM/PM Examiners Initials BJ

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	none obs.	
Transformers	20.9	0	0	OK	none obs.	
CO Sensors				Visible		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
6 & 7 belts	Trash accumulations	removed

PRE-SHIFT REMARKS all areas appeared safe AT TIME  
of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Certificate # 03892

Certificate # 9362

Certificate # 8395

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04162

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-22-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:55 AM/PM PM Examiners Initials JD

Time of Examination Start 735 AM/PM AM End 9 AM/PM PM Examiners Initials JD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	Rock Dust Drine Area	SENT MEN TO DUST DONE JD
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	#6 Belt transformer Slutage, Rock Dust, no High Voltage signs	SENT MEN TO CLEAN DONE JD
CO Sensors	VISA	SA	EXAM	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
Backside #7 Drive	Bolt too far from R: b	Set timber
#1 Tailpiece #6 Belt	Coal accumulations	cleaned

PRE-SHIFT REMARKS All areas appeared safe at the time of exam except those noted Above

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ MSHA04163

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-23-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM/PM)

End 5:00 (AM/PM)

Examiners Initials LD

Time of Examination Start 3 (AM/PM)

End 5 (AM/PM)

Examiners Initials OS

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	Float Dust Head - XCS	sent men to work on Dusted 4-23-07 mc
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	None observed	
#7	20.9	0	0	ok	None observed	
3rd North 1	20.9	0	0	ok	None observed	
3rd North 2	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
CO Sensors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

*all areas examined appear safe at Time of  
preshift except what is noted above*

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04164

Certificate # \_\_\_\_\_

Counter Signature

**Signature**

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-23-07

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 110 AM/PM Examiners Initials DD mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	COAL ACC. AT TAIL	cleaned 4-23-07
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
kitchen	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#2 belt	DEEP WATER XCUT 3704 AND 6 TO 7	Pumped 4-23-07 mc
#3 belt	DEEP WATER XCUT 405 AND 47	Pumped 4-23-07 mc

PRE-SHIFT REMARKS All AREAS appeared safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # ZPX

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04165

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 4235

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-23-07

SECTION/AREA Belt  
 Examiners Initials JK/RL

Time of Examination Start 700 AM/PM AM End 9.45 AM/PM PM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0.0	0.0	OK	none obs	
#2	20.9	0.0	0.0	OK	none obs	
#3	20.9	0.0	0.0	OK	none obs.	
#4	20.9	0.0	0.0	OK	none obs	
#5	20.9	0.0	0.0	OK	none obs	
#6	20.9	0.0	0.0	OK	none obs	
#7	20.9	0.0	0.0	OK	none obs	
Belt Kitchens	20.9	0.0	0.0	OK	none obs	
Trons	20.9	0.0	0.0	OK	none obs	
C.B. Monitors	20.9	0.0	0.0	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Headwall	accrue	cleaned 4-23-07

PRE-SHIFT REMARKS all areas appeared safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7959  
 Certificate # 6401  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04166

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-24-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM

End 5:30  AM  PM

Examiners Initials KL/RL

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0	OK	none obs	
#2	20.9	0.0	0	OK	none obs	
#3	20.9	0.0	0	OK	none obs	
#4	20.9	0.0	0	OK	accumulation of dust	Sept min to work on cleaned 4-24-07
#5	20.9	0.0	0	OK	none obs	
#6	20.9	0.0	0	OK	none obs	
#7	20.9	0.0	0	OK	none obs	
# Belt Kitchen	20.9	0.0	0	OK	none obs	
Trams	20.9	0.0	0	OK	none obs	
C. O. Monitor				exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

**SIGNATURE**  
 \_\_\_\_\_  
 \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04167

Certificate # 7954  
 Certificate # 6801  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 \_\_\_\_\_

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-24-07

SECTION/AREA Belt

Time of Examination Start 11:00 AM/PM

End 1:05 AM/PM

Examiners Initials MC/DD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0		OK	none observed	
#2	20.9	0.0		OK	Accum Tailpiece	Sent man to work on Cleaned 4-24-07
#3	20.9	0.0		OK	none observed	
#4	20.9	0.0		OK	none observed	
#5	20.9	0.0		OK	Accum drive	Cleaned 4-24-07
#6	20.9	0.0		OK	Accum Head roller	Sent man to work on Done 2-24-07
#7	20.9	0.0		OK	sloughage in walkway cut 112	Sent man to work on Done 2-24-07
TREAS FOREMANS	20.9	0.0		OK	none observed	
Kitchen	20.9	0.0		OK	none observed	
CO MON. TOR				VISUAL EXAM	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas Appraised Reasonably Safe  
AT Time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04168

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-24-07 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 955 AM/PM PM Examiners Initials RL/MK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none	
#5	20.9	0	0	OK	acc hood locker	cleaned up 4-24-07
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformer	20.9	0	0	OK		
Kitchen	20.9	0	0	OK	none observed	
CO Sensor	Visual alarm OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

Pre-Shift/Mine Examiner [Signature] Certificate # 6901

Pre-Shift/Mine Examiner [Signature] Certificate # 795A

Pre-Shift/Mine Examiner [Signature] Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner [Signature] Certificate # \_\_\_\_\_

Counter Signature [Signature] 2MSHA04169 Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-25-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 5:30 AM/PM

Examiners Initials AK/RJ

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	OK	acc tail piece	working on done 4-25-07
#2	20.9	0	0	OK	none	
#3	20.9	0	0	OK	none	
#4	20.9	0	0	OK	none	
#5	20.8	0	0	OK	acc hood roller	cleaned up 4-25-07
#6	20.9	0	0	OK	none	
#7	20.9	0	0	OK	none	
Belt Kitchens	20.9	0	0	OK	none	
Trams	20.9	0	0	OK	none	
L.O. Monitors	around					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All other areas appeared safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7934

Certificate # 6401

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04170

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-25-07 SECTION/AREA Belts

Time of Examination Start 1100 ~~AM~~/PM End 115 AM/~~PM~~ Examiners Initials DD MC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0	ok	none obs.	
#2	21	0	0	ok	none obs.	
#3	21	0	0	ok	Roller piles headroller to Drive	working on cleaned 4-25-07
#4	21	0	0	ok	none obs.	
#5	21	0	0	ok	COAL ACC. @ Drive	working on DONE 4-25-07
#6	21	0	0	ok	none obs.	
#7	21	0	0	ok	none obs.	
Kitchen	21	0	0	ok	none obs.	
TRANS.	21	0	0	ok	none obs.	
COMONITORS				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04171

Signature

Counter Signature \_\_\_\_\_

Certificate # 8462



# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-25-07 SECTION/AREA Belt

Time of Examination Start 1030 AM/PM (AM) End 1200 AM/PM (AM) Examiners Initials KR/RC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none	
#3	20.9	0	0	OK	none	
#4	20.9	0	0	OK	none	
#5	20.9	0	0	OK	none	
#6	20.9	0	0	OK	none	
#7	20.9	0	0	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Supplemented - Belt areas appeared safe at time of exam

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 6401

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_ 2MSHA04173 Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-26-07

SECTION/AREA Belt

Time of Examination Start 346  AM  PM

End 428  AM  PM

Examiners Initials RL

Time of Examination Start 300  AM  PM

End 537  AM  PM

Examiners Initials RL/RK

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none "	
#3	20.9	0	0	OK	none "	
#4	20.9	0	0	OK	none "	
#5	20.9	0	0	OK	none "	
#6	20.9	0	0	OK	none "	
#7	20.9	0	0	OK	none "	
TRANS	20.9	0	0	OK	none "	
Belt Kitchen	20.9	0	0	OK	none "	
C.O. Monitor	checked EXAM					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 pad	acc	cleaned RL

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Pre-Shift/Mine Examiner **Signature** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6401  
 Certificate # 7954  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ 2MSHA04174

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-26-07

SECTION/AREA BELTS

Time of Examination Start 11:00 AM End 1:10 AM Examiners Initials mc/DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	DEEP WATER WENT BY 1/2 HOLE IN STOPPING BS	Done 4-26-07 Done 4-26-07
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF EXAM

**Signature**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**Signature**

Counter Signature

2MSHA04175

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-26-07

SECTION/AREA Belts

Time of Examination Start 7:05 AM/PM  AM  PM

End 9:43 AM/PM

Examiners Initials RJR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	↙	none obs	
#2	20.9	0	0	↙	none obs.	
#3	20.9	0	0	↙	none obs	
#4	20.9	0	0	↙	none observed	
#5	20.9	0	0	↙	none "	
#6	20.9	0	0	↙	none obs	
#7	20.9	0	0	↙	needs dust removal	vent man started 4-26-07
Belt Kitchen	20.9	0	0	↙	none obs	
Trams	20.9	0	0	↙	none obs	
CO Monitors	20.9	0	0	↙	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe at time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954  
 Certificate # 6401  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04176

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 4285

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-27-07

SECTION/AREA Belt

Time of Examination Start 3:00 (AM/PM) End 5:35 (AM/PM) Examiners Initials K/RL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	acc tail piece	SENT MEN TO CLEAN DONE 4-27-07
#2	20.9	0	0	OK	acc head roller	SENT MEN TO CLEAN DONE 4-27-07
#3	20.9	0	0	OK	none	
#4	20.9	0	0	OK	none	
#5	20.9	0	0	OK	none	
#6	20.9	0	0	OK	none	
#7	20.9	0	0	OK	none	
Belt Ketcher	20.9	0	0	OK	none	
Trans.	20.9	0	0	OK	none	
Co. Monitor	normal			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appear safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954  
 Certificate # 6401  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04177

Certificate # 7435

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-27

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:00 AM/PM

Examiners Initials JD

Time of Examination Start 11 AM/PM

End 105 AM/PM

Examiners Initials JD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	Roller piles Between AccXC35 Acc tail	SENT MEN TO CLEAN Done 4-27-20
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	Roller piles just out by Tail Back side	SENT MEN TO CLEAN Done 4-27-20
#5	20.9	0	0	ok	none obs	
#6	20.9	0	0	ok	Roller piles X2 - Head	SENT MEN TO CLEAN DONE
#7	20.9	0	0	ok	Dust 14 - Tail	WORKING ON DONE
Belt kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all Areas appeared safe at time of exam except those noted above

Pre-Shift/Mine Examiner SIGNATURE  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04178

Counter Signature SIGNATURE

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4 27 07

SECTION/AREA Belts

Time of Examination Start 8:40 AM/PM AM End 9 AM/PM PM Examiners Initials GA

Time of Examination Start 7:00 AM/PM AM End 8:40 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 8:30 AM/PM PM Examiners Initials TC

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	α	Roller piles #1 had rise	Done 4/28/07 Sent people to clean
#7	20.9	0	0	α	Needs dust x cut 13 total	Sent people to dust
Kitchen	20.9	0	0	ok	none observed	Done 4/28/07
Transformers	20.9	0	0	ok	none observed	
co generators	20.9	0	0	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 05892  
 Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_

2MSHA04179

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 05892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-28-07

SECTION/AREA BELTS

Time of Examination Start 3:00  AM  PM End 4:50  AM  PM Examiners Initials BP

Time of Examination Start 3:00  AM  PM End 5:00  AM  PM Examiners Initials R

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Roller Piles - 3 to Drive ACC AT TAILPIECE	WORKING ON 2D - 3 to Drive Done
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Trucks/Tractors	20	0	0	OK	none observed	
CO SENSORS				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than listed About All Areas  
SAFE AT TIME OF EXA-

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Certificate # 9362

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04180

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-28-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:38 AM/PM

Examiners Initials 20

Time of Examination Start 11 AM/PM

End 12:45 AM/PM

Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	ACC at tail	WORKING ON Done 4-28-07 SD
#2	20.9	0	0	ok	ACC tail	WORKING ON Done 5G
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above.

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04181

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4/28/07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:45 AM/PM PM Examiners Initials JL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	ACC AT Tail	working on
#3	20.9	0	0		OK	None obs.	
#4	20.9	0	0		OK	None obs.	
#5	20.9	0	0		OK	None obs.	
#6	20.9	0	0		OK	None obs.	
#7	20.9	0	0		OK	None obs.	
Kitchen	20.9	0	0		OK	None obs.	
Transformers	20.9	0	0		OK	None obs.	
Clo sensors					Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than listed above All Areas  
Safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9562

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04182

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-29-07 SECTION/AREA Belts

Time of Examination Start 3:00  AM/PM End 5:47  AM/PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	ALL AT TAIL	WORKING ON DONE 4-29 JD
#2	20.9	0	0	OK	ALL AT TAIL	WORKING ON NONE 4-29 JD
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
TRANSFORMER	20.9	0	0	OK	None obs.	
C/S SENSOR				OK	None obs.	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than noted above all AREAS  
SAFE AT TIME OF EXAM

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ **2MSHA04183** Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-29-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials LD  
 Time of Examination Start 11 AM/PM End 1245 AM/PM Examiners Initials LD  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_  
 Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	ACC-XC 33 ACC-XC 35	BEING CLEANED DONE 4-29 LD
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	ACC Tail Backside	BEING CLEANED DONE 4-29 LD
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O Sensors	visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above

**SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_  
 Counter Signature \_\_\_\_\_

2MSHA04184

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-29-07

SECTION/AREA BELTS

Time of Examination Start 7:01 AM/PM PM

End 8:43 AM/PM PM

Examiners Initials BP

Time of Examination Start 7:00 AM/PM PM

End 9:20 AM/PM PM

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	OK	Deep water 39-40	Sent people to pump it CA Done 4/29/07
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	none observed	
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

Pre-Shift/Mine Examiner SIGNATURE

Certificate # 9399

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04185 \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature SIGNATURE

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4.30.07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 4:50 AM/PM

Examiners Initials BP

Time of Examination Start 3:00 AM/PM

End 5:05 AM/PM

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.1	0.0	0.0	OK	Acc. at Tail	cleaned for new to clean 4.30.07
#2	20.0	0.0	0.0	OK	none observed	
#3	20.0	0.0	0.0	OK	none observed	
#4	20.0	0.0	0.0	OK	none observed	
#5	20.0	0.0	0.0	OK	none observed	
#6	20.0	0.0	0.0	OK	none observed	
#7	20.0	0.0	0.0	OK	none observed	
Kitchen	20.0	0.0	0.0	OK	none observed	
Transformer	20.0	0.0	0.0	OK	none observed	
CO sensors	20.0	0.0	0.0	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04186

Counter Signature SIGNATURE \_\_\_\_\_

Certificate # 4705

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-30-07 SECTION/AREA Belts

Time of Examination Start 1100  AM  PM End 1.30 AM  PM Examiners Initials RK/RJ

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0	0	α	none obs.	
#2	20.9	0	0	α	none obs.	
#3	20.9	0	0	α	none obs.	
#4	20.9	0	0	α	none obs. <del>obs. dust from</del> 78 & 67	sent man
#5	20.9	0	0	α	none obs.	
#6	20.9	0	0	α	none obs.	
#7	20.9	0	0	α	none obs.	
Best Kitchen	20.9	0	0	α	none obs.	
Trans.	20.9	0	0	α	none obs.	
L.O. Monitor	used EXHA					

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 79521

Pre-Shift/Mine Examiner **SIGNATURE** Certificate # 6401

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** 2MSHA04187 Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 4-30-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM (M) End 930 AM/PM (M) Examiners Initials DDmc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	ok	Acc @ Tail	Sent men to work on Done 5-1-07
#2	20.9	0.0	0.0	ok	need dust curtains to arrive	Sent men to work on Done 5-1-07
#3	20.9	0.0	0.0	ok	Acc @ Tail needs dust @ Tail	Sent men to work on Done 5-1-07
#4	20.9	0.0	0.0	ok	Deep water @ 7 1/2	Sent men to work on Done 5-1-07
#5	20.9	0.0	0.0	ok	none observed	
#6	20.9	0.0	0.0	ok	none observed	
#7	20.9	0.0	0.0	ok	none observed	
Trans.	20.9	0.0	0.0	ok	none observed	
Kitchen	20.9	0.0	0.0	ok	none observed	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 7325  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04188

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-1-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:05 AM/PM Examiners Initials MG/DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed need dust Headlamp only 100'	Dusted 5-1-07
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	None observed	
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
TRANSFORMERS	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO MONITORS				visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
at time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04189

Certificate # 2025  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-1-07

SECTION/AREA Belt

Time of Examination Start 11.05 (AM/PM)

End 1.28 (AM/PM)

Examiners Initials 15/12

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs	
#7	20.9	0	0	OK	none obs.	
Belt Kitcher	20.9	0	0	OK	none	
Turns	20.9	0	0	OK	none obs	
C.O. Monitor stand				OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Certificate # 0401

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04190

Certificate # 8962

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-1-07

SECTION/AREA Belt

Time of Examination Start 700 AM/PM AM End 920 AM/PM PM Examiners Initials DD MC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21	0	0		ok	none obs.	
#2	21	0	0		ok	none obs.	
#3	21	0	0		ok	none obs.	
#4	21	0	0		ok	none obs.	
#5	21	0	0		ok	none obs.	
#6	21	0	0		ok	none obs.	
#7	21	0	0		ok	none obs.	
Belt kitchen	21	0	0		ok	none obs.	
Trans.	21	0	0		ok	none obs.	
CD monitors				Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of exam

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 7375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04191

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-2-07

SECTION/AREA Belts

Time of Examination Start 300  AM  PM End 530  AM  PM Examiners Initials D/mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	oil acc #1 Drive	washed & cleaned 5-2-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	coal acc. X-117 in walkway Needs dust X-117 to trail	Done 5-2-07
TRANS.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CD Sensor			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04192  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 7375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-20-07

SECTION/AREA Belt

Time of Examination Start 11:00 AM/PM

End 1:13 AM/PM

Examiners Initials K.K./J.M.

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		α	none obs.	
#2	20.9	0	0		α	none obs	
#3	20.9	0	0		α	none obs	
#4	20.9	0	0		α	none obs	
#5	20.9	0	0		α	none obs	
#6	20.9	0	0		α	accum tail	cleaned 5.20.07
#7	20.9	0	0		α	none obs	
Belt Kitchens	20.9	0	0		α	none obs	
Trans	20.9	0	0				
C.O. Monitors	checked				EXAM		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8297

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04193

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-2-07 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 940 AM/PM PM Examiners Initials DD mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	COAL ACC. AT TAIL	working on cleaned 5-3-07
#4	20.9	0	0	ok	Oil acc. @ Drive	working on cleaned 5-3-07
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
Transformers	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04194

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8058

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-3-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~/PM End 525 ~~AM~~/PM Examiners Initials DD mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Oil Acc. @ Drive COAL Acc. @ Tail piece	cleaned 5-3-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	COAL Acc. @ Take-up under belt	cleaned 5-3-07
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	none obs.	
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04195

Certificate # 8058  
 Certificate # 7375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-3-07

SECTION/AREA Belts

Time of Examination Start 1100 AM/PM End 140 AM/PM Examiners Initials RJ/RK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	0	none observed	
#2	20.9	0	0	0	none obs	
#3	20.9	0	0	0	none observed	
#4	20.9	0	0	0	none observed	
#5	20.9	0	0	0	none obs	
#6	20.9	0	0	0	none obs	
#7	20.9	0	0	0	none obs	
Ketchers	20.9	0	0	0	none observed	
Transformer	20.9	0	0	0	none observed	
CO Room	Visual	Visual	Visual	0		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6401  
 Certificate # 7954  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04196

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-3-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM  AM  PM End 920 AM/PM  AM  PM Examiners Initials DD mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		ok	Acc. AT Tail	working on Cleaned 5-4-07
#2	20.9	0	0		ok	none obs.	
#3	20.9	0	0		ok	none obs.	
#4	20.9	0	0		ok	Deep water 72 1/2	working on Pumped 5-4-07
#5	20.9	0	0		ok	Acc. AT Drive	working on Drive 5-4-07
#6	20.9	0	0		ok	none obs.	
#7	20.9	0	0		ok	none obs.	
Kitchen	20.9	0	0		ok	none obs.	
TRANS.	20.9	0	0		ok	none obs.	
C O Sensors					Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Alerts site at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04197  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 7375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-4-07

SECTION/AREA Belts

Time of Examination Start 3:00 ~~AM~~PM End 5:00 ~~AM~~PM Examiners Initials mc/pm

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	CO sensor at 3 tail pipe don't work	MAINTENANCE SENT TO REPAIR <u>Done</u>
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitORS				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375  
 Certificate # 8297  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04198

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-4-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:05 PM AM/PM

Examiners Initials LD

Time of Examination Start 11 AM/PM

End 12:30 AM/PM

Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
#3	20.9	0	0	ok	none observed	
#4	20.9	0	0	ok	none observed	
#5	20.9	0	0	ok	Roller Piles #09 - flood	genset to clean Done 5-4-07
#6	20.9	0	0	ok	none observed	
#7	20.9	0	0	ok	Rib sluffed, KC114 none observed JD	went to get timber Done 5-4-07
Belt Kitchen	20.9	0	0	ok	none observed	
transformers	20.9	0	0	ok	none observed	
C/O monitors	Visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all areas appeared safe at the time of exam except those noted above

Pre-Shift/Mine Examiner

**SIGNATURE** [Redacted]

Certificate #

9660

Pre-Shift/Mine Examiner

Certificate #

6622

Pre-Shift/Mine Examiner

Certificate #

Pre-Shift/Mine Examiner

Certificate #

Counter Signature

**SIGNATURE** [Redacted]

2MSHA04199

Certificate #

7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-4-07

SECTION/AREA BELTS

Time of Examination Start 7:00 AM/PM  End 8:40 AM/PM  Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	Acc under crutch Bld	Sent man to work on. Date 5-5-07 BP
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none observed	
#4	20	0	0	OK	none observed	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
CO monitors				OK	W/Sant Exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04200

Certificate # 03892

2MSHA04201