



**PRE-SHIFT  
BELTS**

2MSHA04202

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-25-07

SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 1:10  AM  PM Examiners Initials MC DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	Accum in place oil Accum Drive	sent men to work on <u>Done</u>
#2	20.9	0	0		OK	none observed	
#3	20.9	0	0		OK	none observed	
#4	20.9	0	0		OK	dust 96-103	sent men to dust
#5	20.9	0	0		OK	none observed	
#6	20.9	0	0		OK	Accum Drive	sent men to work on <u>cleaned 2-25-07</u>
#7	20.9	0	0		OK	none observed	
Kitchen	20.9	0	0		OK	none observed	
Transformers	20.9	0	0		OK	none observed	
CD monitors					VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_  
 2MSHA04203

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-25-07

SECTION/AREA Belt

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials RR/RL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	Need dust Henswolbr to 0	done 2-25-07 RR
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	Acc. At drive Need dust 96 to 103	Cleared drive 2-25-07 RR workshop 96 to 103
#5	20.9	0	0	OK	Acc. At drive	Cleared drive 2-25-07 RR
#6	20.9	0	0	OK	None obs	
#7	20.9	0	0	OK	None obs	
Belt Kitchen	20.9	0	0	OK	None obs	
Trams.	20.9	0	0	OK	None obs	
C.O. Monitor					Manual EXAM	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Access approved Safe at time of Exam except as noted above

**SIGNATURE**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Certificate # 4375  
 Certificate # 6401  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 \_\_\_\_\_

2MSHA04204

Counter Signature \_\_\_\_\_

Certificate # 4375

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-26-07

SECTION/AREA Belts

Time of Examination Start 300 AM/PM

End 531 AM/PM

Examiners Initials SR/RL

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none	
#4	20.9	0	0	OK	See below HCC XG 93	Working on dusted 2-26-07
#5	20.9	0	0	OK	HCC Head roller	Working on
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Belt Katcher	20.9	0	0	OK	none observed	
Trans.	20.9	0	0	OK	none observed	
C.O. Monitor				Visual exam	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

All other areas appeared safe at time of exam. #4 Belt 96 to 103 (Coal Acc in walkway & against Stoppings and Needs dusted. Dusted 96 to 103 2-26-07

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6401

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04205

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-26-07

SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~ PM End 1:10 AM/~~PM~~ Examiners Initials KM

Time of Examination Start 11:00 ~~AM~~ PM End 1:15 AM/~~PM~~ Examiners Initials PD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Acc drive	SENT MEN TO CLEAN DOME DR
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs.	
CO monitors	visual OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9329

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04206

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2.26.07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM End 9:00 AM/PM Examiners Initials LR/KK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acc. At Drive	Working on Done 2/27/07 CA
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	accum 100 to 105	working on
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	accum, headchiller	working on Done 2/27/07 CA
Belt Kitchen	20.9	0	0	OK	none obs.	
Trans.	20.9	0	0	OK	none obs.	
C.O. Monitor	normal					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#6 headchiller	accum	cleaned 2/26/07 KK

PRE-SHIFT REMARKS Please equipment safe at time of Exam except as noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Certificate # 4375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04207

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-27-07

SECTION/AREA BELTS

Time of Examination Start 3:00 ~~AM~~/PM

End 5:15 ~~AM~~/PM

Examiners Initials DEL

Time of Examination Start 4:30 ~~AM~~/PM

End 5:10 ~~AM~~/PM

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	OK	NONE obs	
#2	20.8	0	0	OK	NONE obs	
#3	20.8	0	0	OK	NONE obs	
#4	20.8	0	0	OK	ACCUM 100 TO 103	WORKING ON <sup>Done</sup> 2/27/07
#5	20.8	0	0	OK	NONE obs	
#6	20.8	0	0	OK	NONE obs	
#7	20.8	0	0	OK	NONE obs	
Belt Kitchen	20.8	0	0	OK	NONE obs	
TRANS.	20.8	0	0	OK	NONE obs	
CO. Monitor	20.8	0	0	OK	NONE obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All AREAS APPREED SAFE AT TIME OF EXAM.  
Except on Noted Above.

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9659

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04208

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 22707

SECTION/AREA Belts

Time of Examination Start 11 AM/PM

End 115 AM/PM

Examiners Initials DD

Time of Examination Start 1100 AM/PM

End 115 AM/PM

Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed 	
#2	20.9	0	0	ok		
#3	20.9	0	0	ok		
#4	20.9	0	0	ok		
#5	20.9	0	0	ok		
#6	20.9	0	.1	ok		
#7	20.9	0	.1	ok		
Belt Kitchen	20.9	0	0	ok		
Transformers	20.9	0	0		none observed	
CO Monitors	visual exam ok					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04209

Counter Signature SIGNATURE

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-27-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:20 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 9:20 AM/PM PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM \_\_\_\_\_ End \_\_\_\_\_ AM/PM \_\_\_\_\_ Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None Observed	
#3	20.9	0	0	OK	None Observed	
#4	20.9	0	0	OK	None Observed	
#5	20.9	0	0	OK	None Observed	
#6	20.9	0	0	OK	None Observed	
#7	20.9	0	0	OK	None Observed	
Belt Kitchen	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
CO monitors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8325

Certificate # 9589

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04210

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-28-07 SECTION/AREA Belts

Time of Examination Start 3:25  AM  PM End 5:35  AM  PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	-2 Tox-cut 6 Needs dust	BEING DUSTED Done
#2	20	0	0	OK	None Observed	
#3	20	0	0	OK	None Observed	
#4	20	0	0	OK	None Observed	
#5	20	0	0	OK	acc drive	SENT MAN TO CLEAN Done
#6	20	0	0	OK	None Observed	
#7	20	0	0	OK	None Observed	
Kitchen	20	0	0	OK	None Observed	
Transformers	20	0	0	OK	None Observed	
co sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Except as noted above all areas appeared reasonably safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 8395

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04211

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 22807

SECTION/AREA Belts

Time of Examination Start 11 AM/PM

End 1245 AM/PM

Examiners Initials dy

Time of Examination Start 11:00 AM/PM

End 1:00 AM/PM

Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	Cross under need fixed XC 34	SENT MEN TO FIX DONE
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	Roller piles, indicate Rock Pass Head-tail	SENT MEN TO DUST CONTINUED
#6	20.9	0	0	OK	none observed	
#7	20.9	0	.8	OK	None observed	
Belt Trench	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
COMONITORS				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
X-CWT 104	RETURN STOPPING DAMAGED	REPAIRED JG

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622  
 Certificate # 9660  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04212

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-28-07

SECTION/AREA BELTS

Time of Examination Start 7:00 ~~AM~~ ~~PM~~ End 8:30 AM ~~PM~~ Examiners Initials BP

Time of Examination Start 7:34 AM ~~PM~~ End 9:05 AM ~~PM~~ Examiners Initials R

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Rock Dust Hazard	Sent men to dust done 2/29/07
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kirchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO Sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than noted above all other areas seemed reasonably safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04213

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-1-07 SECTION/AREA Belts.

Time of Examination Start 3:41 AM/PM End 3:40 AM/PM Examiners Initials K

Time of Examination Start 3:13 AM/PM End 5:16 AM/PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Needs Dusted <del>70-766</del>	WORKING ON IT Done JD
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs	
#4	20.9	0	0	OK	Oil ACC AT DRIVE Needs Dusted x70-66	WORKING ON IT Done JD
#5	20.9	0	0	OK	None obs	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
Transformer	20.9	0	0	OK	None obs.	
C/O Monitors					Visual Exam	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Other than noted Above Above All  
Other AREAS APPEARED safe At Time of Exam

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9362

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature SIGNATURE 2MSHA04214 Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3/07 SECTION/AREA BELTS

Time of Examination Start 11 AM/PM End 1 AM/PM Examiners Initials dg

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	Coal accum. at Drive	BEING CLEANED UP
#6	20.9	0	2	ok	Coal accum. at Drive	BEING CLEANED UP
#7	20.9	0	2	ok	Roller Piles 127-136 122-125 114-119	BEING CLEANED UP
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
C/O MONITORS				ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift  
(except what is noted above)

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622

Certificate # 9660

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04215

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-1-07

SECTION/AREA Belts

Time of Examination Start 8:15 AM/PM AM

End 9:30 AM/PM AM

Examiners Initials BP

Time of Examination Start 7:50 AM/PM AM

End 9:20 AM/PM AM

Examiners Initials BT

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20 9	0	0	ok	none observed	
#2	20 9	0	0	ok	none observed	
#3	20 9	0	0	ok	none observed	
#4	20 9	0	0	ok	none observed	
#5	20 9	0	0	ok	none observed	
#6	20 9	0	0	ok	none observed	
#7	20 9	0	0	ok	Roller Piles <sup>123<sup>1</sup>-125</sup> <sub>127-131</sub>	Done 3/1/07 working on it
Kitchen	20 9	0	0	ok	none observed	
Transformers	20 9	0	0	ok	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

2MSHA04216

Counter Signature \_\_\_\_\_

Certificate # 05892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-2-07 SECTION/AREA Belts

Time of Examination Start 3:20 AM/PM End 5:05 AM/PM Examiners Initials BP

Time of Examination Start 3:00 AM/PM End 5:30 AM/PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO sensors					Visual Exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas appeared safe at time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04217

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3.2.07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials TR/EM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	Acc. AT Tripieca	sent people to clean Done 3.2.07
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	Acc. AT drive	sent people to clean Done 3.2.07
#6	20.9	0	0	OK	Acc. AT drive	sent people to clean Done 3.2.07
#7	20.9	0	0	OK	Acc. AT Headrollor	sent people to clean Done 3.2.07
Kitchen	20.9	0	0	OK	None obs.	
TRANSFORMERS	20.9	0	0	OK	None obs.	
CO Monitors	Visual	Visual	Visual	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam except as noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8291

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04218

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-2-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM  AM  PM End 915 AM/PM  AM  PM Examiners Initials DD/km

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	Acc. AT Handroller	working on cleaned 3-2-07
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	Acc. AT Drive	cleaned 3-2-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
TRANS.	20.9	0	0	ok	none obs.	
CD monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 Drive	Acc. of COAL	cleaned

PRE-SHIFT REMARKS All areas safe at time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

2MSHA04219

Counter Signature

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-3-07

SECTION/AREA BELTS

Time of Examination Start 3:00 AMPM

End 5:12 AMPM

Examiners Initials MC/KAL

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	OK	NONE OBSERVED	
#2	20.9	0.0	0.0	OK	NONE OBSERVED	
#3	20.9	0.0	0.0	OK	Accum Tailpiece	sent man to clean Done 3-3-07
#4	20.9	0.0	0.0	OK	NONE OBSERVED	
#5	20.9	0.0	0.0	OK	Accum Drive	Done 3-3-07 sent man to clean
#6	20.9	0.0	0.0	OK	NONE OBSERVED	
#7	20.9	0.0	0.0	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0.0	0.0	OK	NONE OBSERVED	
Kitchen	20.9	0.0	0.0	OK	NONE OBSERVED	
COMPUTERS	20.9	0.0	0.0	OK/SUR/EXAM/OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7378

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

2MSHA04220

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-3-07 SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 1:15  AM  PM Examiners Initials LR/RC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	Q	None obs.	
#2	20.9	0	0	Q	None obs.	
#3	20.9	0	0	Q	None obs.	
#4	20.9	0	0	Q	None obs.	
#5	20.9	0	0	Q	None obs.	
#6	20.9	0	0	Q	None obs.	
#7	20.9	0	0	Q	None obs.	
Belt Catcher	20.9	0	0	Q	None obs.	
Trains	20.9	0	0	Q	None obs.	
<i>CO. Monitor removed EXAM</i>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas exposed safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Certificate # 6401

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04221

Certificate # 4935

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-3-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM  AM  PM End 920 AM/PM  AM  PM Examiners Initials DD/MC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	oil acc. at Drive	working on cleaned 3-3-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	Acc. AT Tailpiece	working on cleaned 3-3-07
#4	20.9	0	0	ok	Acc. AT Tailpiece	working on cleaned 3-3-07
#5	20.9	0	0	ok	Acc. AT Drive	working on cleaned 3-3-07
#6	20.9	0	0	ok	none obs.	
#7	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CD monitors				Visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of  
exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 73.73  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_  
 2MSHA04222

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-4-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM/PM End 5:30  AM/PM Examiners Initials KM/DO

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	x95 return stoping need	repair. Ass man to fix
#5	20.9	0	0	OK	acc drive	send man to clean
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	acc head roller	sent man to clean
Trans.	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
CO monitors	visual exam			OK		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
Belts 5,6,7	needs dust	Dusted
#6 Drive	COAL ACCUMULATIONS	cleaned

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_

2MSHA04223

Certificate # 4205

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-4-07 SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM End 1:20 AM  PM Examiners Initials LR/VK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	Deep water 6 to 7	Pumping Done 3-4-07
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	Return Stopping damaged	Working on Done 3-4-07
#5	20.9	0	0	OK	Acc. #1 Drive	Working on Done 3-4-07
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	Acc. #1 Headrollor Drive to Headrollor Needs dust	Working on Done 3-4-07
TRANSFORMERS	20.9	0	0	OK	None obs	
Kitchen	20.9	0	0	OK	None obs	
COM Monitors	4: SWAL	EXAM	OK			

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam except as noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375  
 Certificate # 7954  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04224

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-4-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:05 AM/PM PM Examiners Initials KM

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Acc drive	working on CLEANED 3-4-07
#6	20.9	0	0	OK	Acc drive	working on CLEANED 3-4-07
#7	20.9	0	0	OK	Acc head roller	working on done 3-4-07
Trans	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
CO monitors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at the time of exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04225

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-5-07 SECTION/AREA BELTS

Time of Examination Start 3:00 AM/PM End 5:10 AM/PM Examiners Initials MC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	needs dusted Head to Tail	BEING DUSTED DONE <u>EG</u>
#3	20.9	0	0	OK	Headroll to take up needs dust	BEING DUSTED DONE <u>EG</u>
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
CO monitors				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE  
AT TIME OF PRE-SHIFT

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375  
 Certificate # 9379  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04226

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 7488

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-5-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials LD

Time of Examination Start 11 AM/PM End 1:00 AM/PM Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	ok	Float Dust Portal Tok6	BEING DUSTED Done LD
#2	20.9	0	0	ok	Codaccum Tail piece <sup>small spill</sup>	BEING CLEANED Done LD
#3	20.9	0	0	ok	NONE observed	
#4	20.9	0	0	ok	ACC Tail - one xc In by	SENT MAN TO CLEAN CLEANED 3-5-07
#5	20.9	0	0	ok	NONE observed	
#6	20.9	0	0	ok	NONE observed	
#7	20.9	0	0	ok	Drive <sup>float dust</sup> to overhead <sup>needs</sup> dust	BEING DUSTED Done LD
* Transformers	20.9	0	0	ok	NONE observed	
Kitchen	20.9	0	0	ok	NONE observed	
CO monitors	visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift except where noted above

Pre-Shift/Mine Examiner [Signature]  
 Pre-Shift/Mine Examiner [Signature]  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04227

Counter Signature [Signature]

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-5-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM  AM  PM End 9:00 AM/PM Examiners Initials BP

Time of Examination Start 7:30 AM/PM  AM  PM End 9:35 AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM  AM  PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	needs dusted xcs-6	Being Dusted Done 3607 G
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	ACC AT TAIL ONE XC INBY	Being Shoveled Done 3607 G
#5	20	0	0	ok	none obs.	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO Sensors	20	0	0	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than listed above ALL AREAS  
seemed Reasonably safe AT TIME of Exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

2MSHA04228

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-6-07 SECTION/AREA Belts

Time of Examination Start 3:05 AM/PM End 5:16 AM/PM Examiners Initials BP

Time of Examination Start 3:31 AM/PM End 5:30 AM/PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Acc at tail piece Needs Dusted 24-33	WORKING DONE JD
#2	20.9	0	0	OK	none obs.	
#3	20.3	0	0	OK	Acc at tail piece <del>none observed</del>	getting met on it Done JD
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
co sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas secured Personally safe AT TIME  
of Exam Except noted above

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04229

**SIGNATURE** \_\_\_\_\_

Counter Signature \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-6-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM

End 1:00 AM/PM

Examiners Initials LD

Time of Examination Start 11 AM/PM

End 1 AM/PM

Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.8	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.8	0	0	OK	none observed	
#5	20.8	0	0	OK	acc at tail acc at head	BEING CLEANED DONE
#6	20.8	0	0	OK	acc one xc out Br cross over	SENT MEN TO CLEAN DONE
#7	20.8	0	0	OK	none observed	
Kitchen	20.8	0	0	OK	none observed	
transformers	20.8	0	0	OK	none observed	
CO Sensors	visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all areas examined appear safe at time of  
preshift except what is noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Certificate # 6622

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04230

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-6-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM End 9:20 AM/PM Examiners Initials TR

Time of Examination Start 7:00 AM/PM End 8:55 AM/PM Examiners Initials BH

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	Acc tail	Done 3-7-07
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None obs.	
Transformer	20.9	0	0	OK	None obs.	
Closets				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam except as noted above

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362  
 Certificate # 8395  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04231

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Certificate # 0382

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-7-07

SECTION/AREA Belts

Time of Examination Start 3:00 ~~AM~~/PM

End 5:05 ~~AM~~/PM

Examiners Initials K

Time of Examination Start 3:00 ~~AM~~/PM

End 5:05 ~~AM~~/PM

Examiners Initials BD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	none obs.	
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Transducers	20.9	0	0	OK	none obs.	
Gas sensors.				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9399

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04232

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 7285

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3 20 07 SECTION/AREA Belts

Time of Examination Start 11 AM/PM End 12 45 AM/PM Examiners Initials EG

Time of Examination Start 11:00 AM/PM End 1:00 AM/PM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	None observed	
#5	20.9	0	0	ok	None observed	
#6	20.9	0	0	ok	ACC. from cross over out by XC	WORKING ON Done LD
#7	20.9	0	0	ok	None observed	
Kitchen	20.9	0	0	ok	None observed	
Warehouse	20.9	0	0	ok	None observed	
Gas sensors	UNUSUAL		EXAM	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 XCS101-102	Bad rollers	Replaced 3-7-07

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Pre-Shift/Mine Examiner SIGNATURE Certificate # 6622

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04233

Counter Signature SIGNATURE Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-7-07

SECTION/AREA BELTS

Time of Examination Start 7:00 AM/PM AM End 7:08 AM/PM PM Examiners Initials BP

Time of Examination Start 7:00 AM/PM AM End 9:30 AM/PM PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0		ok	none observed	
#2	20	0	0		ok	none observed	
#3	20	0	0		ok	none observed	
#4	20	0	0		ok	none observed	
#5	20	0	0		ok	none observed	
#6	20	0	0		ok	none observed	
#7	20	0	0		ok	none observed	
Kitchen	20	0	0		ok	none observed	
Transformers	20	0	0		ok	none observed	
CO sensors					Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

**SIGNATURE**  
 \_\_\_\_\_  
 \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9367  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04234

**SIGNATURE**  
 \_\_\_\_\_  
 Counter Signature

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-8-07

SECTION/AREA BELTS

Time of Examination Start 3:00  AM  PM End 5:10  AM  PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	ACC AT TA <sup>1</sup> Roller BAD Bottom 101-102	SENT MEN TO FIX Done 3-8-07 AB
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
#7	20.9	0	0	OK	Roller Piles 120-126 + 114-112	BEING CLEANED
Kitchen	20.9	0	0	OK	none observed	
Transformers	20.9	0	0	OK	none observed	
CO Sensors	20.9	0	0	OK	Visual Exam	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than noted above all other areas  
safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature SIGNATURE \_\_\_\_\_  
 \_\_\_\_\_

2MSHA04235

Certificate # 7488

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3 8 07

SECTION/AREA Belts

Time of Examination Start 11:30 AM/PM

End 1 AM/PM

Examiners Initials dg

Time of Examination Start 11:00 AM/PM

End 1:10 AM/PM

Examiners Initials J.D

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	none observed	
# 2	20.9	0	0	OK	none observed	
# 3	20.9	0	0	OK	none observed	
# 4	20.9	0	0	OK	ACC at Tail	BEING CLEANED done dg
# 5	20.9	0	0	OK	none observed	
# 6	20.9	0	0	OK	none observed	
# 7	20.9	0	0	OK	Roller Piles 120-126 112-114	BEING CLEANED
TRANSFORMERS	20.9	0	0	OK	None observed	112-114 DONE
Kitchen	20.9	0	0	OK	None observed	
CO SENSORS				Visual Exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

Pre-Shift/Mine Examiner SIGNATURE  
 Pre-Shift/Mine Examiner SIGNATURE  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6622  
 Certificate # 9660  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04236

Counter Signature SIGNATURE

Certificate # 7488

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-8-07 SECTION/AREA Belts

Time of Examination Start 7:30 AM/PM AM End 9:00 AM/PM PM Examiners Initials BP  
 Time of Examination Start 7:45 AM/PM AM End 9:40 AM/PM PM Examiners Initials TC  
 Time of Examination Start \_\_\_\_\_ AM/PM \_\_\_\_\_ End \_\_\_\_\_ AM/PM \_\_\_\_\_ Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No  
 Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_  
 Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none obs	
#2	20	0	0	OK	none observed	
#3	20	0	0	OK	none obs.	
#4	20	0	0	OK	none obs.	
#5	20	0	0	OK	none observed	
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	Roller Pilets 120 to 126	getting men on it Done 2907 ct
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO sensors		Visual Exam		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS other than listed Above All other   
overhead areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 9599  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 9362  
 Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 03892  
 2MSHA04237

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-9-07 SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM End 5:20  AM  PM Examiners Initials BP

Time of Examination Start 3:47  AM  PM End 5:30  AM  PM Examiners Initials KL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	ok	none observed	
#2	20	0	0	ok	none observed	
#3	20	0	0	ok	none observed	
#4	20	0	0	ok	none observed	
#5	20	0	0	ok	none observed	
#6	20	0	0	ok	none observed	
#7	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
Co Sensors	20	0	0	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9529  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

2MSHA04238

Certificate # 1125

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-9-07

SECTION/AREA Belts

Time of Examination Start 11:12 AM/PM

End 1:25 AM/PM

Examiners Initials LR/RR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	accum. hydrocarbon	sediment & clean cleaned 3-9-07
#6	20.9	0	0	OK	None observed	
#7	20.9	0	0	OK	None observed	
# Belt/Kitchen	20.9	0	0	OK	None observed	
Trans.	20.9	0	0	OK	None observed	
C.O. Monitors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam.

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

SIGNATURE

2MSHA04239

Counter Signature \_\_\_\_\_

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-9-07

SECTION/AREA Belts

Time of Examination Start 700 AM/PM End 940 AM/PM Examiners Initials DD/km

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	Acc. At Drive	working on CLEARED 3-9-07
#6	20.9	0	0	ok	Acc. At Headroller	working on CLEARED 3-9-07
#7	20.9	0	0	ok	Acc. At Headroller	working on CLEARED 3-9-07
Trans	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO monitors	Visual exam			ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 9379  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

2MSHA04240

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-10-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 5:21 AM/PM

Examiners Initials MC

Time of Examination Start 300 AM/PM

End 525 AM/PM

Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Accum Tailpiece	sent me to clean done 3-10-07
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	Accum Tailpiece	sent me to clean done 3-10-07
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	Accum drive	sent me to clean done 3-10-07
#6	20.9	0	0	OK	Accum drive	sent me to clean done 3-10-07
#7	20.9	0	0	OK	None observed	
TRAPS FORMERS	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO MONITORS				2MSHA EXAM		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#7 Headroller	Acc. of coal	cleaned 3-10-07
#6 Headroller	Acc. of coal	cleaned 3-10-07
#5 Drive	Acc. of coal	cleaned 3-10-07

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

2MSHA04241

Counter Signature \_\_\_\_\_

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-10-07 SECTION/AREA Belts

Time of Examination Start 11:05  AM  PM End 1:20  AM  PM Examiners Initials LR/RL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
#6	20.9	0	0	OK	None obs.	
#7	20.9	0	0	OK	None obs.	
Turnos.	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
CO Monitor	V. 300	L	Exam	OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 4325

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 6401

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 4935

2MSHA04242

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-10-07

SECTION/AREA Belt

Time of Examination Start 7:00 AM/PM AM End 9:15 AM/PM PM Examiners Initials Km/mc

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	none obs.	
#4	20.9	0	0	OK	none obs.	
#5	20.9	0	0	OK	Acc drive	Cleaned 3-10-07
#6	20.9	0	0	OK	none obs.	
#7	20.9	0	0	OK	stopping out for 129 Return ACC head rollers	Cleaned 3-10-07
Trans	20.9	0	0	OK	none obs	
Kitchen	20.9	0	0	OK	none obs	
CO monitors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas appeared safe at time of exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7575

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

SIGNATURE

2MSHA04243

Counter Signature \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-11-07

SECTION/AREA Belts

Time of Examination Start 300  AM/PM End 530  PM Examiners Initials DDKM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none obs.	
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	Acc. AT drive	Working on drive 3-11-07
#6	20.9	0	0	ok	Acc. of COAL Drive to xc-	Working on drive 3-11-07
#7	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
C.O monitors				visual ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04244

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Certificate # 4735



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-12-07

SECTION/AREA BELTS

Time of Examination Start 11:00  AM  PM End 11:15  AM  PM Examiners Initials BP  
 Time of Examination Start ~~11:00~~ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#6	20	0	0	OK	none observed	
#7	20	0	0	OK	none observed	
Kitchen	20	0	0	OK	none observed	
Transformers	20	0	0	OK	none observed	
CO Sensors				Visual Exam		
#1						
#2						
#3						
#4						
#5						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas approved  
Safe at time of Exam

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04246

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 03992

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3 12 07 SECTION/AREA BELTS

Time of Examination Start 7 AM/PM (M) End 8:35 AM/PM (M) Examiners Initials LD

Time of Examination Start 7:00 AM/PM (M) End 8:45 AM/PM (M) Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>A1</u>						
<u>2</u>						
<u>3</u>						
<u>4</u>						
<u>5</u>						
<u>6</u>						
<u>7</u>						
<u>Kitchen Belt</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>ok</u>	<u>None observed</u>	
<u>Belt Transformer</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>ok</u>	<u>None observed</u>	

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe  
at time of pre-shift  
Belts 1 thru 7 idle

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 662  
 Certificate # 9660  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature SIGNATURE \_\_\_\_\_  
 \_\_\_\_\_

2MSHA04247

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-13-07

SECTION/AREA Belts

Time of Examination Start 3:00 (AM)/PM

End 5:00 (AM)/PM

Examiners Initials LD

Time of Examination Start 3 (AM)/PM

End 5:00 (AM)/PM

Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
#3	20.9	0	0	OK	none observed	
#4	20.9	0	0	OK	none observed	
#5	20.9	0	0	OK	none observed	
#6	20.9	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none observed	
transformer	20.9	0	0	OK	none observed	
CO Sensors	Visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

2MSHA04248

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-13-07 SECTION/AREA BELTS

Time of Examination Start 11:00 ~~AM~~ PM End 12:18 ~~AM~~ PM Examiners Initials BP

Time of Examination Start 11:10 ~~AM~~ PM End 12:20 ~~AM~~ PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20.9	0	0	OK	none obs.	
# 2	20.9	0	0	OK	none obs.	
3 <sup>rd</sup> North 1				OK	none obs.	
#3 <sup>rd</sup> North 2	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
TRANSFORMERS	20.9	0	0	OK	none obs.	
Clo sensors				OK	none obs.	
V. Sec Exam						

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04249

Certificate # 9362

Certificate # 9599

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-13-07

SECTION/AREA Belts

Time of Examination Start 7:10 AM/PM (AM) End 8:45 AM/PM (PM) Examiners Initials JG  
 Time of Examination Start 7:30 AM/PM (AM) End 8:30 AM/PM (PM) Examiners Initials JG  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	none observed	
#2	20.9	0	0	ok	none observed	
3rd Nth #1	20.9	0	0	ok	no High Voltage sign	WORKING ON
3rd Nth #2	20.9	0	0	ok	Belt Side Trans room #7 and #10 stoppings in need of repair	DONE JG SENT MEN TO REPAIR DONE JG
kitchen	20.9	0	0	ok	none observed	
Transformers	20.9	0	0	ok	none observed	
CO Sensors	visual exam					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of exam except those noted above

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04250

**SIGNATURE**  
 Counter Signature \_\_\_\_\_

Certificate # 7485





# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-14-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:50 AM/PM PM Examiners Initials JD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Floet Dust XC 31-Tail	going to dust Done JD 3-14-07
#2	20.9	0	0	OK	none observed	
3rd M <sup>th</sup> #1	20.9	0	0	OK	none observed	
3rd M <sup>th</sup> #2	20.9	0	0	OK	exposed bolt between XC 10 and XC 11	going to set timber Done JD 3-4-07
Kitchen	20.9	0	0	OK	none observed	
Transformers					none observed	
CO Sensors				visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04253

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7485



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-15-07 SECTION/AREA Belts

Time of Examination Start 11:00 AM End 12:35 PM Examiners Initials BP

Time of Examination Start 11:15 AM End 12:38 PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
# 1	20	0	0	ok	none observed	
# 2	20	0	0	ok	none observed	
3 <sup>rd</sup> North #1	20	0	0	ok	none observed	
3 <sup>rd</sup> North #2	20	0	0	ok	none observed	
Kitchen	20	0	0	ok	none observed	
Transformers	20	0	0	ok	none observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
#5 tail	Not guarded	Guarded tail

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner [Signature] Certificate # 9599

Pre-Shift/Mine Examiner [Signature] Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04255

Counter Signature [Signature] Certificate # 03992





# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-16-07 SECTION/AREA Belts

Time of Examination Start 11:00 ~~AM~~/PM End 12:30 AM/~~PM~~ Examiners Initials KM/DO  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_  
 Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_  
 Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs.	
3 <sup>rd</sup> north #1	20.9	0	0	OK	none obs.	
3 <sup>rd</sup> north #2	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs.	
Trans	20.9	0	0	OK	none obs.	
CO monitors	visual exam OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Ases appeared safe at the time of exam

**SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9379  
 Certificate # 8058  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04258

**SIGNATURE** \_\_\_\_\_  
 Counter Signature \_\_\_\_\_

Certificate # 8162

# PRE-SHIFT BELTS

DATE OF EXAMINATION 2-16-07

SECTION/AREA S. 205

Time of Examination Start 7:20 AM/PM  End 8:04 AM/PM  Examiners Initials LR/SL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0.0	0.0	↔	none obs.	
#2	20.9	0.0	0.0	↔	none obs.	
#3	20.9	0.0	0.0	↔	none obs.	
#4	20.9	0.0	0.0	↔	none obs.	
Kitchen	20.9	0.0	0.0	↔	none obs.	
Trans.	20.9	0.0	0.0	↔	none obs.	
S.O. monitor visual exam						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS areas appeared safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Certificate # 4325

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE**

2MSHA04259

Certificate # 4185



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-17-07

SECTION/AREA Belt

Time of Examination Start ~~11:27~~ 11:27 AM/PM End ~~11:07~~ 11:07 AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
3 <sup>RD</sup> NORTH #1	20.9	0	0	OK	None observed	
3 <sup>RD</sup> NORTH #2	20.9	0	0	OK	None observed	
TRANSFORMERS	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
CO monitors				VLS 4A/ EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04261

Certificate # 7375

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE**

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-17-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:05 AM/PM PM Examiners Initials AK/LR

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	21.0	0.0	0.0	OK	none obs	
#2	20.9	0.0	0.0	OK	Acc. at tailpiece	Working on cleaned 3-18-07
3 worth #1	20.9	0.0	0.0	OK	None obs.	
3 worth #2	20.4	0.0	0.0	OK	None obs.	
Belt Kitchen	20.9	0.0	0.0	OK	None obs	
Trams	20.9	0.0	0.0	OK	none obs	
C.O. Monitors				visual	OK	

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas approved Safe at time of Exam except as noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954

Certificate # 4325

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

2MSHA04262

Counter Signature \_\_\_\_\_

Certificate # 4735

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-18-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM

End 4:05 AM/PM

Examiners Initials RR/KR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none obs.	
#2	20.9	0	0	OK	none obs	
3rd Shift #1	20.9	0	0	OK	none obs	
3rd Shift #9	20.9	0	0	OK	none obs.	
Kitchen	20.9	0	0	OK	none obs	
Tram	20.9	0	0	OK	none obs	
C.O. Monitor	used			EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7954  
 Certificate # 4375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04263

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-18-07

SECTION/AREA Belts

Time of Examination Start 1100  AM  PM End 122 AM  PM Examiners Initials DD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	Acc@ Tail	cleaned 3-18-07
#2	20.9	0	0	ok	none obs.	
3 <sup>rd</sup> North #1	20.9	0	0	ok	none obs.	
3 <sup>rd</sup> North #2	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
Trans.	20.9	0	0	ok	none obs.	
CO Sensors		Visual	ok			

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#1 Drive	oil Acc@ Drive	Degreased & Cleaned

PRE-SHIFT REMARKS All Areas safe At time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04264

Certificate # 8058

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 7462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-18-07

SECTION/AREA Belt

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<i>all Belts FOLIE</i>						

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE**

Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04265 \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE**

Certificate # 03892





# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-20-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM End 4:55  AM  PM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	Trash By Drive XCI	Sending man to clean Date 3-20-07
#2	20.9	0	0	OK	none obs	
3rd North #1	20.9	0	0	OK	none obs	
3rd North #2	20.9	0	0	OK	Acc Back sid fender Hindering Accscs fire eq	Sending people to clean Date 3-20-07
Kitchen	20.9	0	0	OK	none obs	
transformers	20.9	0	0	OK	none obs	
CO Sensors	Visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

**SIGNATURE** [Redacted]

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04268

Counter Signature **SIGNATURE** [Redacted]

Certificate # [Signature]

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-20-07

SECTION/AREA BELTS

Time of Examination Start 11:00  AM  PM End 12:45  AM  PM Examiners Initials BP

Time of Examination Start 11:15  AM  PM End 12:00  AM  PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CR/M/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs.	
3rd North #1	20	0	0	OK	none observed	
3rd North #2	20	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none obs.	
Transformer	20	0	0	OK	none observed	
CO SENSORS	20	VISUAL EXAM				

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of EXAM

Pre-Shift/Mine Examiner **SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE**

2MSHA04269

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-20-07

SECTION/AREA Belts

Time of Examination Start 7:05 AM/PM AM

End 8:20 AM/PM PM

Examiners Initials LP

Time of Examination Start 7 AM/PM AM

End 745 AM/PM PM

Examiners Initials ag

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
3rd North #1	20.9	0	0	OK	None obs	
3rd North #2	20.9	0	0	OK	None obs	
Kitchen	20.9	0	0	OK	None observed	
transformers	20.9	0	0	OK	None observed	
CO Sensors	visual exam			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Pre-Shift/Mine Examiner SIGNATURE  
 Pre-Shift/Mine Examiner SIGNATURE  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04270

Counter Signature SIGNATURE

Certificate # 7485



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-21-07

SECTION/AREA Belts.

Time of Examination Start 11:10  AM  PM

End 1:12 AM  PM

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		OK	None obs.	
#2	20.9	0	0		OK	None observed	
3rd north #1	20.9	0	0		OK	None obs.	
3rd north #2	20.9	0	0		R	None observed	
Kitchen	20.9	0	0		OK	None obs.	
Transformer	20.9	0	0		OK	None obs.	
CO sensor					Visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362  
 Certificate # 8395  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_  
 2MSHA04272

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-21-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:25 AM/PM PM Examiners Initials LD

Time of Examination Start 7 AM/PM AM End 7:45 AM/PM PM Examiners Initials LD

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3 <sup>rd</sup> North #1	20.9	0	0	ok	none observed	
3 <sup>rd</sup> North #2	20.9	0	0	ok	none observed	
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
CO Sensors				visual exam ok		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#2 Belt Headsets	scrapped piles	cleaned & washed

PRE-SHIFT REMARKS All areas examined appear safe at Time of pre-shift

Pre-Shift/Mine Examiner SIGNATURE Certificate # 9660

Pre-Shift/Mine Examiner SIGNATURE Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04273

Counter Signature SIGNATURE Certificate # 7488



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-22-07

SECTION/AREA Belts

Time of Examination Start 12:05 AM/PM AM End 1:03 AM/PM PM Examiners Initials BH

Time of Examination Start 12:18 AM/PM AM End 1:05 AM/PM PM Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None Observed	
#2	20.9	0	0	OK	None observed	
3 <sup>rd</sup> North #1	20.9	0	0	OK	None observed	
3 <sup>rd</sup> North #2	20.9	0	0	OK	None Observed	
Kitchen	20.9	0	0	OK	None Observed	
Transformers	20.9	0	0	OK	None Observed	
CO monitors		Visual exam		OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8395  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

2MSHA04275

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-22-07

SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 8:25 AM/PM PM Examiners Initials ZD  
 Time of Examination Start 7 AM/PM AM End 7:35 AM/PM PM Examiners Initials ZD  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
3rd North #1	20.9	0	0	OK	None observed	told Scott from Beltsman to clean ZD
3rd North #2	20.9	0	0	OK	None Back side of feeder	told Section foreman to clean zone ZD
Kitchen	20.9	0	0	OK	None observed	
transformers	20.9	0	0	OK	None observed	
CO Sensors				V. SW/ exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
3rd North #1	Bad R. b out by Drive	Bring down R. b ZD

PRE-SHIFT REMARKS all areas examined appear safe at Time of pre-shift except what is noted above

**SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6627  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04276

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-23-07

SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 4:35 AM/PM Examiners Initials JD  
 Time of Examination Start 3 AM/PM End 3:35 AM/PM Examiners Initials JG  
 Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None observed	
#2	20.9	0	0	OK	None observed	
3rd North #1	20.9	0	0	OK	None observed	
3rd North #2	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
Transformers	20.9	0	0	OK	None observed	
CO Sensors				Visual exam OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS

all areas examined ~~and~~ appear safe at time of pre-shift

Pre-Shift/Mine Examiner **SIGNATURE**  
 Pre-Shift/Mine Examiner **SIGNATURE**  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** 2MSHA04277

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-23-07

SECTION/AREA BELTS

Time of Examination Start 11:00 AM/PM End 12:06 AM/PM Examiners Initials MCKm

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	none observed	
#2	20.9	0	0	OK	none observed	
3 <sup>RD</sup> NORTH #1	20.9	0	0	OK	none observed	
3 <sup>RD</sup> NORTH #2	20.9	0	0	OK	none observed	
TRANSFORMERS	20.9	0	0	OK	none observed	
Kitchen ✓	20.9	0	0	OK	none observed	
CO SENSORS				VISUAL EXAM OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 7375  
 Certificate # 9379  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04278

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8468

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-23-07 SECTION/AREA Belts

Time of Examination Start 7:00 AM/PM AM End 9:00 AM/PM PM Examiners Initials RR/UK

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None obs.	
3 <sup>rd</sup> North #1	20.9	0	0	OK	None obs.	
3 <sup>rd</sup> North #2	20.9	0	0	OK	None obs.	
Turns Formers	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
CO SENSORS	Vis. SUMP Exam			OK		

ON-SHIFT HAZARDS IDENTIFIED	LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 4325

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_ Certificate # 7954

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04279

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-24-07 SECTION/AREA Belts

Time of Examination Start 3:00 AM/PM End 5:00 AM/PM Examiners Initials SR/25

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0		α	none obs.	
#2	20.9	0	0		α	none obs.	
3rd Shift #1	20.9	0	0		α	none obs.	
3rd Shift #2	20.9	0	0		α	none obs. from fall out by 2 BREAKS	working on Done 3-24-07
Belt Kitchen	20.9	0	0		α	none obs.	
Trans.	20.9	0	0		α	none obs.	
C.O. Monitor	equal			EXAM	α		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas appeared reasonably safe except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04280

Certificate # 7954

Certificate # 4325

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 4735









# PRE-SHIFT BELTS

DATE OF EXAMINATION 3.25.07 SECTION/AREA Belts

Time of Examination Start 700 AM/PM AM End 930 AM/PM PM Examiners Initials RR

Time of Examination Start \_\_\_\_\_ AM/PM \_\_\_\_\_ End \_\_\_\_\_ AM/PM \_\_\_\_\_ Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM \_\_\_\_\_ End \_\_\_\_\_ AM/PM \_\_\_\_\_ Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1		00	00	OK	None obs.	
#2	20.9	00	00	OK		
3 <sup>rd</sup> North #1	20.9	00	00	OK		
3 <sup>rd</sup> North #2	20.9	00	00	OK		
Kitchen	20.9	00	00	OK		
Trucks	20.9	00	00	OK	None obs.	
CO Monitors	Visual Exam OK			OK		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Area appeared safe at time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4375  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04285

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 8462







# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-27-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM End 4:45  AM  PM Examiners Initials DP

Time of Examination Start 3:00  AM  PM End 5:33  AM  PM Examiners Initials JL

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CR/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	None obs.	
#2	20	0	0	OK	None obs.	
3 <sup>rd</sup> North #1	20	0	0	OK	None obs. ACC AT HEAD ROLLER STRUCTURE ADJ AT RIGHT OVERCAST	Men working on. DONE TO
3 <sup>rd</sup> North #2	20	0	0	OK	None obs.	
Kitchen	20	0	0	OK	None obs.	
Transformers	20	0	0	OK	None obs.	
CO monitors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All Areas Except Listed Above  
Safe at time of exam

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599  
 Certificate # 9362  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04289

Counter Signature SIGNATURE \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 32707 SECTION/AREA BELTS

Time of Examination Start 1125 AM/PM AM End 130 AM/PM PM Examiners Initials dy

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1 Belt	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3rd no #1	20.9	0	0	ok	None observed	
3rd no #2	20.9	0	0	ok	roller piles to 11 feet	SENT MAN TO CLEAN DONE JC
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
COMPARATORS	U/S	U/S	U/S	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appears safe at time of pre-shift (except what's noted above)

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6432  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04290

Counter Signature SIGNATURE \_\_\_\_\_

Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-27-07

SECTION/AREA Belts

Time of Examination Start 7:20 AM/PM  AM  PM End 9:47 AM/PM  AM  PM Examiners Initials TC

Time of Examination Start 7:00 AM/PM  AM  PM End 8:20 AM/PM  AM  PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM  AM  PM End \_\_\_\_\_ AM/PM  AM  PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO		CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0		OK	none obs	
#2	20.9	0	0		OK	none obs.	
3 <sup>rd</sup> North #1	20	0	0		OK	none obs	
3 <sup>rd</sup> North #2	20	0	0		OK	none obs	
#3	20.9	0	0		OK	none obs.	
#4	20.9	0	0		OK	none obs.	
#5	20	0	0		OK	none obs	
Kitchen	20.9	0	0		OK	none obs.	
Transformers	20.9	0	0		OK	none obs.	
Co monitors					Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
# Take-up	oil spill	Dusted Area LP

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Certificate # 9589

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

2MSHA04291

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 03892

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-28-07

SECTION/AREA Belts

Time of Examination Start 3:00  AM  PM

End 4:15  AM  PM

Examiners Initials BD

Time of Examination Start 3:00  AM  PM

End 5:20  AM  PM

Examiners Initials TC

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None obs.	
#2	20.9	0	0	OK	None observed	
#3	20.9	0	0	OK	None observed	
#4	20.9	0	0	OK	None observed	
#5	20.9	0	0	OK	acc under Drive Needs Dusted Hand Pad	SENT MEN TO CLEAN cleaned & dusted
3 <sup>rd</sup> North #1	20.9	0	0	OK	None observed	
3 <sup>rd</sup> North #2	20.9	0	0	OK	None observed	
Kitchen	20.9	0	0	OK	None observed	
Transformer	20.9	0	0	OK	None observed	
CO sensors				Visual Exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION
<del> </del>	<del> </del>	<del> </del>

PRE-SHIFT REMARKS Other than Graded Areas safe

AT Time of Exam

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9599

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04292

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 7488

# PRE-SHIFT BELTS

DATE OF EXAMINATION 32807 SECTION/AREA BELTS

Time of Examination Start 1120 AM/PM End 1 AM/PM Examiners Initials dy

Time of Examination Start 1110 AM/PM End 1:00 AM/PM Examiners Initials slp

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	None observed	
#2	20.9	0	0	ok	None observed	
#3	20.9	0	0	ok	Needs Rock dusting	BEING DUSTED Done dy
#4	20.9	0	0	ok	Needs Rock dusting	BEING DUSTED Dusted 678 to 928 dy
#5	20.9	0	0	ok	None observed	

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear Reasonable by safe at time of pre-shift (except what is noted above)

**SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 6622

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # 9660

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_ Certificate # \_\_\_\_\_

2MSHA04293

Counter Signature **SIGNATURE** \_\_\_\_\_ Certificate # 7485

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-28-07 SECTION/AREA Belts

Time of Examination Start 7:06 AM/PM AM End 9:18 AM/PM PM Examiners Initials JC

Time of Examination Start 7:06 AM/PM AM End 9:25 AM/PM PM Examiners Initials BP

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_ Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_ Signature \_\_\_\_\_

Called Out By \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20	0	0	OK	none observed	
#2	20.9	0	0	OK	none obs.	
#3	20.9	0	0	OK	DEEP WATER XC45 & XC47	sent men to pump Done CA 32907
#4	20.9	0	0	OK	needs dusted 92-TAD	sent men to dust Done CA 32907
#5	20	0	0	OK	none observed	
Kitchen	20.9	0	0	OK	none obs.	
Transformer	20	0	0	OK	none obs.	
Clo sensor				VISUAL EXAM		

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
main west	Stopping at Feeder	Keenel

PRE-SHIFT REMARKS All areas appeared safe at time of Exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9362

Certificate # 9599

Certificate # \_\_\_\_\_

Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 03892

2MSHA04294



# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-29-07

SECTION/AREA Belts

Time of Examination Start 11:00 AM/PM End 1:15 AM/PM Examiners Initials J.D.

Time of Examination Start 12 AM/PM End 130 AM/PM Examiners Initials J.D.

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	ACC at Tail	BEING CLEANED
#2	20.9	0	0	ok	Flot Dust Headroller #1X	BEING OUSED Done 3-29-07 J.D.
#3	20.9	0	0	ok	None observed	
#4	20.9	0	0	ok	Roller - piles 99, 88, 68 ACC XE 76, 90	WORKING ON Done 3-29-07 J.D.
#5	20.9	0	0	ok	Pile under Drive	WORKING ON Done 3-29-07 J.D.
Kitchen	20.9	0	0	ok	None observed	
Transformers	20.9	0	0	ok	None observed	
CO Sensors				visual exam ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS all areas examined appear safe at Time of Preshift (except what is noted above)

Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner SIGNATURE \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 9660  
 Certificate # 6622  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04296

Counter Signature SIGNATURE \_\_\_\_\_

Certificate # 7485





# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-30-07

SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM

End 1:15  AM  PM

Examiners Initials LR/KR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	TAIL Needs Dusted AND Stack Tube Needs cleaned	Working on both corrected 3-30-07 KR
#2	20.9	0	0	OK	None obs.	
#3	20.9	0	0	OK	None obs.	
#4	20.9	0	0	OK	None obs.	
#5	20.9	0	0	OK	None obs.	
Kitchen	20.9	0	0	OK	None obs.	
TRANS.	20.9	0	0	OK	None obs.	
C/O SENSORS	Visual Exam OK					

**ON-SHIFT HAZARDS IDENTIFIED**

LOCATION	HAZARDS	ACTION
#5 Drive	Acc. of Coal	Cleaned 3-30-07 KR

PRE-SHIFT REMARKS Area approved Safe at time of Exam except as noted above

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_

Certificate # 4375  
 Certificate # 7954  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

2MSHA04299

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-30-07

SECTION/AREA Belts

Time of Examination Start 735 AM/PM  AM  PM End 930 AM/PM  AM  PM Examiners Initials DD

Time of Examination Start 817 AM/PM  AM  PM End 905 AM/PM  AM  PM Examiners Initials RM

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Signature \_\_\_\_\_

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	<del>none obs.</del> Acc. @ Tail	Cleaned working on 3-30-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	none obs.	
#4	20.9	0	0	ok	none obs.	
#5	20.9	0	0	ok	Acc. at Drive	working on cleaned 3-30-07
TRANS.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors				Visual exam		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam

Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner **SIGNATURE** \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_ 2MSHA04300 \_\_\_\_\_  
 Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058  
 Certificate # 9379  
 Certificate # \_\_\_\_\_  
 Certificate # \_\_\_\_\_

Counter Signature **SIGNATURE** \_\_\_\_\_

Certificate # 8462

# PRE-SHIFT BELTS

DATE OF EXAMINATION 3-31-07

SECTION/AREA Belts

Time of Examination Start 300 ~~AM~~PM End 530 ~~AM~~PM Examiners Initials DD PC

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM End \_\_\_\_\_ AM/PM Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	ok	acc x cut & inbetween DPS ✓	Ass. men to clean Done 3-31-07
#2	20.9	0	0	ok	none obs.	
#3	20.9	0	0	ok	Acc. of Coal @ Tail	Ass. men to clean Done 3-31-07
#4	20.9	0	0	ok	Acc. @ Tail	Ass. men to clean Done 3-31-07
#5	20.9	0	0	ok	None Observed	
Trans.	20.9	0	0	ok	none obs.	
Kitchen	20.9	0	0	ok	none obs.	
CO Sensors			Visual	ok		

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS All areas safe at time of exam. except those noted above

**SIGNATURE**

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8058

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 8462

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04301

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

**SIGNATURE**

Counter Signature \_\_\_\_\_

Certificate # 4135

# PRE-SHIFT BELTS

DATE OF EXAMINATION 5-31-07

SECTION/AREA Belts

Time of Examination Start 11:00  AM  PM

End 1:15  AM  PM

Examiners Initials RH/HR

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Time of Examination Start \_\_\_\_\_ AM/PM

End \_\_\_\_\_ AM/PM

Examiners Initials \_\_\_\_\_

Exam. Called Out -  Yes  No

Called Out By \_\_\_\_\_

Report Received by \_\_\_\_\_

Called Out By \_\_\_\_\_

Called Out By \_\_\_\_\_

Signature

LOCATION	O <sub>2</sub>	CH <sub>4</sub> %	CO	CRM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
#1	20.9	0	0	OK	None	
#2	20.9	0	0	OK	None	
#3	20.9	0	0	OK	None	
#4	20.9	0	0	OK	Deep water #73	Pumped 3-31-07
#5	20.9	0	0	OK	None	
Belt Kitaker	20.9	0	0	OK	None	
Trans.	20.9	0	0	OK	None	
L.O. Monitors	4: SUKAL Expm OK					

ON-SHIFT HAZARDS IDENTIFIED

LOCATION	HAZARDS	ACTION

PRE-SHIFT REMARKS Areas approved Safe at time of Exam except as noted above

SIGNATURE

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 4325

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # 6401

Pre-Shift/Mine Examiner \_\_\_\_\_

2MSHA04302

Certificate # \_\_\_\_\_

Pre-Shift/Mine Examiner \_\_\_\_\_

Certificate # \_\_\_\_\_

SIGNATURE

Counter Signature \_\_\_\_\_

Certificate # 8462

