



Section I--Violation Data

1. Date Mo Da Yr 12/06/2011	2. Time (24 Hr. Clock) 0800	3. Citation/ Order Number 8256983
4. Served To Berman Cornett (Safety Director)		5. Operator PERFORMANCE COAL COMPANY, et al
6. Mine UPPER BIG BRANCH MINE-SOUTH		7. Mine ID 46-08436 (Contractor)
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

A Qualified electrician(agent of the Operator) has failed to make an adequate weekly examination of the Fairchild scoop (serial #T339-255), during the weeks prior to 04.05.2010. This scoop is located at the Mother Drive Construction Area, adjacent to spad #24452. The scoop was readily available for use on 04.05.2010. It is located in an area affected by a mine explosion on 04.05.2010.

(1) Order #8256984 is to be issued for the fifteen defects affecting the permissibility of the scoop.

(2) Citation #8256985 is issued citing 30 C.F.R. Part 75.1107-9(a)(1) for defects that affect the dry chemical fire suppression system installed on this scoop.

Some of these conditions are obvious to the most casual observer and have

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input checked="" type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 75.512
--------------	--	-------------------	---

Section II--Inspector's Evaluation

10. Gravity:

A. Injury or Illness (has) (is): No Likelihood Unlikely Reasonably Likely Highly Likely Occurred

B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling Fatal

C. Significant and Substantial: Yes No D. Number of Persons Affected: 010

11. Negligence (check one) A. None B. Low C. Moderate D. High E. Reckless Disregard

12. Type of Action 104(d)(2) 13. Type of Issuance (check one) Citation Order Safeguard Written Notice

14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice E. Citation/
Order Number 8082692 F. Dated Mo Da Yr
03/17/2009

15. Area or Equipment Fairchild scoop (serial # T339-255)

16. Termination Due	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
---------------------	------------------	------------------------

Section III--Termination Action

17. Action to Terminate

18. Terminated	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
----------------	------------------	------------------------

Section IV--Automated System Data

19. Type of Inspection (activity code) E16	20. Event Number 4440348	21. Primary or Mill
22. Signature Patrick Alan Stanfield		23. AR Number 23908

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input type="checkbox"/> <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 12/06/2011	3. Citation/ Order Number 8256983
4. Served To Berman Cornett (Safety Director)	5. Operator PERFORMANCE COAL COMPANY, et al	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

Continuation of 8. Condition or Practice

existed for a significant amount of time. The cited condition is obvious and extensive. The cited condition poses a high degree of danger to the scoop operator and HG 22 miners, located inby. If an adequate examination had been conducted some of these conditions (hazards) should have been detected and corrected. An agent of the Operator (Qualified electrician) is required to examine this electrical equipment on a weekly basis.

The Operator has engaged in aggravated conduct constituting more than ordinary negligence. This is an unwarrantable failure to comply with a mandatory standard.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
------------------------------------	------------------------	-------------------------------------	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E16	10. Event Number 4440348		
11. Signature Patrick Alan Stanfield	AR Number 23908	12. Date Mo Da Yr 12/06/2011	13. Time (24 Hr. Clock) 0800