Mine Citation/Order

U.S. Department of Labor Mine Safety and Health Administration

Section I-Violation Data 1. Date Mo Da Yr 2. Time (24 Hr. Clock) 3. Citation/ 8256994 Order Number 12/06/2011 0800 4. Served To 5. Operator PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 7. Mine ID 6. Mine 46-08436 (Contractor) UPPER BIG BRANCH MINE-SOUTH 8a. Written Notice (103g) 8. Condition or Practice

Adequate short circuit protection is not being provided for the #137 Pump, located on the North Mains. A 10/5 AWG power cable supplies 480 volts to the pump. A Cutler-Hammer circuit breaker (labeled as "137 pump"), with an adjustable trip of 300 to 700 amps, provides power to this circuit. The instantaneous is set on low-300 amps. The circuit breaker cannot be set low enough for the cable/equipment. The circuit breaker for #137 Pump is in the AEEI transformer (serial # 27201-1400-1008) , located adjacent to spad # 24357.

The operator has a history of similar violations. The cited condition is located in an area affected by an explosion on 04.05.2010.

This citation is being issued to the following entities as a unitary

										See Cor	itinuation Form (MSF	1A Form 7000-3a) 🛛 🗹
9. Violation A. Health B. Section Safety ✔ of Act Other				C. Part/Section of Title 30 CFR			75.518					
Section IIInspec	tor's Evalu	ation										
10. Gravity:												· · · ·
A. Injury or	liiness (h	as) (is):	No Likelih	nood	Unlikely		Reasonabl	y Likely	\checkmark	Highly Llkely	Occu	rred
B. Injury or sonably b			No Los	st Work	days 📋 🛛 Lost V	Vorko	lays Or Restr	icted D	uty 🗸	Permanen	tly Disabling	Fatal
C. Significa	nt and Su	Ibstantial	: Ye	s 🗸	No 🗌					D. Number o	f Persons Affected	^{d:} 002
11. Negligence	(check o	ne)	A. None		B. Low	С. М	oderate		D. High	✓ E	. Reckless Disreg	ard 🗌
12. Type of Act	tion 1	04(a)			13. Type of Issu	uance	e (check one)	Cita	ation 🖌	Order	Safeguard	Written Notice
14. Initial Action A. Citation	n B. Or	der 📋	C. Safegu	ard 🗌	D. Written Notice		E. Citation/ Order Nu	mber			F. Dated	Mo Da Yr
16. Termination	Due	A. Date	Mo Da 01/05/2		B. Time (24 Hr. Clo	ock)	0800)				
Section III-Termin	nation Actio	on			· · · · · · · · · · · · · · · · · · ·							
17. Action to Te	· · · ·	Mol	Da Yr						<u>.</u>			
A. Date B. Time (24			(24 Hr. Clock	4 Hr. Clock								
Section IVAutom	ated Syste	em Data									····· ·	
19. Type of Insp (activity cod		E16	20. Event	t Numbe	4440348	8	21. P	rimary o	or Mill			
22. Signature Patrick Alan Stanfield						23. AR Number 23908						
MSHA Form 7000 established a Nation enforcement action	onal Small	Business	and Agricultu	ure Regula	the provisions of the Sr atory Ombudsman and forcement activities an	10 Reg	gional Fairness	Boards t	to receive	comments from :	small businesses abo	out federal agency

enforcement actions. The Onbudshan annually evaluates enforcement activities and rates each agency's responsiveness to small business. In you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.



Mine Citation/Order Continuation

U.S. Department of Labor

Section I	Subsequent Action/Continue

Mine Safety and Health Administration

Section I-Subsequent Action/Continuation Data						
1. Subsequent Action 1a. Continuation 2. Dat	ted Mo Da Y riginal Issue) 12/06/2011	Yr 3. Citation/ Order Number 8256994				
4. Served To	5. C	Operator				
Berman Cornett (Safety Director)	PEI	PERFORMANCE COAL COMPANY, et al				
6. Mine	7. M	Mine ID (Contractor)	_			
UPPER BIG BRANCH MINE-SOUTH		46-08436				
Section II-Justification for Action	· · ·					

Continuation of 8. Condition or Practice

operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

Section III-Subsequent Action Taken						See Continuation Form	
8. Extended To A. Date Mo D.	a Yr	B. Time (24 Hr. Clock)		C. Vacated	D. Terminated	E. Modified	
Section IV-Inspection Data			18				
9. Type of Inspection E16	10. E [,]	vent Number 4440348			·		
11. Signature		AR Number	12. Date	Mo Da Yr	13. Time (24 Hr. Cloc	ck)	
Patrick Alan Stanfield		23908		12/06/2011	0800		
MSHA Form 7000-3a, Mar 85 (revised)							