Mine Citation/Order

U.S. Department of Labor Mine Safety and Health Administration

Section I--Violation Data 3. Citation/ Mo Da Yr 1. Date 2. Time (24 Hr. Clock) 8258603 Order Number 12/06/2011 0800 5. Operator 4. Served To PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 7. Mine ID 6. Mine 46-08436 (Contractor) UPPER BIG BRANCH MINE-SOUTH 8a. Written Notice (103g) 8. Condition or Practice The AEEI transformer (serial #11521-500-398) is not being properly maintained, in that; (1) high voltage cables are entering/exiting the transformer. As of 04.05.2010, it was being used as a Splice box, instead of a transformer. The electrical map has it listed as "OUT OF SERVICE". This transformer is located along the track at crosscut # 120 of the North Mains. The disconnects are The cited condition could lead a miner to think the transformer is not open. energized, resulting in a shock hazard. This transformer is located in an area affected by an explosion on 04.05.2010. The Operator is issued a high number of similar citations upon inspection of the underground electrical equipment, following the accident. See Continuation Form (MSHA Form 7000-3a) 1 C. Part/Section of 9. Violation A. Health B. Section Title 30 CFR 75.512 of Act Safety 🗸 Other Section II-Inspector's Evaluation 10. Gravity: Occurred Highly Likely No Likelihood Unlikely 🗸 Reasonably Likely A. Injury or Illness (has) (is): B. Injury or illness could rea-Lost Workdays Or Restricted Duty 🗸 Permanently Disabling Fatal No Lost Workdays sonably be expected to be: D. Number of Persons Affected: C. Significant and Substantial: 001 Yes 🗌 No 🗸 C. Moderate E. Reckless Disregard 11. Negligence (check one) A. None B. Low D. High 🗸 Written Notice Safeguard 13. Type of Issuance (check one) Citation 🗸 Order 12. Type of Action 104(a) F. Dated Mo Da Yr E. Citation/ 14. Initial Action D. Written Notice Order Number B. Order C. Safeguard A. Citation 15. Area or Equipment Mo Da Yr 16. Termination Due B. Time (24 Hr. Clock) A. Date 0800 01/05/2012 Section III--Termination Action 17. Action to Terminate Mo Da Yr 18. Terminated A. Date B. Time (24 Hr. Clock Section IV-Automated System Data 21. Primary or Mill 19. Type of Inspection 20. Event Number 4440348 E16 (activity code) 23. AR Number 22. Signature 23908 Patrick Alan Stanfield In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has MSHA Form 7000-3, Apr 08 (revised) established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the

enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine	Citatio	n/Order
Conti	nuatior	า

**U.S. Department of Labor** Mine Safety and Health Administration

|--|

Section I-Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Мо 12/(	Da 06/201		3. Citation/ Order Number	8258603			
4. Served To					5. Operator				
Berman Cornett (Safety Director)					PERFORMANCE COAL COMPANY, et al				
6. Mine			7	'. Mine ID		<i>.</i>	(Contractor)		
UPPER BIG BRANCH MINE-SOUTH					46-0843	6			
Section II–Justification for Action									

Continuation of 8. Condition or Practice

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

											See Continuation Form
Section III-Subsequent Act	tion Take	า									
8. Extended To A. Date	Mo	Da	Yr	B. Time (24	Hr. Clock)			C. Va	cated	D. Terminated	E. Modified
Section IV-Inspection Data	1					·					
9. Type of Inspection	E16		10. E <sup>.</sup>	vent Number	4440348					· .	
11. Signature					AR Number	12. Date	Мо	Da	Yr	13. Time (24 Hr. Ck	ock)
Patrick Alan Stanfield 23908		23908	12/06/2011			2011	0800				

MSHA Form 7000-3a, Mar 85 (revised)