Mine Citation/Order

U.S. Department of Labor Mine Safety and Health Administration

Section I--Violation Data 2. Time (24 Hr. Clock) 3. Citation/ 1. Date Mo Da Yr 8258609 Order Number 0800 12/06/2011 5. Operator 4. Served To PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 6. Mine 7. Mine ID 46-08436 UPPER BIG BRANCH MINE-SOUTH (Contractor) 8a. Written Notice (103g) 8. Condition or Practice The canopy on the Bucyrus shield hauler (serial #630-1027R1) is not

installed in a manner that will afford the equipment operator the designed protection, in the event of a roof or rib fall. Three of the four bolts to attach the canopy to the shield hauler are missing. The cited condition also presents another hazard. If the canopy is not securely attached to the frame of the equipment it may become dislodged and fall on the operator, resulting in crushing injuries.

The Bucyrus shield hauler is located near spad #22552. This area was affected by an explosion on 04.05.2010. The machine was not in use on this date, however it is readily available for use.

This citation is being issued to the following entities as a unitary

									See Co	ntinuation Fe	orm (MSH.	A Form 7000-3a)	
9. Violation A. Health B. Section Safety ✓ of Act Other			C. Part/Section of Title 30 CFR			75.1710-1							
Section IIInspe	ctor's Evalu	uation											
10. Gravity:			·										
A. Injury o	r illness (h	as) (is):	No Likelih	ood	Unlikely 🖌	Reasonab	ly Likely		Highly Likely	/	Occur	red	
B. Injury o sonably	r illness co be expect		No Los	t Workda	ays 📃 🛛 Lost Wo	rkdays Or Res	tricted D	uty 🔽	Permaner	ntly Disabli	ng 🗌	Fatal	
C. Significa	ant and Su	ubstantia	: Ye	s 🗌	No 🔽				D. Number o	of Persons	Affected	: 001	
11. Negligenc	e (check c	one)	A. None]	B. Low C.	Moderate V		D. High	E E	E. Reckles	s Disrega	ard	
12. Type of A	ction 1	04(a)			13. Type of Issuar	nce (check one) Cit	ation 🖌	Order	Safegua	ard 🗌	Written Notice]
14. Initial Action A. Citation	on 📋 B.OI	rder	C. Safegu	ard 🗌 🕻	D. Written Notice	E. Citation Order N				F. I	Dated	Mo Da Yr	
16. Terminatic		A. Date	Mo Da 01/05/2		B. Time (24 Hr. Clock) 080	0						_
Section IIITerm	ination Acti	on											
17. Action to 1		Ma	Da Yr		• · · · ·								
18. Terminate	A. Date		Jarr	B. Time	(24 Hr. Clock								
Section IV-Auto	mated Syste	em Data											
19. Type of In: (activity co		E16	20. Event	Number	4440348	21. (Primary	or Mill	-				
22. Signature	Pat	rick Al	an Stanfi	eld					23. AR	Number	23	908	_
MSHA Form 700 established a Na			In accord and Agricultu	ance with the second seco	he provisions of the Smal ory Ombudsman and 10	ll Business Regu Regional Fairnes	atory Enf	orcement f	airness Act of 1 comments from	996, the Sm small busin	nall Busine esses abo	ess Administration has	3

established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order Continuation U.S. Department of Labor Mine Safety and Health Administration

tration

Section I-Subsec	uent Action/Continuation Data

1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Мо 12/06	Da 5/2011		3. Citation/ Order Number	8258609	
4. Served To				Operat			
Berman Cornett (Safety Director)			P	ERFO	RMANCE CO.	AL COMPANY, et al	
6. Mine			7.	Mine ID		((Contractor)
UPPER BIG BRANCH MINE-SOUTH					46-0843		
Section IIJustification for Action							

Continuation of 8. Condition or Practice

operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

		See Continuation Form
Section III-Subsequent Action Taken		
8. Extended To A. Date Mo Da	Yr B. Time (24 Hr. Clock)	C. Vacated D. Terminated E. Modified
Section IV-Inspection Data		
9. Type of Inspection E16	0. Event Number 4440348	
11. Signature	AR Number 12	. Date Mo Da Yr 13. Time (24 Hr. Clock)
Patrick Alan Stanfield	23908	12/06/2011 0800

MSHA Form 7000-3a, Mar 85 (revised)