



Section I--Violation Data

1. Date Mo Da Yr 12/06/2011	2. Time (24 Hr. Clock) 0905	3. Citation/ Order Number 8405552
4. Served To Berman Cornett-Safety Director		5. Operator PERFORMANCE COAL COMPANY, et al
6. Mine UPPER BIG BRANCH MINE-SOUTH		7. Mine ID 46-08436 (Contractor)
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

The Fletcher Roof Bolter S/N 2005-5325 is not being maintained in a safe operating condition. The machine was cited for not being maintained in permissible condition, not maintaining the ATRS, not maintaining the trailing cable, not maintaining the frame grounding and not maintaining the lighting system. There are not records of weekly electrical examination being conducted on the machine. The roof bolter was available to be placed in service, therefore the unit must be examined and maintained in a safe operating condition. This machine is located in the area affected by the explosion on 4/5/2010. The mine is on a 103(i) spot inspection for methane liberations and has a history of ignitions, poor roof conditions and explosions. Citations 8258550, 8258547, 8258555, 8258556, 8405542, 8258548 and 8258549 are issued in conjunction for conditions.

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input checked="" type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 75.512
--------------	--	----------------------	--

Section II--Inspector's Evaluation

10. Gravity:

A. Injury or Illness (has) (is): No Likelihood  Unlikely  Reasonably Likely  Highly Likely  Occurred

B. Injury or illness could reasonably be expected to be: No Lost Workdays  Lost Workdays Or Restricted Duty  Permanently Disabling  Fatal

C. Significant and Substantial: Yes  No  D. Number of Persons Affected: 010

11. Negligence (check one) A. None  B. Low  C. Moderate  D. High  E. Reckless Disregard

12. Type of Action 104(d)(2) 13. Type of Issuance (check one) Citation  Order  Safeguard  Written Notice

14. Initial Action A. Citation  B. Order  C. Safeguard  D. Written Notice  E. Citation/  
Order Number 8082692 F. Dated Mo Da Yr  
03/17/2009

15. Area or Equipment The roof bolter 2005-5325.

16. Termination Due	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
---------------------	------------------	------------------------

Section III--Termination Action

17. Action to Terminate

18. Terminated	A. Date Mo Da Yr	B. Time (24 Hr. Clock)
----------------	------------------	------------------------

Section IV--Automated System Data

19. Type of Inspection (activity code) E16	20. Event Number 4440348	21. Primary or Mill
22. Signature Randall Lewis		23. AR Number 24262

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input type="checkbox"/> <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 12/06/2011	3. Citation/ Order Number 8405552
4. Served To Berman Cornett-Safety Director	5. Operator PERFORMANCE COAL COMPANY, et al	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

Continuation of 8. Condition or Practice

The mine has a history of similar violations.

The operator has engaged in conduct constituting more than ordinary negligence. This is unwarrantable failure to comply with a mandatory standard.

This citation is being issued to the following entities as a unitary operator: Performance Coal Company, Massey Coal Services, A.T. Massey Coal Company, Inc., and Massey Energy Company.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E16	10. Event Number 4440348		
11. Signature Randall Lewis	AR Number 24262	12. Date Mo Da Yr 12/06/2011	13. Time (24 Hr. Clock) 0905