

STARTED  
4-1-10

# EXAMINATION OF BELT CONVEYORS

COMPANY Performance Coal

MINE UBB

LOCATION NAOMA Raleigh WV  
Post Office County State

1917

...

...

...

...

...

...

...

...

...

...

...

...

Use Intelligible Pencil or Ink

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-1-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Bickford, Mike Elswick Time 2:30 AM or PM

Report received by: Russell Gunnor  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Spot cleaned 10 to 3 bak, Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<sup>Tail need add. cleaning</sup> Needs Additional cleaning Drive to Discharge	RG	✓		
NORTH NO. 5	Needs Spot Cleaned 60-Flow thru, TAKEUP Needs Cleaned	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	ME	✓		
Longwall	Needs Dusted	ME	✓		
GLORY HOLE	D-Box + Pump OK	ME	✓		
TG2 NO. 1	Needs spot cleaned + Dusted	SAB	✓		
TG2 NO. 2	Needs Dusted, Tail needs Add. cleaning	SAB	✓		
HG22 #1	Needs add. cleaning + Dusted (working on dusting)	SAB	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, chargers OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: John Wilton 1539A John Sharp 32476  
Russell Gunnor 1536A Scott Halstead 37567  
John Bickford 26176 Michael Elswick 31521  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M... 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

**ON-SHIFT  
EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 4-1-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow	RG
Ellis 5	Shoveled v-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, Raw dusters at Tail + Drive, (Spot cleaned on Drive-Head)	RG
NORTH 5	cleaned on tail, cleaned V-Plow at Flowthru Raw Duster	SH
NORTH 6	cleaned V-Plow, cleaned at Tail SAB	SH
NORTH 7	cleaned on offside of Tailpiece	ME
LONGWALL	cleaned Spillage at Head, Set pump Behind Drive	SH
GLORY HOLE		
TG-22NO. 1		
TG-22NO. 2		
HG-22 #1		

Refuge chambers 8, 9, 6, 8 OK + phones working at time of exam

SIGNED BY: Russell Dunroe 1536-A  
 Belt Examiners and Certificate Numbers  
John Bufford  
 Belt Examiners and Certificate Numbers

Scott Halstead 37567  
Michael Slavich 31521

COUNTERSIGNED BY T. M. [Signature] 33389  
 Mine Foreman Certificate No. Superintendent Certificate No.





Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT: AM AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<sup>8115 4</sup> SOUTH NO. 1	None Observed	GU	—		
<sup>8115 5</sup> NORTH NO. 1	Needs spot cleaned & dusted	GU	—		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Drive to Discharge needs spot cleaned	GU	✓		
NORTH NO. 5	Needs spot cleaned 60-Feet run	GU	✓		
NORTH NO. 6	Needs spot cleaned & dusted	GU	—		
NORTH NO. 7	NEEDS DUSTED	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box OK.	JS	✓		
LBB NO. 1					
LBB NO. 2					
H6 #22 #1	NEEDS ADD DUSTING	JS	✓		
Long wall	NEEDS DUSTED	JS	✓		
T622 #1	NEED SPOT CLEAN & DUSTED	JS	✓		
T622 #2	NEED SPOT CLEAN & DUSTED	JS	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

0664 0610 20.8602  
PC'S CHARGES REPPS TRAVELERS OK

SIGNED BY: [Signature] 15397  
Belt Examiners and Certificate Numbers  
[Signature] 32476  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357  
Mine Foreman Certificate No. Superintendent Certificate No.

46543—BJW Printing & Office Supplies  
Russell Dunnoe 1536-A Michael Elwick 31521 Scott Halstead 37567

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT: owl 1600 AM OR PM TO 300 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1 <i>Ellis</i>	<i>change roll bc fix chain 100 ft etc</i>	
NORTH 1 <i>Ellis</i>	<i>change roll bc fix chain 110 ft etc</i>	
NORTH 2		
NORTH 3		
NORTH 4	<i>cleaned on Tail change roll etc fix chain drum 13.</i>	<i>GU</i>
NORTH 5	<i>cleaned Fan Turn</i>	<i>GU</i>
NORTH 6	<i>cleaned Fan Turn change roll tail export etc</i>	<i>CU</i>
NORTH 7	<i>clean on Head RUN DUSTER</i>	<i>JS</i>
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<i>T6 28* 1</i>	<i>cleaned on walkway R/S Roll</i>	<i>JS</i>

*Checked out by Refy = 6-8-89 OK*

SIGNED BY: *[Signature]* 1579A  
 Belt Examiners and Certificate Numbers  
*[Signature]* 32476  
 Belt Examiners and Certificate Numbers  
 COUNTERSIGNED BY *T. Name* 33359  
 Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT: DAY AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Elswick Time 2:20 AM or PM

Report received by: Russell Burnoe  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	None Observed	RG	✓		
Ellis 5	Needs spot cleaned + Dusted, Tail need add. cleaning	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
* NORTH NO. 4	Needs spot cleaned Drive-Discharge	RG SH	✓		
NORTH NO. 5	Needs Spot Cleaned 60-flow-thru	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	ME	✓		
Longwall	Belt needs Dusted	SH	✓		
GLORY HOLE	Pumpt D-Box OK	ME	✓		
TG-22 NO. 1	Needs Dusted	ME	✓		
TG-22 NO. 2	Tail needs add. cleaning, Needs Dusted	ME	✓		
HG-22 #1	Needs Add. Dusting	ME	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO at time of exam  
Travelways, Power Centers, D-Boxes, chargers OK at time of exam  
Visual Check of CO monitors OK at time of exam

\* chained down walkway side Btwn 12-13 BK,

SIGNED BY: Russell Burnoe 1536-A Scott Halstead 37567  
 Belt Examiners and Certificate Numbers  
Michael Elswick 3152/1 Dlen Ullman 1539A  
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY To Name 33309  
 Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow	RG
Ellis 5	Cleaned on Tail	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned on tail, cleaned V-Plow at flow thru	SH
NORTH 6		
NORTH 7		
Longwall	cleaned on Mud around Drive Area & Dusted	SH
GLORY HOLE		
TG-22 NO. 1		
TG-22 NO. 2		
HG-22 #1		

Refuge Chambers 6, 8, 89 BK all clear at EXAM time  
All Phones Working

SIGNED BY: Russell Gunnge 1536-A Scott Holstead 37567  
Belt Examiners and Certificate Numbers  
Michael E. Darrick 31521

COUNTERSIGNED BY T. Plow 35357  
Mine Foreman Certificate No. Superintendent Certificate No.

**PRE-SHIFT**

**EXAMINATION OF BELT CONVEYORS**

Use Indelible Pencil or Ink

DATE 4-2-10 SHIFT: EVE AM OR PM TO AM OR PM 830 AM OR TO 1100 AM OR PM  
**ON-SHIFT EXAM.** **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	none observed	GU	—		
Ellis 5	Tail Needs Add Cleaning <i>needs spot cleaned &amp; dusted</i>	GU	—		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned Drive - Discharge	GU	—		
NORTH NO. 5	Needs spot cleaned 60-Fw thru	GU	—		
NORTH NO. 6	Needs spot cleaned & dusted	GU	—		
NORTH NO. 7	Needs Dusted	WC	—		
Uwall 10	Belt needs Dusted	WC	—		
GLORY HOLE	Pump & D-Box OK	WC	—		
T62 NO. 1	} no power no pres hit				
T62 NO. 2					
H62 #1	Needs Add Dusting	WC	—		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OBCHY OB CO 20.8602

PCS, charger, D-Box, Pump, Trimmers OK

SIGNED BY: [Signature] 1539A

Belt Examiners and Certificate Numbers

Wallace Campbell 1354A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY [Signature] 33387

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT: EVE 6:00 AM OR PM TO 8:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	ACTION TAKEN	INT.
Ellis 5	Tail grabbed off, cleaned on Tail, change Blow Aug	6:01/96
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK Phones are working

SIGNED BY: [Signature] 1579A

Belt Examiners and Certificate Numbers

Willow Campbell 1354-A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore

33357

Mine Foreman

Certificate No.

Superintendent

Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT: Owl AM OR PM TO 2:00 AM OR PM TO 6:00 AM OR PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	Needs Dusted; Tail needs Add Cleaning	GU	✓		
Ellis #5	Needs spot cleaned & dusted, Tail needs Add cleaning	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned Hd - Drives	GU	✓		
NORTH NO. 5	needs spot cleaned 60' Pbw - tmw	GU	✓		
NORTH NO. 6	needs spot cleaned & dusted	GU	✓		
NORTH NO. 7	Needs Dusted	WC	✓		
Lt Wall	Needs Dusted	WC	✓		
GLORY HOLE	O-Box & Pump OK	WC	✓		
TR22 NO. 1	Belts Idle				
TR22 NO. 2	NO Power				
HC22 #1	Needs Add Dusting	WC	✓		

**\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OB 64, OB 60, 208 22  
PC's, Chargers, Pumps, Tractors OK

SIGNED BY: Don Allen 15399  
 Belt Examiners and Certificate Numbers  
William Campbell 1354A  
 Belt Examiners and Certificate Numbers

Johnny Neely 33472

COUNTERSIGNED BY: T. Blaine 33359 Mine Foreman Certificate No. \_\_\_\_\_ Superintendent Certificate No. \_\_\_\_\_

46543-BJW Printing & Office Supplies  
Russell Dunnoe 1536A Mike Elwood 31521 Scott Halstead 37567

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT: 0w1 100 AM OR PM TO 300 AM OR PM AM OR PM TO AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside: Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	cleaned on tail	GU
Ellis 5	cleaned on tail	GU
NORTH 2		
NORTH 3		
NORTH 4	change roll h.c.	
NORTH 5	cleaned Faw from	GU
NORTH 6	cleaned Faw from, Shoveled on V-plow	GU/BC
NORTH 7	change roll h.c.	
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

checked out by Refuges 6-8-89 OK phonescore working

SIGNED BY: [Signature] 1539A  
Belt Examiners and Certificate Numbers  
William Campbell 1354A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359  
Mine Foreman Certificate No. Superintendent Certificate No.

## PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT: DAY AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM PM  
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom John Neely, Mike Elswick Time 2:15 AM or PM PM

Report received by: Russell Gunnar  
 Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Tail needs add. cleaning, Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned, Tail needs add. cleaning	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned Drive-Discharge	RG SH	✓		
NORTH NO. 5	Needs Spot Cleaned 60-Flowthru	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	ME	✓		
Edgwall	Needs Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	ME	✓		
TG-22 NO. 1	Needs Dusted	JN	✓		
TG-22 NO. 2	Needs Dusted, Tail needs add. cleaning, <sup>water 1/2 bak</sup> outby Feeder	JN	✓		
HG-22 #1	Needs spot cleaned + Dusted	JN	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4, 20.8% O2, 0ppm CO at time of exam  
Travelways, Power Centres, D-Boxes, Chargers, KVAs OK at time of exam  
Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnar 15367A  
 Belt Examiners and Certificate Numbers  
Mike Elswick 31521  
 Belt Examiners and Certificate Numbers

Scott Holstead 37564  
John Neely 33472

COUNTERSIGNED BY  
 Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

ON-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 4-3-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM  
 ON-SHIFT EXAM. AM OR PM TO AM OR PM  
 PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
 Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow	RG
Ellis 5	Cleaned on Tail	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned tail Roller	SH
NORTH 6		
NORTH 7	cleaned on outside of belt at Flow Through	ME
Linnwall	cleaned on Drive area & Dusted, cleaned Discharge	SH
GLORY HOLE		ME
T6-22NO. 1	CLEAN TAIL + V Plow - Dust Area	JN
T6-22NO. 2	DUST HEAD AREA	JN
HG-22 #1		

Refuge chambers 6, 8, 89 clear at EXAM time  
 All Phones Working

SIGNED BY: Russell Gunnig 1536-A Scott Halstead 37527  
Belt Examiners and Certificate Numbers  
Mike Stewart 31521  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
 Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT: EVE AM OR PM TO AM OR PM 800 AM OR PM TO AM OR PM 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN	
<del>ELIS 4</del>		<u>GU</u>	<u>✓</u>			
<del>ELIS 5</del>		<u>GU</u>	<u>✓</u>			
NORTH NO. 2						
NORTH NO. 3						
NORTH NO. 4			<u>GU</u>	<u>✓</u>		
NORTH NO. 5			<u>GU</u>	<u>✓</u>		
NORTH NO. 6			<u>BC</u>	<u>✓</u>		
NORTH NO. 7		<u>Fire Bessed PCT Chargers</u>	<u>BC</u>	<u>✓</u>		
<del>L/WALL</del>		<u>all clear</u>	<u>BC</u>	<u>✓</u>		
GLORY HOLE			<u>BC</u>	<u>✓</u>		
<del>TG 22</del> NO. 1	<u>no Power</u>					
<del>TG 22</del> NO. 2	<u>no Power</u>					
<u>HG22#1</u>		<u>BC</u>	<u>✓</u>			

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG CH4 OG CO 20P202

PC'S, Chargers, D-Box, TRACK, TRAVELWAYS OK

SIGNED BY: Olson 1339A

Belt Examiners and Certificate Numbers

William Campbell 1354A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_

Mine Foreman

Certificate No.

Superintendent

Certificate No.



Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT: EVE AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Done Fire Run no Hot Rollers or Fires	GU			✓
Ellis 5		GU			✓
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4		GU			✓
NORTH NO. 5		GU			✓
NORTH NO. 6		WC			✓
NORTH NO. 7		WC			✓
Linell		KM			✓
GLORY HOLE					
TG22 NO. 1	Belt Idle				
TG22 NO. 2	Belt Idle				
HG22		BB			✓

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: \_\_\_\_\_

OG CH4, OG CO, 20.8302  
Travelways Clear

SIGNED BY: Brad Bony 1122-A Kevin W. Medley 38810  
Belt Examiners and Certificate Numbers  
William Campbell 1354-A  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.



Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4.4.10 SHIFT: EUC. AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS NO. 4	IDLE PCS, Pumps + D'Boxes OK	SAB	✓		
ELLIS NO. 5		SAB	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Pumps + PC + D'Boxes OK	SAB JN	-		
NORTH NO. 5	Pumps, PCs + D'Boxes OK	SAB JN	✓		
NORTH NO. 6	PCS OK	SAB JN	✓		
NORTH NO. 7	PC, charger	SAB JN	-		
Lg. Walk	IDLE	JS	✓		
GLORY HOLE	Pumps + D'Box OK	SAB JN	-		
TG 22 NO. 1	IDLE	JS	✓		
TG 22 NO. 2					
HG 22 #1	IDLE	JS JN	✓		

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 0% CO 20.8% AT TIME OF EXAM  
CHARGERS, POWER CENTER, D-BOXES OK AT OF EXAM

SIGNED BY: [Signature] 32476 Belt Examiners and Certificate Numbers  
[Signature] 26171 Belt Examiners and Certificate Numbers  
[Signature] 33472

COUNTERSIGNED BY \_\_\_\_\_  
Mine Foreman Certificate No. Superintendent Certificate No.

Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-4-10 SHIFT: EVE. AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed \_\_\_\_\_

BELTS	ACTION TAKEN	INT.
<u>ELLIS 4</u>		
<u>ELLIS 5</u>		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
<u>GLORY HOLE</u>		
LBB NO. 1		
LBB NO. 2		

REFUGE BOXES 6, 8, 89 OK AT TIME OF EXAM.

SIGNED BY: John Buford 26176 Johnny Neely 33472  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
Belt Examiners and Certificate Numbers

Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_



Use Indelible Pencil or Ink

# ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-5-10 SHIFT: Owl AM OR PM TO AM OR PM AM OR PM TO AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom \_\_\_\_\_ Time \_\_\_\_\_ AM or PM

Report received by: \_\_\_\_\_  
Signed

BELTS	ACTION TAKEN	INT.
4 ELLIS	DUSTED TAIL	JS
5 ELLIS	ROCK DUSTED HEAD	JS
NORTH 2		
NORTH 3		
NORTH 4	Helped cleaned on tail + V' Plow	JA, JW, JS
NORTH 5	Cleaned on tail + flow thru	JA
NORTH 6	Cleaned on flow thru + tail	JA
NORTH 7	Clean on TAIL	
GLORY HOLE		
TR NO. 1	clean on off side of TAIL	JN
TR NO. 2		

Checked Refuges 6, 8 + 89 Bahr, Phones OK

SIGNED BY: John A. Buehler 26176  
Belt Examiners and Certificate Numbers  
John D. [unclear] 32476  
Belt Examiners and Certificate Numbers

Johnny Neely 33472

COUNTERSIGNED BY \_\_\_\_\_ Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

Use Indelible Pencil or Ink

# PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 4-5-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM  
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes  No  By Whom Mike Elswick Time 2:30 AM or PM

Report received by: Scott Halstead 37567  
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis # 4	Needs Added Dusting	SH	✓		
Ellis # 5	Needs Dusted	SH	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 5	Needs Spot Cleaned 60-flow thru	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Belt needs Dusted	M.E.			
<del>Longwell</del>	Needs Spot Cleaned & Dusted	SH	✓		
GLORY HOLE	D-Box & Pump - OK	M.E.			
TC NO. 1	needs Dusted	M.E.			
TC NO. 2	tail needs Cleaned	M.E.			
HG 22	Belt needs Spot Cleaned & Dusted	M.E.			

\*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH<sub>4</sub>, 20.8% O<sub>2</sub>, 0ppm CO Detected at EXAM  
Power Centers, D-Boxes, Chargers, track & Travel ways Clean at EXAM  
Visual CK of CO Monitors - Clean

SIGNED BY: Scott Halstead 37567  
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY \_\_\_\_\_  
Belt Examiners and Certificate Numbers

Mine Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Superintendent \_\_\_\_\_ Certificate No. \_\_\_\_\_

