

State of West Virginia
Earl Ray Tomblin, Governor

WV Office of Miners' Health, Safety & Training
C. A. Phillips, Acting Director
1615 Washington Street East • Charleston, West Virginia • 25311-2126
Telephone 304-558-1425 • Fax 304-558-1282
www.wvminesafety.org

IN THE MATTER OF:

**THE INVESTIGATION OF THE
APRIL 5, 2010 MINE EXPLOSION
AT UPPER BIG BRANCH MINE.**

SUBPOENA

TO: Randy Gwinn


(b) (7)(C)

You are hereby **COMMANDED**, pursuant to W. Va. Code Section 22A-2-66(d), to appear and give testimony regarding the above referenced investigation on February 9, 2011 at 1:00 p.m. in classroom 121 at the Mine Academy located at 1301 Airport Road, Beaver, West Virginia 25813. The West Virginia Office of Miners' Health, Safety and Training, the Mine Safety and Health Administration, and the Governor's Independent Investigation Team will participate in the interview.

Given under my hand this 2nd day of February, 2011.

(b) (7)(C)

C.A. Phillips, Acting Director



STATE OF WEST VIRGINIA
Earl Ray Tomblin, Governor

WV Office of Miners' Health, Safety & Training
C.A. Phillips, Acting Director

AFFIDAVIT OF SERVICE

IN THE MATTER OF:

**THE INVESTIGATION OF THE
APRIL 5, 2010 MINE EXPLOSION
AT UPPER BIG BRANCH MINE.**

**STATE OF WEST VIRGINIA,
COUNTY OF KANAWHA, to-wit:**

I, Robert J. MacDonald, being first duly sworn, do testify and aver as follows:

1. That I am a credible person over the age of 21 years.
2. That on the 5th day of February, 2011. I personally served (b) (7)(C) who is over the age of sixteen and resides with Randy Gwinn, with a Subpoena at (b) (7)(C)
(b) (7)(C)


Further your affiant says not.

(b) (7)(C)


/ **Robert J. MacDonald**

Taken, subscribed and sworn to by **Robert J. MacDonald**, this the 7th day of February, 2011.

My commission expires: December 25, 2011



(b) (7)(C)



Performance
UBB Longwall
Saturday, 4/3/2010
A Crew, Electrician

Equipment	Job Description	Estimated Time	Comments/Initials
Face Conveyor	Check sandwich plates, install missing roll pins, record shield number at missing plate (On-Shift)	15 minutes	(b) (7)(C)
	Check face chain tension with pretensometer and record here and on production report, pretensioner reading: <u>9</u> Face <u>10</u> Gob. (On-Shift)	10 minutes	
	Check midface cable slack - verify that cable tied up good, secure as needed (On-Shift)	5 minutes	
Kamat Pumps	Check oil pressure gauge and record (On-Shift)	5 minutes	
	Check for leaks and repair as needed (On-Shift)	5 minutes	
	Check gearcase oil level, add 320 synthetic as needed (On-Shift)	5 minutes	
Longwall Starter	Visually inspect communications cables, plugs and receptacles (On-Shift)	5 minutes	
Emulsion Mix Car	Check oil level in Neet (raw) oil tank and record level in in percentage from panelview <u>45</u> %. (On-Shift)	5 minutes	
Power Center	Verify that high voltage gloves are present, stored in a bag and not older than 6 months from test date. (On-Shift)	5 minutes	
Shearer	Service grease points: Hinge Pins (4), Rack Wheels (4), Ranging Arm Jack Pins (4). (On-Shift)	30 minutes	
	Oil cowls. (On-Shift)	5 minutes	
	Check water sprays and wrap-around. (On-Shift)	10 minutes	
	Check controller case water light, if lit, report this to chief electrician (On-Shift)	5 minutes	
	Check condition of cable handler stand off, are bolts missing? Are clamps and bolts tight? Record findings (On-Shift)	5 minutes	