

U.S. Department of Labor  
Mine Safety and Health Administration  
Educational Field and Small Mine Services



Location \_\_\_\_\_ Date \_\_\_\_\_

Competent Person \_\_\_\_\_ Duration \_\_\_\_\_ Time \_\_\_\_\_

### PPE and Electrical Safety

#### 1) Protect your valuable assets!

- Look at your hands and fingers
- Look at your feet
- You are using your eyes [56.15004](#)

**USE YOUR PPE!!**

#### 2) Electrical Safety

- Use only grounded or double insulated electrical tools and equipment
- Use GFCI receptacles or pigtails in damp or wet locations at mines or when in confined spaces.
- Inspect your electrical tools, cords and equipment
  - a. Make sure the ground prong isn't broken off
  - b. Inspect cords for nicks, cracks and visible wiring or conductors
    - Never attempt to repair a cut or broken electrical cord
    - Never use electrical tool trigger locks [56.14116](#)
    - Always lock and tag out electrical boxes when making repairs [56.12016](#)

- Fatal grams: [56.12016](#)

- Attendees: