

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Rib		3. Date/Time of Accident 07/29/2010 11:55 AM		4. Date/Time of Death 07/29/2010 01:18 PM		5. Fatal Case No 42							
6. Mine Information :															
a) Mining Company Name Consolidation Coal Company			b) Mine Name Loveridge #22			c) Parent of Mining Company CONSOL Energy Inc									
7. Mine Location :		a) City Fairview		b) County Marion		c) State WV		8. Mine ID Number: 46-01433		9. Union: YES					
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND		11. Number of Mine Employees:		a) Total 640	b) Underground 583	c) Open Pit/Quarry 0		d) Mill/Prep Plant 57	e) Other 0						
12. Contractor Name:						13. Union		14. Contractor ID Number:							
15. Contractor Address:		a) City			b) County		c) State		d) Zip Code						
16. Number of Contractor Employees:		a) Total	b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other							
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 143		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0								
19. Location of Accident								20. Mining Height:							
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 03-Open Pit		<input checked="" type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> 99-Office Facility	Feet 8	Inches 0				
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1													
23. Victim Information :				a) Name Jesse Adkins		b) Age 39									
c) Regular Job Title: Miner Operator			d) Activity at Time of Accident: Integral Roof Bolter				<input checked="" type="checkbox"/> Mine Employee								
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days							
a) Total:	8	0	0	b) at the mine:	3	16	0	c) at activity (23d)	3	8	0	d) with Contractor	0	0	0
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.: (304) 986-6033									

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

On Thursday, July 29, 2010, at approximately 11:55 a.m., the left side integral roof bolter operator was fatally injured when he was struck with a rib measuring approximately 193 inches long by 55 inches high and up to 16 inches thick at the Loveridge No. 22 Mine, MSHA I.D. No. 46-01433. The accident occurred on the top portion of an overcast being driven on the No. 9 South Mains Section between the No. 4 and No. 6 entries near the future 18D section belt trench. The victim had installed one test roof bolt and was near the left rear bumper of the machine when the accident occurred. The rib sheared, pinning the victim against the machine. The victim was removed from between the continuous mining machine and the rock using jacks and cribs. First aid was administered although no vital signs were detected by EMTs. The victim was transported to the surface and then to Fairmont General Hospital by ambulance where he was pronounced dead upon arrival.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Voest Alpine			29. Model:			
30. District: C0300 Morgantown		32. Field Office: Bridgeport WV			33. Event Number: 6260527	
34. Accident Investigator: Mike Kelley Todd Anderson			35. MSHA Person Notified: Greg Fetty (DataTrac)		Date 07/29/2010 12:18 P	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared LS for Bob E. Cornett, DM <i>RTK</i>			Date 07/30/2010	
38. Reason For Amendment:						