

1 Section Equipment
Started 12-22-08

**EXAMINATION OF
ELECTRICAL EQUIPMENT**

#1
section

Company WBB
Mine _____
Location _____
Post Office County State

Re-order from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, W. Va. 25818
Phone (304) 253-_____

Date _____

Form 6—1492
(March 1970)

Budget Bureau No. 42-R1589
Approval expires 9-30-71

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. This book is approved by the Director of The West Virginia Department of Mines and The U. S. Bureau of Mines.

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-26-08	#1 section	Section Idle All week			D Shrewsbury 8-4018

12-29-08 #1 SCOOP 2 Fork LIFT CHARGER
 NO DANGEROUS CONDITIONS WERE FOUND AT TIME OF EXAMINATION
 FIRE SUPPRESSION OK ALSO.
 That made 4250

Weekly tests of grounding devices (diodes)

12-29-08	#1 CM 4918	OK at time of exam	fire suppression OK	CH4 monitor OK
	#2 CM 5871	replaced light bulb	fire suppression OK	CH4 monitor OK
	Bolter 2004328	OK at time of exam	fire suppression OK	
	Bolter 2005358	OK at time of exam	fire suppression OK	
	feeder 542147	repaired guard	fire suppression OK	
	SC 17503	OK at time of exam	fire suppression OK	
	SC 17504	made splice	fire suppression OK	
	SC 17505	OK at time of exam	fire suppression OK	
	#1 SCOOP T339-396	Changed plug (light)	fire suppression OK	
	#2 SCOOP T339-224	OK at time of exam	fire suppression OK	
	Service SCOOP	OK at time of exam	fire suppression OK	

Monthly examinations of methane monitors

fork lift	repaired oil leak	fire suppression OK
scoop chargers	OK at time of exam	fire suppression OK
fork lift chargers	OK at time of exam	fire suppression OK
Power center	OK at time of exam	fire ^{ext.} suppression OK
Pressure pump	OK at time of exam	fire ext. OK
Belt head & take up	OK at time of exam	fire suppression OK

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	
12-29-08	175035C	None observed		GB 3-481		1-2
12-30-08	#1 Bolter	Usually Insp free surp. Arca light out	1 Replaced	GB 3-481		C
1-2-09	396 scoop	Usually Insp fire surp. Spot light out	1 Replaced	GB 3-481		C
		Brake pressure gauge loose in deck	1 Repaired			
1-2-09	396 scoop charger	Usually Insp fire surp. None observed		GB 3-481		
1-3-09	#1 Pressure pump	usually Insp fire surp. None observed		GB 3-481		
Examinations of low-medium voltage power circuit breakers (monthly)						
1-2-9	#1 section	#2 scoop batteries need cleaned	cleaned	Crishmond		1-
		#2 Bolter dust filters need changed	changed	Crishmond		
		#3 SC need red button "ox fire supp.	Installed	Crishmond		
		power center none seen		Crishmond		
1-2-9	#1 section	#1 scoop & Fork Tr. charger	cleaned dirty to plug	Crishmond		
1-2-09	#1 SCOP & Fork Lift charger	No dangerous conditions were found at time of examination. Fire suppression OK #150.				
						Put Value 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-2-09	#1 Section				
	Cm 4918	repaired guard		checked fire suppression + CB Trip - OK	
	Cm 5811	repaired oil leak		checked fire suppression + CB Trip - OK	
	feeder 54-2147	washed - repaired grease	hose	checked fire suppression - OK	
	#2 sc 17504	washed		checked fire suppression - OK	
	Service scoop	none observed		checked fire suppression - OK	
	fork lift	none observed		checked fire suppression - OK	
	emergency ride	cleaned off			

Weekly tests of grounding devices (diodes)

Section Power Center	ground faulted breakers, checked e stop
#1 section head	repaired take-up + guard checked fire suppression - OK

D Shrewsbury 8-9018

1-5-09 17503 sc Dirty / Washed CB 3-481
 Visually Inspect fire sup.

1-6-09 #1 Bolter oil leak to bat wings causing bat wings to leak off!
 Replaced all hoses to bat wings corrected problem.
 Visually Inspect fire sup. CB 3-481

1-7-09 396 scoop Dirty / Washed CB 3-481

Monthly examinations of methane monitors

1-8-09 396 scoop charged Visually Inspect fire sup. None observed CB 3-481

1-9-09 #1 Pressure pump Visually Inspect fire sup. None observed CB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	Da
1-9-09	#1 Section					1-
	CM 4918	repaired light + oil leak		checked fire suppression + CB trip		
	CM 5811	repaired guard		checked fire suppression + CB trip		
	feeder 54-2147	washed		checked fire suppression		1-8
	#2 SC 17504	washed		checked fire suppression		
	Service Scoop	none observed at time of exam		checked fire suppression		1-1
	fork lift	" " " "		checked fire suppression		
	emergency ride	" " " "				
	Power Center	replaced mat + ground strap		ground resistance 26 ohms		
		ground faulted breakers + checked E stop		18 ohms		
	#1 section head	none observed at time of exam		checked fire suppression		1-1
				D Shrewsbury 8-4018		1-1

Examinations of low- medium-voltage power circuit breakers (monthly)

1-1

1-

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-8-09	#1 section	#2 SCOOP #2 Bolter #3 SC	none seen poor suction off side oil filter leaking	none Replaced blower Replaced filter	L. Richmond
1-8-09	#1 section	#1 Scoop & Fork Tr. charger power center	Receptacle #10 is broken	Tagged out	L. Richmond

1-10-09 #1 SCOOP & Fork Lift CHARGER. No dangerous conditions were found at time of examination. Fire suppression etc. also.

Weekly tests of grounding devices (diodes)

~~Not used~~
4-250

1-12-09	#1 Bolter	2 Area lights out & 1 spot light	1 Replaced	GB 3-481
1-13-09	17523	None observed		GB 3-481
1-13-09	396 scoop	1 spot light out	1 Replaced	GB 3-481
1-14-09	396 scoop charger	None observed		GB 3-481
1-15-09	#1 Pressure pump	None observed		GB 3-481

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-15-9	#1 section	#2 SCOOP	Bulb out	Replaced	CRichmond
		#2 Bolter	none seen	none	
		#3 SC	Very dirty	washed	
		#1 charger	none seen	none	
1-15-9	#1 section	power center	trash on top	cleaned off	CRichmond

1-20-09 #1 Bolter None observed
 Visually Insp fire surp CB 3-481

Weekly tests of grounding devices (diodes)

1-21-09 17503 SC checked cable Re-tape all placed in cable
 Visually Insp fire surp CB 3-481

1-21-09 396 scoop None observed
 Visually Insp fire surp CB 3-481

1-21-09 396 scoop charger None observed
 Visually Insp fire surp CB 3-481

1-23-09 #1 Pressure pump None observed
 Visually Insp fire surp CB 3-481

Monthly examinations of methane monitors

1-22-9 #1 section #2 SCOOP Batteries need cleaned. Cleaned. CRichmond
 #2 Bolter oil leak at gauges inside. Fixed
 #3 SC 2 cable splices need redone. Fixed
 #1 charger none seen
 1-22-9 #1 section power center none seen CRichmond

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-23-09	#1 Section				
cm 4918		replaced area light	checked fire suppression + CB trip		
cm 5811		repaired cable	checked fire suppression + CB Trip		
feeder 54-2147		washed	checked fire suppression		
#2 sc 17504		taped cable & washed	checked fire suppression		
Service scoop		cleaned trash off	checked fire suppression		
fork lift		repaired oil leak	checked fire suppression		
emergency side		changed	none observed at time of exam.		
Power center		ground faulted breakers + checked E stop			
#1 Section belt head		none observed at time of exam.	checked fire suppression		

Shrewsbury 8-4018

1-23-09 #1 SCOOP & Fork Lift changed.
 no dangerous conditions were found at time of examination
 Fire suppression ok also.

Examinations of low- medium-voltage power circuit breakers (monthly)

1-27-09	#1 Bolter	Area light out / Replaced bulb & lens	GB 3-481
		Visually Insp fire surp.	
1-27-09	17503 sc	None observed	GB 3-481
		Visually Insp fire surp	
1-28-09	396 scoop	Dirty / Washed	GB 3-481
		Visually Insp fire surp.	
1-28-09	396 scoop charger	None observed	GB 3-481
		Visually Insp fire surp	
1-30-09	#1 Pressure pump	None observed	GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-29-9	#1 section	#2 SCOP	arcing when trimmed.	Repaired tree.	L. Richmond
		#2 Bolter	Cable grounded.	Repaired.	L. Richmond
		#3 SC	none seen.	None.	L. Richmond
		Power center	none seen.	None.	L. Richmond
1-29-9	#1 section	#1 charger	none seen.	None.	L. Richmond
1-30-09	#1 SCOP & FORK LIFT CHARGER				
No dangerous conditions were found at time of examination.					
Fire suppression OK #150.					

Paul Miller 4-250

Weekly tests of grounding devices (diodes)

1-30-09	cm 4918	replaced sniffer,	calibrated chg monitor	checked fire suppression
	cm 5811	taped cable	calibrated chg monitor	checked fire suppression
	feeder 54-2147	replaced radiator		checked fire suppression
	#2 SC 17504	washed		checked fire suppression
	Service scoop	cleaned trash off		checked fire suppression
	fork lift	none observed		checked fire suppression
	emergency ride	none observed at time of exam		
	Power Center	ground faulted breakers	+ checked & stop	
	#1 section #1 head	repaired roller		checked fire suppression
	#1 section #2 head	repaired take up carriage	+ guard	checked fire suppression

Monthly examinations of methane monitors

#1 section #2 head transformer	ground faulted breakers + checked & stop
2 head take up	needs start switch "ordered"

L. Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-3-09	#1 Bolter	Made splice in cable	GB 3-481		
		Visually Insp fire surp			
2-4-09	17503 sc	None observed	GB 3-481		
		Visually Insp fire surp			
2-5-09	396 scoop charger	None observed	GB 3-481		
		Visually Insp fire surp			
2-5-09	396 scoop	Brakes would not lock up when			
		PANIC bar was pushed.			
		Replaced solenoid system, problem corrected	GB 3-481		
		visually Insp fire surp.			
2-6-09	#1 Pressure pump	None observed	GB 3-481		
2-6-09	#1 SCISSOR	FOR THE LIFT CHARGER			
		No dangerous conditions were found at time			
		of examination. FIRE SUPPRESSION OK #150.			
		Next Review 4-25-09			

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-6-09	#1 Section	calibrated	both cm chy monitors		
	cm 4918	repaired light	checked fire suppression + c.b trip		
	cm 5811	repaired light	checked fire suppression + c.b trip		
	feeder 54-2147	washed	checked fire suppression + c.b trip		
	#2 sc	made splice	checked fire suppression		
	Service scoop	cleaned trash off	checked fire suppression		
	fork lift	repaired hose	checked fire suppression		
	emergency ride	repaired light			

Weekly tests of grounding devices (diodes)

Power Center	replaced receptacle + 2 monitors	36 r
	ground faulted breakers + checked monitors	18 r
#1 head + takeup	none observed at time of slam	checked fire suppression
#2 head + takeup	none observed at time of slam	checked fire suppression
#2 head transformer	ground faulted breakers + checked monitor	

2-6-9	#1 section	#2 SCOP	char across bet's not secure.	secured.	Richmond
		#2 Baller	Bulb out on T-Bar	Replaced.	Richmond
		#3 SC	PSF Gauge Leaking oil in deck.	Replaced gauge.	Richmond
		Power center.	CRKT #10 needs receptacle.	Replaced.	Richmond

Monthly examinations of methane monitors

6-9	#1 section	#1 charger	none seen	none	Richmond
-----	------------	------------	-----------	------	----------

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	L
2-9-09	175235C	Had Inadequate splice in cable / Visually Insp fire surp	Replaced	GB 3-481	2-	
2-10-09	#1 boiler	Area light out / Replaced old splice Visually Insp fire surp	Replaced	GB 3-481	2	
2-11-09	394 scoop chdgr	None observed Visually Insp fire surp	None observed	GB 3-481		
2-11-09	394 scoop	TRam sticking / Dirty / Washed Visually Insp fire surp.	Replaced tram spring	GB 3-481		
2-12-09	# pressure pump	None observed		GB 3-481		

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-13-9	#1 section	#2 Scoop	Hard to steer.	Replaced hydraulic pump.	L Richmond
		#3 SC	Dirty.	washed.	L Richmond
		#2 Batter.	P.S.T. gauge leaking oil in deck.	Replaced gauge.	L Richmond
		#1 charger.	Right side not charging.	Replaced capacitor. OK.	L Richmond
2-13-9	#1 section	Power center.	circuit #12 needs monitor.	Replaced.	L Richmond

Weekly tests of grounding devices (diodes)

2-13-09	#1 section				
	cm 4918	washed - repaired light	checked fire suppression + c.b. trip		
	cm 5811	washed - repaired light	re-entw cable checked fire suppression + c.b. trip		
	feeder 54-2147	washed	checked fire suppression		
	#2 SC	washed - made splice	checked fire suppression		
	Service Scoop	OK at time of exam	checked fire suppression		
	fork lift	changed hose	checked fire suppression		
	emergency ride	changed cleaned trash off			
	Power Center	ground faulted breakers	checked E Stop		
	#1 head & takeup	OK at time of exam	checked fire suppression		
	#2 head & takeup	OK at time of exam	checked fire suppression		

Monthly examinations of methane monitors

#2 head transformer	ground faulted breakers	checked E Stop
---------------------	-------------------------	----------------

D Shrewsbury 8-4010

2-13-09 #1 Scoop & Fork Lift charger, no drip out
 conditions were found at time of examination.
 Fire suppression sensor had got broke off. Replaced OK now
 just with 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-20-09	#1 Section	Calibrated both Cm chy monitors			2
	Cm 4918	washed - repaired light	checked fire suppression + CB trip		
	Cm 5811	washed, repaired light	checked fire suppression + CB trip		
	feeder 54-2147	washed, repaired light	checked fire suppression + CB trip		
	55C	washed, taped cable	checked fire suppression		2
	Service scoop	cleaned trash off	checked fire suppression		
	fork lift	OK at time of exam	checked fire suppression		
	Emergency ride	cleaned trash off			
	Power Center	ground faulted breakers	checked E stop		
	#1 head + takeup	OK at time of exam	checked fire suppression		
	#2 head + takeup	OK at time of exam	checked fire suppression		
	#2 head powercenter	ground faulted breakers	checked E stop		

D Shrewsbury 8-4018

Examinations of low- medium-voltage power circuit breakers (monthly)

2-20-09	#1 RB	None observed	GB 3-481
		Usually Insp fire sup	
2-20-09	17503 5C	Dirty / Washed	GB 3-481
		Usually Insp fire sup	
2-20-09	396 scoop	Replaced Head light	GB 3-481
		Usually Insp fire sup	
2-20-09	396 scoop charger	None observed	GB 3-481
		Usually Insp fire sup	
2-20-09	#1 Pressure pump	None observed	GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-20-09	#1 section	#25C00P	None seen	none	LRichmond
		#35C	none seen	none	LRichmond
		#2 Butler	oil leak	Fixed	LRichmond
		#1 charger	None seen	none	LRichmond
2-20-09	#1 section	power center	none seen	none	LRichmond

Weekly tests of grounding devices (diodes)

2-25-09
 # 1 SCOOP & Fork Lift charger. No abnormalities
 conditions were found at time of examination
 Fire suppression OK #150.
 Pat Neala 4-250

2-24-09 17503 SC None observed CB 3-481
 Usually Insp fire sup
 2-24-09 #1 Boiler Bad place w cable / Cut out made splice CB 3-481
 Usually Insp fire sup

Monthly examinations of methane monitors

2-25-09 396 SCOP Replaced head light CB 3-481
 Usually Insp fire sup
 2-25-09 396 SCOP charger None observed CB 3-481
 Usually Insp fire sup
 2-26-09 #1 Pressure pump None observed CB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-27-9	#1 section	#2 SCOP	transficking	Fixed	Richmond
		#2 Boiler	Bad suction offside	Fixed	Richmond
		#3 SC	dirty	washed	Richmond
		power center	none seen	None	Richmond
2-27-9	#1 section	#1 charger	door ajar	secured	Richmond

2-27-09	#1 Section				
cm 4918	taped cable	checked fire suppression	C B trip + battery backup		
	replaced battery backup				
cm 5811	repaired light	checked fire suppression	C B trip + battery backup		
feeder 54-2147	washed	checked fire suppression + C B trip			
#2 SC 17504	washed	taped cable	checked fire suppression		
Service scoop	none observed	at time of exam	checked fire suppression		
fork lift	replaced seat	replaced hose	checked fire suppression		
emergency ride	replaced tire	cleaned trash off			

Examinations of low- medium-voltage power circuit breakers (monthly)

Power center	replaced sc circuit panel	ground faulted breakers	36 #
		checked E stop	18 #
#1 head + takeup	none observed	at time of exam	checked fire suppression
#2 head + takeup	none observed	at time of exam	checked fire suppression
#3 head power center	ground faulted breakers	checked E stop	

2/2/09 @ LT/RB level Wind not working properly S Shrewsbury 8-40-8

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	#1 Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3/2/09	#1 2T/RB ON Reel	Level wind not working properly.	Knocking up cable	Replaced level wind	GB 3-481
		leak in suction	Replaced 1 suction nipple & 2 dust hoses		GB 3-481
3-13/09	17003 SC	Usually Insp fire surp.	None observed		GB 3-481
3-14/09	396 scoop	Spot light out / Dirty	Replaced / washed		GB 3-481

Weekly tests of grounding devices (diodes)

3-4-09	396 scoop charger	Usually Insp fire surp	None observed		GB 3-481
3-6-09	#1 Pressure pump	Repaired Intruder gland			GB 3-481
3-6-9	#1 section	#2 scoop	Batteries need water.	watered	L Richmond
		#3 SC	Broken light lens.	Replaced	L Richmond
		#2 Bolts	None seen	None	L Richmond
		power center	Two area light bulbs out.	Replaced	L Richmond
3-6-9	#1 section	#1 charger	None seen	None	L Richmond

Monthly examinations of methane monitors

3-6-09 #1 SCOOP & Tank LIFT CHARGER.
 No Dangerous Conditions were Found at Time of Examination.
 Fire Suppressor OK HSO.

Sent via 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-10-09	#1 Section	#1 Roof Belter	Worn Splice	Re Insulated Splice	ID-3-631
3-10-09	#1 Section	#1 Scoop Charger	Bad Light Bulb	Replace Light Bulb	ID-3-631
3-4-09	#7 Section	calibrated both cm chy monitors			
	cm 4918	replaced light, repaired guard	checked fire suppression		
		checked cB trip + battery backup			
	cm 5811	replaced light	checked fire suppression	cB trip + battery backup	
	feeder	washed	checked fire suppression + cB trip		
	#2 SC 17504	washed	checked fire suppression		
	Service scoop	cleaned trash off	checked fire suppression		
	fork lift	none observed at time of exam	checked fire suppression		
	emergency side	cleaned			
	Power Center	replaced ground strap	ground faulted breakers	checked E stop	
	#1 head + takeup	none observed	at time of exam		
	#2 head + takeup	none observed	at time of exam		

Examinations of low- medium-voltage power circuit breakers (monthly)

#2 head Power Center ground faulted breakers + checked E stop
 B Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3/13-09	#1 section				
3/13-09	cm 4918	replaced light & globe	re-entered cable	checked fire suppression	
		checked cB trip + battery backup			
	cm 5811	none observed at time of exam		checked fire suppression	
		checked cB trip + battery backup			
	feeder	none observed at time of exam		checked fire suppression + cB trip	
	#2 sc 17504	none observed at time of exam		checked fire suppression	
	Service scoop	none observed at time of exam		checked fire suppression	

Weekly tests of grounding devices (diodes)

fork lift	none observed at time of exam	checked fire suppression
emergency ride	cleaned off	
Power Center	cleaned off	ground faulted breakers
#1 head + takeup	none observed at time of exam	checked E stop
#2 head + takeup	none observed at time of exam	
#2 head Power Center	ground faulted breakers	+ checked E stop

Shrewsbury 8-4018

3-9-09 #1 Bolter spot light out | Replaced socket & light GB 3-481
 Visually Insp. fire surp.

Monthly examinations of methane monitors

3-10-09 17503 sc NONE observed GB 3-481
 Visually Insp. fire surp.

3-11-09 396 scoop spot light out | Replaced GB 3-481
 Dirty | washed
 Visually Insp. fire surp.

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-11-09	396	scoop charger	None observed		GB 3-481
3-12-09	#1	Pressure pump	Usually Inspr fire surp. None observed		GB 3-481
3-12-09	#1	Bolter	Cable knotted up with mixer cable Cut Bolter cable got knots out and made splice		GB 3-481
3-13-9	#1 section	#2 scoop	none seen	—	LR Shmud
		#2 Bolter	none seen	—	LR Shmud
		#3 SC	none seen	—	LR Shmud
		powercenter	none seen	—	LR Shmud
3-13-9	#1 section	#1 charger	none seen	—	LR Shmud
3-16-09	#1	bolter	Area light out Suction bw on off side	Replaced Repaired	GB 3-481
Examinations of low- medium-voltage power circuit breakers (monthly)					
3-17-09	17503	SC	Usually Inspr fire surp. None observed		GB 3-481
3-18-09	396	scoop	Dirty Usually Inspr fire surp	Washed	GB 3-481
3-19-09	396	scoop charger	None observed Usually Inspr fire surp		GB 3-481
3-20-09	#1	Pressure pump	Display going out. Ordered new display		GB 3-481

7642

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-20-09	#1 section	calibrated both cm chy monitors			
	4918 cm	repaired light + panel opening, checked fire suppression			
		C.B trip + battery backup			
	5811	repaired light	checked fire suppression	C.B trip + battery backup	
	feeder	taped cable	checked fire suppression + C.B trip		
	#2 sc 17504	washed	checked fire suppression		
	service scoop	cleaned trash off	checked fire suppression		
	fork lift	repaired oil leak	checked fire suppression		

Weekly tests of grounding devices (diodes)

emergency side	none observed at time of exam		
Power Center	repaired ground strap	ground faulted breakers	
#1 head + ts	+ checked E stop		
#1 head + takeup	none observed at time of exam	checked fire suppression	
#2 head + takeup	none observed at time of exam	checked fire suppression	
#2 head Power Center	ground faulted breakers	+ checked E stop	

Shrewsbury 8-4018

Monthly examinations of methane monitors

3-20-9	#1 section	2 scoop	oil leak in deck	Fixed	CRizhml
		2 Bolter	3 bulbs out	Replaced	
		3 SC	cable cut to leads	Repaired	
		1 charger	none seen		
		power center	trashed up	cleared top	CRizhml

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	Date
3-27-09	#1 Section	4918 cm repaired light		checked fire suppression, CB trip + battery backup		3
		5811 cm re-entered cable		checked fire suppression, CB trip + battery backup		
		feeder washed		checked fire suppression + CB trip		3
		#2 SC 17504 washed, taped cable		checked fire suppression		
		service scoop none observed at time of exam		checked fire suppression		
		fork lift repaired hyd leak		checked fire suppression		
		emergency ride changed tire				
		Power Center repaired ground strap		checked E stop + ground faulted breakers		
		#1 head + Takeup none observed at time of exam		checked fire suppression		
		#2 head + Takeup repaired guard		checked fire suppression		
		#2 head Power Center none observed at time of exam				3-

Examinations of low- medium-voltage power circuit breakers (monthly)

checked E stop + ground faulted breakers 3-

J Shrewsbury 8-4018

3-23-09	#1 Boiler	boiler start switch would not work from off side drill deck		Start switch coupling in wide came loose Repaired coupling	CB 3-481	
3-24-09	17503 SC	visually Insp fire surp. None observed		visually Insp fire surp.	CB 3-481	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-26-09	396 scoop	Dirty	Washed	oper. observed Batterys smoking checked batteries. found 3 cells that needed replaced Danged off batteries. scouted for repairs to be made #3 set of batteries. Repairs made same day on evening shift	GB 3-481
3-26-09	396 scoop charger	None observed	Usually Insp fire surp	GB 3-481	
Weekly tests of grounding devices (diodes)					
3-27-09	#1 Pressure pump	None observed			GB 3-481
3-27-9	#1 section	#2 scoop	Battery plug defective. Replaced	Richmond	
		#3 SC	Very dirty	washed.	Rich
		#2 Bolter	Bad splize	Made splize.	Richmond
		power center	Need ground straps(?)	Replaced two.	Richmond
3-27-9	#1 section	#1 charger	oil cans on charger.	Removed.	Richmond
3-30-09	#1 bolter	Dirty	Washed	Area light out	GB 3-481
				Usually Insp fire surp.	
Monthly examinations of methane monitors					
4-1-09	17503SC	None observed			GB 3-481
			Usually Insp fire surp.		
4-2-09	396 scoop	UV bad on broken	Replaced broken	both spot lights out on near	GB 3-481
				Replaced light sockets	
			Usually Insp fire surp		
4-2-09	396 scoop charger	None observed			GB 3-481
			Usually Insp fire surp		

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-3-09	#1 Pressure pump		None observed		CP 3-487
4-3-09	#1 Section	Calibrated chy monitors on both cm's			
	4918 cm	repaired 2 lights & battery backup		checked fire suppression & c.B trip washed	
	5811 cm	repaired light & guard c.B trip & battery backup		checked fire suppression washed	
	feeder	repaired oil leak		checked fire suppression & c.B trip	
#25C	17504	washed		checked fire suppression	
	Service Scoop	washed		checked fire suppression	
	fork lift	none observed at time of exam		checked fire suppression	
	Emergency ride	none observed at time of exam			
	Power Center	repaired ground strap & ground faulted breakers		checked E stop	

Examinations of low- medium-voltage power circuit breakers (monthly)

#1	head & takeup	none observed at time of exam		checked fire supp	
#2	head & takeup	none observed at time of exam		checked fire supp	
#2	head Power Center	none observed at time of exam		checked E stop & ground faulted breakers	

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-3-9	#1 section	#2 SCOP	Bad batteries	Replaced	Richmond
		#2 Bolter	3 bulbs out	Replaced	Richmond
		#3 SC	Bad place in cable	Repaired	Richmond
		#1 charger	GROUND CLAMP NOT CONNECTED	Connected	Richmond
4-3-9	#1 section	power center	2 Bolts missing from top shield	Replaced	Richmond

Weekly tests of grounding devices (diodes)

4-9-09	4918 cm	repaired light + re-entered cable	checked fire suppression + battery backup	CB trip
	5811 cm	repaired light	checked fire suppression + CB trip + battery backup	
	feeder	none observed at time of exam	checked fire suppression + CB trip	
	#2 SC 17504	washed	checked fire suppression	
	service scops	washed	checked fire suppression	
	fork lift	none observed at time of exam		
	Power Center	cleaned	checked E stop + ground faulted breakers	
	#1 head + Takeup	repaired guard	checked fire suppression	
	#2 head + Takeup	none observed at time of exam	checked fire suppression	

Monthly examinations of methane monitors

#2 head	Power Center	none observed at time of exam	checked E stop + ground faulted breakers
---------	--------------	-------------------------------	--

Shrewsbury 8-5018

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-6-09	175035C	None observed			GB 3-481
4-7-09	#1 Bolter	Usually Insp fire surp. Bad oil leak at operators deck / lost control power / loose fuse in panel		Replaced hose Repaired	GB 3-481
4-8-09	396 scoop	Usually Insp fire surp. Dirty washed			GB 3-481
4-8-09	396 scoop charger	usually Insp fire surp. at charging station Had blown control power fuse	Had no control power on Breakers		GB 3-481
4-9-09	#1 Pressure pump	Usually Insp fire surp. None observed			GB 3-481

Examinations of low-medium-voltage power circuit breakers (monthly)

4-9-9	#1 section	#2 SCOP (2245 SCOP)	bad tape switch	Replaced	L. Richman
		#2 Bolter (328 bolter)	T.R.S hose leaking	Replaced	
		#3 SC (17505)	nuisance tripping of breaker	Made splice	
		#1 charger	none seen	none	
4-9-9	#1 section	power center	none seen	none	L. Richman

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-13-09	175035e	Re-taped All Repairs in cable			GB 3-481
		Usually Fwsp fire supp.			
4-14-09	#1 Bolter	Damaged packing Gland to lights. Replaced			GB 3-481
		Re-taped all repair places in cable			GB 3-481
		Tape 2 nicks in cable Jacket			
		Usually Fwsp fire supp.			

Weekly tests of grounding devices (diodes)

4-15-09	396 scoop	Damaged battery plug on scoop batteries	Replaced		GB 3-481
		Usually Fwsp fire supp			
4-15-09	396 scoop charger	Charger pushed back against stopping	Could not get to controls to stop charger in case of problem		
		pull away from stopping			GB 3-481
		Usually Fwsp fire supp			

4-17-09

#1 Pressure pump	Pump Knocking Circuit breaker	#2 motor to pump grounded	Disabled #2 pump wiring on #1 order		
		Pump to replace bad on			GB 3-481

Monthly examinations of methane monitors

17-9	#1 section	#2 scoop	Circuit breaker going bad.	Replaced.	LRichmond
		#2 Bolter	lampy post lamp missing.	Replaced.	LRichmond
		#3 SC	Red button missing on off side fire supp.	Reported.	LRichmond *
		#1 charger	none seen	none	LRichmond
		power centers	none seen	none	LRichmond
19-9	#1 section	#35C 17505	Replaced red button for fire supp.		LRichmond *

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-17-09	#1 section	Calibrated ch4 monitors on both C.m's			
4918 cm		repaired light + battery backup	checked fire suppression, C.B trips		
5811 cm		repaired light + battery backup	checked fire suppression, C.B trips		
feeder		Taped cable + washed	checked fire suppression + C.B trips		
#2 sc 17504		washed + taped cable	checked fire suppression + C.B trips		
service scoop		cleaned	checked fire suppression		
fork lift		repaired oil leak	checked fire suppression		
emergency ride		none observed at time of exam			
Power Center		repaired ground strap	checked E stop + ground faulted		
#1 head + takeup		repaired guard	checked fire suppression		
#2 head + takeup		cleaned stringon sprays +	checked fire suppression		
#2 head power center		none observed at time of exam	checked E stop + ground faulted		

Examinations of low- medium-voltage power circuit breakers (monthly)

+ ground faulted breakers

M Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-23-09	#1 section				
	4918 cm	repaired light, washed + CB Trip	checked fire suppression, battery backup		
	5811 cm	repaired light, washed + CB Trip	checked fire suppression, battery backup		
	feeder	washed, repaired oil leak	checked fire suppression + CB Trip		
	#2 sc 17504	washed, repaired oil leak	checked fire suppression		
	service scoop	none observed at time of exam	checked fire suppression		

Weekly tests of grounding devices (diodes)

fork lift	repaired oil leak	changed fire ext.	checked fire suppression
emergency side	none observed at time of exam		
Power Center	repaired ground strap	checked E stop + ground faulted	
#1 head + takeup	raised starter box + mats	checked fire suppression	
#2 head + takeup	none observed at time of exam	checked fire suppression	
#2 head power center	none observed at time of exam	checked E stop + ground faulted	
splitter 51 break	none observed at time of exam		
#3 head Power Center	none observed at time of exam		

4-21-09 #1 RTAB Cable had several splices | Replaced trailing cable GB 3-481
 Suction low oper. side | Replaced dust Hose GB 3-481

Monthly examinations of methane monitors

visually Insp fire surp. GB 3-481
 4-22-09 17503 sc No observed has no been ran this week GB 3-481
 visually Insp fire surp

4-23-09 396 scoop Dirty / washed CB 3-481
 spot light out | Replaced
 visually Insp fire surp

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-23-09	396	scoop charger	None observed		GB 3-481
		visually	Insup	fire surp	
4-24-09	#1	Pressure pump	pump faulting out on High Voltage		
		Contracted App. Power	had problem with supply power		
		problem taking care of			GB 3-481
4-27-09	IT/RB		None observed		GB 3-481
		visually	Insup	fire surp.	
5-1-09	#1 section				
4918 cm		repaired guard + light	checked fire suppression		
		battery backup + C.B. Trip			
5811 cm		re-entered repaired light	checked fire suppression		
		battery backup + C.B. Trip			
feeder		re-entered pull cord switch + washed			

Examinations of low- medium-voltage power circuit breakers (monthly)

		checked fire suppression + C.B. Trip			
#2 sc 17504		repaired cable + washed	checked fire suppression		
service scoop		none observed at time of exam	checked fire suppression		
fork lift		repaired oil leak	checked fire suppression		
emergency ride		replaced jack			
Power Center		cleaned off	ground faulted breakers + checked E Stop		

D. Shrewsbury 8-408

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-24-9	#1 section	2 scoop (224)	No Lights	Replaced fuses	L Richmond
		2 BATTERY (398)	Light socket bad at left boom	Replaced	L Richmond
		3 SC (10595)	none seen	none	Chish
		POWER CENTER	2 bolts missing on top lids	Replaced	Chish
4-24-9	#1 section	#1 charger	none seen	none	Chishmore

Weekly tests of grounding devices (diodes)

5-1-09	#1 section	#1 head + takeup	none observed at time of exam	checked fire suppression
		#2 head + takeup	repaired guards	checked fire suppression
		#2 head Power Center	none observed at time of exam	ground faulted breakers + checked E stop
		splitter 51 wt	none observed at time of exam	checked E stop
		#3 head + takeup	new setup	checked fire suppression
		#3 head Power Center	none observed at time of exam	checked E stop + ground faulted breakers

D Shrewsbury 8-4018

Monthly examinations of methane monitors

4-28-09	17503 SC	None observed / did not run this week	GA 3-481
		Visual Insp fire surp.	
4-29-09	396 scoop	Dirty xl washed	GB 3-481
		visually Insp fire surp.	
4-29-09	396 scoop charger	None observed	GB 3-481
		visually Insp fire surp.	

EXAMINATION OF ELECTRICAL EQUIPMENT


Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-1-9	#1 section	#2 scoop	circuit breaker won't reset.	Adjusted. ok.	L Richmond
		#3 SC	very dirty	washed. ok.	L Richmond
		#2 Bolter	Area light socket between booms is bad.	Replaced.	L Richmond
		#1 charger	Ground clamp pulled loose.	Fixed.	L Richmond
5-1-9	#1 section	power center	none seen	None.	L Richmond

Weekly tests of grounding devices (diodes)

5-5-09	#1 RB	AREA LIGHT OUT ON BACK OF MACHINE		ORDERED PARTS (NEED BULBS)	
5-5-09		INSPECTED	FIRE SUPPRESSION	VISUALLY	
5-5-09	396 SCOOP CHARGER		NONE OBSERVED	NONE	Dewitt 3-558
		INSPECTED	FIRE SUPPRESSION	VISUALLY	

5-5-9	#2 RB	Area light out		replaced bulb	
5-5-9	#1 Charger	no observed		none	


 Tracey Lambert 3-261

~~Monthly examinations of methane monitors~~

5-8-9	#1 section	#2 scoop	none seen		L Richmond
		#2 Bolter	2 bulbs out on off side	Replaced.	L Richmond
		#3 SC	Bad split on cable.	Spliced.	L Richmond
		#1 charger	none seen		L Richmond
8-9	#1 section	power center	none seen		L Richmond

EXAMINATION OF ELECTRICAL EQUIPMENT


Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-8-09	#1 Section				
4918 cm	repaired 2 lights	checked fire suppression, battery lockups + CB trip			
5811 cm	repaired light	checked fire suppression, battery lockup + CB trip			
feeder	repaired light	checked fire suppression + CB trip			
#2 SC 17504	washed	checked fire suppression			
Service Scoop	none observed at time of exam	checked fire suppression			
fork lift	none observed at time of exam	checked fire suppression			
emergency ride	charged				
Power Center	cleaned off	ground faulted breakers + checked E stop			
#1 head + takeup	none observed at time of exam	checked fire suppression			
#2 head + takeup	repaired guard	+ checked fire suppression			
#2 head PC	none observed at time of exam	ground faulted breakers + checked E stop			
splitter 51 hr.	none observed at time of exam				
#3 head + takeup	none observed at time of exam	+ checked fire suppression			

Examinations of low- medium-voltage power circuit breakers (monthly)

#3 head PC none observed at time of exam ground faulted breakers + checked E stop

D Shrewsbury 8-4018

5-12-09	#2 RB	2004-328 DDR	ratty splice	reinsulated splice	
5-12-09	#1 charger		no observed	none	
5-12-09	#1 Scoop	T339-224	light out	replaced bulb	
5-15-09	#1 Head		checked fire suppression	4-138 Tracy Lambert 3-261	
5-15-09	#1 Head		changed 3 light bulbs	B Farley 4-139	
5-15-09	#1 Take up		cleaned up	changed leaking hyd hose	
5-15-09	#1 Take up		bolt missing on door	Put New Bolt B Farley 4-138	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-15-9	#1 section	#2 SCOOP	none seen	None	L Richmond
		#2 Bolter	poor suction offside	Replaced suction hose	L Richmond
		#3 SSC	cut place in cable	Repaired	L Richmond
		#1 charger	none seen	None	L Richmond
5-15-9	#1 section	power center	Feeder cat head in different receptacle.	Put 10 tags on new receptacle.	L Richmond
5-15-9	#1 section	power center	Jm. 5811 needs 10 tag on cat head.	Installed.	L Richmond
Weekly tests of grounding devices (diodes)					
5-21-09	#1 Head	checked fire suppression	4-138	Brian Farley	
5-21-09	#1 Head	changed Busted light Bulb	4-138	Brian Farley	
5-21-09	#1 Head	Take up	NONE observed	Brian Farley	4-138
5-29-09	#1 ^{Belt} Head	checked fire suppression	OK	4-138	Brian Farley
5-29-09	# Take up	cleaned of oil and debris	4-138	Brian Farley	
5-29-09	# Belt head	cleaned Power center	OFF	4-138	Brian Farley
5-29-09	#1 Belt Head	Put missing Rubber mat	Back at Take up.	Brian Farley	4-138

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-15-09	#1 section	calibrated both cm chy monitors			
4918 cm		changed 3 bulbs repaired oil leak + washed			
		checked fire suppression battery backup + c B trip			
5811 cm		repaired light repaired cable			
		checked fire suppression battery backup + c B trip			
feeder		repaired water valve checked fire suppression + c B trip			
#2 sc 17504		taped cable + washed		checked fire suppression	
service scoop		cleaned		checked fire suppression	
fork lift		none observed at time of exam		checked fire suppression	
emergency side		cleaned trash off			
Power Center		cleaned replaced ground strap			
		ground faulted breakers + checked E stop			
#2 head + takeup		added landmine + checked fire suppression			
#2 head Power Center		ground faulted breakers + checked E stop			
splitter 51 bk		none observed at time of exam		checked E stop	

Examinations of low- medium-voltage power circuit breakers (monthly)

#3 head + takeup		none observed at time of exam		checked fire suppression	
#3 head Power Center		none observed at time of exam			
		ground faulted breakers + checked E stop			

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-22-9	#1 section	2 scoop	batteries need watered	watered batts.	Richmond
		2 Boiler	cable damaged	Repaired cable.	Richmond
		3 SC	side boards striking roof bolt heads.	Removed side boards.	Richmond
		Power center	none seen.	none seen.	Richmond
5-22-9	#1 section	#1 charger	actuator not extended out.	Extended out remove actuator for fire supp.	Richmond

Weekly tests of grounding devices (diodes)

5-22-09	#1 Section	4918 cm	out of Service	repaired light + washed	
			checked fire suppression	battery backup + CB trip	
		5811 cm	repaired 2 lights	made splice + washed	
			checked fire suppression	battery backup + CB trip	
		feeder	washed	checked fire suppression + CB trip	
		#2 SC 17504	washed	checked fire suppression	
		service scoop	cleaned trash off	checked fire suppression	
		fork lift	repaired oil leak	checked fire suppression	
		emergency ride	replaced jack		
		Power Center	replaced 2 Panels + 2 receptacle covers	ground faulted breakers + checked E stop, checked Monitors all OK at time of exam	
				Monthly examinations of methane monitors	
		#2 head + takeup	replaced sawkey	+ checked fire suppression	
		#2 head Power Center	ground faulted breakers	+ checked E stop + monitors	
		Splitter 51 break	none observed at time of exam	checked E stop	
		#3 head + takeup	repaired guard	+ checked fire suppression	
		#3 head Power Center	replaced 100A breaker	, checked E stop + monitors	
		60044 cm 6044	checked fire suppression	CB trip + battery backup	Shrewsbury 8-9-08
			+ washed		

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-29-09	#1 Section				
CM 4918		changed 2 lights + CB trip		checked fire suppression battery backup	
CM 5811		made splice + changed light battery backup + CB trip		checked fire suppression	
feeder		replaced megcon switch		checked fire suppression + CB trip	
#2 SC 17504		made splice		checked fire suppression	
service scoop		watered batteries		cleaned trash off	checked fire suppression
fork lift		none observed at time of exam			checked fire suppression
emergency ride		replaced light + cleaned off			
Power Center		checked monitors + ground faulted + E stop			all OK at time of exam
#2 head + takeup		none observed at time of exam			checked fire suppression at time of exam
#2 Power Center		checked monitors + ground faulted + E stop			all OK at time of exam
splitter 51 BK		checked inst. test + ground test + E stop			all OK at time of exam

Examinations of low- medium-voltage power circuit breakers (monthly)

#3 head + takeup		none observed at time of exam			checked fire suppression
#3 Power Center		checked monitors, ground faulted + E stop			
CM 6044		all OK at time of exam			
CM 6044		checked fire suppression CB trip + battery backup + washed			

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-29-9	#1 section	#2 scoop	slow steering	changed filters	L Richmond
		#3 SC	cable needs splice repaired	Fixed cable	L Richmond
		#2 Bolter	3 bulbs need replaced	Replaced bulbs	L Richmond
		#1 charger	door needs one bolt	Put bolt in door	L Richmond
5-29-9	#1 section	power center	#4 circuit panel has opening/hole	closed opening	L Richmond

Weekly tests of grounding devices (diodes)

6-4-09 #1 Section

cm 4918 out of service

cm 5811 calibrated ch4 monitor changed 2 lights taped cable

checked battery backup, fire suppression + CB Trip

feeder changed light checked fire suppression + CB Trip

#2 SC 17504 made splice washed checked fire suppression

service scoop watered batteries cleaned trash off checked fire suppression

fork lift none observed at time of exam checked fire suppression

emergency side out of service

Power Center checked monitors, ground faulted + checked E Stop

#2 head + takeup none observed at time of exam + checked fire suppression

Monthly examinations of methane monitors

#2 head Power Center checked monitors, ground faulted + checked E Stop

splitter 51BK checked test buttons + E Stop

#3 head + takeup repaired guard checked fire suppression

#3 head Power Center checked monitors, ground faulted + E Stop

6044cm calibrated ch4 monitor checked fire suppression CB Trip + battery backup

Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	Da
6-11-09		4918cm out of service				
		5811cm calibrated chy monitor		replaced light		
				checked fire suppression		
				c.B trip + battery backup + washed		
		feeder - taped cable + washed		checked fire suppression + c.B trip		
		#2 2sc 17504		made 2 splices + washed		
				checked fire suppression		
		service scoop		watered batteries		
				cleaned trash off		
				checked fire suppression		
		fork lift		repaired oil leak		
		checked fire suppression				
		emergency ride		repaired light		
		Power Center		replaced 3 ground straps		
				checked monitors + ground faulted		
				+ checked E stop		
		#2 head + takeup		none observed at time of exam		
				checked fire suppression		
		#2 Power Center		checked monitors + ground faulted		
				+ checked E stop		6
		splitter 51 v.k		checked test buttons + E stop		6
		#3 head + takeup		none observed at time of exam		6
				checked fire suppression		6-1
Examinations of low- medium-voltage power circuit breakers (monthly)						
		#3 Power Center		checked monitors + E stop + ground faulted		
		6044 am		re-entered cable		
				checked fire suppression		
				c.B trip + battery backup		
D Shrewsbury R-4018						
6-15-9	#2 boiler	opening in spot light operatorside		cleaned + sealed		6-21
6-16-9	#1 charger	no observed		none		6-21
Tracey Lambert 3-261						6-24
						6-24
						6-21
						6-24

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-19-09					
4918 cm		calibrated ch ₄ monitor		checked fire suppression	
		checked battery backup + c B trip			
5811 cm		calibrated ch ₄ monitor		checked fire suppression	
		checked battery backup + c B trip		cleaned fire supp sprays	
4044		calibrated ch ₄ monitor		checked fire suppression	
		checked battery backup + c B trip		cleaned fire supp sprays	
		+ re-entered cable			
feeder -		washed taped cable		checked fire suppression + c B trip	
#25C 17504 -		made splice		washed + checked fire suppression	
fork lift -		replaced light		checked fire suppression	
emergency ride -		not in use			
Power Center -		replaced ground strap		checked monitors + ^{E stop} c B trip + ground faulted	
#2 head + takeup		cleaned slip eye		+ checked fire suppression	
#2 head Power Center -		checked monitors		+ E stop + ground faulted	

Examinations of low- medium-voltage power circuit breakers (monthly)

51BK splitter - checked with test buttons + E stop

#3 head + takeup none observed at time of exam checked fire suppression

#3 head Power Center - checked monitors + E stop + ground faulted

service scoop - OK at time of exam, checked fire suppression

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-24-09	17503 SC	Checked cable cut 4 splices and or repairs from cable and made splice Re-positioned leads in cable reel Visually Insp fire pump			GB 3-481
6-25-09	#1 boiler	Made repair to cable both panic switches at open deck cracked and showed a lot of wear // Replaced switches also replaced on off side open deck			
Weekly tests of grounding devices (diodes)					
		visually Insp fire pump			GB 3-481
6-25-09	396 scoop charger		None observed		
6-26-09	396 scoop		Had brake hold down straps on both sets of batteries // Replaced straps		
		Visually Insp fire pump on scoop & charger			GB 3-481
6-26-09	#1 Pressure pump		None observed		GB 3-481
6-26-9	#1 section	#2 scoop	none seen	none	Richmond
		#2 Boiler	Bad oil leak at TRS. corrected.		Richmond
		#3 SC	cable damaged.	Made splice.	Richmond
		#1 charger	none seen	none	Richmond
6-29-9	#1 section	power center	window for disconnect dirty	cleaned window.	Richmond
Monthly examinations of methane monitors					
7-1-09	17503 SC		None observed		GB 3-481
		visually Insp fire pump.			
7-1-09	#1 RB	Machine would cut off when vibrating. problem rock had damaged panic strip found cut in cable. repaired visually Insp fire pump		Checked Replaced	GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-26-09	#1 Section	Calibrated all cm's chy monitors			
4918 cm		checked fire suppression, battery backup + c.B trip		washed	
5811 cm		checked fire suppression, battery backup + c.B trip			
6044 cm		checked fire suppression, battery backup + c.B trip		washed	
feeder		checked fire suppression, c.B trip +		washed	
#2 sc 17504		checked fire suppression, washed + made splice			
fork lift		changed light + checked fire suppression			
emergency ride		not in use			
service scoop		replaced light	checked fire suppression		
Power Center		replaced ground strap + ground faulted	checked monitors + c.B trip	E stop	
#2 head + takeup		cleaned fire supp. sprays off + checked			
#2 head Power Center		checked monitors, c.B trip + ground faulted		E stop	
#3 head + takeup		checked fire suppression + repaired guard			
#3 head Power Center		replaced monitor - checked monitors, E stop			

Examinations of low- medium-voltage power circuit breakers (monthly)

51 BK splitter	+ ground faulted	checked with test buttons + E stop			
7-2-09 394 scoop			M Shrewsbury	8-4018	
7-2-09 394 scoop	Spot light out	Replaced		GB 3-481	
7-2-09 394 scoop charger	usually Insp fire sup.	Broke off part of fire sup.			
pipes that goes over batteries		replaced			
	usually Insp fire sup			GB 3-481	
7-3-09 #1 pressure pump		None observed		GB 3-481	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-3-9	#1 section	#2 SCOP	circuit breaker not set in deck.	Adjusted linkage.	Richmond
/	/	#3 SC	Head light loose at deck end.	Secured.	Richmond
/	/	#2 Bolter	Two bulb out on Lf. Rt Booms.	Replaced.	Richmond
7-3-9	#1 section	#1 Charger	none seen	none	Richmond
		power center	none seen	none	Richmond

7-3-09 #1 section

4918 cm checked fire suppression, battery backup & c.B trip + repaired light

Weekly tests of grounding devices (diodes)

5811 cm out of service

6044 cm checked fire suppression, battery backup & c.B trip + taped cable

fuder washed - checked fire suppression, c.B trip + repaired oil leak

#2 SC 17504 replaced cable, washed, checked fire suppression

fork lift repaired oil leak + checked fire suppression

emergency ride not in use

service scoop cleaned trash off checked fire suppression

Power Center repaired ground strap checked monitors, E stop + ground faulted

#2 head + takeup checked fire suppression repaired hawk eye

#2 head Power Center checked fire monitors, E stop + ground faulted

#3 head + takeup checked fire suppression + repaired guard

Monthly examinations of methane monitors


#3 head Power Center replaced monitor, checked monitors, E stop + ground faulted

51 dual splitter checked with test buttons + E stop

D Shrewsbury 8-9018

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-6-9	#2 RB	opening in area, light	cleaned & sealed		 Tracy Lambert 3-261 CB 3-481
7-7-9	#1 Charger	no observed	none		
7-8-09	1703 SC	None observed			
		Visually Insp fire surp.			
7-8-09	#1 Bolter	Repaired bad oil leak opr. station			CB 3-481
		Visually Insp fire surp.			
7-9-09	394 SCOP	Replaced broke breaker Re-set cable			
		Replaced Cable			CB 3-481
		Visually Insp fire surp.			
7-9-09	394 SCOP charger	None observed			CB 3-481
		Visually Insp fire surp.			
7-10-09	#1 Pressure pump	Conduit pulled back out of packing gland for No 1 motor / repaired conduit			CB 3-481

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-9-9	1 section	2 scoop	opening in mail panel	sealed to .04	L Richmond
		2 Bolter	2 area lights out	Replaced bulbs	L Richmond
		3 SC	Load indicator broken	Installed new one	L Richmond
		1 charger	none seen	none	L Richmond
7-9-9	1 section	power center	two fire extinguishers bad	Replaced both	L Richmond
9-10-09	1 Section #1	Head	None observed	Brain Tubing	270138
2-10-09	1 Section	tkt. JD	None observed	Brain Tubing	475038

Weekly tests of grounding devices (diodes)

7-10-09 #1 Section Calibrated chy monitors on all 3 c.m's

4918 cm took out of service

5811 cm checked fire suppression - battery backup + cB trip + repaired cable

6044 cm checked fire suppression - battery backup + cB trip washed + taped cable

feeder checked fire suppression - ~~battery backup~~ + cB trip + repaired light

17504 SC checked fire suppression + washed

forklift checked fire suppression + repaired light

emergency ride - not in use

service scoop - checked fire suppression replaced bond plug

Power Center - checked monitors, E stop + ground faulted

#2 head + takeup replaced mats as needed checked fire suppression

Monthly examinations of methane monitors

#2 head power center - checked monitors, E stop + ground faulted

#51 break splitter checked with test buttons + E stop

#3 head + takeup repaired guard checked fire suppression

#3 head power center checked monitors, E stop + ground faulted

D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-16-09	1 Head 1 section	#1 Head 2000	None observed	Re Posted	B. Farley 4-138
7-10-09	1 Head 1 section	#1 Take up	None observed	Re Posted	Brian Taylor
7-17-9	#1 section	#2 Scoop	Breaker reset needs adjusted.	Adjusted	4-138 L. Richmond
		#2 Bolter	none seen	none	L. Richmond
		#3 SC	cable cut at anchor	Repaired	L. Richmond
		#1 charger	none seen	none	L. Richmond
7-17-9	#1 section	power center	top trashed up	cleaned	L. Richmond

Weekly tests of grounding devices (diodes)

7-13-9	#2 bilter	oil leak inside	tightened hose on deck trim		
7-14-9	#1 charger	no observed	none		
7-15-9	#2 Scoop T339-224	oil leak in deck	tightened hose		Tracy Lambert 3-261
		#2 Scoop (224)	Park brake needs adjusted.	corrected	L. Richmond
		#3 SC (15505)	Bad oil leak at filter.	corrected	L. Richmond
		#2 Bolter (2004328)	none seen	none	L. Richmond
		#1 charger	ground clamp connection loose.	corrected	L. Richmond
7-24-9	#1 section	power center	some voltages not I.D.	corrected on panels.	L. Richmond

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-15-09	17003 sc	None observed			
		Visual Insp. fire surp.			
7-15-09	#1 Bolter	Pulled cable into Area light out	Made splice		
		Replaced bulb			
		Visual Insp fire surp.			
7-16-09	396 Batts	Charger	None observed		
		Visual Insp fire surp.			
7-16-09	396 scarp	Replaced strap across batteries			
		Visual Insp fire surp.			
7-17-09	#1 Pressure pump	None observed			

Examinations of low- medium-voltage power circuit breakers (monthly)

7-10-09	1 section 1 Head	#1 Bolt Head	checked fire suppressor, SLP,	4-138	Brian Tully
7-16-09	1 Section 1 Head	#1 Bolt Head Take up	None observed	4-138	Brian Tully

7-12-09 53brk line splitter E Stop Knocked power to sub station when tested
 5brk North line splitter E Stop Knocked power to 53brk when tested
 Checked E stops with State Electrical Inspectors Randy Smith & Tim Brown

T E Sheets
8-11

7
7

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-17-09	#1 Section				
	4918 cm	checked out of service			
	5811 cm	calibrated chy monitor, checked fire suppression, C.B. trip, + battery backup			
	6044 cm	calibrated chy monitor, checked fire suppression, C.B. trip + battery backup			
	feeder	washed checked fire suppression + C.B. trip			
	17504.5C	checked fire suppression + taped cable			
	forklift	repaired seal, replaced jack + checked fire suppression			
	emergency ride	not in use			


Weekly tests of grounding devices (diodes)

Service scoop	cleaned trash off + checked fire suppression
Power Center	replaced matt + fire ext. checked monitors, E stop + ground faulted
#2 head + takeup	checked fire suppression + picked up trash
#2 head Power Center	checked monitors, C.B. trip + ground faulted
#51 brack splitter	checked with test buttons + E stop + had jacks set on sit.
#3 head + takeup	checked fire suppression
#3 head Power Center	replaced ground strap, checked monitors, E stop + ground faulted

D Shrewsbury 8-4018

Monthly examinations of methane monitors

7-20-9	#2 Bulter	Area light out off side helper station	replaced bulb	
7-21-9	#1 Charger	not observed	no	


 Tracy Lambert 8-20

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-22-09	17563 5c	None observed			GB 3-481
7-23-09	396 SCOOP	Usually Insp fire surp Replaced Hyd. pump on scoop Washed scoop Repaired rear spot light			GB 3-481
7-24-09	#1 Pressure pump	Usually Insp fire surp Set pump to get water AWAY from pump			GB 3-481
7-28-09	396 SCOOP CHARGER #1 BOLT ER	None OBSERVED NOT IN SERVICE (GRADING BOTTOM ON SECTION)	None		David Kelly 3-558
7-29-09	17503 5/c	None OBSERVED	None		David Kelly
7-30-09	396 SCOOP	OIL LEAK IN DECK	TIGHTENED FITTING		David Kelly 3-558

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
------	----------	----------------------------------	----------------------	--------------	----------

7-24-09	#1 Section				
4918		checked fire suppression c.B trip + battery backup			
5811		checked fire suppression c.B trip + battery backup + taped cable			
6044		checked fire suppression c.B trip + battery backup + taped cable			
feeder		taped cable checked fire suppression + c.B trip			
17504 SC		made splice + taped cable + checked fire suppression			
forklift		repaired light + checked fire suppression			
emergency ride		not in use			

Weekly tests of grounding devices (diodes)

service scoop		cleaned off + checked fire suppression			
Power Center		checked monitors, E stop + ground faulted			
#2 head + takeup		replaced power pac ^{guard} + checked fire suppression			
#2 head Power Center		checked monitors, E stop + ground faulted			
#51 lb splitter		checked with test buttons + E stop			
#3 head + takeup		replaced power pac + checked fire suppression			
#3 head PC		checked monitors, E stop + ground faulted			

Shrewsbury 8-4018

Monthly examinations of methane monitors

7-27-9	#2 Roof better	opening in main panel	cleaned and sealed panel		
28-9	#1 charger	no rock dust at charger	place five bags on corner by charger		

Tracy Lambert 3-261

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-31-09	#1 Section				
4918 cm		calibrated ch4 monitor, checked fire suppression c.B. trip + battery backup			
5811		calibrated ch4 monitor, checked fire suppression + c.B. trip battery backup + repaired guards			
6044		calibrated ch4 monitor, checked fire suppression c.B. trip + battery backup			
feder		checked fire suppression, c.B. trip + repaired cable			
17504 sc		checked fire suppression + repaired cable			
forklift		checked fire suppression			
emergency ride		not in use			
service scoop		checked fire suppression + cleaned off			
Power Center		replaced 2 monitors checked monitors, E. stop + ground faulted			
#2 head + takeup		checked fire suppression + repaired guard			
#2 head power center		changed out checked monitors E. stop + ground faulted			

Examinations of low- medium-voltage power circuit breakers (monthly)

51 break splitter	checked with test buttons + E. stop
#3 head + takeup	checked fire suppression
#3 head Power Center	checked monitors, E. stop + ground faulted
105 break Power Center	checked monitors, E. stop + ground faulted

A Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-31-9	#1 section	# 2 Scoop	tree damaged by brake disc.	Repaired & relocated.	L. Richmond
		# 2 Bolter	none seen	none	L. Richmond
		# 3 SC	old place in cable need tape.	Retaped	L. Richmond
		# 1 charger	none seen	none	L. Richmond
7-31-9	#1 section	power center	Need 2 ground straps	Installed	L. Richmond

Weekly tests of grounding devices (diodes)

8/4/09	#1 SC SECTION	#1 BOLTER	SPOTLIGHT BROKE OFF OF T-BAR	PUT BACK ON	<i>[Signature]</i>
		396 SCOP CHARGER	REPLACED PLUG ON CHARGER CORD		<i>[Signature]</i> 3-358
8-4-9	#2 Rod bolter	opening in 2 area light	cleaned & sealed		<i>[Signature]</i>
8-5-9	#1 charger	none observed	no		<i>[Signature]</i>
8-7-9	#1 section	# 2 SCOP (22V)	none seen, non rated	Tracy Lambert 3-261	L. Richmond
		# 2 Bolter (2004328)	area bulb out	Replaced	L. Richmond
		# 3 SC (17505)	cable damaged	Repaired cable	L. Richmond
		# 1 charger	none seen	none	L. Richmond
8-7-9	#1 section	power-center	#17503 not in correct breaker	connected	L. Richmond

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-7-09	#1 Section	4918 cm calibrated ch4 monitor, checked fire suppression, CB trip, battery backup + repaired guards			
		5811 cm calibrated ch4 monitor, checked fire suppression, CB trip, battery backup + repaired guards			
		10044 cm calibrated ch4 monitor, checked fire suppression, CB trip, battery backup feeder checked fire suppression, CB trip			
		17504 sc checked fire suppression + washed fork lift out of service			
		emergency side not in use			
		service scow checked fire suppression + cleaned trash off			
		Power center checked monitors, E stop + ground faulted			
		#2 head + takeup checked fire suppression, slip + seq, + repaired guard			
		#2 head PC checked monitors, E stop + ground faulted			
		51 break splitter checked with test buttons + E stop			

Examinations of low- medium-voltage power circuit breakers (monthly)

#3 head + takeup	repaired guards, fire suppression + checked, slip + seq
#3 head PC	checked monitors, E stop + ground faulted
105 break PC	checked monitors E stop + ground faulted

J Shrewsbury 8-4-08

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

8-5-09 17503SC None observed
usually Insp fire surp. QB 3-481

8-6-09 396 scoop Bad tree to scoop batteries, replaced
tree and battery plug
Dirty | Washed
Usually Insp fire surp QB 3-481

Weekly tests of grounding devices (diodes)

8-7-09 #1 Pressure pump None observed QB 3-481
8-14-9 #1 section #2 Scoop dirty washed L Richmond
#2 Bolter cable damaged, repaired L Richmond
#3 SC cable ground, made splice L Richmond
#1 charger none seen, none L Richmond
8-14-9 #1 section power center none seen, none L Richmond

8-14-09 17503SC Bad splice in cable / Cut out and also
removed old splice made splice QB 3-481
usually Insp fire surp
8-14-09 Pressure pump None observed QB 3-481

Monthly examinations of methane monitors

8-21-09 #1 section #2 Scoop none seen none L Richmond
#2 Bolter light bulb out Replaced L Richmond
#3 SC none seen none L Richmond
#1 charger none seen none L Richmond
8-21-09 #1 section power center Top latch on cat head 12504 bad. Replaced
cat head. L Richmond

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-24-09	#1 RB	Bad place in cable / Made splice Visually Insp fire sup.		CB 3-481	
8-25-09	396 scoop	None observed visually Insp fire sup.		CB 3-481	

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-28-9	#1 section	#2 scoop (324)	tram dropping out.	Replaced dir. sw.	L Richmond
		#3 SC (17505)	none seen	none	L Richmond
		#2 Bolter (328)	none seen	none	L Richmond
		#1 charger	none seen	none	L Richmond
8-28-9	#1 section (at 30 BRK.)	power center	needs H.V. signs.	Installed.	L Richmond

Weekly tests of grounding devices (diodes)

9-11-09	#1 section	#2 scoop	batteries dry, watered.		L Richmond
		#3 SC	none seen	none	L Richmond
		#2 Bolter	none seen	none	L Richmond
		#1 charger	none seen	none	L Richmond
9-11-09	#1 section	power center	needs mats.	installed mats	L Richmond

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Equip went over by Inspector & Elec
Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-17-09	17503 SC	None observed		GB 3-481	
	17504 SC	None observed		GB 3-481	
	17505 SC	None observed		GB 3-481	
9-17-09	#1 Bolter	spot light knocked off Cut seven places out of cable made to splice Usually inst. fire surp.		GB 3-481	
9-17-09	#2 bolter	Bad place in cable jacket / Made repair Usually Insp fire surp.		GB 3-481	
9-18-09	#1 section	Under construction			
	feeder -	out of service			
	17504 -	none observed	checked by insp.		
	service scoop -	none observed at time of exam			
	Power Center -	replaced mats + ground strap checked monitors, E stop & ground faulted			
Examinations of low- medium-voltage power circuit breakers (monthly)					
	#1 head PC	checked monitors E stop & ground faulted replaced mats			
					D Shrewsbury 8-4018
9-19-09					
	4918	calibrated ch4 monitor, checked fire suppression + c B trip			
	5811	calibrated ch4 monitor, checked fire suppression + c B trip			
					D Shrewsbury 8-4018

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-25-09	17503 sc	spot lights out /	Repaired wiring		GB 3-481
		Usually Trip fire surp.			
9-25-09	#1 bolter	bolts sheered on front spot light /	Mounted light		GB 3-481
		Usually Trip fire surp.			
9-25-09	#1 Pressure pump	Pump wet in panel /	Disconnected power		GB 3-481
		put heat in panel /	Corrected problem		

Weekly tests of grounding devices (diodes)

9-25-09	#1 section				
4918 cm		checked fire suppression + CB trip			
5811 cm		checked fire suppression + CB trip			
feeder		checked fire suppression + CB trip			
17504		checked fire suppression			
service scoop		none observed at time of exam	checked fire suppression		
forlift		none observed at time of exam	checked fire suppression		
#1 head PC		checked monitors E stop + ground faulted			
section PC		checked monitors E stop + ground faulted			
#1 section #1 head		under construction	out of service		

D Shrewsbury 8-4018

Monthly examinations of methane monitors

9-30-09	#1 bolter	Delay start switch bad /	Replaced		GB 3-481
		Usually Trip fire surp.			
9-30-09	17503 sc	None observed			GB 3-481
		Usually Trip fire surp.			
#1 Pressure pump		None observed			GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-2-09					
4918 cm		checked fire suppression + CB trips + repaired guard			
5811 cm		checked fire suppression + CB trip			
feeder		checked fire suppression + CB trip + repaired pull cord			
175045c		checked fire suppression + made made splice			
service scoop		checked fire suppression + cleaned trash off			
fork lift		checked fire suppression + changed light			
#1 head PC		checked monitors E stop + ground faulted			
#1 head		checked fire suppression			
section PC		cleaned off checked monitors E stop + ground faulted			

D. Shrewsbury 8-4018

Examinations of low- medium-voltage power circuit breakers (monthly)

10-5-09 #1	2005-358 RB	Made repair to suction hose Cable jacket cut / made cable repair Visually Insp. fire surp.		CB 3-481	
10-6-09	396 scoop	Spot light out / Replaced visually, Insp. fire surp DIRTY / Washed		CB 3-481	
10-7-09	396 SCOOP charger	None observed visually Insp. fire surp.		CB 3-481	
10-7-09	4919cm	Methane Monitor not reading right II replaced Resd out and sniffer, Calibrated problem corrected		CB 3-481	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-2-9	#1 section	#25 Scoop	Bad panic switch	Replaced	L Richmond
[]	#2 Bolter	2 Bad tape switches	Replaced	L Richmond
		#3 SC	Bad place in cable	Repaired	L Richmond
		#1 charger	needs rock dust	Installed	L Richmond
10-2-9	#1 section	power center	need 3 ground straps	Installed	L Richmond

Weekly tests of grounding devices (diodes)

10-8-09	Calibrated	Both CH4 monitors on cm	4-701	Andrew	
10-8-09	#1 section	#1 head starter box	put bolts in door to sugar doors	4-701	Andrew Lucas
10-8-09	Srv SC	Scoop rope as secured at time of Exam	4-701	Andrew Lucas	
10-8-09	5811 cm	checked E-Strip battery back up and fire suppression	Replaced bolts and thread blocks on cutter motor shield	4-701	Andrew

10-8-09 17503 sc Repaired oil leak at pump motor QLS 3-481

Taped splices in cable

Visually Inspect fire sup.

10-8-09 #1 Pressure pump None observed QLS 3-481

10-10-09 Forklift none observed at time of exam Andrew Lucas 4-701 Andrew Lucas 4-701

Monthly examinations of methane monitors

10-10-09	4918	Checked E-Strip battery back up and fire suppression	Replaced bolts and thread blocks on cutter motors	
10-10-09	Feeder	checked E-Strip and fire suppression		
10-10-09	Section PS	checked monitors E-stop and Ground Fault with push Button	Read Ground Resistors 995 38.5 Ω 480 18.5 Ω	Andrew Lucas 4-701
10-10-09	#1 head po	checked E-stop and Ground Fault with push Button		
10-10-09	17504	checked fire suppression & washed		Andrew Lucas 4-701

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10/14/09	#2005358 RB	Crushed entrance glands to Front spot lights / Blowed Fuses going to lights Replaced entrance glands re-ended light tree and replaced fuses Visually Insp fire surp.			
10/14/09	396 scoop	Spot light out in rear / Replaced Dirty / washed Visually Insp fire surp			
10/16/09	170035C	None observed			
10/16/09	396 charging station	Visually Insp fire surp Replaced Entire cable Replaced area lights Visually Insp fire surp			

GO 3-48/
GB 3-48/

GB 3-48/

Examinations of low- medium-voltage power circuit breakers (monthly)

10/17/09 #1 Pressure pump

None observed

GO 3-48/

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-8-9	#1 section	#2 RB	Replaced 2 area light bulbs		L Richmond
		#3 SC	none seen		L Richmond
		#1 charger powercenter	needs ground clamp need breaker in circuit #6	Installed	L Richmond
10-8-9	#1 section	#2 SCOP	gang needs replaced	Replaced gang	L Richmond

Weekly tests of grounding devices (diodes)

10-12-9	#1 RB	opening in area light	Cleaned + sealed light		L Richmond
10-13-09	Feeder checked	CB Trip and fire suppression	remounted Dead man	4-701	Quinn
10-15-09	4914 cm	checked CB Trip Battery Backup and fire suppression	washed	4-701	Quinn
10-15-09	17504	checked fire suppression	changed spot light that was out	4-701	Quinn
10-15-09	5811 cm	checked CB Trip Battery Backup and fire suppression	went over cable	Repaired	Quinn
10-15-9	#1 charger	no observed	none		L Richmond
10-15-9	#2 SCOP	opening in deck panel	Cleaned + sealed panel		L Richmond
10-15-9	#3 SC	cable pulled out of clamp on reel	connected		L Richmond
10-15-9	#2 Boiler	cable damaged	Repaired		L Richmond
10-15-9	#2 Boiler	area light broken on front behind TRS	Replaced		L Richmond
10-15-9	powercenter	2 Bolts missing from top lids	Replaced		L Richmond

Monthly examinations of methane monitors

Section power center Ground fault with push button checked E Stop 10-13-09
 Replaced Breaker in circuit #6
 Replaced #80 panel circuit #8

Quinn 4-701


EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-22-09	17503 SC	None observed	GB 3-487		LC
10-23-09	#1 Pressure pump	Entrance gland pulled loose / repaired		GB 3-487	10
					10
					10
					LC
					10
Examinations of low- medium-voltage power circuit breakers (monthly)					
10-23-9	# 3 SC	Hose burst to conveyor lift (oil leak)		Replaced	L. Pishner
	# 2 Batter	Bad suction on left boom		Fixed leaks	L. Pishner
	# 1 charger	Fire extinguisher bad.		Replaced	L. Pishner
	# 2 scoop edyn	Trashed up & dirty		Cleaned off	L. Pishner
10-23-9	power center	Need top cleaned		cleaned	L. Pishner


EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10.19.9	#1RB	No observed	none		 Lambert 3-261
10.20.9	396 scoop charger	no observed	none		
10.20.9	396	dirty & open in breaker panel	washed & cleaned & sealed		
10.23.9	#35C	ratty splice	reinsulated splice		Lambert 3-261
10-23-09	5811	miner	No Dangerous Condition Found		
		Activated Fire suppressor, PCT, and E-stops			
		All working good Battery back up OK			Mitchell 4-250
Weekly tests of grounding devices (diodes)					
10-23-09	4919	miner	Found PLAC in cable that needed replacement		
		Found fault in light bulb on off side.			
		Activated Fire supp, Power center TRIP, and E-stops			Mitchell 4-250
10-23-09	17504	SC	checked cable, diodes, visual fire suppression checked lights panel bars All OK No other dangerous condition found		Mitchell 4-250
10:24.09	section power center	ground faulted breakers, check monitor circuits, checked breaker settings			Mitchell 4-250
		No dangerous conditions found			
10-24-09	CLA back 114T	checked fans, lights, greasing, visual on fire suppression, found one bad fire extinguisher			Mitchell 4-250
Monthly examinations of methane monitors					
10-24-09	Maintenance Vehicle	found dirty (cleaned), break light fire suppression all OK			Mitchell 4-250
10-24-09	UBB #1 belt transporter	No dangerous condition found at time of examination			Mitchell 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10/26/09	2005-358 Bolter	Bolter	Area light out / Fixed leak in suction	Replaced	
10/26/09	396 scoop charger	scoop charger	visually Insp fire surp. None observed	GB 3-481 GB 3-481	
10-28-9	396 scoop	scoop	visually Insp fire surp. Lightout on rear operator side	replaced bulb	

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-30-09	175034	Checked Cable	visually Exam fire suppression Pinic bars lights	none observed at time of Exam	
10-30-9	#1 section	#2 Scoop, 22%	Need rail at main panel.	Installed	Richmond
		#2 Bolter, 200x328	Bad oil leak on rt. boom.	Replaced hose.	Richmond
		#3 SC, 17505	none seen		Richmond
		#1 charger	none seen		Richmond
10-30-9	#1 section	power center	no mat at disconnect.	Installed mat.	Richmond

Weekly tests of grounding devices (diodes)

10-28-09	Calibrated	Both CH4 monitors on Cms	4-701	Quilley	
10-28-09	Checked	fire suppression CB trip and Battery Backup	4-701	Quilley	
10-28-09	Item checked	fire suppression CB trip Battery Backup	4-701	Quilley	
10-29-09	175045L	Checked cable	visually examined fire suppression	none observed at time of exam	4-701 Quilley
10-30-09	Fork lift	and charger	none observed at time of exam	4-701	Quilley
10-30-09	Sensit. Scoop	Dirty	cleaned	4-701	Quilley
10-30-09	speeder	arc light out	Replaced light	4-701	Quilley

Monthly examinations of methane monitors

10-26-09	#1 BeH Head	visually examined fire suppression	all ok at time of Exam	4-701	Quilley
----------	-------------	------------------------------------	------------------------	-------	---------

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement


Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11/13/09	170035c	Bad place in cable / cut out 2 splices and bad splice made splice			
		Visually Insp fire surp		GD 3-481	
11/13/09	396	scoop changer	None observed	GD 3-481	
		Visually Insp fire surp			
11/4/09	396	scoop	Dirty / washed		
		Visually Insp fire surp		GD 3-481	
11/4/09	#1 Bolter	Repaired lead at open drill station			
		visually Insp fire surp		GD 3-481	

11-6-09 4918




Examinations of low- medium-voltage power circuit breakers (monthly)


EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)


Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2 NOV 9	# 2 Roof Bolters	2 Area light had openings	Cleaned + sealed lights		 P. Lomas 4-269
11-7-09	#2 scoop 224		Grab in deck	cleaned	
	#1 charger		None Observed	None	
	#3 S.C. 17505		leads showing on 2 splices	Remade splices	
	Powercenter		Replaced ground strap on Cathod		

Weekly tests of grounding devices (diodes)

11-6-09	Calibrated Both CH4 monitors	4-701	
11-6-09	5811 Cm	checked fire suppression Battery Backup and CB Trip	4-701 
11-6-09	4918 Cm	checked fire suppression Battery Backup and CB Trip	
11-6-09	17504 S.C.	usually examined fire suppression went over cable Re-taped splices	
11-6-09	Sock list	none observed at time of exam	
11-6-09	Service Riddle	none observed at time of exam	
11-6-09	Fooder	usually examined fire suppression went over cable Re-taped splices Replaced Area light	

6 NOV 9 #3 S.C. 2 faulty splices re-insulated splices  3-261

Monthly examinations of methane monitors

11-6-09 section powercenter Replaced Rockdust & mats at powercenter 4-701 

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11-9-9	#2 RB	2 area lights out + opening in area light	replace 2 bulbs + cleaned seal	light enclosure	JAD
11-10-9	#2 charger	no observed	none		JAD
11-11-9	224 scoop	lights out on front of scoop	replaced bulb	sealed enclosure	JAD
11-10-09	#1 Bolter	Replaced fuse to spot lights Replaced hoses leaking at Drill Head		GB 3-481	
11-11-09	17003 SC	Visually Insp fire sup Cut 2 old splices out of cable with About 30' of cable made splice		GB 3-481	
11-11-09	396 scoop	Visually Insp fire sup None observed		GB 3-481	
11-12-09	396 scoop charger	Visually Insp fire sup None observed		GB 3-481	
11-13-09	#1 Pressure pump	Visually Insp fire sup None observed		GB 3-481	

Tracey Lambert 3-261

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11-13-09	#1 section	2 Scoop 224	none seen	none	L Richmond
		2 Bolter 328	offside fire supp bottle need button.	Installed.	
		3 SC 17505	cable has 3 bad places.	Replaced cable.	
		1 charger	none seen.	none	
11-13-09	#1 section	power center	charger needs 10 tags.	installed.	Richmond

Weekly tests of grounding devices (diodes)

11/12/09	4918 Cm	1 DTC charger's cutter bus and gear case ag			
11/12/09	5811 Cm	Calibrated ch 4 monitor checked fire suppression buttons Backup and strip		Replaced light 4-701	
11/12/09	Foralift and charger	none observed at time of exam	4-701	Checked	
11/12/09	Service scoop and charger	none observed at time of exam	4-701	Checked	
11/12/09	17504 SC	visually examined fire suppression attached cable	4-701	Checked	
11/13/09	Spedac	visually examined fire suppression wires over cable	4-701	checked splices	

11-19-09 17503 SC
 Made repairs to side boards
 Dirty Washed
 visually Insp fire surp
 CB 3-481

Monthly examinations of methane monitors

11-20-09 394 scoop
 Dirty / Washed
 Replaced foot switch
 visually Insp fire surp
 CB 3-481

11-20-09 #1 Pressure pump
 None observed
 CB-3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Inspector
11-17-9	#1 RB	checked Arc light out	replaced bulb or sealed enclosure		[Signature]
11-17-9	396 Charger	no observed	none		[Signature]
11-18-9	224 Scoop	opening in breaker panel	Cleaned and sealed enclosure		[Signature]
11-20-09		Calibrated both CH4 monitors 4-701			[Signature]
11-20-09	4518 cm	checked fire suppression Battery Backup & CB trip			[Signature]
11-20-09	5811 cm	checked fire suppression Battery Backup & CB Trip	worn out cable taped up splices		[Signature]
11-20-09	Feeder	visually examined fire suppression	worn out cable		[Signature]
11-20-09	Service Scoop	none observed at time of exam			[Signature]
11-20-09	17504	visually examined fire suppression	worn out cable and taped splices		[Signature]
11-20-09	CLA Forklift	pump down not in use at time of exam			[Signature]
11-20-9	#3 SC	no observed at time of exam	none		[Signature]
11-23-09	#1 Left RB	None observed			GB 3-481
		Visually Inspected fire suppr.			

Examinations of low- medium-voltage power circuit breakers (monthly)

11-23-09	17503 SC	Cable has several places /	Replaced entire cable		
		Visually Inspected fire suppr.			GB 3-481
11-23-09	#1 Pressure pump	None observed			GB 3-481
11-25-09		Calibrated both CH4 monitors 4-701			[Signature]
11-25-09	5811 Rtem	checked fire suppression Battery backup and CB trip	worn out cable & taped splices		[Signature]
11-25-09	4918 Rtem	checked fire suppression Battery backup and CB trip	worn out cable & taped splices	Replaced arc light	[Signature]
11-25-09	17504 SC	visually examined fire suppression	worn out cable	Added new cable to SC	[Signature]
11-25-09	Feeder	visually examined fire suppression	Replaced Arc light		[Signature]
11-25-09	Service Scoop	none observed			[Signature]
11-25-09	CLA Forklift	pump down not in use at time of exam			[Signature]
11-25-09		checked at time of exam			[Signature]

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11/19/09	inside the Deck	Box # 22508 12500-105	at left hand on one section	none observed	Richms
11-20-9	#1 section	# 2 scoop # 2 Batter # 3 SC # 1 charger	opening in main panel over .004 OPER side needs new motor needs new button on fire supp. bottle none seen	sealed panel Installed Installed none	Richms Richms Richms Richms
11-20-9	#1 section	power center	ID tags missing on 17504 brkr.	Installed	Richms
11-20-9	#1 section				

Weekly tests of grounding devices (diodes)

11-24-9	396 Scoop charger	no observed	none		3-261
11-25-9	396 scoop	opening in deck panel	cleaned & sealed		3261
12-2-09	17503 SC	None observed			GB 3-481
12-2-09	#1 RB	Visually Insp fire supp Replaced light tree to front spot lights			GB 3-481
12-2-09	396 scoop charger	Visually Insp fire supp None observed			GB 3-481
12-2-09	396 scoop	visually Insp fire supp Bad battery plug on car batteries / Plug on order			

Monthly examinations of methane monitors

visually Insp fire supp.

11-27-9	#1 section	# 2 scoop # 3 SC # 2 Batter # 1 charger	Batt Lids need secured, secured lids new cable has damaged place. none seen none seen	secured lids Repaired none none	Richms Richms Richms Richms
11-27-9	#1 section	power center	needs nut at disconnect.	Installed nut.	Richms

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-4-09	5811 Cm	checked Battery Backup Fire suppression CB trip	went over cable	Relayed splices	4-701 Andy Durr
12-4-09	4918 Cm	checked Fire suppression Battery Backup CB trip	went over cable	Relayed splices	4-701 Andy Durr
12-4-09	1750456	switches examined Fire suppression went over cable	relayed splices	changed Spot light	4-701 Andy Durr
12-4-09	Feeder	switches examined Fire suppression	changed Arc flash	check & stop	4-701 Andy Durr
12-4-09	Service	scoop none observed at time of exam			4-701 Andy Durr
12-4-09	CHA Fork	1 ft none observed at time of exam			4-701 Andy Durr

Examinations of low- medium-voltage power circuit breakers (monthly)

12-9-09	Section power center	changed 480 receptacles	Ground fault w/ push button		Andy Durr 4-701
		Checked all Face Equip. with Wayne Miller	No violations		12-10-09
12-11-09	17503 sc	None observed	visually Insp fire sup.		
12-11-09	#1 boiler	None observed	visually Insp fire sup.		
12-11-09	396 scoop	None observed	visually Insp fire sup.		
12-11-09	396 scoop charger	None observed	visually Insp fire sup.		
12-11-09	#1 Pressure pump	None observed	visually Insp fire sup.		

QB 3-981

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
Weekly tests of grounding devices (diodes)					
12-17-09		Calibrated Both CH4 monitors on cms	4-701	Andru Jones	
12-17-09	4918 cm	checked fire suppression and Battery Box	Had three bad area lights	changed lights	Mag Damaged
	Area light	4-701	Andru Jones		
12-17-09	5811 Gm	checked fire suppression battery backup and CB Trip	Had Area light out	Replaced Area light	4-701 Andru Jones
12-17-09	17504 SC	visually examined fire suppression	needs washed	4-701	Andru Jones
				changed box on SC	
12-17-09	Feedar	visually examined fire suppression	checked E Stop	Damaged Junction Box	Forced man Switch Reported
					4-701 Andru Jones
12-17-09	CLA Fork lift	needs washed	4-701	Andru Jones	
12-17-09	CLA Fork lift	none observed	4-701	Andru Jones	
12-17-09	Service Scoop	needs cleaned	4-701	Andru Jones	
12-17-09	Bonder	none observed	4-701	Andru Jones	
12-17-09	H2 Boller	3 Area lights out	changed lights	visually examined fire suppression	
Monthly examinations of methane monitors					
12-17-09	PMW charger	none observed at time of exam	4-701	Andru Jones	
12-17-09	Section power center	closed off and replaced	Rock Dust	4-701	Andru Jones
12-17-09	#1 section #1 Head	Had Single Phase Breaker	Replaced Breaker	4-701	Andru Jones
12-17-09	#1 section #2 Head	no rock dust	Replaced Dust	4-701	Andru Jones

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examined by
12-23-09	4918 cm	Section Idll 4-701			Andrew Dineen
12-23-09	5811 cm	Section Idll 4-701			Andrew Dineen
12-23-09	17504 cm	Section Idll 4-701			Andrew Dineen
12-23-09	Feeder	Section Idll 4-701			Andrew Dineen
12-23-09	CLA Forklift and charger	Section Idll 4-701			Andrew Dineen
12-23-09	Service Scoop and Bender	Section Idll 4-701			Andrew Dineen
12-23-09	Section power center	Section Idll 4-701			Andrew Dineen
12-23-09	#1 section	#2 scoop	chains needs some repairs.	Repaired.	L. Richmond
		#2 Bolter	water box needs refilled.	Filled.	L. Richmond
		#3 SC	Tram in first point only.	Reset VFD.	L. Richmond
		#1 charger	none seen	none	L. Richmond
12-23-09	#1 section	power center	several circuits need 10's	labeled circuits	L. Richmond

Examinations of low- medium-voltage power circuit breakers (monthly)

12/26/09	#1 bolter	None observed			
12/26/09	17503 sc	No observed			
12/26/09	396 scoop	Replaced	Rear spot light		
12/26/09	396 charger	None observed			
12/26/09	#1 Pressure pump	None observed			
12/26/09	4918 cm	None observed			
12/26/09	17504 sc	None observed			
12-26-09	5811 cm	None observed	at Time of exam		Mike Dickson 4-706
12-26-09	Feeder	None observed	at Time of exam		Mike Dickson 4-706
12-26-09	Fork lift and charger	None observed	at Time of exam		Mike Dickson 4-706
12-26-09	Service scoop	None observed	at Time of exam		Mike Dickson 4-706

CtB 3/481

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-23-09	#1 Section #1 head	none observed	4-701	Andrew Ince	
12-23-09	#1 Section #2 head	none observed	4-701	Andrew Ince	
12-23-09	#1 Section power center	4-701	Andrew Ince		
12-26-09	#2 2004328 RT Boller	None observed at Time of exam		Mike Dickson	4-706
12-29-09	#1 Section	none observed			
12-29-09	Section power center	Dirty no rock Dust	Cleaned off and Replaced Dusty	Andrew Ince	4-701
12-28-09	#1 Section #2 Boller	none spot lights out	Replaced light	Andrew Ince	4-701
12-28-09	#1 Section	17505 SC needs washed		Andrew Ince	4-701

Weekly tests of grounding devices (diodes)

1-1-10	396 Scoop	opening in head light	cleaned + sealed light		
1-1-10	396 Scoop chargers	no observed	none		
1-1-10	#1 SC	cable damage	made splice		
1-1-10	#1 RB	2 area lights out	replaced bulbs		
2-10	4918 LICM	None observed at Time of exam		Mike Dickson	4-706
2-10	5811 RTCM	replaced spot light		Mike Dickson	4-706
2-10	Feeder	None observed at Time of exam		Mike Dickson	4-706
2-10	service scoop and hoses	None observed at Time of exam		Mike Dickson	4-706
2-10	17504 SC	None observed at Time of exam		Mike Dickson	4-706
2-10	Fuck lift and chargers	None observed at Time of exam		Mike Dickson	4-706

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-4-10	#283	2 blown area lights Fire suppression OK at time of exam	replaced bulbs		
1-4-10	#1 boiler	Made splice in cable visually Inspected fire sup		GB 3-481	
1-4-10	17503 SC	None observed visually Inspected fire sup		GB 3-481	
1-4-10	396 scoop	replaced spot light visually Inspected fire sup			
1-4-10	394 scoop charger	None observed visually Inspected fire sup			
1-4-10	#1 Pressure pump	None observed		GB 3-481 GB 3-481	

Examinations of low- medium-voltage power circuit breakers (monthly)

1/11/2010	#1 Belt Head	visually examined fire suppression, completed monthly exam on belt power box	Cleaned off box	4-201 Andrew Lucas
1/11/2010	#2 Belt head	visually examined fire suppression, completed monthly exam on belt power box	Cleaned off Box	4-201 Andrew Lucas
1/13/2010	#1 Section #1 Belt kVA	checked E-stop none observed at time of exam		4-201 Andrew Lucas
1/13/2010	Section #2 Belt kVA	checked E-stop none observed at time of exam		4-201 Andrew Lucas
1/13/2010	Section power center	checked E-stop none observed at time of exam		4-201 Andrew Lucas

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-8-2010	5811 Cm	checked fire suppression Battery Backup and CB top went over cable			4-701 Andrew Lucas
1-8-2010	4918 Cm	checked fire suppression Battery Backup and CB top went over cable			4-701 Andrew Lucas
1-8-2010	17504	visually examined fire suppression mats washed			4-701 Andrew Lucas
1-8-2010	Feeders	visually examined fire suppression checked E stop none observed at time of exam			4-701 Andrew Lucas
1-8-2010	Service Scoop	none observed at time of exam			4-701 Andrew Lucas
1-8-2010	Bender	none observed at time of exam			4-701 Andrew Lucas
1-8-2010	CHA Forklift and charger	none observed at time of exam			4-701 Andrew Lucas

Weekly tests of grounding devices (diodes)

1-8-10	#1 section	#2 Scoop 224	oil leak in deck	Fixed oil leak	Richmond
		#2 Bolter 2004328	Feed jack hose off side leaking	Fixed	Richmond
		#3 SC 17505	None seen	None	Richmond
		Fork Lift charger	At new location at Glory hole	All ok.	Richmond
1-8-10	#1 section	Powercenter	#3 circuit has broken receptacle	Tagged out & dangerous	Richmond
1-11-10	#1 Bolter		Bolts sheared off to spot light on front	repaired	
			visually inspect fire sup.		
1-11-10	#2 Bolter		6 Area lights + 1 spot light out	replaced bulbs	
			visually inspected fire suppression		

Monthly examinations of methane monitors

1-12-09	1-12-10	396 scoop charger	None observed		
			visually inspect fire sup.		
1-12-10		#1 charger	Mat missing & no rack dust	replaced mat and rack dust	GB 3-481
1-13-10		224 Scoop	Front lights unmounted	mounted lights	3-261

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1/15/10	38116 m	checked fire suppression Battery Backup E-stops and CB trip	all ok at time of exam	4-701	Andrew Dineen
1/15/10	4919 cm	checked fire suppression Battery Backup E-stops and CB trip	all ok at time of exam	4-701	Andrew Dineen
1/15/10	17504	visually examined fire suppression & washed		4-701	Andrew Dineen
1/15/10	Feeder	visually examined fire suppression had Arc light out	Replaced Bulb	4-701	Andrew Dineen
1/15/10	Service scarp	none observed at time of exam		4-701	Andrew Dineen
1/15/10	Border	none observed at time of exam		4-701	Andrew Dineen
1/15/10	Service Scarp charger	not in use at time of exam		4-701	Andrew Dineen
1/15/10	CIA Fork lift and charger	none observed at time of exam		4-701	Andrew Dineen

1/15/10	396 scarp	None observed		GB 3-481	
		visually Insp fire scarp			
1/15/10	17503 sc	None observed		GB 3-481	
		visually Insp fire scarp			
1/15/10	#1 Pressure pump	Entrance gland pulled loose made repair		GB 3-481	

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT


Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-15-10	#1 section	#2 Scoop 2 Bolter 3 SC Fork Lift Charger	oil leak at front of machine. one area bulb out. None seen ground clamp loose.	corrected Replaced Tightened	LRichmond LRichmond LRichmond
1-15-10	#1 sect	power center	need dust cover on #11 receptacle.	Installed	LRichmond

Weekly tests of grounding devices (diodes)

12-16-10 J.B. Long MA trip
 No battery Indicator / on order
 Park brake weak
 Tram good, brakes good, steering good
 Bell working but needs replaced
 Drive seat needs replaced / on order

Mail Vocab 4-250

1-18-10	#1 Roof bolter	no observed	none		
1-19-10	396 charger	no mat	replaced mat		
1-20-10	224 Scoop	park brake doesn't work	adjusted brakes + tested		

Monthly examinations of methane monitors

1-20-10	396 scoop	Replaced stat light Visually Insp fire sup			GB 3-481
1-22-10	17503 sc	None observed Visually Insp fire sup			GB 3-481
1-22-10	#1 Pressure pump	Re-entered packing glands in thermal overloads			GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1/22/10		calibrated both L14 monitors on CM's			
1/22/10	4918cm	checked fire suppression battery backup CB trip and E-stops	went over cable	Retaped Splices	4-201 [Signature]
1/22/10	4918cm	checked fire suppression battery backup CB trip and E-stops	went over cable	Retaped Splices	4-201 [Signature]
1/22/10	17504	visually examined fire suppression	none observed		4-201 [Signature]
1/22/10		Service scoop	none observed		4-201 [Signature]
1/22/10		Bonder	none observed		4-201 [Signature]
1/22/10		LIASOK lift & charger	none observed		4-201 [Signature]
1/22/10		pressure pump	none observed		4-201 [Signature]
1/22/10		Bonder	visually examined fire suppression	went over cable Retaped Splices	Area light out Changed bulb 4-201 [Signature]

1-26-10	396 charger	no observed	none	[Signature]
1-27-10	396 scoop	opening in deck panel	cleaned & sealed panel	[Signature]

Examinations of low-medium-voltage power circuit breakers (monthly)

1-28-10	#1 section	#2 500p	no strap across batteries	Installed	[Signature]
		#2 Bolter	Light bulb out at rt. boom	Replaced	[Signature]
		#3 5c	none seen	none	[Signature]
		power center	needed strap for LCM	Installed	[Signature]
1-28-10	#1 section	Fork Lift charger	none seen	none	[Signature]

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1/29/10	58112m	checked Fire suppression Battery Backup E-stops and CB Trip	Went over cable	4-701	Amundson
1/29/10	4918cm	checked Fire suppression Battery Backup E-stops and CB Trip	Went over cable	4-701	Amundson
1/29/10	Feeder	visually examined Fire suppression checked power center top green light out	Replaced Bulb	4-701	Amundson
1/29/10	175045C	visually examined Fire suppression needs washed		4-701	Amundson
1/29/10	Pressure pump	none observed		4-701	Amundson
1/29/10	Service Scoop	needs cleaned and washed		4-701	Amundson
1/29/10	Bender	none observed at time of exam		4-701	Amundson
1/29/10	CLA Fork lift	on 6 charger	Replaced Dust & t. charger	4-701	Amundson

Weekly tests of grounding devices (diodes)

2-2-10	#1 Botler	Lens cracked on 2 area lights /	Replaced		
		Usually Trip Fire sup			GB 3-481
2-2-10	175035C	None observed			
		Usually Trip fire sup			GB 3-481
2-3-10	396	Pressure gauges popped loose in deck /	Replaced All gauges		
		And secured			
		Usually Trip fire sup.			GB 3-481

Monthly examinations of methane monitors

2-4-10	#1 section	#2 scoop no tank breather, oil spurting out.	Installed CRichmond breather		
		#2 Botler TR5 Light has opening.	Sealed to .004 CRichmond		
		#3 5C	None seen		
		powercenter	several top lid bolts out.	Replaced bolt, CRichmond	
2-4-10	#1 section	Fork lift charger	Ground clamp loose.	Tightened CRichmond	

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2/5/10		Calibrated Both CH4 monitors on cms 4-701			Andrew Jones
2/5/10	5811 cm	checked fire suppression Battery Backup e-stops and C.B.T.P.P. light on area light		changed blubwentaer cable	929
2/5/10	4918 cm	checked fire suppression Battery Backup e-stops and C.B.T.P.P. went over cables		replaced splices 4-701	Andrew Jones
2/5/10	17504 SC	visually examd fire suppression and washed			4-701 Andrew Jones
2/5/10	CLA Fork lift and charger	replaced Dist of charger			4-701 Andrew Jones
2-5-10	Service Scoop	None observed at time of exam			4-706 Mike Dickson
2-5-10	Bondar	None observed at time of exam			4-706 Mike Dickson
2-5-10	pressure pump	None observed at time of exam			4-706 Mike Dickson
2-5-10	feeder	visual exam fire suppression vent over cable			none observed at time of exam 4-706 Mike Dickson
2-5-10	17503 SC	Entrance gland loose on area light		checked & corrected	
2-8-10	#2 8B	replaced 2 area light out		Replaced	
2-9-10	#1 Charger	no observed		none	

Examinations of low- medium-voltage power circuit breakers (monthly)

2-8-10	#1 RB	Replaced 2 leaky noses around drill head			CB 3-481
		visually insp fire surp			
2-9-10	17503 SC	None observed			
		visually insp fire surp			CB 3-481
2-10-10	396 charger	Charging card bad		replaced	
		visually insp fire surp			CB 3-481
2-10-10	396 scoop	lens busted on front spot light		replaced	
		visually insp fire surp			CB 3-481
2-12-10	#1 Pressure pump	None observed			CB 3-481
2-12-10	JB hang Emergency rde	Front bearing Hub Assy. broke		replaced	
		Bad bearing on rear axle		replaced bearing and axle	
		Batteries weak		replaced all batteries	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-12-10		battery Indicator missing	100	Order	CRB 3-481
2-13-10	5811 CM	checked Battery back up Fire suppression e-stops and EB Trip	Replaced 3 Area lights	4-701	Andrew
2-13-10	4811 CM	checked Fire suppression Battery back up e-stops and CB Trip	want out cable	Replaced Area light	4-701 Andrew
2-13-10	1750	usually examined Fire suppression	none observed	at time of exam	4-701 Andrew
2-13-10		CHA Fork lift and charger	none observed	at time of exam	4-701 Andrew
2-13-10		Forker usually examined Fire suppression	want over cable	none observed	4-701 Andrew
2-13-10		Service Scoop & Forker	none observed	at time of exam	4-701 Andrew

Weekly tests of grounding devices (diodes)

2-11-10	#1 section	#2 Scoop 224	Very dirty	washed	Richmond
		#7 55 17505	cable damaged	Repaired	Rich
		#2 Forker 200K358	3 more lights out	Replaced	Rich
		Fork TK charger	none seen	none	Rich
2-11-10	#1 section	power center	ground straps loose (3)	Tightened	Richmond
2-16-10		PMV Charger	no mat	replaced mat	3-261
2-17-10		224 Scoop	no lights	replaced	3-261

Monthly examinations of methane monitors

2-15-10	#1 section	#2 Scoop	brake needs adjusted	adjusted	Richmond
	" "	#3 55	none seen	none	Rich
	" "	#2 Forker	cable damaged	Repaired	Richmond
	" "	Fork TK charger	none seen	none	Richmond
2-18-10	" "	power center	Need ground strap on CRKT 10	Install	Richmond ground strap

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-16-10	17503 SC	Cable riding on splice at Anchor / Moved cable			
		Visually Insp fire sup		GB 3-481	
2-17-10	396 scoop	Dirty / Washed			
		Visually Insp fire sup		GB 3-481	
2-17-10	396 scoop charger	None observed			
		Visually Insp fire sup		GB 3-481	

2/20/10 5811 CM checked fire suppression Battery backup CB trips and E-stops went over cable. Replaced 1 Analogy 4-701 (Andy Jones)

2/20/10 4918 CM checked fire suppression Battery backup CB trips and E-stops went over cable 4-701 (Andy Jones)

2/20/10 17504 Visually examined fire suppression needs washed 4-701 (Andy Jones)

2/20/10 Fuder Visually examined fire suppression checked E-stop went over cable 4-701 (Andy Jones)

2/20/10 Service Scoop none observed at time of exam 4-701 (Andy Jones)

2/20/10 CLA Forklift none observed at time of exam 4-701 (Andy Jones)

2/20/10 Bender none observed at time of exam 4-701 (Andy Jones)

2/20/10 Pressure pump none observed at time of exam 4-701 (Andy Jones)

Examinations of low- medium-voltage power circuit breakers (monthly)

2-26-10	PMV Charger	no fire extinguisher	replaced		
2-26-10	224 Scoop	Park brake out of adjustment	adjusted brakes tested ok		

2-22-10 #1 bolter Replaced busted hose at Drill station off side
 Visually Insp fire sup
 GB 3-481

2-23-10 17503 SC None observed
 Visually Insp fire sup
 GB 3-481

2-24-10 17503 bad breaker at power center / switched breakers
 2-24-10 396 scoop charger None observed
 Visually Insp fire sup
 GB 3-481

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-25-10	396 scoop	Dirty / Washed			GB 3-481
2-26-10	#1 Pressure pump	Touch screen bad on computer read-out	Replaced		GB 3-481
3-2-10					
	5M 5811 miner	Permissibility checked		A Lucas	
	5M 4918 miner	Permissibility checked		A Lucas	
	Bolton 2004328	Permissibility checked		A Lucas	
Weekly tests of grounding devices (diodes)					
3-2-10	17504 SC	did permissibility with Federal inspector	none observed	4-701	Andrew Jones
3-2-10	Feeder	visually examined fire suppression checked E-stop		4-701	Andrew Jones
3/3/10	Section power center	Ground faulted Breakers with push button checked all octest Buttons on 995 Circuits	Replaced ground resistors 995 36.8 Ω 480 17.7 Ω	checked E-stop	4-701 Andrew Jones
3/3/10	Service scoop	visually examined fire suppression	need cleaned gth and washed	4-701	Andrew Jones
3/3/10	Paradox	none observed at time of exam		4-701	Andrew Jones
3/3/10	GIA Fork lift	needs washed		4-701	Andrew Jones
3/3/10	Fork lift charger	none observed at time of exam		4-701	Andrew Jones
2-26-10	1 section	2 scoop	Head light bulb out	Replaced	CRISHMOR
2-26-10		Fork lift charger	none seen	none	CRISHMOR
2-26-10		power center	bad s.c. card	Replaced	CRISHMOR
2-26-10		2 Batter	none seen	none	
2-26-10		3 SC	none seen	none	
Monthly examinations of methane monitors					
3 MAR 10	396 Scoop	light housing	loose, missing set screw	tightened housing & replaced set screw	3661
5 MAR 10	17503 SC	ratty splice		reinsulated splice	3661
5 MAR 10	Pressure Pump	no mat		replaced	3661

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3/2/2010	5811cm	Checked fire suppression battery backup, E stops & CB trip, had area light out	Replaced Bulb	4-701	Andrew Jones
3/7/2010	4918cm	checked fire suppression battery backup, E stops & CB trip	2 Bad fire suppression sprays	Replaced sprays	4-701 Andrew Jones
3/7/2010		celebrated Both CH4 monitors on cm's			
3/7/2010	Clark lift	needs washed	Had light out	replaced bulb	4-701 Andrew Jones
3/2/2010	CLA Fork lift charger	not used	replaced dust	4-701	Andrew Jones

3-8-10 396 scoop charger Batteries sumper bad / Took out of service going to get cable to fix New jumper
 usually trap fire sup.

3-10-10 #1 boiler None observed
 usually trap fire sup. 3-481

Examinations of low- medium-voltage power circuit breakers (monthly)

3-8-10	#2 boiler	3 area lights out	3 area lights out	Replaced bulbs	326
3-5-10	#1 section	#2 scoop	pump motor defective	Replaced	Richmond
		#3 SC	none seen	none	Richmond
		power center	back s-c panel	Replaced	Richmond
		fork lift charger	none seen	none	Richmond
3-5-10	#1 sect	#2 Boiler	opening in front light	closed to 804	Richmond

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-8-10		Permissibility checked on 17504 SC OK None observed at time of exam	4-706		Mike Dickens
3-9-10		Permissibility checked on feeder changed 2 lights OK	4-706		Mike Dickens
3-8-10		Permissibility checked on service scoop. changed one light OK	4-706		Mike Dickens
3-11-10		visually exam fire suppression went over cables retaped OK	4-706		Mike Dickens

3-8-10 #1 Boiler Changed several leaking Hyd. hoses
 VISUALLY Insp fire sup

Weekly tests of grounding devices (diodes)

3-9-10 396 scoop charger Battery jumpers bad / Made new set of jumpers
 Charge cable bad coming out of charger / Replaced
 VISUALLY Insp fire sup. CB 3-481

3-10-10 396 scoop Dirty / Washed
 VISUALLY Insp fire sup CB 3-481

3-12-10 4918 mine check fire suppression battery Back up E-stops and CB Trip replaced on over light OK 4-706 Mike Dickens

3.12.10 Pressure pump none observed none
 3.12.10 #1 SC none observed none

Monthly examinations of methane monitors

3/13/10 5811 Cm checked fire suppression Battery back up E-stops & CB Trip Analight out. Replaced Bulb 4-701 [Signature]

3/13/10 Greaser Visually examined fire suppression checked E-stop all ok at time of Exam 4-701 [Signature]

3-12-10 #25 coop - 224 light tree damaged Repaired L Richmond

#3 SC - 17505 cable damaged two places Repaired L Richmond

powercenter ground strap loose on box Tightened clamp L Richmond

Fork lift charger set screw loose on batt plug Tightened set screw L Richmond

3-12-10 #2 Boiler - 2009328 2 light bulbs bad replaced L Richmond

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-15-10	#1 Boiler	Repaired several oil leaks oper. side control valve Assy. leaking	usually Trip fire sup.	ordered part	GB 3-481
3-16-10	170035C	Ajuster	Circuit breaker at power center to 800 amps	Just. trip	GB 3-481
3-17-10	396 charging station	None observed	usually Trip fire sup		GB 3-481

Weekly tests of grounding devices (diodes)

3-17-10	396 scoop	None observed	usually Trip fire sup		
3-19-10	#1 Pressure pump	None observed			GB 3-481
3/20/10	17504 SC	usually Examined	Fire Suppression went over	Retaped Splices	4-701 Andrew Shear
3/20/10	Service scoop & Radar	None observed	at time of Exam		4-701 Andrew Shear
3/22	section power center	cleaned off power center	→ Replaced Dust		4-701 Andrew Shear
3-22-10	#1 RB	Area light out	replaced		3-261
3-23-10	Feeder	usually examined	Fire suppression checked	Estop Area light out	Replaced Bulb 4-701 Andrew Shear
3-23-10	396 Charging Station	no observed	none		3-261
3/24/10	Service scoop	None observed	at time of Exam	none	4-701 Andrew Shear

Monthly examinations of methane monitors

3-24-10	224 Scasp	park brakes didn't set when breaker Knocks	adjusted brake		3-261
3-25-10	17504 SC	usually Inspected	Fire suppression went over cable	Retaped splices ok	4-838
3-26-10	5871 cm	check fire suppression	Battery back up Estops and c.B.R.P	Had Area light out	Replaced Bulb 4-701 Andrew Shear
3-26-10	CLASSICAL stand charger	none observed	at time of Exam		4-701 Andrew Shear
3-26-10	4918 emmer	check fire suppression	Battery back up Estop and c.B.R.P	Had to replace area light socket and bulb	4-706 Mike Dehans
3-29-10	1 sec 1 head	Visual Examination on fire suppression	Clear Sprays		4-838

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-24-10	396 scoop	Replaced fire Washed scoop			CB 3-481
1-25-10	17503 sc	Usually Insp fire sup Has a bad buggy anchor	1 Order		CB 3-481
1-26-10	#1 Pressure pump	Usually Insp fire sup	None observed		CB 3-481
3-30-10	Powercenter	checked all recept using test buttons read grounding resistors checked			
	E-step OK	480 = 17.9 Ω 995 = 37.1 Ω	reported		Bl Well 4-535
3-30-10	Feeder	visibly check fire suppression check E-step			
3-30-10	396 Scoop charger	Remote fire suppression not hung	Hung fire suppression		Bl Well 4-535
3-31-10	4918 Miner	cal. methane monitor OK	reported		Bl Well 4-535
3-31-10	5811 miner	cal. methane monitor OK	reported		Bl Well 4-535
3-31-10	Service Scoop	none observed at time of exam	reported		Bl Well 4-535
3-31-10	Bonder	none observed at time of exam	reported		Bl Well 4-535

Examinations of low- medium-voltage power circuit breakers (monthly)

3-31-10	396 Scoop	battery end off side light lens busted	parts on order		Bl Well 4-535
4-1-10	Coker sc	Visual exam of fire suppression	light out	Replaced	Bl Well 4-535
4-2-10	5411 cm	checked fire suppression Battery Bank E-Steps and CB Trip	Ass light out	Replaced Bulb	Bl Well 4-535
4-2-10	4518 cm	checked fire suppression Battery Bank E-Steps and CB Trip	Ass light out	Replaced fire suppression sprays	Bl Well 4-535
4-2-10	#1 pressure pump	None observed			Bl Well 4-535
4-2-10	17503 SC	visual exam fire suppression and vent over cable 2 splines OK			Bl Well 4-535
4-2-10	1302 #1 bolt head	visual exam fire suppression OK			Bl Well 4-535