

Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Powered Haulage	3. Date/Time of Accident 03/08/2016 11:06 PM	4. Date/Time of Death 03/08/2016 11:06 PM	5. Fatal Case No 2
-----------------------------------	---	---	--	-----------------------

6. Mine Information :

a) Mining Company Name Staker & Parson Companies	b) Mine Name Beck Street South	c) Parent of Mining Company CRH PLC
---	-----------------------------------	--

7. Mine Location :	a) City Salt Lake City	b) County Salt Lake	c) State UT	8. Mine ID Number: 42-00410	9. Union: NO
--------------------	---------------------------	------------------------	----------------	--------------------------------	-----------------

10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M	11. Number of Mine Employees:	a) Total 25	b) Underground 0	c) Open Pit/Quarry 25	d) Mill/Prep Plant 0	e) Other 0
--	-------------------------------	----------------	---------------------	--------------------------	-------------------------	---------------

12. Contractor Name:	13. Union	14. Contractor ID Number:
----------------------	-----------	---------------------------

15. Contractor Address:	a) City	b) County	c) State	d) Zip Code
-------------------------	---------	-----------	----------	-------------

16. Number of Contractor Employees:	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
-------------------------------------	----------	----------------	--------------------	--------------------	----------

17. Number of Persons in Mine at Time of Accident:	18. Number of Persons Unaccounted For:
a) Mine Employees: 11	a) Mine Employees: 0
b) Contractor Employees: 0	b) Contractor Employees: 0

19) Location of Accident	20. Mining Height:
<input type="checkbox"/> 01-Underground <input type="checkbox"/> 02-Surface at Underground <input checked="" type="checkbox"/> 03-Open Pit <input type="checkbox"/> 06-Dredge Mining	Feet Inches 20 0
<input type="checkbox"/> 07-Advance Mining <input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 30-Mill/Prep Plant <input type="checkbox"/> 99-Office Facility <input type="checkbox"/> Other (specify)

21. Nonfatal Injuries: 0	22. Fatal Injuries: 1
-----------------------------	--------------------------

23. Victim Information :	a) Name Blaine K. Linck	b) Age 54
--------------------------	----------------------------	--------------

c) Regular Job Title: Equipment Operator	d) Activity at Time of Accident: Haul Truck	<input checked="" type="checkbox"/> Mine Employee
---	--	---

24. Experience :	Years Weeks Days	Years Weeks Days	Years Weeks Days	Years Weeks Days
a) Total:	5 2 4	b) at the mine:	0 18 2	c) at activity (23d)
			0 18 2	d) with Contractor
				0 18 2

25. Autopsy Performed: If Yes, Location	26. Mine Telephone No.: (801) 298-7500
--	---

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
At approximately 22:50, a search began for a haul truck when the truck and driver failed to return for a load. At 23:06, the victim was found in the cab of the haul truck at the bottom of the embankment, 60 feet below the dump point. The victim was found unresponsive and partially submerged in water. CPR was attempted, but the victim was not able to be resuscitated.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar	29. Model: 775E
--	--------------------

30. District: M6000 Rocky Mountain	32. Field Office: Salt Lake City UT	33. Event Number: 6697459
---------------------------------------	--	------------------------------

34. Accident Investigator: Joseph Summers	35. MSHA Person Notified: Peter A. Del Duca	Date 03/08/2016	Time 11:24 PM
--	--	--------------------	------------------

36. Type of Report: Initial	37. Name of Preparer and Date Prepared: Peter Del Duca	Date 03/09/2016
--------------------------------	---	--------------------

38. Reason For Amendment: