ISSUE DATE: 09/24/09

LAST VALIDATED: 03/31/2021

PROGRAM INFORMATION BULLETIN NO. P09-33

FROM: LINDA F. ZEILER

Acting Director of Technical Support

KEVIN G. STRICKLIN
Administrator for
Coal Mine Safety and He

Coal Mine Safety and Health

SUBJECT: Effects of PVC Cement Vapors on Handheld Gas Detectors

Scope

This Program Information Bulletin (PIB) applies to coal mine operators and independent contractors.

Purpose

This PIB alerts the mining industry to the potential for false or elevated methane and carbon monoxide readings caused by curing PVC cement vapors when using handheld gas detectors.

Information

Adequate seals are crucial to improve protection for miners from explosions and prevent potentially explosive or toxic gasses from migrating into active working areas of underground coal mines. The Mine Safety and Health Administration (MSHA) issued an ETS on sealing abandoned areas on May 22, 2007 (72 F.R. 28796), and a final rule was published on April 18, 2008 (73 F.R. 21182). The final rule included a prohibition of metallic sampling pipes in seals constructed after October 20, 2008. For this reason, PVC pipes are commonly used to comply with this requirement. The most common method for connecting segments of a pipe, fittings and valves is to weld the components using PVC cement. The curing process for this PVC cement releases vapors which can cause a false or elevated methane and carbon monoxide response.

To avoid false or elevated readings of methane and carbon monoxide caused by PVC cement vapors, sample pipe and valve installations should be completed as soon as possible at seal sites to allow the PVC cement to become fully cured. After the curing process is completed, the cement will no longer produce vapors in sufficient quantity to

affect the readings of the handheld detectors. In addition, examiners should assure the sample pipe is properly purged after the curing process is completed to remove any residual vapors remaining in the sample pipe.

Mine operators may also consider using threaded fittings on sample pipe, which can be welded onto the pipe in advance of installation. This would allow segments to be connected underground without the use of PVC cement.

Background

In the course of evaluating the atmosphere within sealed areas of coal mines, gas samples are collected through gas sample pipes installed through seals. These tests and samples are used to monitor the atmosphere within sealed areas. Recently, miners were evacuated from a mine after handheld gas detectors used to test the atmosphere in the sealed area indicated methane and carbon monoxide levels exceeding acceptable limits. Bottle samples collected from the sealed area subsequently indicated no measurable methane or carbon monoxide levels.

MSHA investigators found that vapors from the PVC cement used to weld the PVC pipes, fittings, and control valves affected the response of the combustible and toxic gas sensors. Further laboratory testing confirmed that PVC cement that is not fully cured can produce vapors in sufficient quantity to cause false or elevated methane and carbon monoxide readings.

Internet Availability

This PIB may be viewed on the Internet by accessing the MSHA home page and choosing "Compliance Info" and "Program Information Bulletins."

Authority

Federal Mine Safety and Health Act of 1977, as amended, 30 U.S.C. § 801 et. seq.; 30 C.F.R. § 75.337.

Issuing Office and Contact Persons

Mine Safety and Health Enforcement, Safety Division Don Vickers, (202) 693-9760

E-mail: Vickers.Donald@dol.gov

Technical Support, Pittsburgh Safety and Health Technology Center Thomas Morley, (412) 386-6965 E-mail: morley.thomas@dol.gov

Distribution

MSHA Program Policy Manual Holders Coal Mine Operators Independent Contractors Special Interest Groups