## Mine Citation/Order

## U.S. Department of Labor Mine Safety and Health Administration



Section I-Violation Data 1. Date Mo Da Yr 2. Time (24 Hr. Clock) 3. Citation/ 4900295 Order Number 0800 12/06/2011 5. Operator 4. Served To PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 7. Mine ID 46-08436 UPPER BIG BRANCH MINE-SOUTH (Contractor) 8. Condition or Practice 8a. Written Notice (103g)

Undervoltage protection is not being provided for the Cutler-Hammer circuit breaker supplying power to the #1 Section Belt (HG 22). This circuit breaker is installed in the AEEI transformer/starter (serial #22908-1200-1005), located adjacent to spad #24120, between the #1 and #2 entries. The #1 Section Belt circuit breaker supplies power to two 150 H.P. motors. The motors have different disconnects.

The cited condition is located in an area affected by an explosion on 04.05.2010.

This citation is being issued to the following entities as a unitary

operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company. See Continuation Form (MSHA Form 7000-3a) 9. Violation B. Section C. Part/Section of A. Health Safety 🗸 of Act Title 30 CFR 75.900 Other Section II-Inspector's Evaluation 10. Gravity: Occurred A. Injury or Illness (has) (is): No Likelihood Unlikely 🗸 Reasonably Likely Highly Llkely B. Injury or illness could rea-No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling Fatal sonably be expected to be: D. Number of Persons Affected: C. Significant and Substantial: 001 Yes 🗌 No 🗸 11. Negligence (check one) C. Moderate D. High E. Reckless Disregard A. None B. Low Written Notice 12. Type of Action 13. Type of Issuance (check one) Citation Order -Safeguard 104(a)14. Initial Action F. Citation/ F. Dated Mo Da Yr Order Number A. Citation B. Order C. Safeguard D. Written Notice 15. Area or Equipment Mo Da Yr 16. Termination Due A. Date B. Time (24 Hr. Clock) 0800 01/05/2012 Section III-Termination Action 17. Action to Terminate Mo Da Yr 18. Terminated A. Date B. Time (24 Hr. Clock Section IV-Automated System Data 19. Type of Inspection 20. Event Number 21. Primary or Mill 4440348 E16 (activity code) 22. Signature 23. AR Number 23908 Patrick Alan Stanfield

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.