## Mine Citation/Order

## U.S. Department of Labor Mine Safety and Health Administration



Section I--Violation Data 3. Citation/ 2. Time (24 Hr. Clock) 1. Date Mo Da Yr 8258613 Order Number 0800 12/06/2011 5. Operator 4. Served To PERFORMANCE COAL COMPANY, et al Berman Cornett (Safety Director) 7. Mine ID 46-08436 UPPER BIG BRANCH MINE-SOUTH (Contractor) 8a. Written Notice (103g) 8. Condition or Practice

Terminations have not been made in the ends of the 4/0 high voltage cables (3) inside the enclosure of the AEEI (American Electric Equipment Inc. splitter serial # 22909-1005) as per the manufacturer's specification (3M). The shielding over the individual conductors is cut and does not extend to a ground. The high voltage splitter is located at crosscut #79 of the North Mains.

This splitter was energized on 04.05.2010. The area was affected by an explosion on 04.05.2010. The operator is issued a high number of similar citations, upon inspection of the underground electrical equipment, following the explosion.

This citation is being issued to the following entities as a unitary See Continuation Form (MSHA Form 7000-3a) C. Part/Section of 9. Violation B. Section A. Health Title 30 CFR 75.810 Safety 🗸 of Act Other Section II-Inspector's Evaluation 10. Gravity: Highly Llkely Occurred A. Injury or Illness (has) (is): No Likelihood Unlikely 🗸 Reasonably Likely B. Injury or illness could rea-Lost Workdays Or Restricted Duty 🗸 Permanently Disabling Fatal No Lost Workdays sonably be expected to be: D. Number of Persons Affected: C. Significant and Substantial: 001 No 🗸 Yes 🗀 11. Negligence (check one) C. Moderate E. Reckless Disregard A. None B. Low D. High 🗸 Written Notice Safeguard 12. Type of Action 13. Type of Issuance (check one) Citation 🗸 Order \_\_\_ 104(a) F. Dated Mo Da Yr E. Citation/ 14. Initial Action D. Written Notice Order Number A. Citation B. Order C. Safeguard 15. Area or Equipment Mo Da Yr 16. Termination Due A. Date B. Time (24 Hr. Clock) 0800 01/05/2012 Section III--Termination Action 17. Action to Terminate Mo Da Yr 18. Terminated A. Date B. Time (24 Hr. Clock Section IV-Automated System Data 19. Type of Inspection 21. Primary or Mill 20. Event Number 4440348 E16 (activity code) 23. AR Number 22. Signature Patrick Alan Stanfield 23908

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-F34-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

## Mine Citation/Order Continuation

## U.S. Department of Labor Mine Safety and Health Administration



Section I-Subsequent Action/Continuation Data				·			
1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Мо 12/0	Da )6/201	• • •	3. Citation/ Order Number	8258613	
4. Served To			5. Operator				
Berman Cornett (Safety Director)				PERFORMANCE COAL COMPANY, et al			
6. Mine				7. Mine II	16.0042	(Co	ntractor)
UPPER BIG BRANCH MINE-SOUTH				46-08436			
Section II Justification for Action							

Continuation of 8. Condition or Practice

operator: Performance Coal Company, Massey Coal Services, Inc., A.T. Massey Coal Company, Inc., and Massey Energy Company.

		See Continuation Form	n 🗌
Section IIISubsequent Action Taken			
8. Extended To A. Date Mo Da Y	B. Time (24 Hr. Clock)	C. Vacated D. Terminated E. Modified	
Section IVInspection Data			
9. Type of Inspection E16	Event Number 4440348		
11. Signature	AR Number 12.	. Date Mo Da Yr 13. Time (24 Hr. Clock)	
Patrick Alan Stanfield	23908	12/06/2011 0800	