

Appendix H – Violations Cited during Section 103(i) Spot Inspections at UBB

October 1, 2008 – April 5, 2010

Standard		Type Action		
		104(a)	104(d)(2)	Total
316(b) of Act	Accident preparedness and response	1		1
72.630(b)	Drill dust control	1		1
75.202(a)	Protection from falls of roof, face and ribs	4		4
75.211(d)	Roof testing and scaling	1		1
75.220(a)(1)	Roof control plan	4		4
75.310(a)(3)	Installation of main mine fans		1	1
75.312(g)(1)	Main mine fan examinations and records	1		1
75.325(b)	Air quantity	3		3
75.333(b)(1)	Ventilation controls		1	1
75.333(b)(3)	Ventilation controls	1		1
75.333(c)(2)	Ventilation controls	1		1
75.333(d)(2)	Ventilation controls	1		1
75.333(d)(3)	Ventilation controls	1		1
75.333(f)	Ventilation controls	1		1
75.333(h)	Ventilation controls	4		4
75.342(a)(4)	Methane monitors	1		1
75.350(a)	Belt air course ventilation		1	1
75.363(a)	Hazardous conditions; posting, correcting and recording	1		1
75.364(b)(5)	Weekly examination	1		1
75.370(a)(1)	Mine ventilation plan; submission and approval	5	1	6
75.380(d)(1)	Escapeways	1		1
75.380(d)(4)	Escapeways		1	1
75.380(d)(4)(iv)	Escapeways	1		1
75.380(d)(7)	Escapeways	2		2
75.380(d)(7)(iv)	Escapeways	2		2
75.381(c)(5)(i)	Escapeways	1		1
75.400	Accumulation of combustible materials		1	1
75.400-2	Cleanup program	1		1
75.604(b)	Permanent splicing of trailing cables	1		1
75.807	Installation of high-voltage transmission cables	1		1
75.1403	Other safeguards	3		3
75.1702	Smoking; prohibition	1		1
75.1702-1	Smoking programs	1		1
75.1725(a)	Machinery and equipment; operation and maintenance	1		1
77.1102	Warning signs; smoking and open flame	1		1
77.1109(e)	Quantity and location of firefighting equipment	1		1
Total		50	6	56