


Remote Control Best Practices

Tramming While Positioned Within The Turning Radius Of The Remote Control Continuous Miner Can Be Fatal



The pump motor should be de-energized, and all machine motion stopped, when the trailing cable or water line has to be repositioned in close proximity to the machine