

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 11/13/2010 08:15 AM		4. Date/Time of Death 11/13/2010 08:15 AM		5. Fatal Case No 20		
6. Mine Information :										
a) Mining Company Name Hutchins Sand & Gravel			b) Mine Name Hutchins Sand & Gravel			c) Parent of Mining Company Paul M Leighton				
7. Mine Location :		a) City Hutchins		b) County Dallas		c) State TX		8. Mine ID Number: 41-04611		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M		11. Number of Mine Employees:		a) Total 5	b) Underground 5	c) Open Pit/Quarry 5		d) Mill/Prep Plant 5		e) Other 5
12. Contractor Name: Dennis' Heavy Equipment Repair						13. Union NO		14. Contractor ID Number: A1494		
15. Contractor Address:		a) City Krum		b) County Denton		c) State TX		d) Zip Code 76249		
16. Number of Contractor Employees:		a) Total 1		b) Underground 1		c) Open Pit/Quarry 1		d) Mill/Prep Plant 1		e) Other 1
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 4		b) Contractor Employees: 1			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :		a) Name Dennis L. Speicher			b) Age 42					
c) Regular Job Title: Mechanic		d) Activity at Time of Accident: Mechanic <input checked="" type="checkbox"/> Contractor Employee								
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:		23		b) at the mine: 1		c) at activity (23d) 23		d) with Contractor 23		
25. Autopsy Performed: NO						26. Mine Telephone No.: (972) 225-3030				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was underneath a front-end loader checking a hydraulic leak when it rolled and struck him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Kawasaki			29. Model: 80ZV		
30. District: M5000 South Central		32. Field Office: Dallas TX			33. Event Number: 6546635
34. Accident Investigator: David Hamm		35. MSHA Person Notified: Mac Burriss		Date 11/13/2010	Time 08:38 A
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher			Date 11/15/2010
38. Reason For Amendment: Item #14					