

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 07/02/2013 12:15 PM		4. Date/Time of Death 07/02/2013 12:15 PM		5. Fatal Case No 10							
6. Mine Information :															
a) Mining Company Name Peabody Midwest Mining, LLC			b) Mine Name Wildcat Hills Mine-Underground			c) Parent of Mining Company Peabody Energy									
7. Mine Location : a) City Eldorado			b) County Saline		c) State IL		8. Mine ID Number: 11-03156		9. Union: NO						
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND		11. Number of Mine Employees:		a) Total 240	b) Underground 234	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other 6						
12. Contractor Name:					13. Union		14. Contractor ID Number:								
15. Contractor Address:			a) City		b) County		c) State		d) Zip Code						
16. Number of Contractor Employees:					a) Total	b) Underground	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other					
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 57		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident								20. Mining Height:							
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input checked="" type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches					
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility				6	0					
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1													
23. Victim Information :					a) Name Nathaniel Clarida		b) Age 35								
c) Regular Job Title: Continuous Miner Operator			d) Activity at Time of Accident: Continuous Miner Operator				<input checked="" type="checkbox"/> Mine Employee								
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days							
a) Total:	11	1	0	b) at the mine:	0	8	0	c) at activity (23d)	10	0	0	d) with Contractor	0	0	0
25. Autopsy Performed: If Yes, Location YES To be announced								26. Mine Telephone No.: (618) 273-8604							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
Fatal accident occurred 7/2/2013 when a battery powered coal hauler pinned a person between the battery end bumper and the coal rib in the last open crosscut between entry No. 4 and No. 5 of Unit No. 2 (MMU 003-0).

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Stamler			29. Model: BH 18 H			
30. District: C0800 Vincennes		32. Field Office: Benton IL			33. Event Number: 4253517	
34. Accident Investigator: Harry E. Wilcox			35. MSHA Person Notified: Steven Miller		Date 07/02/2013	Time 12:38 PM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Harry Wilcox			Date 07/02/2013	
38. Reason For Amendment:						