

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 10/05/2013 01:30 PM		4. Date/Time of Death 10/05/2013 01:59 PM		5. Fatal Case No 16		
6. Mine Information :										
a) Mining Company Name White County Coal, LLC			b) Mine Name Pattiki			c) Parent of Mining Company Alliance Resource Partners LP				
7. Mine Location :		a) City Carmi		b) County White		c) State IL		8. Mine ID Number: 11-03058		9. Union: NO
10. Primary Mineral Mined: BITUMINOUS			11. Number of Mine Employees:		a) Total 312	b) Underground 275	c) Open Pit/Quarry 27		d) Mill/Prep Plant 10	e) Other 10
12. Contractor Name:						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 18		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		5	5		
21. Nonfatal Injuries: 0			22. Fatal Injuries: 1							
23. Victim Information :										
a) Name Robert E. Smith					b) Age 47					
c) Regular Job Title: General Laborer			d) Activity at Time of Accident: Driving battery golf cart				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:	15	6	b) at the mine:	15	6	c) at activity (23d)	15	6	d) with Contractor	
25. Autopsy Performed: If Yes, Location YES Campbell Funeral home, Norris City, IL						26. Mine Telephone No.: (618) 382-2136				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was driving a battery powered golf cart (company number 7) along the second 48 travel way at cross cut number 6-5, traveling in an outby direction. The golf cart turned over on top of him pinning him under the golf cart. A miner traveling behind the victim in a diesel vehicle (company number 7359) tried to remove the victim but couldn't move the cart. He called for help on the radio on his vehicle, and when help arrived, he and another miner pried the cart up enough to pull the victim from the cart. No pulse was found, the victim was not breathing, and his abdomen was swollen. CPR was started and continued to the surface where a paramedic took over CPR.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model: GC15			
30. District: C0800 Vincennes		32. Field Office: Marion IL			33. Event Number: 4254623		
34. Accident Investigator: Larry D. Morris			35. MSHA Person Notified: Michael D. Rennie		Date 10/05/2013		Time 01:44 PM
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Larry D. Morris				Date 10/07/2013	
38. Reason For Amendment: Correct contractor data.							