

Preliminary Report of Accident



| | | | | | | | | | | | | |
|--|---|---|---|--|----------------|--|-------------------------|---|-------------------------|------------------|---|--------------------|
| 1. Accident Type: Fatal Injury | | 2. Accident Classification Powered Haulage | | 3. Date/Time of Accident 06/13/2013 01:34 PM | | 4. Date/Time of Death 06/13/2013 02:24 PM | | 5. Fatal Case No 9 | | | | |
| 6. Mine Information : | | | | | | | | | | | | |
| a) Mining Company Name Stevens Creek Quarry Inc | | | b) Mine Name Stevens Creek Quarry | | | c) Parent of Mining Company Richard Voss | | | | | | |
| 7. Mine Location : | | a) City Cupertino | | b) County Santa Clara | | c) State CA | | 8. Mine ID Number: 04-01676 | | 9. Union: YES | | |
| 10. Primary Mineral Mined: CRUSHED & BROKEN STONE MININ | | | 11. Number of Mine Employees: | | a) Total 16 | b) Underground 16 | c) Open Pit/Quarry 2 | | d) Mill/Prep Plant 2 | e) Other 14 | | |
| 12. Contractor Name: | | | | | | 13. Union | | 14. Contractor ID Number: | | | | |
| 15. Contractor Address: | | | | | | | | | | | | |
| a) City | | | b) County | | | c) State | | d) Zip Code | | | | |
| 16. Number of Contractor Employees: | | | | | | | | | | | | |
| a) Total | | b) Underground | | c) Open Pit/Quarry | | d) Mill/Prep Plant | | e) Other | | | | |
| 17. Number of Persons in Mine at Time of Accident: | | | | | | 18. Number of Persons Unaccounted For: | | | | | | |
| a) Mine Employees: 16 | | b) Contractor Employees: | | | | a) Mine Employees: 0 | | b) Contractor Employees: | | | | |
| 19) Location of Accident | | | | | | | | | 20. Mining Height: | | | |
| <input type="checkbox"/> 01-Underground | <input checked="" type="checkbox"/> 03-Open Pit | <input type="checkbox"/> 07-Advance Mining | <input type="checkbox"/> 30-Mill/Prep Plant | <input type="checkbox"/> Other (specify) | | | | | Feet | Inches | | |
| <input type="checkbox"/> 02-Surface at Underground | <input type="checkbox"/> 06-Dredge Mining | <input type="checkbox"/> 08-Retreat Mining | <input type="checkbox"/> 99-Office Facility | | | | | | | | | |
| 21. Nonfatal Injuries: | | | 22. Fatal Injuries: | | | 1 | | | | | | |
| 23. Victim Information : | | | | | | | | | | | | |
| a) Name Jose A. Gonzalez | | | | | b) Age 50 | | | | | | | |
| c) Regular Job Title: Mechanic | | | | d) Activity at Time of Accident: Operating haul truck | | | | <input checked="" type="checkbox"/> Mine Employee | | | | |
| 24. Experience : | | | | | | | | | | | | |
| Years Weeks Days | | | Years Weeks Days | | | Years Weeks Days | | | Years Weeks Days | | | |
| a) Total: | 15 | 15 | 5 | b) at the mine: | 15 | 15 | 5 | c) at activity (23d) | 15 | 15 | 5 | d) with Contractor |
| 25. Autopsy Performed: If Yes, Location NO | | | | | | 26. Mine Telephone No.: (408) 253-2512 | | | | | | |

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was operating a 35 ton articulated haul truck down a haul road. The truck went out of control and hit a berm, propelling it in the air. The truck came to a stop with the bed overturned and the cab upright. The victim was ejected from the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

| | | | | | | |
|--|--|---|---|--|------------------------------|-----------------|
| 28. Equipment Manufacturer: Volvo | | | 29. Model: A35D | | | |
| 30. District: M7000 Western | | 32. Field Office: Vacaville CA | | | 33. Event Number: 6592442 | |
| 34. Accident Investigator: Chad Hilde | | | 35. MSHA Person Notified: Patricia Borer | | Date 06/13/2013 | Time 02:46 P |
| 36. Type of Report: Initial | | 37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i> | | | Date 06/14/2013 | |
| 38. Reason For Amendment: | | | | | | |