PR001
16-Dec-13

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Falling, Rdling or Sliding Rock /Materl	12/13/2013 10:50 AM	12/13/2013 04:00 PM	21

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Brown Brothers Sand Company	Wittichen Stephen Plants	Brown Brothers Sand Company

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Junction City	Talbot	GA	09-00265	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
CONSTRUCTION SAND & GRAVEL M	7	0	3	3	1

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident: a) Mine Employees:	b) Contractor Employees:	18. Number of Persons Unaccounted For: a) Mine Employees:	b) Contractor Employees:
3	0	0	0

19) Location of Accident
- [ ] 01-Underground
- [x] 03-Open Pit
- [ ] 07-Advance Mining
- [ ] 30-Mill/Prep Plant
- [ ] Other (specify)
- [ ] 02-Surface at Underground
- [ ] 06-Dredge Mining
- [ ] 08-Retreat Mining
- [ ] 99-Office Facility

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
0	1

23. Victim Information : a) Name	b) Age
Paul D. Barnes	53

c) Regular Job Title:	d) Activity at Time of Accident:	[x] Mine Employee
Utility Worker	Standing on bank in pit	

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	19	7	0	b) at the mine:	19	7	0	c) at activity (23d)	19	7	0	d) with Contractor	0	0	0

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
YES	Atlanta, Georgia	(706) 269-3257

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was standing near the edge of a 27-foot bank when the bank collapsed engulfing him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:

30. District:	32. Field Office:	33. Event Number:
M3000 Southeastern	Macon GA	6644785

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Billy Randolph	Judith Etterer	12/13/2013	11:18 A

36. Type of Report:	37. Name of Preparer and Date Prepared:	Date
Initial	Mike Hancher MH	12/16/2013

38. Reason For Amendment: