

PR001
07-Apr-14

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Material		3. Date/Time of Accident 03/27/2014 09:00 AM		4. Date/Time of Death 03/30/2014		5. Fatal Case No 4							
6. Mine Information :															
a) Mining Company Name Baillio Sand Company Inc			b) Mine Name LORD FARM #5			c) Parent of Mining Company John M Baillio									
7. Mine Location :		a) City Virginia Beach		b) County Virginia Beach (City)		c) State VA		8. Mine ID Number: 44-06068		9. Union: NO					
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M			11. Number of Mine Employees:		a) Total 3	b) Underground 0	c) Open Pit/Quarry 3	d) Mill/Prep Plant 0	e) Other 0						
12. Contractor Name:						13. Union		14. Contractor ID Number:							
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code							
16. Number of Contractor Employees:															
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other											
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees:		b) Contractor Employees:		a) Mine Employees:		b) Contractor Employees:									
3		0		0		0									
19) Location of Accident									20. Mining Height:						
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)					Feet	Inches					
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility												
21. Nonfatal Injuries:			22. Fatal Injuries:												
			1												
23. Victim Information :															
a) Name Robert J. Devich					b) Age 64										
c) Regular Job Title: Foreman				d) Activity at Time of Accident: Moving slurry pipe				<input checked="" type="checkbox"/> Mine Employee							
24. Experience :	Years		Weeks		Days		Years		Weeks		Days				
a) Total:	32	0	0	b) at the mine:	32	0	0	c) at activity (23d)	32	0	0	d) with Contractor	0	0	0
25. Autopsy Performed: If Yes, Location YES Norfolk, VA								26. Mine Telephone No : (754) 477-0114							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The miner was seriously injured when he was struck by a section of plastic water pipe as it was being moved by an excavator. The victim was transported to a hospital where he died three days later as a result of his injuries.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Daewoo			29. Model: DH220LC				
30. District: M2000 Northeastern		32. Field Office: Staunton VA			33. Event Number: 0822859		
34. Accident Investigator: Gary C. Merwine			35. MSHA Person Notified: Joseph H. Bosley		Date 04/03/2014		Time 08:00 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>			Date 04/04/2014		
38. Reason For Amendment:							