

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification: Machinery		3. Date/Time of Accident: 04/17/2014 04:00 PM		4. Date/Time of Death: 04/17/2014 04:00 PM		5. Fatal Case No: 7		
6. Mine Information :										
a) Mining Company Name: Hafenstine Construction			b) Mine Name: Hafenstine Plant #1			c) Parent of Mining Company: Donald P. Hafenstine				
7. Mine Location :		a) City: Alma		b) County: Wabaunsee		c) State: KS		8. Mine ID Number: 14-01708		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M		11. Number of Mine Employees:		a) Total: 5	b) Underground: 0	c) Open Pit/Quarry: 4		d) Mill/Prep Plant: 0	e) Other: 1	
12. Contractor Name:						13. Union:		14. Contractor ID Number:		
15. Contractor Address:		a) City:		b) County:		c) State:		d) Zip Code:		
16. Number of Contractor Employees:										
a) Total:		b) Underground:		c) Open Pit/Quarry:		d) Mill/Prep Plant:		e) Other:		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 3		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet	Inches	
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name: Harold Steege			b) Age: 58							
c) Regular Job Title: Truck Driver				d) Activity at Time of Accident: Walking near haul truck				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days	
a) Total:		4 26 0	b) at the mine:		4 26 0	c) at activity (23d):		4 26 0	d) with Contractor	
25. Autopsy Performed: If Yes, Location YES Topeka, KS						26. Mine Telephone No.: (785) 765-3580				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
An excavator was loading material in a haul truck parked in the pit. When the victim exited the truck, he was struck by the bucket of the excavator and pinned against the truck.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 320L		
30. District: M6000 Rocky Mountain		32. Field Office: Topeka KS			33. Event Number: 6618583
34. Accident Investigator: Lee A. Hughes			35. MSHA Person Notified: Kenneth Valentine		Date: 04/17/2014
					Time: 04:02 P
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date: 04/18/2014
38. Reason For Amendment: Item #24 a,b,c					