

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 05/09/2014 09:30 PM		4. Date/Time of Death 05/09/2014 10:20 PM		5. Fatal Case No 12		
6. Mine Information :										
a) Mining Company Name Mississippi Sand, LLC			b) Mine Name Mississippi Sand Seagraves			c) Parent of Mining Company Cemtech International Inc; Synergy Materials Inc				
7. Mine Location :		a) City Seagraves		b) County Gaines		c) State TX		8. Mine ID Number: 41-05004		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M		11. Number of Mine Employees:		a) Total 19	b) Underground 0	c) Open Pit/Quarry 0	d) Mill/Prep Plant 18		e) Other 1	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:		a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant		e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 6		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries:		22. Fatal Injuries:			1					
23. Victim Information :				a) Name Miguel A. Nino		b) Age 20				
c) Regular Job Title: Groundman			d) Activity at Time of Accident: Rail loadout			<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:		9	4	b) at the mine:		9	4	c) at activity (23d)		
d) with Contractor		9	4							
25. Autopsy Performed: If Yes, Location YES South Plains Pathology, Lubbock, TX						26. Mine Telephone No.: (432) 847-2788				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was unloading a rail car using a mobile rail barge truck conveyor and was entangled in the feed end of the conveyor.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Wilson Mfg			29. Model: 342d		
30. District: M5000 South Central		32. Field Office: Carlsbad NM			33. Event Number: 6609041
34. Accident Investigator: Laurence M. Dunlap			35. MSHA Person Notified: David L. Weaver		Date 05/09/2014
					Time 09:46 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>			Date 05/12/2014
38. Reason For Amendment:					