

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Hoisting		3. Date/Time of Accident 06/02/2014 01:30 PM		4. Date/Time of Death 06/02/2014 01:30 PM		5. Fatal Case No 13				
6. Mine Information :												
a) Mining Company Name Silver Opportunity Partners LLC			b) Mine Name Sunshine Mine			c) Parent of Mining Company Sunshine Silver Mines Corp						
7. Mine Location :		a) City Kellogg		b) County Shoshone		c) State ID		8. Mine ID Number: 10-00089		9. Union: NO		
10. Primary Mineral Mined: SILVER ORE MINING, N.E.C.			11. Number of Mine Employees:	a) Total 29	b) Underground 6	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other 23			
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:				a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total	b) Underground	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other				
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:						
a) Mine Employees: 23		b) Contractor Employees: 0		a) Mine Employees: 0		b) Contractor Employees: 0						
19) Location of Accident									20. Mining Height:			
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 04-Dredge Mining	<input type="checkbox"/> 05-Advance Mining	<input type="checkbox"/> 06-Retreat Mining	<input type="checkbox"/> 07-Mill/Prep Plant	<input type="checkbox"/> 08-Office Facility	<input type="checkbox"/> Other (specify)	Feet Inches			
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1										
23. Victim Information :												
a) Name Nicholas P. Rounds				b) Age 36								
c) Regular Job Title: Shaft Repairman				d) Activity at Time of Accident: Shaft Repair				<input checked="" type="checkbox"/> Mine Employee				
24. Experience :	Years Weeks Days		Years Weeks Days			Years Weeks Days			Years Weeks Days			
a) Total:	18	14	1	b) at the mine:	1	14	1	c) at activity (23d):	1	14	1	d) with Contractor
25. Autopsy Performed: NO						26. Mine Telephone No.: (208) 783-1659						

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

Two miners were working in a shaft standing on a work platform attached to a skip. The skip moved and the victim was crushed between the skip and the shaft timber.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:				
30. District: M7000 Western		32. Field Office: Boise ID				33. Event Number: 6594753		
34. Accident Investigator: Steven Kidwell			35. MSHA Person Notified: James Fitch			Date 06/02/2014		Time 03:03 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>				Date 06/03/2014		
38. Reason For Amendment:								