PR001
25-Nov-14

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Falling, Rolling or Sliding Rock /Materl	11/18/2014 12:10 PM	11/18/2014 01:05 PM	21

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Alcoa World Alumina LLC	Bayer Alumina Plant	Alcoa Inc

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Point Comfort	Calhoun	TX	41-00320	YES

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
ALUMINA MILLING	697			457	240

12. Contractor Name:	13. Union	14. Contractor ID Number:
Turner Industries Group LLC	NO	HPQ

15. Contractor Address: a) City	b) County	c) State	d) Zip Code
Baton Rouge	East Baton Rouge	LA	70805

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
318			318	

17. Number of Persons in Mine at Time of Accident:		18. Number of Persons Unaccounted For:	
a) Mine Employees: 429	b) Contractor Employees: 318	a) Mine Employees: 0	b) Contractor Employees: 0

19) Location of Accident

- [ ] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [ ] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [x] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries:	22. Fatal Injuries:
0	1

23. Victim Information : a) Name	b) Age
Jerry McClelland	42

c) Regular Job Title:	d) Activity at Time of Accident:	
Job Site Supervisor	Installing Tank Door	[x] Contractor Employee

24. Experience :	Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days		Years	Weeks	Days
a) Total:	19	23	3	b) at the mine:	0	15	5	c) at activity (23d)	0	7	2	d) with Contractor	19	23	3

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
NO		(361) 987-6948

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A crane was lifting a 2,500 pound door to be installed on a filtrate tank. The welded pad eye on the door broke loose and the door fell, pinning the victim on the concrete floor.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:

30. District:	32. Field Office:	33. Event Number:
M5000 South Central	San Antonio TX	6652599

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Mark Williams	James T. Murph	11/18/2014	12:23 P

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Amended	Mike Hancher MH	11/20/2014

38. Reason For Amendment:

Items No. 12, 14