



Section I--Violation Data

1. Date Mo Da Yr 07/24/2008	2. Time (24 Hr. Clock) 1200	3. Citation/ Order Number 7018226
4. Served To Gary Peacock	5. Operator GENWAL RESOURCES INC and UEI	
6. Mine CRANDALL CANYON MINE	7. Mine ID 42-01715 (Contractor)	
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

30 CFR 50.20(a) requires that the mine operator mail a completed 7000-1 form to MSHA within 10 days after an accident occurs. The mine operator failed to submit this form for a coal outburst accident that occurred on August 3, 2007 in the Main West South Barrier section. Company records indicated that the coal outburst interrupted regular mining activity for more than one hour. The event threw coal into the mine opening, knocked a miner down and damaged a ventilation control.

See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input type="checkbox"/> Other <input checked="" type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 50.20(a)
--------------	--	-------------------	---

Section II--Inspector's Evaluation

10. Gravity:				
A. Injury or Illness (has) (is): No Likelihood <input checked="" type="checkbox"/> Unlikely <input type="checkbox"/> Reasonably Likely <input type="checkbox"/> Highly Likely <input type="checkbox"/> Occurred <input type="checkbox"/>				
B. Injury or illness could reasonably be expected to be: No Lost Workdays <input checked="" type="checkbox"/> Lost Workdays Or Restricted Duty <input type="checkbox"/> Permanently Disabling <input type="checkbox"/> Fatal <input type="checkbox"/>				
C. Significant and Substantial: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>				D. Number of Persons Affected: 000
11. Negligence (check one) A. None <input type="checkbox"/> B. Low <input type="checkbox"/> C. Moderate <input checked="" type="checkbox"/> D. High <input type="checkbox"/> E. Reckless Disregard <input type="checkbox"/>				
12. Type of Action 104(a)		13. Type of Issuance (check one) Citation <input checked="" type="checkbox"/> Order <input type="checkbox"/> Safeguard <input type="checkbox"/>		
14. Initial Action A. Citation <input type="checkbox"/> B. Order <input type="checkbox"/> C. Safeguard <input type="checkbox"/> D. Written Notice <input type="checkbox"/>			E. Citation/ Order Number	F. Dated Mo Da Yr
15. Area or Equipment				

16. Termination Due	A. Date Mo Da Yr 07/28/2008	B. Time (24 Hr. Clock) 1200
---------------------	-----------------------------------	--------------------------------

Section III--Termination Action

17. Action to Terminate		
18. Terminated	A. Date Mo Da Yr	B. Time (24 Hr. Clock)

Section IV--Automated System Data

19. Type of Inspection (activity code) E16	20. Event Number 4011361	21. Primary or Mill
22. Signature Signature		23. AR Number 23709/23305

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I—Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 07/24/2008	3. Citation/ Order Number 7018226 - 01
4. Served To Gary Peacock	5. Operator GENWAL RESOURCES INC and UEI (Contractor)	
6. Mine CRANDALL CANYON MINE	7. Mine ID 42-01715	

Section II—Justification for Action

The operator submitted a completed 7000-1 form to MSHA for the coal outburst accident that occurred on August 3, 2007.

See Continuation Form

Section III—Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	---------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV—Inspection Data

9. Type of Inspection E16	10. Event Number 4011361		
11. Signature Signature	AR Number 23709	12. Date Mo Da Yr 08/06/2008	13. Time (24 Hr. Clock) 1234