

✓
Crandall General Mine

**PRESHIFT/ON-SHIFT REPORT
FOR
GENERAL MINE**

GENWAL

Mine Name

ID Number

SECTION / AREA

2MSHA02978

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-8-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 800 AM/PM AM END 917 AM/PM PM Examiners Initials DD
 TIME OF EXAMINATION START 740 AM/PM AM END 930 AM/PM PM Examiners Initials R/KK
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	ok	none observed	
Main Haulage North seals	20.9	0	0	DD	ok	none observed	
Main west Haulage seals	20.9	0	0	R/KR	ok	none observed	
3rd North Haulage seals	20.9	0	0	DD	ok	none observed	
1st Right Haulage seals	20.9	0	0	DD	ok	none observed	
TRANS.	20.9	0	0	R/KR	ok	none observed	
chargers	20.9	0	0	R/KR	ok	none obs.	
Storage Area	20.9	0	0	DD	ok	none observed	
wash down	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 7735

2MSHA02979

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-9-07

SECTION/AREA General 1

TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 4:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:35 AM/PM
 END 5:40 AM/PM
 END _____ AM/PM

Examiners Initials RL/KL
 Examiners Initials RL
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>midwest haulage seals</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>M. West haulage seals</u>	<u>20.9</u>	<u>θ</u>	<u>0</u>	<u>RL/KL</u>	<u>α</u>	<u>none obs</u>	
<u>3 west haulage seals</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none observed</u>	
<u>1st right haulage</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none obs</u>	
<u>storage area</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none</u>	
<u>warehouse</u>	<u>20.9</u>	<u>α</u>	<u>α</u>	<u>RL</u>	<u>α</u>	<u>none</u>	
<u>Trams</u>	<u>20.9</u>	<u>θ</u>	<u>0</u>	<u>RL/KL</u>	<u>α</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>θ</u>	<u>0</u>	<u>RL/KL</u>	<u>α</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
 PRE-SHIFT/MINE EXAMINER CERT. # 4375
 PRE-SHIFT/MINE EXAMINER CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7375

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-9-07 SECTION/AREA Gem Mine 1 / /

TIME OF EXAMINATION START 11:51 AM/PM END 1:03 AM/PM Examiners Initials mc
 TIME OF EXAMINATION START 11:50 AM/PM END 12:40 AM/PM Examiners Initials LD
 TIME OF EXAMINATION START 11:30 AM/PM END 1:37 AM/PM Examiners Initials DD

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	mc	ok	none observed	
Main North Haulage Seals	20.9	0	0	mc	ok	none observed	
Main West Haulage Seals	20.9	0	0	mc LD/DD	ok	none obs.	
3 rd North Haulage Seals	20.9	0	0	mc	ok	none observed	
1 st Right Haulage	20.9	0	0	mc	ok	none observed	
Transformers	20.9	0	0	mc LD/DD	ok	none obs.	
Chargers	20.9	0	0	mc/LD	ok	none observed	
Storage Area	20.9	0	0	DD	ok	none obs.	
Washdown	20.9	0	0	DD	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7325
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 8058
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7375

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-9-07 SECTION/AREA Pen Mine 1

TIME OF EXAMINATION START 9:00 AM/PM AM END 9:40 AM/PM AM Examiners Initials RL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____
 CALLED OUT BY _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	RL	OK	none	
North Main Haulage Seals	21	0	0	RL	OK	none observed	
Main West Haulage Seals	21	0	0	KK/BR	OK	none obs	
3rd North Haulage Seals	21	0	0	RL	OK	none observed	
1st Right	21	0	0	RL	OK	none observed	
Storage area	21	0	0	RL	OK	none observed	
Washdown	21	0	0	RL	OK	none observed	
Transformers	21	0	0	KK/BR	OK	none obs	
Chargers	21	0	0	KK/BR	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-10-07

SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 345 AM/PM
 TIME OF EXAMINATION START 300 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:00 AM/PM
 END 540 AM/PM
 END _____ AM/PM

Examiners Initials LR
 Examiners Initials KR/RL
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None observed	
Main North ^{Haulage} Seals	20.9	0	0	LR	OK	None observed	
Main West ^{Haulage} Seals	20.9	0	0	R ^L KR/RL	OK	None	
3 rd North ^{Haulage} Seals	20.9	0	0	LR	OK	None observed	
1 st Right	20.9	0	0	LR	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Washdown Area	20.9	0	0	LR	OK	None observed	
Turnstems	20.9	0	0	R ^L KR/RL	OK	None	
Chargers	20.9	0	0	R ^L KR/RL	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-10-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 12:32 AM/PM
 TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:58 AM/PM
 END 1:45 AM/PM
 END _____ AM/PM

Examiners Initials P2
 Examiners Initials mc/DD
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None Observed	
Main North seals ^{Haulage}	20.9	0	0	PL	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	mc/DD	OK	none observed	
1st Right	20.9	0	0	mc/DD	OK	none observed	
Transformers	20.9	0	0	PL/mc/DD	OK	none observed	
Chargers	20.9	0	0	mc/DD	OK	none observed	
Wash down	20.9	0	0	DD	OK	none observed	
Storage area	20.9	0	0	DD	OK	none observed	
3rd North seals ^{Haulage}	20.9	0	0	mc/DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam.

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8462
 CERT. # 7375
 CERT. # 8058
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-10-07 SECTION/AREA 2m/11/1

TIME OF EXAMINATION START 7:51 AM/PM (P) END 9:05 AM/PM (P) Examiners Initials KK
 TIME OF EXAMINATION START 7:10 AM/PM (P) END 9:30 AM/PM (P) Examiners Initials LR/RL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>in North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>in West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/RL</u>	<u>α</u>	<u>none obs.</u>	
<u>3rd flight Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>1st flight</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none obs.</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/RL</u>	<u>α</u>	<u>none obs.</u>	
<u>Charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/RL</u>	<u>α</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4373
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 4373

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-11-07 SECTION/AREA Geoffrey 1

TIME OF EXAMINATION START 3:49 (AM/PM) END 5:10 (AM/PM) Examiners Initials KK
 TIME OF EXAMINATION START 3:15 (AM/PM) END 5:35 (AM/PM) Examiners Initials KYR/RL
 TIME OF EXAMINATION START _____ (AM/PM) END _____ (AM/PM) Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	α	none obs	
M. North haulage seals	20.9	0	0	KK	α	none obs	
M. West haulage seals	20.9	0	0	KYR/RL	α	none obs	
S. North haulage seals	20.9	0	0	KK	α	none obs	
1 st flight	20.9	0	0	KK	α	none obs	
Storage area	20.9	0	0	KK	α	none obs	
Washdown	20.9	0	0	KK	α	none obs	
Trains 1	20.9	0	0	KK	α	none obs	
chargers	20.9	0	0	KK	α	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
 PRE-SHIFT/MINE EXAMINER CERT. # 4325
 PRE-SHIFT/MINE EXAMINER CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892 2MSHA02986

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6.11-07

SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:52 AM/PM
 TIME OF EXAMINATION START 11:40 AM/PM
 TIME OF EXAMINATION START 12:00 AM/PM

END 1:05 AM/PM
 END 1:30 AM/PM
 END 12:40 AM/PM

Examiners Initials FM
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North haulage seals	20.9	0	0	FM	OK	none observed	
Main West haulage seals	20.9	0	0	FM BH/TC	OK	None Observed	
3rd North haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM BH/TC	OK	None Observed	
chargers	20.9	0	0	FM BH/TC	OK	None Observed	
Storage Area	20.9	0	0	FM	OK	none observed	
wash down	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER CERT. # 6325
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03897

2MSHA02987

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-11-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 7:40 AM/PM
 TIME OF EXAMINATION START 8:35 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 9:10 AM/PM
 END 9:15 AM/PM
 END _____ AM/PM

Examiners Initials SW
 Examiners Initials LD
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	oil acc. under #3 mainrip	dusted 6/11/07
Main North ^{seals} haulage	21.0	0	0	SW	OK	none observed	
Main ^{seals} west haulage				SW	OK	none observed	
3rd North ^{seals} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	
Transformers	20.9	0	0	SW	OK	none observed	
chargers	20.9	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINE **Signature** CERT. # 9548
 PRE-SHIFT/MINE EXAMINE CERT. # 9660
 PRE-SHIFT/MINE EXAMINE CERT. # _____
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6/20/07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 3 AM/PM END 3:40 AM/PM Examiners Initials SW
 TIME OF EXAMINATION START 3:20 AM/PM END 4:35 AM/PM Examiners Initials SW
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
46 Parking	21.0	0	0	SW	OK	none observed	
Main Seeds North Haulage	21.0	0	0	SW	OK	none observed	
Main Seeds Pumps West Haulages	20.9	0	.2	SW	OK	none observed	
3rd No Haulage Seeds	21.0	0	0	SW	OK	none observed	
15 Right	21.0	0	0	SW	OK	none observed	
Storage area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dy	OK	None observed	
Transformers	20.9	0	0	SW	OK	none observed	
Chargers	20.9	0	.1	SW	OK	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel at time of exam.

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 6692
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-12-07 SECTION/AREA Bermine / /

TIME OF EXAMINATION START 11:00 AM/PM AM END 12:03 AM/PM PM Examiners Initials MC
 TIME OF EXAMINATION START 11:45 AM/PM AM END 1:38 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START 11:45 AM/PM AM END 1:15 AM/PM PM Examiners Initials TC

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
main north Haulage seals	20.9	0	0	MC	OK	none observed	
main west Haulage seals	20.9	0	0	MC/BH/TC	OK	None Observed	
3 rd North Haulage seals	20.9	0	0	MC	OK	none observed	
1 st Right Haulage	20.9	0	0	MC	OK	none observed	
TR Aux Pannels	20.9	0	0	MC/BH/TC	OK	None Observed	
Ch. Regres	20.9	0	0	MC/BH/TC	OK	None Observed	
Storage Area	20.9	0	0	TC	OK	None observed	
wash down	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03992

2MSHA02990

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-12-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:55
 TIME OF EXAMINATION START 8:45
 TIME OF EXAMINATION START _____

AM/PM AM/PM
 AM/PM AM/PM
 AM/PM _____

END 9:20 AM/PM
 END 9:40 AM/PM
 END _____ AM/PM

Examiners Initials SW
 Examiners Initials LD
 Examiners Initials _____

EXAM. CALLED OUT YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SCAB} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SCAB} haulage				LD SW	OK	timber knocked out XC 127, 125	SENT MEN TO RE-SET Done LD
3rd North ^{SCAB} haulage	21.0	0	0	SW	OK	none observed	
1st Right haulage	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	LD SW	OK	none observed	
chargers	20.9	0	0	LD SW	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West	Section Chargers, Dust	Rock Dusted

PRE-SHIFT REMARKS all areas appeared safe at the time of exam except those noted above

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA02991

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-13-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 3:05 AM/PM
 TIME OF EXAMINATION START 3 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 4:25 AM/PM
 END 7:30 AM/PM
 END _____ AM/PM

Examiners Initials SW
 Examiners Initials dg
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{slab} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{sub} haulage	20.9	0	.1	SW dg	OK	none observed	
3rd North ^{slab} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW dg	OK	none observed	
chargers	20.9	0	0	SW dg	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dg	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at
Time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA02992

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6.13.07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:56 ~~AM/PM~~ END 1:08 ~~AM/PM~~ Examiners Initials FM
 TIME OF EXAMINATION START 11:45 ~~AM/PM~~ END 1:38 ~~AM/PM~~ Examiners Initials BH
 TIME OF EXAMINATION START 11:50 ~~AM/PM~~ END 1:40 ~~AM/PM~~ Examiners Initials TC

EXAM. CALLED OUT YES/NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	FM BHTC	OK	None observed	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM BHTC	OK	None observed	
chargers	20.9	0	0	FM BHTC	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	
Wash down	20.9	0	0	TC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 08892

2MSHA02993

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-13-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:10
 TIME OF EXAMINATION START 7:12
 TIME OF EXAMINATION START _____

AM/PM (AM) END 8:20 AM/PM (PM)
 AM/PM (PM) END 7:40 AM/PM (PM)
 AM/PM _____ END _____ AM/PM _____

Examiners Initials SW
 Examiners Initials dg
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{Subs} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{Subs} haulage	20.9	0	0	SW dg	OK	none observed	
3rd North ^{Subs} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW dg	OK	none observed	
Chargers	20.9	0	0	SW dg	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dg	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appears safe at
Time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7480

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6/4/07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:00 ~~AM~~/PM END 4:25 ~~AM~~/PM Examiners Initials SW
 TIME OF EXAMINATION START 3:00 ~~AM~~/PM END 5:10 ~~AM~~/PM Examiners Initials LD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
ag Paeking	21.0	0	0	SW	OK	none observed	
Main Seals	21.0	0	0	SW	OK	dusty roadways	watered 6-14-07
North Haulage				LD SW	OK	deep water at 38 # haulage	pumped 6-14-07
Main Pump Seals				LD SW	OK		
West Haulage	21.0	0	0	SW	OK	needs water roadway	watered 6-14-07
3rd No Haulage	21.0	0	0	SW	OK	none observed	
1st Right				LD SW	OK	none observed	
Transformers				LD SW	OK	none observed	
chargers				LD SW	OK	none observed	
Storage area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	LD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-14-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 12:03 AM/PM AM END 1:27 AM/PM PM Examiners Initials FM
 TIME OF EXAMINATION START 12:00 AM/PM AM END 1:30 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 11:55 AM/PM AM END 1:40 AM/PM PM Examiners Initials BH

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North haulage seals	20.9	0	0	FM	B	None observed	
Main West haulage seals	20.9	0	0	FM BH TC	OK	None obs.	
3 rd North haulage seals	20.9	0	0	FM	OK	None observed	
1 st Right	20.9	0	0	FM	B	None observed	
Transformers	20.9	0	0	FM TC BH	OK	None obs.	
Chargers	20.9	0	0	FM TC	OK	None obs.	
Storage Area	20.9	0	0	FM	OK	None observed	
Wash down	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8397
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA02996

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-14-07

SECTION/AREA General 1 Mine 1 1

TIME OF EXAMINATION START 7:45
 TIME OF EXAMINATION START 8:30
 TIME OF EXAMINATION START _____

AM/PM AM END 9:20 AM/PM PM
 AM/PM PM END 9:20 AM/PM PM
 AM/PM _____ END _____ AM/PM _____

Examiners Initials SW
 Examiners Initials JD
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (0)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage ^{seals}	21.0	0	0	SW	OK	none observed	
Main West haulage ^{seals}	20.9	0	0	SW JD	OK	none observed	
3rd North haulage ^{seals}	21.0	0	0	SW	OK	gob plus need dust	SENT MKN TO DOST
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW JD	OK	none observed	
chargers	20.9	0	0	SW JD	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	JD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam. except those noted above

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7488

2MSHA02997

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-15-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 3 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 4:25 AM/PM
 END 3:40 AM/PM
 END _____ AM/PM

Examiners Initials dy
 Examiners Initials dy
 Examiners Initials _____

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SEATS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SEATS} haulage	20.9	0	0.2	SW dy	OK	none observed	
3 rd North ^{SEATS} haulage	21.0	0	0	SW	OK	none observed	
1 st Right.	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW dy	OK	none observed	
chargers	20.9	0	0	SW dy	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	20.9	0	0	dy	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

Main West

LOCATIONS	HAZARDS	ACTIONS
chargers (3)	Trash	cleaned & dusted

PRE-SHIFT REMARKS all areas examined appear safe at time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA02998

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6.15.07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:49 ~~AM~~/PM END 1:05 ~~AM~~/PM Examiners Initials EM
 TIME OF EXAMINATION START 11:30 ~~AM~~/PM END 1:30 ~~AM~~/PM Examiners Initials DD mc
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	EM	OK	NONE observed	
MAIN North haulage seals	20.9	0	0	EM	OK	NONE observed	
MAIN West haulage seals	20.9	0	0	DD/mc	OK	none observed	
3rd North haulage seals	20.9	0	0	EM	OK	NONE observed	
1st Right	20.9	0	0	EM	OK	NONE observed	
Transformers	20.9	0	0	EM/DD/mc	OK	none observed	
chargers	20.9	0	0	EM/DD/mc	OK	none observed	
Storage Area	20.9	0	0	DD	OK	none observed	
Washdown	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8397
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 875
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR _____ Signature _____ CERT. # 8462

2MSHA02999

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-15-07

SECTION/AREA Penitentiary

TIME OF EXAMINATION
 TIME OF EXAMINATION
 TIME OF EXAMINATION

START 7:55
 START 7:15
 START _____

AM/PM (AM)
 AM/PM (AM)
 AM/PM _____

END 8:30 AM/PM (AM)
 END 9:35 AM/PM (AM)
 END _____ AM/PM _____

Examiners Initials AL
 Examiners Initials BT/BR
 Examiners Initials _____

EXAM. CALLED OUT --- YES/NO X

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RL	OK	none observed	
Main North Seal	21	0	0	RL	OK	none obs.	
Main West Seal	21	0	0	RL/NA	OK	none obs	
3rd North Seal	21	0	0	RL	OK	none observed	
1st Light	21	0	0	RL	OK	none observed	
Transformers	21	0	0	RL/NA	OK	none obs.	
Chargers	21	0	0	RL/NA	OK	None obs	
Storage Area	21	0	0	RL	OK	none obs.	
Workdown	21	0	0	RL	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at
time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7951
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4373
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-16-07 SECTION/AREA Gen. Mine 1 1

TIME OF EXAMINATION START 305 AM/PM END 430 AM/PM Examiners Initials LR
 TIME OF EXAMINATION START 305 AM/PM END 382 AM/PM Examiners Initials LR
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None observed	
Main North Haulage Seals	20.9	0	0	LR	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/KK RL	OK	None observed	
3 rd North Haulage Seals	20.9	0	0	LR	OK	None observed	
1 st Right	20.9	0	0	LR	OK	None observed	
Tramway	20.9	0	0	LR/KK RL	OK	None observed	
Chargers	20.9	0	0	LR/KK RL	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Washdown	20.9	0	0	LR	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6701
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8262

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-16-07

SECTION/AREA Gen. Mine 1

TIME OF EXAMINATION START 11:15 AM/PM
 TIME OF EXAMINATION START 12:30 AM/PM
 TIME OF EXAMINATION START 11:35 AM/PM

END 11:48 AM/PM
 END 12:45 AM/PM
 END 1:36 AM/PM

Examiners Initials R
 Examiners Initials PC
 Examiners Initials mc/DD

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	OK	None Observed	
Main North <small>Harlage Seals</small>	20.9	0	0	PC	OK	None Observed	
Main West <small>Harlage Seals</small>	20.9	0	0	mc/DD	OK	None Observed	
3rd North <small>Harlage Seals</small>	20.9	0	0	R	OK	None Observed	
1st Right	20.9	0	0	R	OK	None Observed	
Transformers	20.9	0	0	R mc PC/DD	OK	None Observed	
Chargers	20.9	0	0	mc/DD	OK	None Observed	
Storage Area	20.9	0	0	DD	OK	None Observed	
Washdown	20.9	0	0	DD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe
at time of pre-shift

Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9293
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7575
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03002

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6/6/07 SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 735 AM/PM AM END 845 AM/PM PM Examiners Initials LR
 TIME OF EXAMINATION START 730 AM/PM AM END 750 AM/PM PM Examiners Initials KK/RL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None observed	
Main North Haulage Seals	20.9	0	0	LR	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/KK RL	OK	None obs.	
3 rd North Haulage Seals	20.9	0	0	LR	OK	None observed	
1 st Right	20.9	0	0	LR	OK	None observed	
TRANS Sump	20.9	0	0	LR/KK RL	OK	None observed	
Chargers	20.9	0	0	LR/KK RL	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Wash down Area	20.9	0	0	LR	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 7259
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # _____

COUNTER SIGNATURE _____ CERT. # 4375

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-17-01

SECTION/AREA 2m/11m

TIME OF EXAMINATION START 3:40 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:35 AM/PM
 END 4:00 AM/PM
 END _____ AM/PM

Examiners Initials XX/LC
 Examiners Initials RC
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>α</u>	<u>none observed</u>	
<u>M. North Hauling seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>α</u>	<u>none observed</u>	
<u>M. West Hauling seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>α</u>	<u>none obs.</u>	
<u>3 West Hauling seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>α</u>	<u>none obs</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>α</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>α</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR</u>	<u>α</u>	<u>none obs</u>	
<u>Travis</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>α</u>	<u>none obs</u>	
<u>charger</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>LR/KK</u>	<u>α</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift.

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954
 CERT. # 4375
 CERT. # 6800
 CERT. # _____

Signature

COUNTER SIGNATUR

CERT. # 8462

2MSHA03004

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-17-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 12:00 AM/PM AM
 TIME OF EXAMINATION START 1:00 AM/PM AM
 TIME OF EXAMINATION START _____ AM/PM _____

END 12:49 AM/PM AM
 END 1:20 AM/PM AM
 END _____ AM/PM _____

Examiners Initials PC
 Examiners Initials DDmc
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	PC	ok	None Observed	
^{Haulage} Main North seals	20.9	0	0	PC	ok	None Observed	
^{Haulage} Main West seals	20.9	0	0	DD/mc	ok	none obs.	
^{Haulage} 3 rd North seals	20.9	0	0	PC	ok	None Observed	
1 st right	20.9	0	0	PC	ok	None Observed	
Transformers	20.9	0	0	DD/mc	ok	none obs.	
Storage area	20.9	0	0	DD	ok	none obs.	
Wash down	20.9	0	0	DD	ok	none obs.	
Chargers	20.9	0	0	DD/mc	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe
At time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 2462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 2462

2MSHA03005

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-17-07

SECTION/AREA Pen Mine 1

TIME OF EXAMINATION
TIME OF EXAMINATION
TIME OF EXAMINATION

START 750 AM/PM
START 700 AM/PM
START _____ AM/PM

END 945 AM/PM
END 945 AM/PM
END _____ AM/PM

Examiners Initials RL
Examiners Initials RL
Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>Main North Hoopage Seals</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>Main West Hoopage Seals</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>3rd North Hoopage Seals</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>1st Right</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>Storage Area</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>Waterdown</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>0</u>	<u>none obs.</u>	
<u>Transformers</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL/KK/RR</u>	<u>0</u>	<u>none obs.</u>	
<u>Chargers</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>RL/KK/RR</u>	<u>0</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

Areas appeared safe at time of checks

PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 6401
CERT. # 7954
CERT. # 4373
CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 4735

2MSHA03006

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-18-07

SECTION/AREA Gen. Mine 1 1

TIME OF EXAMINATION START 359
 TIME OF EXAMINATION START 300
 TIME OF EXAMINATION START _____

AM/PM END 525 AM/PM
 AM/PM END 530 AM/PM
 AM/PM END _____ AM/PM

Examiners Initials LR
 Examiners Initials LR/RR
 Examiners Initials _____

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.8	0	0	LR	OK	None observed	
Main North Haulage Seals	20.8	0	0	LR	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/KK RL	OK	None observed	
3 rd North Haulage Seals	20.8	0	0	LR	OK	None observed	
1 st Right	20.8	0	0	LR	OK	None observed	
Storage Area	20.8	0	0	LR	OK	None observed	
Wash Down Area	20.8	0	0	LR	OK	None observed	
Trucks Formers	20.8	0	0	LR/KK RL	OK	None observed	
Chargers	20.8	0	0	LR/KK RL	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER _____ **Signature** CERT. # 4325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6201
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ **Signature** CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-18-07

SECTION/AREA Gen Mills

TIME OF EXAMINATION START 11:52 AM/PM
 TIME OF EXAMINATION START 11:45 AM/PM
 TIME OF EXAMINATION START 11:35 AM/PM

END 1:22 AM/PM
 END 1:42 AM/PM
 END 1:35 AM/PM

Examiners Initials FM
 Examiners Initials TC
 Examiners Initials TC

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
haulage							
Main North seals	20.9	0	0	FM	OK	none observed	
haulage							
Main West seals	20.9	0	0	FM/TC	OK	None observed	
haulage							
3rd North seals	20.9	0	0	FM	OK	none observed	
haulage							
1st Right	20.9	0	0	FM	OK	none observed	
Transformers	20.9	0	0	FM/TC	OK	None observed	
chargers	20.9	0	0	FM/TC	OK	None observed	
Storage Area	20.9	0	0	FM	OK	none observed	
washdown	20.9	0	0	TC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03008

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6/8/07 SECTION/AREA Geotone 1

TIME OF EXAMINATION START 745 AM/PM AM END 925 AM/PM PM
 TIME OF EXAMINATION START 730 AM/PM AM END 1018 AM/PM PM
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM

Examiners Initials [Signature]
 Examiners Initials [Signature]
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Cub Parking	20.9	0	.1	dy	dc	None observed	
Main North Seals	20.9	0	0	dy	dc	None observed	
Main West Haulages Seals	20.9	0	.2	dy	OK	None observed	
2nd No Haulages Seals	20.9	0	0	dy	OK	None observed	
1st Right	20.9	0	0	dy	OK	None observed	
Transformers	20.9	0	0	dy	OK	None observed	
Chargers	20.9	0		dy	OK	None observed	
Storage areas	20.9	0	0	dy	OK	None observed	
Washdown	20.9	0	0	dy	dc	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Person appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER [Signature] CERT. # 6642
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE [Signature] CERT. # 4735

2MSHA03009

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-19-07

SECTION/AREA Part Mine 1

TIME OF EXAMINATION START 350 AM/PM
 TIME OF EXAMINATION START 745 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 535 AM/PM
 END 505 AM/PM
 END _____ AM/PM

Examiners Initials RL/PA
 Examiners Initials RL/PA
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	DG	0	none observed	
Main North + haulage Deck	21	0	0	DG	0	none observed	
Main West + haulage Deck	21	0	0	DG RL/PA	0	none obs	
3rd North + haulage Deck	21	0	0	DG	0	none obs	
1st Right	21	0	0	DG	0	none obs	
Transformers	21	0	0	DG RL/PA	0	none obs	
Chargers	21	0	0	DG RL/PA	0	none obs	
Storage Area	21	0	0	DG	0	none obs	
Workdown	21	0	0	DG	0	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # 4622
 PRE-SHIFT/MINE EXAMINER CERT. # 4325
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATUR **Signature** CERT. # 0592

2MSHA03010

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-19-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:52 AM/PM END 1:07 AM/PM Examiners Initials EM
 TIME OF EXAMINATION START 11:50 AM/PM END 1:41 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 12:00 AM/PM END 12:41 AM/PM Examiners Initials JK

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	EM	OK	None observed	
haulage MAIN North seals	20.9	0	0	EM	OK	None observed	
haulage MAIN West seals	20.9	0	0	EM BH/TC	OK	None observed	
3 rd North haulage seals	20.9	0	0	EM	OK	None observed	
1 st Right	20.9	0	0	EM	OK	None observed	
transformers	20.9	0	0	EM BH/TC	OK	None observed	
chargers	20.9	0	0	EM BH/TC	OK	None observed	
Storage Area	20.9	0	0	EM	OK	None observed	
Wash down	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8397
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # _____

Signature

COUNTER SIGNATURE _____

ERT. # 03892

2MSHA03011

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-19-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION
TIME OF EXAMINATION
TIME OF EXAMINATION

START 7:20 AM/PM
START 8:45 AM/PM
START _____ AM/PM

END 9:15 AM/PM
END 9:25 AM/PM
END _____ AM/PM

Examiners Initials Sub
Examiners Initials dg
Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage ^{SCATS}	21.0	0	0	SW	OK	none observed	
Main West haulage ^{SCATS}	20.9	0	.2	SW ^{dg}	OK	none observed	
3rd North haulage ^{SCATS}	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW ^{dg}	OK	none observed	
chargers	20.9	0	0	SW ^{dg}	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown							

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____
PRE-SHIFT/MINE EXAMINER _____
PRE-SHIFT/MINE EXAMINER _____
PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 9548
CERT. # 6622
CERT. # _____
CERT. # _____

COUNTER SIGNATURE _____
Signature

CERT. # 7485

2MSHA03012

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-20-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 3:50 ~~AM/PM~~
 TIME OF EXAMINATION START 4:50 ~~AM/PM~~
 TIME OF EXAMINATION START _____ AM/PM

END 5:25 ~~AM/PM~~
 END 5:30 ~~AM/PM~~
 END _____ AM/PM

Examiners Initials SW
 Examiners Initials ag
 Examiners Initials _____

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage ^{SEALS}	21.0	0	0	SW	OK	none observed	
Main West haulage ^{SEALS}	20.9	0	.1	SW	OK	None observed	
3rd North haulage ^{SEALS}	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW	OK	none observed	
chargers	20.9	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	dy	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

Signature _____
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 6627
 PRE-SHIFT/MINE EXAMINER CERT. # _____
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE _____
 Signature _____
 CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-20-07

SECTION/AREA Gen Mint / /

TIME OF EXAMINATION START 12:06 AM/PM
 TIME OF EXAMINATION START 11:55 AM/PM
 TIME OF EXAMINATION START 12:00 AM/PM

END 1:22 AM/PM
 END 1:38 AM/PM
 END 1:42 AM/PM

Examiners Initials FM
 Examiners Initials TC
 Examiners Initials TC

EXAM. CALLED OUT YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OC	None observed	
MAIN North haulage seals	20.9	0	0	FM	α	None observed	
MAIN West haulage seals	20.9	0	0	FM/TC	α	None Observed	
3rd North haulage seals	20.9	0	0	FM	α	None observed	
1st Right	20.9	0	0	FM	α	None observed	
Transformers	20.9	0	0	FM/TC	α	None Observed	
Chargers	20.9	0	0	FM/TC	α	None Observed	
Storage Area	20.9	0	0	FM	OC	None observed	
Washdown	20.9	0	0	TC	α	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03014

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-20-07

SECTION/AREA General Mine 1

TIME OF EXAMINATION START 8:05
 TIME OF EXAMINATION START 8:25
 TIME OF EXAMINATION START _____

AM/PM AM END 9:30 AM/PM AM
 AM/PM AM END 9:25 AM/PM AM
 AM/PM _____ END _____ AM/PM _____

Examiners Initials SW
 Examiners Initials JD
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SEALS} haulage	20.9	0	0	SW JD	OK	none observed	
3rd North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW JD	OK	none observed	
chargers	20.9	0	0	SW JD	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	20.9	0	0	JD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03015

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-21-07

SECTION/AREA General 1 Mile 1

TIME OF EXAMINATION START 3:55 (AM/PM)
 TIME OF EXAMINATION START 4:38 (AM/PM)
 TIME OF EXAMINATION START _____ (AM/PM)

END 5:25 (AM/PM)
 END 5:20 (AM/PM)
 END _____ (AM/PM)

Examiners Initials dy
 Examiners Initials dy
 Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SEALS} haulage	20.9	0	1.2	SW <u>dy</u>	OK	none observed	
3rd North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW <u>dy</u>	OK	none observed	
chargers	20.8	0	1.1	SW <u>dy</u>	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	20.9	0	0	<u>dy</u>	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
M North	Getting gray	Bulk dusted off

PRE-SHIFT REMARKS all areas examined appear safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ **Signature** CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6622
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____

CERT. # 03892

2MSHA03016

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-21-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:52 ~~AM/PM~~ END 1:10 ~~AM/PM~~ Examiners Initials FM
 TIME OF EXAMINATION START 12:00 ~~AM/PM~~ END 1:37 ~~AM/PM~~ Examiners Initials TC
 TIME OF EXAMINATION START 12:00 ~~AM/PM~~ END 1:42 ~~AM/PM~~ Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
Main North haulage seals	20.9	0	0	FM	OK	None observed	
Main West haulage seals	20.9	0	0	FM TC/BH	OK	none obs.	
3rd North haulage seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	20.9	0	0	FM TC/BH	OK	none obs.	
chargers	20.9	0	0	FM TC	OK	none obs.	
storage Area	20.9	0	0	FM	OK	None observed	
washdown	20.9	0	0	BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe AT time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03017

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-21-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:00 AM/PM AM END 9:05 AM/PM PM Examiners Initials JG
 TIME OF EXAMINATION START 8:40 AM/PM AM END 9:25 AM/PM PM Examiners Initials JG
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG dg	OK	NONE OBSERVED	
3RD NORTH HAULAGE SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	JG dg	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	JG dg	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	dg	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas examined appear safe at times of pre-shift

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 6622
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03018

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-22-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 4:00 AM/PM
 TIME OF EXAMINATION START 4:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:05 AM/PM
 END 5:20 AM/PM
 END _____ AM/PM

Examiners Initials JG
 Examiners Initials SW
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SW JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	SW	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 2485
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATUR

CERT. # 4935

2MSHA03019

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-22-07

SECTION/AREA Gen Minto / /

TIME OF EXAMINATION START 11:47 AM/PM
 TIME OF EXAMINATION START 12:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 1:15 AM/PM
 END 1:45 AM/PM
 END _____ AM/PM

Examiners Initials FM
 Examiners Initials R/TC
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
Main North haulage seals	20.9	0	0	FM	OK	none observed	
Main West haulage seals	20.9	0	0	FM/TC	OK	none observed	
3rd North haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
TRANSformers	20.9	0	0	FM/TC	OK	none observed	
chargers	20.9	0	0	FM/TC	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
wash down	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature
 COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-22-07 SECTION/AREA Gen Mine 1 | |

TIME OF EXAMINATION START 7:44 AM/PM AM END 9:12 AM/PM PM Examiners Initials R
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:50 AM/PM PM Examiners Initials P/OD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ---- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	R	OK	None observed	
Main North Haulage Seals	20.9	0	0	R	OK	None observed	
Main West Haulage Seals	20.9	0	0	P/OD	OK	None Observed	
3rd North Haulage Seals	20.9	0	0	P/OD	OK	None Observed	
1st Right	20.9	0	0	P/OD	OK	None Observed	
Transformers	20.9	0	0	P/OD	OK	None Observed	
Chargers	20.9	0	0	P/OD	OK	None Observed	
Storage area	20.9	0	0	P/OD	OK	None Observed	
Wash down	20.9	0	0	P/OD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonable
Safe at time of Exam.

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 9293
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-23-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:18 AM/PM
 TIME OF EXAMINATION START 3:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 3:47 AM/PM
 END 3:50 AM/PM
 END _____ AM/PM

Examiners Initials R
 Examiners Initials PC/D
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	JR	OK	None Observed	
Main North Haulage seats	20.9	0	0	JR	OK	None Observed	
Main West Haulage seats	20.9	0	0	PC/D	OK	None Observed	
3 rd North Haulage seats	20.9	0	0	PC/D	OK	None Observed	
1 st Right	20.9	0	0	PC/D	OK	None Observed	
Transformers	20.9	0	0	PC/D	OK	None Observed	
Chargers	20.9	0	0	PC/D	OK	None Observed	
Wash down	20.9	0	0	PC/D	OK	None Observed	
Storage area	20.9	0	0	PC/D	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
X cut 9 th intake	deep water	pumped

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam.

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 9293
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 CERT. # 4735

COUNTER SIGNATURE _____ CERT. # _____ 2MSHA03022

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-23-07

SECTION/AREA Gem Mine 1

TIME OF EXAMINATION START 11:50 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM

END 1230 AM/PM
 END 125 AM/PM
 END 1230 AM/PM

Examiners Initials DG
 Examiners Initials RL
 Examiners Initials RR

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	none obs'd	
Main North ^{Howlage} seals	20.9	0	0	DG	OK	none obs'd	
Main West ^{Howlage} seals	20.9	0	0	RL/RR	OK	none observed	
3rd North ^{Howlage} seals	20.9	0	0	RL/RR	OK	none observed	
bet Right	21.0	0	0	RR	OK	none observed	
Transformers	20.9	0	0	RL/RR	OK	none observed	
chargers	20.9	0	0	RL/RR	OK	none observed	
Workdown	21.0	0	0	RR	OK	none observed	
Storage area	21.0	0	0	RR	OK	none observed.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All certian appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER _____ **Signature** CERT. # 41735
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03023

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-23-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION
 TIME OF EXAMINATION
 TIME OF EXAMINATION

START 8:13
 START 730
 START _____

AM/PM
 AM/PM
 AM/PM

END 9:00 AM/PM
 END 940 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DD mc
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	DD/mc	ok	none observed	
3 rd North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
1st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/DD/mc	OK	none observed	
Chargers	20.9	0	0	DD/mc	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	
Storage area	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All AREAS safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 8462
 CERT. # 8058
 CERT. # 7375
 CERT. # _____

COUNTER SIGNATURE _____

ERT. # _____

Signature

2MSHA03024

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-24-07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 3:15 AM/PM PM END 6:06 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 3:30 AM/PM PM END 5:27 AM/PM PM Examiners Initials MG/DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	mc/DD	OK	None observed	
3 rd North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/MC/DD	OK	None Observed	
Chargers	20.9	0	0	mc/DD	OK	None observed	
Wash down	20.9	0	0	mc/DD	OK	None observed	
Storage area	20.9	0	0	mc/DD	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER CERT. # 7375
 PRE-SHIFT/MINE EXAMINER CERT. # 8058
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 4735 2MSHA03025

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-24-07

SECTION/AREA Panel 1

TIME OF EXAMINATION START 1100 AM/PM
 TIME OF EXAMINATION START 12 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 145 AM/PM
 END 130 AM/PM
 END _____ AM/PM

Examiners Initials PR/RL
 Examiners Initials UG
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	DG	OK	none obs	
Main North ^{#haulage} _{Seals}	20.9	0	0	DG	OK	none obs	
Main West ^{#haulage} _{Seals}	20.9	0	0	RL/RR	OK	none observed	
2nd North ^{#haulage} _{Seals}	20.8	0	0	RL/RR	OK	none observed	
1st Right	20.9	0	0	RL	OK	none obs.	
Transformers	20.9	0	0	RL/RR	OK	none obs.	
Chargers	20.9	0	0	RL/RR	OK	none obs.	
Work down	20.9	0	0	LR	OK	none obs	
Storage area	20.9	0	0	LR	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 680
 PRE-SHIFT/MINE EXAMINEE CERT. # 4323
 PRE-SHIFT/MINE EXAMINEE CERT. # 4935
 PRE-SHIFT/MINE EXAMINEE CERT. # _____

COUNTER SIGNATURE _____ ERT. # 8462

2MSHA03026

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-24-07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 2:13 AM/PM AM END 8:05 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:45 AM/PM PM Examiners Initials MC/DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North seals ^{Hauberg}	20.9	0	0	PC	OK	None Observed	
Main West seals ^{Hauberg}	20.9	0	0	MC/DD	OK	none observed	
3 rd North seals ^{Hauberg}	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC	OK	None Observed	
Chargers	20.9	0	0	MC/DD	OK	none observed	
Wash down	20.9	0	0	MC	OK	none observed	
Storage area	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREA APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03027

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-25-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:15 AM/PM
 TIME OF EXAMINATION START 330 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 4:39 AM/PM
 END 550 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DD/ME
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None Observed	
Main North Haulage seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage seals	20.9	0	0	DD/ME	OK	none obs.	
3 rd North Haulage seals	20.9	0	0	DD/ME	OK	none obs.	
1 st Right	20.9	0	0	DD	OK	none obs.	
Transformers	20.9	0	0	DD/ME	OK	none obs.	
Chargers	20.9	0	0	DD/ME	OK	none obs.	
wash down	20.9	0	0	DD	OK	none obs.	
Storage area	20.9	0	0	DD/ME	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 8462
 CERT. # 8058
 CERT. # 233
 CERT. # _____

COUNTER SIGNATURE _____
 Signature _____
 CERT. # 7485

2MSHA03028

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-25-07

SECTION/AREA Brilliant

TIME OF EXAMINATION START 11:15 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:15 AM/PM
 END 12:40 AM/PM
 END _____ AM/PM

Examiners Initials RL
 Examiners Initials FM
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

ALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21	0	0	RL	0	none observed	
Main North Haulage Road	21	0	0	RL	0	none observed	
Main West Haulage Road	209	0	0	FM	0	none observed	
3rd North Haulage Road	209	0	0	FM	0	none observed	
1st Right	209	0	0	FM	0	none observed	
Transformers	209	0	0	FM	0	none observed	
Chargers	209	0	0	FM	0	none observed	
Washdown	209	0	0	FM	0	none observed	
Storage Area	209	0	0	FM	0	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Reasonably safe At time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03029

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-25-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:13 AM/PM AM END 8:30 AM/PM PM Examiners Initials MC
 TIME OF EXAMINATION START 7:45 AM/PM AM END 9:15 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START 7:50 AM/PM AM END 9:40 AM/PM PM Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None Observed	
Main North ^{Handage} _{Seals}	20.9	0	0	MC	OK	None Observed	
Main West ^{Handage} _{Seals}	20.9	0	0	BH/TC	OK	None Observed	
3 rd North ^{Handage} _{Seals}	20.9	0	0	MC	OK	None Observed	
1 st Right Handage	20.9	0	0	MC	OK	None Observed	
Transformers	20.9	0	0	BH/TC MC	OK	None Observed	
Chargers	20.9	0	0	BH/TC MC	OK	None Observed	
Washdown	20.9	0	0	TC	OK	None Observed	
Storage Area	20.9	0	0	TC	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared reasonably safe at time of pre-shift

Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9302
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892 2MSHA03030

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 26 07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 344 AM/PM END 445 AM/PM Examiners Initials GT
 TIME OF EXAMINATION START 340 AM/PM END 525 AM/PM Examiners Initials TC
 TIME OF EXAMINATION START 3170 AM/PM END 525 AM/PM Examiners Initials BT

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GT	OK	None observed	
Main No haulage ^{seals}	21	0	0	GT	OK	None observed	
Main west ^{seals} ^{skidage}	20.9	0	0	TC/BH	OK	none obs.	
3 No haulage ^{seals}	20.9	0	0	GT	OK	None observed	
1st At	20.9	0	0	GT	OK	None observed	
Transformers	20.9	0	0	TC/BH	OK	None obs.	
Chargers	20.9	0	0	TC	OK	None obs.	
Washdown	20.9	0	0	BH	OK	None obs.	
Storage Area	20.9	0	0	TC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # _____

2MSHA03031

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-26-07

SECTION/AREA GenMine

TIME OF EXAMINATION START 11:55 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM

END 1:20 AM/PM
 END 1:50 AM/PM
 END 1:50 AM/PM

Examiners Initials FM
 Examiners Initials SW
 Examiners Initials LR

EXAM. CALLED OUT YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	none observed	
MAIN North haulage seals	20.9	0	0	FM	OK	none observed	
MAIN West haulage seals	21.0	0	0	FM SW	OK	none observed	
3rd North haulage seals	20.9	0	0	FM	OK	none observed	
1st Right	20.9	0	0	FM	OK	none observed	
trans formers	21.0	0	0	FM SW	OK	none observed	
chargers	21.0	0	0	FM SW	OK	none observed	
Storage Area	20.9	0	0	FM	OK	none observed	
Wash down	20.9	0	0	FM	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINEE _____ **Signature** _____ CERT. # 8397
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9548
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ **Signature** _____ CERT. # 7485

2MSHA03032

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 26 07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 800 AM/PM AM END 858 AM/PM PM Examiners Initials GA
 TIME OF EXAMINATION START 7:45 AM/PM AM END 9:40 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:40 AM/PM AM END 9:40 AM/PM PM Examiners Initials BH

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	21	0	0	GA	OK	None observed	
Main No. Haulage ^{seals}	21	0	0	GA	OK	None observed	
Main West Haulage ^{seals}	20.9	0	0	BH/TC	OK	None observed	
3 No. Haulage ^{seals}	20.9	0	0	GA	OK	None observed	
1st RT haulage	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None observed	
Chargers	20.9	0	0	BH/TC	OK	None observed	
Washdown	20.9	0	0	BH/TC	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
3 seal 3A6	Stumbling Hazard	Removed GA

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 03892
 CERT. # 6395
 CERT. # 9362
 CERT. # _____

Signature

COUNTER SIGNATURE _____

CERT. # 03892

2MSHA03033

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 27 07

SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 3:45 AM/PM
 TIME OF EXAMINATION START 3:45 AM/PM
 TIME OF EXAMINATION START 3:46 AM/PM

END 4:47 AM/PM
 END 5:30 AM/PM
 END 5:24 AM/PM

Examiners Initials CA
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	CA	OK	None observed	
Main No Haulage ^{seals}	21	0	0	CA	OK	None observed	
Main West Haulage ^{seats}	20.9	0	0	BH/TC	OK	None Observed	
3rd No Haulage ^{seats}	20.9	0	0	CA	OK	None observed	
1st Right	20.9	0	0	CA	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	TC	OK	None observed	
Storage Area	20.9	0	0	TC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 03892
 CERT. # 8395
 CERT. # 972
 CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 CERT. # 7485

2MSHA03034

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-27-07

SECTION/AREA General Mine / /

TIME OF EXAMINATION START 11:10
 TIME OF EXAMINATION START 11:42
 TIME OF EXAMINATION START _____

~~AM/PM~~ END 12:45 AM/~~PM~~
~~AM/PM~~ END 12:40 AM/~~PM~~
 AM/PM END _____ AM/PM

Examiners Initials SW
 Examiners Initials EM/KC
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/~~NO~~

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	EM	OK	none observed	
Main North haulage ^{haulage} Seal 5	21	0	0	KC/EM	OK	none observed	
Main West haulage ^{Seal 5}	21.0	0	0	SW	OK	none observed	
3 rd North haulage ^{Seal 5}	20.9	0	0	EM	OK	none observed	
1 st Right	20.9	0	0	EM	OK	none observed	
Transformers	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe
At time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8457
 PRE-SHIFT/MINE EXAMINEE CERT. # 9548
 PRE-SHIFT/MINE EXAMINEE CERT. # 8297
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03035

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 27 07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:30 AM/PM AM/PM
 TIME OF EXAMINATION START 7:45 AM/PM AM/PM
 TIME OF EXAMINATION START 7:49 AM/PM AM/PM

END 8:43 AM/PM AM/PM
 END 9:33 AM/PM AM/PM
 END 9:30 AM/PM AM/PM

Examiners Initials GA
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GA	OK	None observed	
Main N/A Haulage	21	0	0	GA	OK	None observed	
Main West Haulage	20.9	0	0	BH/TC	OK	None Observed	
3rd N/A Haulage	20.9	0	0	GA	OK	None observed	
1st Rt	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 03892
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03036

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 28 07

SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 3:05 AM/PM
 TIME OF EXAMINATION START 3:50 AM/PM
 TIME OF EXAMINATION START 3:38 AM/PM

END 4:47 AM/PM
 END 5:25 AM/PM
 END 5:24 AM/PM

Examiners Initials GA
 Examiners Initials TC
 Examiners Initials BH

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	21	0	0	GA	OK	None observed	
Main No Haulage ^{Seals}	21	0	0	GA	OK	None observed	
Mainwest ^{Haulage}	20.9	0	0	TC/BH	OK	None obs.	
3rd No Haulage ^{Seals}	20.9	0	0	GA	OK	None observed	
1st Right	20.9	0	0	GA	OK	None observed	
TRANSVERSE	20.9	0	0	TC/BH	OK	None obs.	
CHARGERS	20.9	0	0	BH	OK	None obs.	
Washdown	20.9	0	0	TC	OK	None obs.	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe
at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 835
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03037

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-28-07

SECTION/AREA Gen Mined

TIME OF EXAMINATION START 11:30 AM PM
 TIME OF EXAMINATION START 11:00 AM PM
 TIME OF EXAMINATION START _____ AM PM

END 12:27 AM PM
 END 12:49 AM PM
 END _____ AM PM

Examiners Initials FM
 Examiners Initials MC
 Examiners Initials _____

EXAM. CALLED OUT _____ YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
haulage Main North seals	20.9	0	0	FM	OK	None observed	
haulage Main West seals	20.9	0	0	ML	OK	None observed	
haulage 3rd North seals	20.9	0	0	MC	OK	None observed	
1st Right	20.9	0	0	MC	OK	None observed	
Transformers	20.9	0	0	MC	OK	None observed	
Chargers	20.9	0	0	ML	OK	None observed	
Washdown	20.9	0	0	ML	OK	None observed	
Storage Area	20.9	0	0	ML	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Arms Appeared Reasonably safe
at time of exam

Signature _____
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 8297
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 COUNTER SIGNATURE _____ CERT. # 7488 2MSHA03038

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6/28/07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:35 AM/PM
 TIME OF EXAMINATION START 7:40 AM/PM
 TIME OF EXAMINATION START 7:45 AM/PM

END 8:45 AM/PM
 END 9:30 AM/PM
 END 9:35 AM/PM

Examiners Initials GA
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	20.9	0	0	GA	OK	None observed	
Main No. Haulage ^{seals}	20.9	0	0	GA	OK	None observed	
Main West Haulage ^{seals}	20.9	0	0	BH/TC	OK	None observed	
3rd No Haulage ^{seals}	20.9	0	0	GA	OK	None observed	
1st Right	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None observed	
Chargers	20.9	0	0	BH/TC	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 03892
 CERT. # 8395
 CERT. # 7362
 CERT. # _____

Signature

COUNTER SIGNATURE _____

CERT. # 03892

2MSHA03039

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6 29 07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:01 AM/PM END 4:16 AM/PM Examiners Initials CT
 TIME OF EXAMINATION START 3:40 AM/PM END 5:30 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 3:49 AM/PM END 5:22 AM/PM Examiners Initials VR

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>U.G. Parking</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>CT</u>	<u>OK</u>	<u>None observed</u>	
<u>Main No. Haulage</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>CT</u>	<u>OK</u>	<u>None observed</u>	
<u>Main West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None Observed</u>	
<u>3rd No Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>CT</u>	<u>OK</u>	<u>None observed</u>	
<u>1st Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>CT</u>	<u>OK</u>	<u>None observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None Observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>None observed</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>None Observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

 Signature
 PRE-SHIFT/MINE EXAMINE CERT. # 03892
 PRE-SHIFT/MINE EXAMINE CERT. # 8395
 PRE-SHIFT/MINE EXAMINE CERT. # 9368
 PRE-SHIFT/MINE EXAMINE, CERT. # _____

 Signature
 COUNTER SIGNATURE CERT. # 4705

2MSHA03040

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-29-07

SECTION/AREA Gen Mnt / /

TIME OF EXAMINATION START 11:52 ~~AM/PM~~
 TIME OF EXAMINATION START 11:15 ~~AM/PM~~
 TIME OF EXAMINATION START _____ ~~AM/PM~~

END 1:17 ~~AM/PM~~
 END 1:45 ~~AM/PM~~
 END _____ ~~AM/PM~~

Examiners Initials FM
 Examiners Initials LR/RR
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/~~NO~~

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	OK	None observed	
haulage MAIN North seals	209	0	0	FM	OK	None observed	
haulage MAIN West seals	209	0	0	FM LR/RR	OK	None observed	
3 rd North haulage seals	209	0	0	FM	OK	None observed	
1 st Right	209	0	0	FM	OK	None observed	
Transformers	209	0	0	FM LR/RR	OK	None observed	
chargers	209	0	0	FM LR/RR	OK	None observed	
Storage Area	209	0	0	FM	OK	None observed	
Wash down	209	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 2904
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-29-07

SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 7:10 AM/PM END 2:58 AM/PM Examiners Initials PC
 TIME OF EXAMINATION START 7:30 AM/PM END 9:45 AM/PM Examiners Initials MC/DD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	MC/DD	OK	none observed	
3 rd North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
transformers	20.9	0	0	PC	OK	None Observed	
Chargers	20.9	0	0	MC/DD	OK	None observed	
Wash down	20.9	0	0	MC	OK	None observed	
Storage area	20.9	0	0	DD	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe
At time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER CERT. # 7375
 PRE-SHIFT/MINE EXAMINER CERT. # 8058
 PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03042

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-30-07

SECTION/AREA Gen 1 Miner

TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 330 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 3:48 AM/PM
 END 540 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DMC
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Haulage area ^{Parking} area	20.9	0	0	PC	OK	None Observed	
Main North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	DD/mc	ok	none observed	
300 North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	DD/mc	ok	none observed	
Chargers	20.9	0	0	DD/mc	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	
Storage area	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe At time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 8462
 CERT. # 8058
 CERT. # 7875
 CERT. # _____

Signature

COUNTER SIGNATUR _____

CERT. # 4935

2MSHA03043

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-30-07

SECTION/AREA 2nd Mine

TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:00 AM/PM
 END 1:50 AM/PM
 END _____ AM/PM

Examiners Initials KK
 Examiners Initials LR/RL
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs	
1st Wash Haulage seals	20.9	0	0	KK	OK	none obs	
2nd Wash Haulage seals	20.9	0	0	LR/RL	OK	none obs	
3rd Wash Haulage seals	20.9	0	0	KK	OK	none obs	
1st roof	20.9	0	0	KK	OK	none obs	
Trans.	20.9	0	0	LR/RL	OK	none obs	
Changers	20.9	0	0	LR/RL	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs	
washdown	20.9	0	0	KK	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
 PRE-SHIFT/MINE EXAMINER CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # 4375
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 6-30-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:30 AM/PM AM END 9:20 AM/PM PM Examiners Initials mc/Km
 TIME OF EXAMINATION START 7:00 AM/PM AM END 8:20 AM/PM PM Examiners Initials DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT YES NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	DD	ok	none obs.	
MAIN NORTH HAULAGE SEALS	20.9	0	0	DD	ok	none obs.	
MAIN WEST HAULAGE SEALS	20.9	0	0	mc/Km	ok	none observed	
3RD NORTH HAULAGE SEALS	20.9	0	0	DD	ok	none obs.	
1ST Right Haulage	20.9	0	0	DD	ok	none obs.	
TRANSFORMERS	20.9	0	0	mc/Km	ok	none observed	
CHARGERS	20.9	0	0	mc/Km	ok	none observed	
WASHDOWN	20.9	0	0	Km	ok	none observed	
STORAGE AREA	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9379
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature
 COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-1-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 3:00 ~~AM~~/PM END 5:35 ~~AM~~/PM Examiners Initials DD/KM
 TIME OF EXAMINATION START 3:00 ~~AM~~/PM END 4:11 ~~AM~~/PM Examiners Initials MC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____
 REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	none observed	
main North Haulage seals	20.9	0	0	MC	OK	none observed	
main West Haulage seals	20.9	0	0	DD/KM	OK	none obs.	
3 rd North Haulage seals	20.9	0	0	MC	OK	none observed	
1 st Right	20.9	0	0	MC	OK	none observed	
Trans.	20.9	0	0	DD/KM	OK	none observed	
Chargers	20.9	0	0	DD/KM	OK	none observed	
Storage Area	20.9	0	0	KM	OK	none obs.	
Washdown	20.9	0	0	DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9329
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-1-07

SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 11:45 AM PM
 TIME OF EXAMINATION START 11:00 AM PM
 TIME OF EXAMINATION START _____ AM/PM

END 1:00 AM/PM
 END 1:20 AM/PM
 END _____ AM/PM

Examiners Initials ZR
 Examiners Initials ZR/LR
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	ZR	OK	None observed	
Main North Haulage Seals	20.9	0	0	ZR	OK	None observed	
Main West Haulage & Seals	20.9	0	0	LR/KK RL	OK	None	
3 rd North Haulage Seals	20.9	0	0	ZR	OK	None observed	
1 st Right	20.9	0	0	ZR	OK	None observed	
Transformers	20.9	0	0	LR/KK RL	OK	None	
Chargers	20.9	0	0	LR/KK RL	OK	None	
Storage Area	20.9	0	0	ZR	OK	None observed	
Washdown Area	20.9	0	0	ZR	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 2800
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 CERT. # 8462

COUNTER SIGNATURE _____

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-1-07 SECTION/AREA Gen mine | |

TIME OF EXAMINATION START 7:30 AM/PM AM END 9:25 AM/PM PM Examiners Initials MC/DD
 TIME OF EXAMINATION START 2:15 AM/PM PM END 8:25 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	PC	OK	None Observed	
MAIN NORTH Haulage seals	20.9	0	0	PC	OK	None Observed	
MAIN WEST Haulage seals	20.9	0	0	MC/DD	OK	None observed	
3 RD NORTH Haulage seals	20.9	0	0	PC	OK	None Observed	
1 ST Right Haulage	20.9	0	0	PC	OK	None Observed	
TRANSFORMERS	20.9	0	0	MC/DD PC	OK	None observed	
CHARGES	20.9	0	0	MC/DD PC	OK	None observed	
WASHDOWN	20.9	0	0	MC	OK	None observed	
STORAGE AREA	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 8462

2MSHA03048

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-2-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:02 ~~AM~~/PM
 TIME OF EXAMINATION START 300 ~~AM~~/PM
 TIME OF EXAMINATION START _____ AM/PM

END 3:49 ~~AM~~/PM
 END 545 ~~AM~~/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DD/mc
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	mc/DD	OK	main west section roadway needs watered	WORKING ON DONE 7-2-07
3 rd North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC mc DD	OK	none observed	
Chargers	20.9	0	0	PC mc DD	OK	none observed	
Wash Down	20.9	0	0	DD	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT
Time of pre-shift

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 8462
 CERT. # 7325
 CERT. # 2058
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-20-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 11:47 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:20 AM/PM
 END 12:20 AM/PM
 END _____ AM/PM

Examiners Initials EMS
 Examiners Initials JK
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	EM	OK	none observed	
Main North haulage seals	20.9	0	0	EM/JK	OK	none observed	
Main West haulage seals	20.9	0	0	JK/JK	OK	None observed	
3rd North haulage seals	20.9	0	0	JK/JK	OK	None observed	
1st Right	20.9	0	0	JK	OK	None observed	
Transformers	20.9	0	0	JK/JK	OK	None observed	
Chargers	20.9	0	0	JK/JK	OK	None observed	
Storage Area	20.9	0	0	JK	OK	None observed	
Wash down	20.9	0	0	JK	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4373
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03050

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-2-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:40 AM/PM AM END 9:40 AM/PM PM
 TIME OF EXAMINATION START 7:20 AM/PM AM END 8:35 AM/PM PM
 TIME OF EXAMINATION START 8:00 AM/PM AM END 9:45 AM/PM PM

Examiners Initials BH
 Examiners Initials DD
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DD	OK	None Observed	
Main North ^{Hanging} seals	20.9	0	0	DD	OK	None Observed	
Main West ^{Hanging} seals	20.9	0	0	DD/BH	OK	None Observed	
3 rd North ^{Hanging} seals	20.9	0	0	DD	OK	None Observed	
1 st Right	20.9	0	0	DD	OK	None observed	
Trans	20.9	0	0	DD/BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/DD/TC	OK	None observed	
Washdown	20.8	0	0	TC	OK	None Observed	
Storage Area's	20.9	0	0	DD	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
m.w. x-wf 137	Tripping hazard	Removed

PRE-SHIFT REMARKS Safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature CERT. # 8395
 PRE-SHIFT/MINE EXAMINEE CERT. # 8058
 PRE-SHIFT/MINE EXAMINEE CERT. # 9362
 PRE-SHIFT/MINE EXAMINEE CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7307

SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 302 AM/PM
 TIME OF EXAMINATION START 3:40 AM/PM
 TIME OF EXAMINATION START 3:45 AM/PM

END 410 AM/PM
 END 520 AM/PM
 END 5:30 AM/PM

Examiners Initials GA
 Examiners Initials BY
 Examiners Initials RE

EXAM. CALLED OUT YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>U.G. Parking</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>Main No. Haulage</u> ^{3 seals}	<u>21</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>Main West Haulage</u> ^{Handls seals}	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None Observed</u>	
<u>3rd No. Haulage</u> ^{6 seals}	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OK</u>	<u>None observed</u>	
<u>1st Pt</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>OS</u>	<u>None observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>None observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>None Observed</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>None Observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
<u>#15 seal</u>	<u>Vent curtain down</u>	<u>Put it back up</u>

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 03892
 CERT. # 8395
 CERT. # _____
 CERT. # _____

COUNTER SIGNATURE _____
 CERT. # 7480

Signature

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7.307

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:43 ~~AM/PM~~
 TIME OF EXAMINATION START 11:00 ~~AM/PM~~
 TIME OF EXAMINATION START 11:00 ~~AM/PM~~

END 1:08 ~~AM/PM~~
 END 1:20 ~~AM/PM~~
 END 1:20 ~~AM/PM~~

Examiners Initials FM
 Examiners Initials SW
 Examiners Initials LH

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
haulage MAIN North seals	20.9	0	0	FM	OK	None observed	
haulage MAIN West seals	21.0	0	0	FM SW	OK	None observed	
haulage 3rd North seals	20.9	0	0	FM	OK	None observed	
1st Right	20.9	0	0	FM	OK	None observed	
Transformers	21.0	0	0	FM SW	OK	None observed	
chargers	21.0	0	0	FM SW	OK	None observed	
Storage Area	20.9	0	0	FM	OK	None observed	
Washdown	20.9	0	0	FM	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel at time of exam.

Signature

PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE

CERT. # 8297
 CERT. # 9548
 CERT. # 8703
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03053

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7 3 07

SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 7:05 AM/PM AM
 TIME OF EXAMINATION START 7:40 AM/PM PM
 TIME OF EXAMINATION START 7:54 AM/PM PM

END 8:34 AM/PM PM
 END 9:42 AM/PM PM
 END 9:46 AM/PM PM

Examiners Initials GA
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Ch.G. Parking</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>α</u>	<u>None observed</u>	
<u>Main No Haulage</u> ^{Seals}	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>α</u>	<u>None observed</u>	
<u>Main West Haulage</u> ^{Seals}	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>α</u>	<u>None observed</u>	
<u>3rd No Haulage</u> ^{Seals}	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>α</u>	<u>None observed</u>	
<u>1st Rt</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>GA</u>	<u>α</u>	<u>None observed</u>	
<u>Transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>α</u>	<u>None observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>α</u>	<u>None observed</u>	
<u>washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>α</u>	<u>None observed</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>α</u>	<u>None observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 03892
 CERT. # 8395
 CERT. # 9362
 CERT. # _____

Signature

COUNTER SIGNATURE _____

CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-4-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 3:00 AM/PM END 4:24 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 3:05 AM/PM END 4:33 AM/PM Examiners Initials K
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO _____ CALL OUT TIME _____ AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North ^{Hantage} _{Seals}	20.9	0	0	BH	OK	None Observed	
Main West ^{Hantage} _{Seals}	20.9	0	0	BH/TC	OK	None obs.	
3 rd North ^{Hantage} _{Seals}	20.9	0	0	BH	OK	None obs.	
1 st Right	20.9	0	0	BH	OK	None obs.	
All transformers	20.9	0	0	TC/BH	OK	None obs.	
Belt kitchen	20.9	0	0	BH	OK	None obs.	
Chargers	20.9	0	0	BH/TC	OK	None obs.	
Washdown	20.9	0	0	TC	OK	None obs.	
Storage Area	20.9	0	0	TC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe
At time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 03897

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-5-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 3:02 AM PM
 TIME OF EXAMINATION START _____ AM PM
 TIME OF EXAMINATION START _____ AM PM

END 5:00 AM PM
 END _____ AM PM
 END _____ AM PM

Examiners Initials RM
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RM	OK	NONE OBSERVED	
Main North Seals & Haulage	20.9	0	0	RM	OK	NONE OBSERVED	
MAIN WEST Haulage & Seals	20.9	0	0	RM	OK	NONE OBSERVED	
3rd North Haulage & Seals	20.9	0	0	RM	OK	NONE OBSERVED	
1st Right	20.9	0	0	RM	OK	NONE OBSERVED	
Transformers	20.9	0	0	RM SW	OK	NONE OBSERVED	
Chargers	20.9	0	0	RM	OK	NONE OBSERVED	
Washdown	20.9	0	0	RM	OK	NONE OBSERVED	
Storage area	20.9	0	0	RM	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared Reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6845
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03056

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-5-07

SECTION/AREA Gen Mining

TIME OF EXAMINATION START 11:02 ~~AM~~ PM
 TIME OF EXAMINATION START 11:15 ~~AM~~ PM
 TIME OF EXAMINATION START _____ AM/PM

END 11:40 ~~AM~~ PM
 END 1:04 AM/~~PM~~
 END _____ AM/PM

Examiners Initials RM
 Examiners Initials MC
 Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLER BY _____
 CALLER BY _____
 CALLER BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	RM	OK	none observed	
Main North Seals & Haulage	20.9	0	0	RM	OK	none observed	
Main West Haulage & Seals	20.9	0	0	MC	OK	none observed	
3rd North Haulage & Seals	20.9	0	0	MC	OK	none observed	
1st Right	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	RM MC	OK	none observed	
Chargers	20.9	0	0	MC	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ **Signature** CERT. # 6545
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ **Signature** CERT. # 8457

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-5-07 SECTION/AREA Gen 1 Mine 1

TIME OF EXAMINATION START 7:00 AM/PM END 8:50 AM/PM Examiners Initials LP
 TIME OF EXAMINATION START 8 AM/PM END 9 AM/PM Examiners Initials LP
 TIME OF EXAMINATION START 7:00 AM/PM END 7:30 AM/PM Examiners Initials LP

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	LP	OK	None observed	
Main No Haulage ^{3 seals}	20.9	0	0	LP	OK	None observed	
main west Haulage + seals	20.9	0	0	LP/TE	OK	None observed	
3rd No Haulage ^{seals}	20.9	0	0	LP	OK	None observed	
1st Rt	20.9	0	0	LP	OK	None observed	
Transformers	20.9	0	0	LP/TE	OK	None observed	
charger	20.9	0	0	LP	OK	None observed	
wash down	20.9	0	0	LP	OK	None observed	
storage Area	20.9	0	0	LP	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas + travel ways appeared safe at time of this exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 6908
 PRE-SHIFT/MINE EXAMINER CERT. # 02892
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03057A

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-6-07

SECTION/AREA Genl Mine 1

TIME OF EXAMINATION START 300 ~~AM/PM~~
 TIME OF EXAMINATION START 300 ~~AM/PM~~
 TIME OF EXAMINATION START 347 ~~AM/PM~~

END 4:45 ~~AM/PM~~
 END 440 ~~AM/PM~~
 END 455 ~~AM/PM~~

Examiners Initials LP
 Examiners Initials CL
 Examiners Initials ~~DD~~ DD

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	DD	ok	none obs.	
main north Haulage seals	20.9	0	0	DD	ok	none obs.	
main west Haulage seals	20.9	0	0	LP/CA	ok	None observed	
3rd North Haulage seals	20.9	0	0	DD	ok	none obs.	
1st Right	20.9	0	0	DD	ok	none obs.	
Transformers	20.9	0	0	LP/CA	ok	None observed	
charger	20.9	0	0	LP/CA	ok	None observed	
wash down	20.9	0	0	LP/CA	ok	None observed	
storage Area	20.9	0	0	LP/CA	ok	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe
At time of exam

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 1908
 CERT. # 03892
 CERT. # 8058
 CERT. # _____

Signature

COUNTER SIGNATUR

ERT. # 8462

2MSHA03057B

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-6-07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 11:00 AM/PM END 11:50 AM/PM Examiners Initials PC
 TIME OF EXAMINATION START 1130 AM/PM END 145 AM/PM Examiners Initials DWA
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North haulage seals	20.9	0	0	PC	OK	None Observed	
Main West haulage seals	20.9	0	0	DD/mc	ok	none observed	
3rd North haulage seals	20.9	0	0	PC	OK	None Observed	
1st Right	20.9	0	0	PC	OK	None Observed	
Trans Formers	20.9	0	0	PC/DD/mc	ok	none observed	
chargers	20.9	0	0	PC/DD/mc	ok	none observed	
storage area	20.9	0	0	DD	ok	none observed	
wash down	20.9	0	0	mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be safe at time of exam

PRE-SHIFT/MINE EXAMINEF Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINEF CERT. # 2058
 PRE-SHIFT/MINE EXAMINEF CERT. # 7375
 PRE-SHIFT/MINE EXAMINEF CERT. # _____

COUNTER SIGNATUR Signature CERT. # 8462

2MSHA03058

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-6-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 8:00 AM/PM AM END 8:50 AM/PM PM Examiners Initials OG
 TIME OF EXAMINATION START 7:00 AM/PM PM END AM/PM Examiners Initials KK/R
 TIME OF EXAMINATION START AM/PM END AM/PM Examiners Initials

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	OG	OK	None observed	
Main body haulage of seals	20.9	0	0	OG	OK	None observed	
M. West haulage seals	20.9	0	0	KK/R	OK	none observed	
West haulage seals	20.9	0	0	KK	OK	none observed	
1st flight haulage	20.9	0	0	KK	OK	none observed	
Tunnels	20.9	0	0	KK/R	OK	none observed	
chargers	20.9	0	0	KK/R	OK	none observed	
Storage area	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appear safe at time of pre-shift.

Signature

PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4735
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 7989
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-7-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 400 AM/PM END 458 AM/PM Examiners Initials KS
 TIME OF EXAMINATION START 300 AM/PM END 554 AM/PM Examiners Initials RTA
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO _____ CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	OG	OK	none obs	
main North Seals	20.9	0	0	OG	OK	none obs	
Major Haulage seals	20.9	0	0	KK/AR	OK	none obs	
3rd Haulage seals	20.9	0	0	KK/AR	OK	none obs	
1st Right	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	LR	OK	none obs	
upshelown	20.9	0	0	LR	OK	none obs	
trains	20.9	0	0	LR/AR	OK	none obs	
chargers	20.9	0	0	LR/AR	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Apparent Safe at time of exam

PRE-SHIFT/MINE EXAMINEE _____ Signature _____
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4735
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____
 CERT. # 8462

2MSHA03060

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-2-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 12:10 AM/PM
 TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START 11:30 AM/PM

END 12:31 AM/PM
 END 1:50 AM/PM
 END 1:52 AM/PM

Examiners Initials PC
 Examiners Initials MC
 Examiners Initials SD

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	CE	None observed	
Main North ^{Haulage} seals	20.9	0	0	PC	CE	None observed	
Main West ^{Haulage} seals	20.9	0	0	MC/DD	OK	none observed	
3rd North ^{Haulage} seals	20.9	0	0	MC/DD	OK	none observed	
1st Right	20.9	0	0	DD	OK	none observed	
Transformers	20.9	0	0	MC/DD	OK	none observed	
Chargers	20.9	0	0	MC/DD	OK	none observed	
Storage area	20.9	0	0	MC/DD	OK	none observed	
Wash Down	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED Reasonably safe
AT Time of preshift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 2462
 PRE-SHIFT/MINE EXAMINER CERT. # 7375
 PRE-SHIFT/MINE EXAMINER CERT. # 8058
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 2462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-7-07

SECTION/AREA Gen. Mine / /

TIME OF EXAMINATION START 7:00 AM/PM
 TIME OF EXAMINATION START 7:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 8:30 AM/PM
 END 9:47 AM/PM
 END _____ AM/PM

Examiners Initials LR
 Examiners Initials RL
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None observed	
Main North Haulage seals	20.9	0	0	LR	OK	None observed	
Main West Haulage seals	20.9	0	0	LR/RL	OK	None observed	
3rd North Haulage seals	20.9	0	0	LR	OK	None observed	
1st Right	20.9	0	0	LR	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Washdown Area	20.9	0	0	LR	OK	None observed	
Transformers	20.9	0	0	LR/RL	OK	None obs	
Chargers	20.9	0	0	LR/RL	OK	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 0401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 2954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 4135

2MSHA03062

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7.8.07 SECTION/AREA Gen. M^o | |

TIME OF EXAMINATION START 340 AM/PM END 505 AM/PM Examiners Initials LR
 TIME OF EXAMINATION START 300 AM/PM END 535 AM/PM Examiners Initials KK/RL
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LR	OK	None observed	
Main North Haulage Seals	20.9	0	0	LR	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/KK RL	OK	None observed	
3 rd North Haulage Seals	20.9	0	0	LR	OK	None observed	
1 st Right	20.9	0	0	LR	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Workdown Area	20.9	0	0	LR	OK	None observed	
Transformers	20.9	0	0	LR/KK RL	OK	None observed	
Chargers	20.9	0	0	LR/KK RL	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4325
 PRE-SHIFT/MINE EXAMINER CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # 7934
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

2MSHA03063

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-8-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:10 AM/PM
 TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 11:50 AM/PM
 END 1:35 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DD/MC
 Examiners Initials _____

EXAM. CALLED OUT ---- YES (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North seals ^{Hoistage}	20.9	0	0	PC	OK	None Observed	
Main West seals ^{Hoistage}	20.9	0	0	DD/MC	ok	none observed	
3 rd North seals ^{Hoistage}	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	DD/MC	ok	none observed	
Chargers	20.9	0	0	DD/MC	ok	none observed	
Wash down	20.9	0	0	MC	ok	none observed	
Storage area	20.9	0	0	DD	ok	none Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Area's appeared to be safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER CERT. # 8058
 PRE-SHIFT/MINE EXAMINER CERT. # 7375
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATUR Signature CERT. # _____

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-8-07 SECTION/AREA Pen Mine 1

TIME OF EXAMINATION START 830 AM/PM AM END 935 AM/PM PM Examiners Initials RL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	RL	OK	trash & dust.	working on
Main North ^{Hoilage} Seals	21	0	0	RL	OK	none observed	
Main West ^{Hoilage} Seals	21	0	0	RL/RR	OK	none observed	
3rd North ^{Hoilage} Seals	21	0	0	RL	OK	none observed	
1st Right	21	0	0	RL	OK	none observed	
Transformers.	209	0	0	LR/RR RL	OK	None observed	
chargers	21	0	0	RL/RR RR	OK	None observed	
Workdown	21	0	0	RL	OK	none observed	
Storage area	21	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 6406
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 COUNTER SIGNATURE _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-9-07 SECTION/AREA beam/101 / /

TIME OF EXAMINATION START 3:46 AM/PM END 5:00 AM/PM Examiners Initials KK
 TIME OF EXAMINATION START 3:00 AM/PM END 5:20 AM/PM Examiners Initials RL/RR
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO Q CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North Haulage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RR</u>	<u>OK</u>	<u>none obs.</u>	
<u>3rd Haulage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st Haulage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RR</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RR</u>	<u>OK</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7959
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6981
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 03792

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7 9 07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11 AM/PM
 TIME OF EXAMINATION START 11-30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 1250 AM/PM
 END 145 AM/PM
 END _____ AM/PM

Examiners Initials CA
 Examiners Initials mc/TC
 Examiners Initials _____

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	20.9	0	0	CA	OK	None observed	
M.No. Haulage ^{seals}	20.9	0	0	CA	OK	None observed	
MAIN west Haulage ^{seals}	20.9	0	0	mc/TC	OK	none observed	
3 No. Haulage ^{seals}	20.9	0	0	CA	OK	None observed	
1st Right	20.9	0	0	CA	OK	None observed	
Transformers	20.9	0	0	mc/TC	OK	none observed	
Chargers	20.9	0	0	mc/TC	OK	none observed	
w/rdown	20.9	0	0	mc	OK	none observed	
Storage Area	20.9	0	0	TC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe
at time of pre-shift

PRE-SHIFT/MINE EXAMINER: _____
 PRE-SHIFT/MINE EXAMINER: _____
 PRE-SHIFT/MINE EXAMINER: _____
 PRE-SHIFT/MINE EXAMINER: _____

CERT. # 03892
 CERT. # 7375
 CERT. # 9362
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-9-07

SECTION/AREA Gen. Mine | |

TIME OF EXAMINATION START 7:20 AM/PM
 TIME OF EXAMINATION START 8:13 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 9:00 AM/PM
 END 9:30 AM/PM
 END _____ AM/PM

Examiners Initials LR
 Examiners Initials SW
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	None observed	
Main North Haulage Seals	20.9	0	0	SW	OK	None observed	
Main West Haulage Seals	20.9	0	0	LR/SW	OK	None observed	
3rd North Haulage Seals	20.9	0	0	SW	OK	None observed	
1st Right	20.9	0	0	SW	OK	None observed	
Storage Area	20.9	0	0	LR	OK	None observed	
Washdown Area	20.9	0	0	LR	OK	None observed	
Trucks Seals	20.9	0	0	LR/SW	OK	None observed	
Plumbers	20.9	0	0	LR/SW	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
M. North #16	Wide Area - Timber out	Reset Timber

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-10-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 4:00 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

ENDS: 1:15 AM/PM
 END 5:30 AM/PM
 END _____ AM/PM

Examiners Initials JG
 Examiners Initials SW
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
K-2170	timber knocked out	reset.

PRE-SHIFT REMARKS AREAS TRAVELED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9548
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-10-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 11:00 ~~AM/PM~~ END 1:12 AM/PM ~~AM/PM~~ Examiners Initials TC
 TIME OF EXAMINATION START 12:14 ~~AM/PM~~ END 12:57 AM/PM ~~AM/PM~~ Examiners Initials MC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	MC	OK	none observed	
MAIN North Seals 3 Haulage	20.9	0	0	MC	OK	none observed	
MAIN West Haulage 3 Seals	20.9	0	0	TC/MC	OK	None observed	
3rd North Seals Haulage	20.9	0	0	TC	OK	none observed	
1st Right Haulage	20.9	0	0	TC	OK	None observed	
Transformers	20.9	0	0	MC/TC	OK	none observed	
Chargers	20.9	0	0	TC	OK	none observed	
Wash Down	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED
 INTAKE GETTING GRAY MAIN WEST 110-137 - "ROCK DUSTED INTAKE"

LOCATIONS	HAZARDS	ACTIONS
110-137	NEEDING DUST	ROCK DUSTED

PRE-SHIFT REMARKS All Areas appeared safe
at time of exam

Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 03892

2MSHA03070

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-10-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:10 AM/PM AM PM
 TIME OF EXAMINATION START 7:00 AM/PM AM PM
 TIME OF EXAMINATION START _____ AM/PM AM PM

END 9:17 AM/PM AM PM
 END 9:12 AM/PM AM PM
 END _____ AM/PM AM PM

Examiners Initials JG
 Examiners Initials SW
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	21.0	0	0	SW	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SW	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW	OK	NONE OBSERVED	
WASH DOWN STORAGE AREA	20.9	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED, REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 0739
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-11-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:40 AM/PM
 TIME OF EXAMINATION START 4:00 AM/PM
 TIME OF EXAMINATION START 2:00 AM/PM

END 4:55 AM/PM
 END 5:05 AM/PM
 END 3:05 AM/PM

Examiners Initials JG
 Examiners Initials JL
 Examiners Initials SM

EXAM. CALLED OUT ----- YES/NO ()

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>PARKING AREA</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>MAIN NORTH HAULAGE-SEALS</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>M. WEST HAULAGE-SEALS</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>3RD NORTH HAULAGE-SEALS</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>1ST RIGHT HAULAGE</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>STORAGE</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>WASHTDOWN</u>	<u>21.0</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>CHARGERS</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	
<u>POWER CENTERS</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JG</u>	<u>OK</u>	<u>NONE OBSERVED</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED APPEARED SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 9759
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03072

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7/1/07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:55 ~~AM/PM~~ END 1 ~~AM/PM~~ Examiners Initials GA
 TIME OF EXAMINATION START 11:00 ~~AM/PM~~ END 1:20 ~~AM/PM~~ Examiners Initials mc
 TIME OF EXAMINATION START 11:50 ~~AM/PM~~ END 1:45 ~~AM/PM~~ Examiners Initials TC

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
U.G. Parking	21	0	0	GA	OK	None observed	
M.No. Haulage ^{Seals}	21	0	0	GA	OK	None observed	
main west ^{Haulage} _{Seals}	20.9	0	0	mc/TC	OK	None observed	
3 No. Haulage ^{Seals}	20.9	0	0	GA	OK	None observed	
1st Right	20.9	0	0	GA	OK	None observed	
Transformers	20.9	0	0	mc/TC	OK	None observed	
Chargers	20.9	0	0	mc/TC	OK	None observed	
washdown	20.9	0	0	TC	OK	None observed	
Storage	20.9	0	0	mc	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe AT Time of pre-shift

Signature _____

PRE-SHIFT/MINE EXAMINER CERT. # 03892
 PRE-SHIFT/MINE EXAMINER CERT. # 7875
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 03895

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-11-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 7:37
 TIME OF EXAMINATION START 9:00
 TIME OF EXAMINATION START 7:02

AM/PM (AM) END 9:00 AM/PM
 AM/PM (AM) END 9:20 AM/PM
 AM/PM (AM) END 9:20 AM/PM

Examiners Initials SW
 Examiners Initials LD
 Examiners Initials SW

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{slots} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{haulage} slots	21.0	0	0	SW SW		none observed	
35th North ^{slots} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	SW SW	OK	none observed	
Transformers	21.0	0	0	SW SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINEE _____ **Signature** _____ CERT. # 9548
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9759
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ **Signature** _____ CERT. # 7488

2MSHA03074

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-12-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 3:40 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 4:05 AM/PM

END 5:15 AM/PM
 END 5:15 AM/PM
 END 5:10 AM/PM

Examiners Initials SW
 Examiners Initials SW
 Examiners Initials JD

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SEALS} haulage	21.0	0	0	SW SW	OK	none observed	
3rd North ^{SEALS} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
Chargers	21.0	0	0	SW SW	OK	none observed	
Transformers	21.0	0	0	SW SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 9779
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03992

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7/12/07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:45 AM/PM
 TIME OF EXAMINATION START 11:40 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:55 AM/PM
 END 1:45 AM/PM
 END _____ AM/PM

Examiners Initials GT
 Examiners Initials TL
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
UG Parking	21	0	0	GT	OK	None observed	
M No. Haulage ^{seals}	21	0	0	GT	OK	None observed	
M. West Haulage ^{seals}	20.9	0	0	TL/MC	OK	none obs.	
3 No Haulage ^{seals}	20.9	0	0	GT	OK	None observed	
1st Right	20.9	0	0	GT	OK	None observed	
Stack Area	20.9	0	0	TL	OK	None obs.	
Wash Down	20.9	0	0	MC	OK	None obs.	
Chargers	20.9	0	0	TL/MC	OK	None obs.	
Transformers	20.9	0	0	TL/MC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at time of Exa

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 03892
 CERT. # 9362
 CERT. # 7321
 CERT. # _____

COUNTER SIGNATURE _____
 Signature
 CERT. # 03892

2MSHA03076

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-12-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:50
 TIME OF EXAMINATION START 7:03
 TIME OF EXAMINATION START 9:04

AM/PM (AM) END 9:00 AM/PM (AM)
 AM/PM (AM) END 9:15 AM/PM (AM)
 AM/PM (AM) END 9:25 AM/PM (AM)

Examiners Initials SW
 Examiners Initials SW
 Examiners Initials LD

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SEALS haulage}	21.0	0	0	SW	OK	none observed	
Main West ^{SEALS haulage}	21.0	0	0	SW	OK	None observed	
3 rd North ^{SEALS haulage}	21.0	0	0	SW	OK	none observed	
1 st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
chargers	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appared SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER. Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 9759
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03077

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-13-07

SECTION/AREA General 1 Mine

TIME OF EXAMINATION START 3:43 AM/PM
 TIME OF EXAMINATION START 3:05 AM/PM
 TIME OF EXAMINATION START 4:25 AM/PM

END 5:15 AM/PM
 END 3:19 AM/PM
 END 5:20 AM/PM

Examiners Initials SW
 Examiners Initials SW
 Examiners Initials SW

EXAM. CALLED OUT YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{seals} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{seals} haulage	21.0	0	0	SW SW	OK	None observed	
3 rd North ^{seals} haulage	21.0	0	0	SW	OK	none observed	
1 st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
wash down	21.0	0	0	SW	OK	none observed	
chargers	20.9	0	0	SW SW	OK	None observed	
Transformers	20.9	0	0	SW SW	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Approved SAFE AT THE TIME
- OF EXAM

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 9548
 CERT. # 9759
 CERT. # 9660
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-13-07 SECTION/AREA Gewmine 1

TIME OF EXAMINATION START 11:58 AM/PM PM END 12:30 AM/PM PM
 TIME OF EXAMINATION START 1:00 AM/PM PM END 12:55 AM/PM PM
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM

Examiners Initials MC
 Examiners Initials DD
 Examiners Initials _____

EXAM. CALLED OUT --- YES/NO CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	MC	OK	none observed	
MAIN NORTH Haulage Seals	20.9	0	0	MC	OK	none observed	
MAIN WEST Haulage Seals	21	0	0	DD	OK	none observed	
3 NORTH Haulage Seals	21	0	0	DD	OK	none observed	
1st Right Haulage	21	0	0	DD	OK	none observed	
JRANS Formers	21	0	0	DD	OK	none observed	
chargers	21	0	0	DD	OK	none observed	
Washdown	21	0	0	DD	OK	none observed	
STORAGE AREA	21	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINER _____

Signature _____

CERT. # 7325
 CERT. # 8058
 CERT. # _____
 CERT. # _____

COUNTER SIGNATUR _____
 Signature _____
 CERT. # 8262

2MSHA03079

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-13-07 SECTION/AREA Gen Mtn | |

TIME OF EXAMINATION START 800 AM/PM END 851 AM/PM Examiners Initials DS
 TIME OF EXAMINATION START 700 AM/PM END 750 AM/PM Examiners Initials KK/RL
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	DG	OK	none obs.	
Main North Seals Haulage	20.9	0	0	DG	OK	none obs.	
Main West Haulage Seals	20.9	0	0	RL/KK	OK	none observed	
3rd North Haulage Seals	20.9	0	0	RL/KK	OK	none observed	
1st Right	20.9	0	0	KK	OK	none observed	
Storage Area	20.9	0	0	RL	OK	none observed	
Washdown	20.9	0	0	RL	OK	none observed	
Chargers	20.9	0	0	KK/RL	OK	none observed	
Transformers	20.9	0	0	KK/RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 4135
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6801
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 4135

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-14-07

SECTION/AREA Con/Min 1

TIME OF EXAMINATION START 300 AM/PM
 TIME OF EXAMINATION START 405 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 550 AM/PM
 END 450 AM/PM
 END _____ AM/PM

Examiners Initials KK/RC
 Examiners Initials DG
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking Area</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>DG</u>	<u>0</u>	<u>none obs</u>	
<u>Main North Haulage Road</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>DG</u>	<u>0</u>	<u>none obs</u>	
<u>Main West Haulage Road</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK/RC</u>	<u>0</u>	<u>none observed</u>	
<u>3rd North Haulage Road</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK/RC</u>	<u>0</u>	<u>none observed</u>	
<u>1st Right</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none observed</u>	
<u>Storage Area</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>0</u>	<u>none obs.</u>	
<u>Whelocum</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK/RC</u>	<u>0</u>	<u>none obs</u>	
<u>Chargers</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK/RC</u>	<u>0</u>	<u>none obs</u>	
<u>Transformer</u>	<u>21</u>	<u>0</u>	<u>0</u>	<u>KK/RC</u>	<u>0</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe
at end of shift

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 0801
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-14-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START 11:42 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:15 AM/PM
 END 12:05 AM/PM
 END _____ AM/PM

Examiners Initials PL
 Examiners Initials R
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	R	↻	None Observed	
Main North haulage seals	20.9	0	0	R	↻	None Observed	
Main West haulage seals	20.9	0	0	PL	↻	None Observed	
3rd North haulage seals	20.9	0	0	PL	↻	None Observed	
1st Right	20.9	0	0	PL	↻	None Observed	
Transformers	20.9	0	0	PL	↻	None Observed	
Changers	20.9	0	0	PL	↻	None Observed	
Storage area	20.9	0	0	PL	↻	None Observed	
Wash down	20.9	0	0	PL	↻	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 8462
 CERT. # 9243
 CERT. # _____
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03082

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-14-07

SECTION/AREA Pen Mine 1

TIME OF EXAMINATION
TIME OF EXAMINATION
TIME OF EXAMINATION

START 800
START 700
START _____

AM/PM
AM/PM
AM/PM

END 930 AM/PM
END 9:30 AM/PM
END _____ AM/PM

Examiners Initials RL
Examiners Initials KK/PG
Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Perking area	21	0	0	RL	OK	none observed	
Main West ^{haulage}	20.9	0	0	KK/PG	OK	none observed	
Main North ^{haulage}	21	0	0	RL	OK	none observed	
3rd North ^{haulage}	21	0	0	RL	OK	none do.	
1st Right	21	0	0	RL	OK	none do.	
Transformers	21	0	0	RL/PG	OK	none observed	
chargers	21	0	0	RL/PG	OK	none observed	
Storage area	21	0	0	RL	OK	none observed	
Workdown	21	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

all areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINE
PRE-SHIFT/MINE EXAMINE
PRE-SHIFT/MINE EXAMINE
PRE-SHIFT/MINE EXAMINER

CERT. # 6401
CERT. # 7959
CERT. # 9585
CERT. # _____

Signature

Signature

COUNTER SIGNATURE

CERT. # 4135

2MSHA03083

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-15-07

SECTION/AREA 2nd/11th

TIME OF EXAMINATION START 309 (A)PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 905 (A)PM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials KK
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>M. North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>none obs</u>	
<u>3rd Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>1st Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>α</u>	<u>none observed</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>none observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>α</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared to be safe at time of exam

Signature _____

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954
 CERT. # 6401
 CERT. # 9895
 CERT. # _____

Signature _____

COUNTER SIGNATURE _____ ERT. # 8402 2MSHA03084

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-15-07 SECTION/AREA Gen. Mine

TIME OF EXAMINATION START 11:00 AM/PM END 12:58 AM/PM Examiners Initials PC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North Haulage seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage seals	20.9	0	0	PC	OK	None Observed	
2nd North Haulage seals	20.9	0	0	PC	OK	None Observed	
1st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC	OK	None Observed	
Chargers	20.9	0	0	PC	OK	None Observed	
Storage area	20.9	0	0	PC	OK	None Observed	
Wash down	20.9	0	0	PC	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam.

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-15-87 SECTION/AREA Gen Mide | |

TIME OF EXAMINATION START 900 AM/PM AM/PM END 942 AM/PM AM/PM Examiners Initials Dh
 TIME OF EXAMINATION START 700 AM/PM AM/PM END 940 AM/PM AM/PM Examiners Initials RR/RL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	Dh	OK	none obs	
M. North Seals + Hangers	20.9	0	0	Dh	OK	none obs	
Main West + Hangers Seals	21	0	0	RR/RL	OK	none observed	
3rd North + Hangers Seals	21	0	0	RR/RL	OK	none observed	
1st Right	21	0	0	RL	OK	none obs.	
Storage area	21	0	0	RR	OK	none obs.	
Workdown	21	0	0	RR	OK	none obs.	
Transformers	21	0	0	RR/RL	OK	none obs.	
Chargers	21	0	0	RR/RL	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature _____

PRE-SHIFT/MINE EXAMINER CERT. # 4135
 PRE-SHIFT/MINE EXAMINER CERT. # 6401
 PRE-SHIFT/MINE EXAMINER CERT. # 7954
 PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature _____

COUNTER SIGNATUR CERT. # 4135

2MSHA03086

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-16-07

SECTION/AREA Gen/No 1

TIME OF EXAMINATION START 300
 TIME OF EXAMINATION START 400
 TIME OF EXAMINATION START _____

AM/PM
 PM
 AM/PM

END 535 AM/PM
 END 442 AM/PM
 END _____ AM/PM

Examiners Initials KK/RL
 Examiners Initials DL
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DL</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>DL</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>1st drift</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KL</u>	<u>OK</u>	<u>none obs</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RL</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RL</u>	<u>OK</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 4735
 CERT. # 7954
 CERT. # 6401
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-16-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:40 AM/PM
 TIME OF EXAMINATION START 11:45 AM/PM
 TIME OF EXAMINATION START 11:55 AM/PM

END 1:45 AM/PM
 END 1:40 AM/PM
 END 1:35 AM/PM

Examiners Initials TC
 Examiners Initials BP
 Examiners Initials BA

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
M. North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
M. West Haulage & Seals	20.9	0	0	TC/BP BH	OK	None obs.	
3rd North Haulage & Seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None obs.	
Wash Down	20.9	0	0	BH	OK	None obs.	
Transformers	20.9	0	0	TC/BP BH	OK	None obs.	
Chargers	20.9	0	0	BP/BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

Safe at time of exam

PRE-SHIFT/MINE EXAMINEE Signature
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINER

CERT. # 9362
 CERT. # 8597
 CERT. # 8395
 CERT. #

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03088

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-16-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:40
 TIME OF EXAMINATION START 7:00
 TIME OF EXAMINATION START 8:15

AM/PM (AM)
 AM/PM (AM)
 AM/PM (AM)

END 9:10 AM/PM (AM)
 END 9:05 AM/PM (AM)
 END 9:15 AM/PM (AM)

Examiners Initials SW
 Examiners Initials SW
 Examiners Initials SW

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage ^{SCALS}	21.0	0	0	SW	OK	none observed	
Main West haulage ^{SCALS}	20.9	0	0	SW SW	OK	none obs	
3rd North haulage ^{SCALS}	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Washdown	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW SW	OK	none obs	
Chargers	20.9	0	0	SW SW	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

all areas appeared safe at
end of exam

Signature

PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE

CERT. # 9548
 CERT. # 7959
 CERT. # 7660
 CERT. # _____

COUNTER SIGNATURE

Signature

CERT. # 7485

2MSHA03089

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-17-07

SECTION/AREA Gen Mine 1 | |

TIME OF EXAMINATION START 9:15
 TIME OF EXAMINATION START 8:45
 TIME OF EXAMINATION START 8:45

AM/PM AM/PM
 AM/PM AM/PM
 AM/PM AM/PM

END 9:15 AM/PM
 END 9:15 AM/PM
 END 5:30 AM/PM

Examiners Initials JS
 Examiners Initials FB
 Examiners Initials SW

EXAM. CALLED OUT YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	SW	OK	none observed	
M. North Haulage & Seals	20.9	0	0	SW	OK	none observed	
m west Haulage & Seals	20.9	0	0	JS	OK	none observed	
3rd North Haulage & Seals	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Storage Area	20.9	0	0	SW	OK	none observed	
Wash Down	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	JS	OK	none observed	
Chargers	20.9	0	0	JS	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS

all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 9585
 CERT. # 9660
 CERT. # 9548
 CERT. # _____

COUNTER SIGNATURE

Signature

CERT. # 03892

2MSHA03090

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-17-07

SECTION/AREA ben mine / /

TIME OF EXAMINATION
TIME OF EXAMINATION
TIME OF EXAMINATION

START 11:45 AM/PM
START 11:52 AM/PM
START 11:55 AM/PM

END 1:30 AM/PM
END 1:50 AM/PM
END 1:40 AM/PM

Examiners Initials TC
Examiners Initials BH
Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____
SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none obs.	
m north Haulage Seals	20.9	0	0	BH	OK	none obs.	
m. west Haulage Seals	20.9	0	0	BPTC BH	OK	none obs.	
3rd north Haulage Seals	20.9	0	0	BH	OK	none obs.	
1st right Haulage	20.9	0	0	BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	none obs.	
Wash Down	20.9	0	0	BH	OK	none obs.	
Transformers	20.9	0	0	TC/BH BP	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9362
CERT. # 8395
CERT. # 2599
CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03091

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-17-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION
TIME OF EXAMINATION
TIME OF EXAMINATION

START 7:55
START 7:00
START _____

AM/PM
AM/PM
AM/PM

END 9:15 AM/PM
END 9:30 AM/PM
END _____ AM/PM

Examiners Initials SW
Examiners Initials SW
Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
CALLED OUT BY _____
CALLED OUT BY _____

REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SCALS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SCALS} haulage	20.9	0	0	SW <u>SW</u>	OK	none obs	
3rd North ^{SCALS} haulage	21.0	0	0	SW	OK	needs dusted	dusted 7-17-07
1st Right	21.0	0	0	SW	OK	needs rock dust	dusted 7-17-07
Storage Area	21.0	0	0	SW	OK	none observed	
washdown	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	SW <u>SW</u>	OK	none obs	
chargers	20.9	0	0	SW <u>SW</u>	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
M West sec- tion intake	Getting gray	Bulk dusted OK

PRE-SHIFT REMARKS

all areas appeared safe at time of Exam

Signature

PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER
PRE-SHIFT/MINE EXAMINER

CERT. # 9548
CERT. # 7954
CERT. # 9680
CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 7485

2MSHA03092

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-18-07 SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:57 AM/PM END 5:30 AM/PM Examiners Initials JG
 TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials JD
 TIME OF EXAMINATION START 3:00 AM/PM END 5:15 AM/PM Examiners Initials SW

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE - SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE - SEALS	20.9	0	0	JG SW	OK	NONE OBSERVED	
3RD NORTH HAULAGE - SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	
WASH DOWN	20.9	0	0	JG	OK	NONE OBSERVED	
POWER CENTER	20.9	0	0	JG SW	OK	NONE OBSERVED	
CHARGENS	20.9	0	0	JG SW	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
346 intake	Getting gray	Bulk dusted

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature
 COUNTER SIGNATURE CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-18-07

SECTION/AREA Gen Mnd.

TIME OF EXAMINATION START 11:00
 TIME OF EXAMINATION START 11:55
 TIME OF EXAMINATION START 12:05

~~AM/PM~~
~~AM/PM~~
~~AM/PM~~

END 11:55 ~~AM/PM~~
 END 1:35 ~~AM/PM~~
 END 12:20 ~~AM/PM~~

Examiners Initials FM
 Examiners Initials BH
 Examiners Initials BH

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	OK	None observed	
MAIN North haulage seals	20.9	0	0	FM	OK	None observed	
MAIN West haulage seals	20.9	0	0	BH/BH	OK	None observed	
3rd North haulage seals	20.9	0	0	BH	OK	None observed	
1ST Right	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	
transformers	20.9	0	0	BH	OK	None observed	
chargers	20.9	0	0	BH	OK	None observed	
Wash down	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8297
 CERT. # 5325
 CERT. # 9397
 CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7/18/07 SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 7:00 AM/PM AM END 9:30 AM/PM PM Examiners Initials SW
 TIME OF EXAMINATION START 8:15 AM/PM PM END 9:30 AM/PM PM Examiners Initials LD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	JG	OK	NONE OBSERVED	
Main North ^{SEAB} haulage	21.0	0	0	JG	OK	NONE OBSERVED	
Main West ^{SEAB} haulage	20.9	0	0	JG SW	OK	NONE OBSERVED	
3rd North ^{SEAB} haulage	20.9	0	0	JG	OK	NONE OBSERVED	
1st Big Lt	20.9	0	0	JG	OK	NONE OBSERVED	
Storage Area	20.9	0	0	JG	OK	NONE OBSERVED	
Transformers	20.9	0	0	JG	OK	NONE OBSERVED	
Chargers	20.9	0	0	JG JG	OK	NONE OBSERVED	
Washdown	21.0	0	0	JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REPORTED REASONABLY SAFE AT TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 7485
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-19-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 3:50 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 4:05 AM/PM

END 5:10 AM/PM
 END 5:35 AM/PM
 END 5:15 AM/PM

Examiners Initials JG
 Examiners Initials SW
 Examiners Initials JR

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	21.0	0	0	SW JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	21.0	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	21.0	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT	21.0	0	0	JG	OK	NONE OBSERVED	
POWER CENTERS	21.0	0	0	SW JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SW JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
<u>MW intake 144-90</u>	<u>Getting gray</u>	<u>Bulk dusted &</u>

PRE-SHIFT REMARKS AREAS TRAVELED REPORTED
REASONABLY SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7485
 PRE-SHIFT/MINE EXAMINER CERT. # 9549
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 CERT. # 03892

2MSHA03096

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-19-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:23 AM/PM END 1:10 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 12:00 AM/PM END 1:50 AM/PM Examiners Initials TC
 TIME OF EXAMINATION START 12:05 AM/PM END 12:30 AM/PM Examiners Initials DP

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Hangage Seals	20.9	0	0	BH	OK	None Observed	
Main West Hangage Seals	20.9	0	0	BH/TC	OK	None observed	
3rd North Hangage Seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	BH/TC	OK	None observed	
Charger Area	20.9	0	0	BH/TC	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9565
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9579
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

2MSHA03097

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-19-07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 8:15 AM/PM AM PM
 TIME OF EXAMINATION START 7:00 AM/PM AM PM
 TIME OF EXAMINATION START 8:10 AM/PM AM PM

END 9:30 AM/PM AM PM
 END 9:25 AM/PM AM PM
 END 9:20 AM/PM AM PM

Examiners Initials JG
 Examiners Initials SJ
 Examiners Initials ZD

EXAM. CALLED OUT --- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	21.0	0	0	JG	OK	MANTRIP NOT BLOCKED #36	BLOCKED JG
MAIN NORTH HAULAGE SEALS	21.0	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE SEALS	21.0	0	0	SJ JG	OK	NONE OBSERVED	
3RD NORTH HAULAGE SEALS	21.0	0	0	JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	21.0	0	0	JG	OK	NONE OBSERVED	
STORAGE	21.0	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	21.0	0	0	JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SJ JG	OK	NONE OBSERVED	
TRANSFORMER	20.9	0	0	SJ JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS REASONABLY SAFE AT
TIME OF EXAMINATION

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 7485
 CERT. # 9548
 CERT. # 9660
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 7485

2MSHA03098

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7 20 07

SECTION/AREA GENERAL MINE 1

TIME OF EXAMINATION START 4:25 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM

END 5:15 AM/PM
 END 5:30 AM/PM
 END 5:25 AM/PM

Examiners Initials JG
 Examiners Initials SJ
 Examiners Initials JD

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
PARKING AREA	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN NORTH HAULAGE-SEALS	20.9	0	0	JG	OK	NONE OBSERVED	
MAIN WEST HAULAGE-SEALS	20.9	0	0	SJ JG	OK	NONE OBSERVED	
1ST RIGHT HAULAGE	20.9	0	0	JG	OK	NONE OBSERVED	
STORAGE	20.9	0	0	JG	OK	NONE OBSERVED	
WASHDOWN	20.9	0	0	JG	OK	NONE OBSERVED	
CHARGERS	20.9	0	0	SJ JG	OK	NONE OBSERVED	
TRANSFORMERS	20.9	0	0	SJ JG	OK	NONE OBSERVED	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS TRAVELED WERE
REASONABLY SAFE AT TIME OF EXAM

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 7485
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-20-07

SECTION/AREA Pen Mine 1

TIME OF EXAMINATION START 1200
 TIME OF EXAMINATION START 11:00
 TIME OF EXAMINATION START _____

AM/PM AM/PM
 AM/PM AM/PM
 AM/PM _____

END 140 AM/PM
 END 155 AM/PM
 END _____ AM/PM

Examiners Initials RL
 Examiners Initials RL/KK
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	RL	OK	none observed	
Main West Haulage Deck	21	0	0	RL	OK	none observed	
Main East Haulage Deck	20.9	0	0	RL/KK	OK	None observed	
3rd North Haulage Deck	21	0	0	RL	OK	none observed	
1st Right	21	0	0	RL	OK	none observed	
Storage	21	0	0	RL	OK	none observed	
Workshop	21	0	0	RL	OK	none observed	
Charger	20.9	0	0	RL/KK	OK	none observed	
Transformer	20.9	0	0	RL/KK	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

Signature

CERT. # 6401
 CERT. # 4325
 CERT. # 7954
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 8462

2MSHA03100

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-20-07 SECTION/AREA Gemmine 1

TIME OF EXAMINATION START 7:30 AM/PM AM END 9:50 AM/PM PM Examiners Initials PC/DD
 TIME OF EXAMINATION START 7:10 AM/PM AM END 7:32 AM/PM AM Examiners Initials PC
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PC	OK	none observed	
main north haulage seals	20.9	0	0	PC	OK	none observed	
main west haulage seals	20.9	0	0	MC/DD	OK	none observed	
3rd north haulage seals	20.9	0	0	MC/DD	OK	none observed	
1st Right Haulage	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	MC/DD	OK	none observed	
Chargers	20.9	0	0	MC/DD	OK	none observed	
Washdown	20.9	0	0	MC	OK	none observed	
Storage Area	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably Safe AT Time of Pre-shift

Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-21-07 SECTION/AREA Gen 1 Mines

TIME OF EXAMINATION START 4:15 AM/PM END 5:14 AM/PM Examiners Initials PC
 TIME OF EXAMINATION START 3:30 AM/PM END 5:41 AM/PM Examiners Initials DDMC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	PL	OK	None Observed	
Main North Haulage seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage seals	20.9	0	0	DDMC	ok	none obs.	
3 rd North Haulage seals	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/DDMC	ok	none obs.	
Chargers	20.9	0	0	PC/DDMC	ok	none obs.	
Wash down	20.9	0	0	DD	ok	none obs.	
Storage area	20.9	0	0	MC	ok	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____

Signature
 CERT. # 2462
 CERT. # 8058
 CERT. # 7375
 CERT. # _____

COUNTER SIGNATURE _____
 Signature _____ RT. # 4135

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-21-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11 AM/PM END 1148 AM/PM
 TIME OF EXAMINATION START 1100 AM/PM END 205 AM/PM
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM

Examiners Initials [Signature]
 Examiners Initials [Signature]
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (2) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Mine Work / Haulage seats</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RG</u>	<u>OK</u>	<u>none obs</u>	
<u>Parking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RG</u>	<u>OK</u>	<u>none obs</u>	
<u>Mine Work Haulage seats</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR/R</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd flight</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR/R</u>	<u>OK</u>	<u>none obs</u>	
<u>1st flight</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR</u>	<u>OK</u>	<u>none obs</u>	
<u>Workshop</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR</u>	<u>OK</u>	<u>none obs</u>	
<u>Trucks</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR</u>	<u>OK</u>	<u>none obs</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RR</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appear safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER. _____ CERT. # 4135
 PRE-SHIFT/MINE EXAMINER. _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER. _____ CERT. # 7969
 PRE-SHIFT/MINE EXAMINER. _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-21-07

SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 2:10 AM/PM
 TIME OF EXAMINATION START 7:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 8:03 AM/PM
 END 9:35 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials mc
 Examiners Initials _____

EXAM. CALLED OUT --- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North haulage seals	20.9	0	0	PC	OK	None Observed	
Main West haulage seals	20.9	0	0	MC/PC	OK	None observed	
3 rd North haulage seals	20.9	0	0	PC	OK	None observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/PC/PC	OK	None observed	
Changers	20.9	0	0	PC/PC/PC	OK	None observed	
Storage area	20.9	0	0	DD	OK	None observed	
Wash down	20.9	0	0	mc	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 8462
 CERT. # 7335
 CERT. # 8058
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 8462

2MSHA03104

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-22-07 SECTION/AREA Ben 1 Mining

TIME OF EXAMINATION START 11:00 ~~AM~~/PM END 5:07 ~~AM~~/PM Examiners Initials PC
 TIME OF EXAMINATION START 330 ~~AM~~/PM END 545 ~~AM~~/PM Examiners Initials DD MC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	DD/MC	OK	none obs.	
3 rd North seals ^{Haulage}	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/MC DD	OK	none obs.	
Chargers	20.9	0	0	PC/MC DD	OK	none obs.	
Storage area	20.9	0	0	MC	OK	none obs.	
Wash down	20.9	0	0	DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature
 CERT. # 4735

2MSHA03105

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-22-07

SECTION/AREA South Mine 1

TIME OF EXAMINATION START 11:05 AM/PM
 TIME OF EXAMINATION START 11:05 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:15 AM/PM
 END 12:15 AM/PM
 END _____ AM/PM

Examiners Initials KK
 Examiners Initials RL
 Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>RL/RR</u>	<u>OK</u>	<u>none observed</u>	
<u>North Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Tright</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washelover</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs.</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/RL</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 4735

2MSHA03106

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-22-07 SECTION/AREA Ben 1 Miner 1

TIME OF EXAMINATION START 7:10 AM/PM AM END 8:11 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:40 AM/PM PM Examiners Initials mc/rd
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.8	0	0	PC	OK	None Observed	
Main North Haulage seals	20.8	0	0	PC	OK	None observed	
Main West Haulage seals	20.9	0	0	mc/rd	OK	none observed	
310 North Haulage seals	20.8	0	0	PC	OK	None Observed	
15 th Right	20.8	0	0	PC	OK	None observed	
Transformers	20.8	0	0	PC/mc/rd	OK	none observed	
Chargers	20.9	0	0	PC/mc/rd	OK	none observed	
Storage area	20.9	0	0	rd	OK	none observed	
Wash down	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7335
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058

COUNTER SIGNATURE _____ Signature _____ CERT. # 8462

2MSHA03107

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 2-23-87 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 3:00 AM/PM END 3:52 AM/PM Examiners Initials PC
 TIME OF EXAMINATION START 3:30 AM/PM END 5:45 AM/PM Examiners Initials DD/mc
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.8	0	0	PC	OK	None Observed	
Main North seals	20.8	0	0	PC	OK	None Observed	
Main West seals	20.9	0	0	DD/mc	OK	none observed	
3 rd North seals	20.8	0	0	PC	OK	None Observed	
1 st Right	20.8	0	0	PC	OK	None Observed	
Trans Formers	20.9	0	0	PC	OK	none observed	
Chargers	20.9	0	0	PC/DD/mc	OK	none observed	
Storage area	20.9	0	0	MC	OK	none observed	
Wash down	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINEE CERT. # 8462
 PRE-SHIFT/MINE EXAMINEE CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4135

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-23-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 1100 (A) AM/PM
 TIME OF EXAMINATION START 1110 (A) AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 129 (A) AM/PM
 END 1210 (A) AM/PM
 END _____ AM/PM

Examiners Initials R/RR
 Examiners Initials KK
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (N)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	KK	0	none obs	
Main West Haulage Deck	21	0	0	KK/RR	0	none observed	
Main North Haulage Deck	21	0	0	KK	0	None obs	
East West Haulage Deck	21	0	0	KK	0	none obs	
bet Right	21	0	0	KK	0	none obs	
Transformers	21	0	0	KK/RR	0	none obs	
Chargers	21	0	0	KK/RR	0	none obs	
Storage area	21	0	0	KK	0	none obs	
Workdown	21	0	0	KK	0	None obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EX AM

PRE-SHIFT/MINE EXAMINEE Signature _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4323
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 4994
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-23-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:10 AM/PM AM END 8:06 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:40 AM/PM PM Examiners Initials DMC
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.8	0	0	PC	OK	None Observed	
Main North ^{Haulage} seals	20.8	0	0	PC	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	mc/100	OK	None Observed	
3rd North ^{Haulage} seals	20.8	0	0	PC	OK	None Observed	
1st Right	20.8	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/mc/100	OK	None Observed	
Chargers	20.9	0	0	PC/mc/100	OK	None Observed	
Storage area	20.9	0	0	mc/100	OK	None Observed	
Wash down	20.9	0	0	mc/100	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe
at time of pre-shift

Signature _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____
 COUNTER SIGNATURE _____ CERT. # 8462

2MSHA03110

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-24-07

SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 7:10 AM/PM
 TIME OF EXAMINATION START 830 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:29 AM/PM
 END 550 AM/PM
 END _____ AM/PM

Examiners Initials PL
 Examiners Initials DD MC
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None observed	
Main North ^{Haulage} seals	20.9	0	0	PL	OK	None observed	
Main West ^{Haulage} seals	20.9	0	0	DD/mc	ok	none observed	
3 rd East ^{Haulage} seals	20.9	0	0	PL	OK	None observed	
1 st Right	20.9	0	0	PL	OK	None observed	
Transformers	20.9	0	0	PL DD mc	ok	none observed	
Chargers	20.9	0	0	PL DD mc	ok	none observed	
Storage area	20.9	0	0	mc	ok	none observed	
Wash down	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
Main West intake	Getting gray	Bulk dusted
144 to 110		

PRE-SHIFT REMARKS All areas safe at time of exam

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-24-07 SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:00 AM/PM END 1:00 AM/PM Examiners Initials SW
 TIME OF EXAMINATION START 11:51 AM/PM END 1:20 AM/PM Examiners Initials FM
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/~~NO~~ CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	FM	CS	none observed	
Main North ^{SEALS} haulage	20.9	0	0	FM	CS	none observed	
Main West ^{SEALS} haulage	20.9	0	0	SW FM	CS	none observed	
3 rd North ^{SEALS} haulage	20.9	0	0	FM	CS	none observed	
1 st Right	20.9	0	0	FM	CS	none observed	
Transformers	20.9	0	0	SW FM	CS	none observed	
Chargers	20.9	0	0	SW FM	CS	none observed	
Storage Area	20.9	0	0	FM	CS	none observed	
Washdown	20.9	0	0	FM	CS	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared reasonably safe at time of exam

Signature
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 7969
 PRE-SHIFT/MINE EXAMINER CERT. # 8297
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03112

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-24-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:50 AM/PM AM END 9:30 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:51 AM/PM AM END 9:42 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START 8:01 AM/PM AM END 8:16 AM/PM PM Examiners Initials BA

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none observed	
Main north seals	20.9	0	0	BH	OK	none observed	
Main W. seals	20.9	0	0	BH TC BP	OK	none observed	
3rd north seals	20.9	0	0	BH	OK	none obs.	
1st right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/BH	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 2599
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-25-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 5:00 ~~AM/PM~~
 TIME OF EXAMINATION START 3:47 ~~AM/PM~~
 TIME OF EXAMINATION START 3:50 ~~AM/PM~~

END 5:10 ~~AM/PM~~
 END 5:15 ~~AM/PM~~
 END 5:32 ~~AM/PM~~

Examiners Initials RP
 Examiners Initials TK
 Examiners Initials BT

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None obs.	
^{Seals} main north hallway	20.9	0	0	BH	OK	None obs.	
^{Seals} main west hallway	20.9	0	0	TC/BH	OK	None obs.	
^{Seals} 3rd north hallway	20.9	0	0	BH	OK	None Observed	
1st Light	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	TC/BH	OK	None obs.	
Charger	20.9	0	0	TC/BH	OK	None obs.	
Storage Area	20.9	0	0	BH	OK	None obs.	
Wash Area	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 9599
 CERT. # 9362
 CERT. # 8395
 CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-25-07 SECTION/AREA Gen. mine / /

TIME OF EXAMINATION START 12:35 AM/PM END 1:10 AM/PM Examiners Initials LD
 TIME OF EXAMINATION START 11:00 AM/PM END 1:15 AM/PM Examiners Initials SW
 TIME OF EXAMINATION START 11:49 AM/PM END 1:05 AM/PM Examiners Initials PG

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parcking Area							
Parcking Area	20.9	0	0	<u>LD</u> <u>PG</u>	ok	none observed	
Main Nth seals Haulage	20.9	0	0	<u>LD</u> <u>PG</u>	ok	none observed	
Main west Haulage seal	20.9	0	0	<u>LD</u> <u>PG</u>	ok	none observed	
3rd Nth Seals Haulage	20.9	0	0	<u>LD</u> <u>PG</u>	ok	none observed	
1st Right	20.9	0	0	<u>LD</u>	ok	none observed	
trans formers	20.9	0	0	<u>LD</u> <u>PG</u>	ok	none observed	
chargers	20.9	0	0	<u>PG</u>	ok	none observed	
storage Area	20.9	0	0	<u>LD</u>	ok	none observed	
wash Down	20.9	0	0	<u>LD</u>	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
<u>#1 Road xca</u>	<u>Timber knocked out</u>	<u>Reset Timber</u>

PRE-SHIFT REMARKS all areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 9895
 PRE-SHIFT/MINE EXAMINER CERT. # 4325
 PRE-SHIFT/MINE EXAMINER CERT. # 9648

COUNTER SIGNATUR Signature CERT. # 2488

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-27-07

SECTION/AREA General mine 1

TIME OF EXAMINATION
 TIME OF EXAMINATION
 TIME OF EXAMINATION

START 8:00
 START 7:45
 START 7:50

AM/PM
 AM/PM
 AM/PM

END 8:22 AM/PM
 END 9:07 AM/PM
 END 9:47 AM/PM

Examiners Initials BP
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Scal ⁹ main north Halage	20.9	0	0	BH	OK	None Observed	
Scal ⁸ main west Halage	20.9	0	0	BP/BH	OK	none observed	
Scal ⁹ 3rd north Halage	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BP/BH	OK	none observed	
charges	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	
wash down	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 9392
 CERT. # 8395
 CERT. # 9362
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 03892

2MSHA03116

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-25-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 4:10 AM/PM END 4:30 AM/PM Examiners Initials BP
 TIME OF EXAMINATION START 3:50 AM/PM END 5:01 AM/PM Examiners Initials TC
 TIME OF EXAMINATION START 3:56 AM/PM END 5:30 AM/PM Examiners Initials BT

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.7	0	0	BH	OK	none obs.	
main north haulage	20.9	0	0	BH	OK	none obs.	
main west haulage	20.9	0	0	BP TC	OK	none observed	
3rd north haulage	20.9	0	0	BT	OK	none obs.	
1st Right	20.9	0	0	BH	OK	none obs.	
Transformers	20.9	0	0	BP TC	OK	none observed	
chargers	20.9	0	0	TC BH	OK	none obs	
Storage Area	20.9	0	0	BH	OK	none obs.	
wash down	20.9	0	0	BH	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9509
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature
 CERT. # 8925

COUNTER SIGNATURE

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-26-07

SECTION/AREA 6m Mine 1

TIME OF EXAMINATION START 11:01 AM/PM
 TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START 11:55 AM/PM

END 12:58 AM/PM
 END 1:05 AM/PM
 END 12:43 AM/PM

Examiners Initials PG
 Examiners Initials LD
 Examiners Initials JW

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North Seals/Haulage	21.0	0	0	SW	OK	none observed	
Main West Haulage/seals	20.9	0	0	PG & LD SW	OK	none observed	
3rd North Haulage/seals	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	20.9	0	0	PG & LD SW	OK	none observed	
Chargers	20.9	0	0	PG/SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	
Wash Down	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
West int. 140 to 88	Getting gray	Dusted

PRE-SHIFT REMARKS All areas appeared safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9895
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE _____
 CERT. # 03892

2MSHA03118

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-26-07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:45 AM/PM AM END 9:30 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:47 AM/PM AM END 9:35 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START 8:60 AM/PM AM END 8:20 AM/PM PM Examiners Initials BP

EXAM. CALLED OUT YES CALL OUT TIME _____ AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
n. north ^{seals} Headings	20.9	0	0	BH	OK	None Observed	
M. west ^{seals} Headings	20.9	0	0	TC/BH	OK	none obs.	
3rd north ^{seals} Headings	20.9	0	0	BH	OK	None Observed	
1st right	20.9	0	0	BH	OK	None Observed	
TRANSFORMERS	20.9	0	0	TC/BP BH	OK	None Obs.	
Chargers	20.9	0	0	BP/BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	none obs.	
Wash Down	20.9	0	0	BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9367
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9599
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-27-07 SECTION/AREA beamville 1 1

TIME OF EXAMINATION START 3:50 AM/PM END 5:17 AM/PM Examiners Initials TC
 TIME OF EXAMINATION START 4:10 AM/PM END 4:50 AM/PM Examiners Initials BP
 TIME OF EXAMINATION START 3:49 AM/PM END 5:30 AM/PM Examiners Initials BH

EXAM. CALLED OUT YES/NO CALL OUT TIME AM/PM
 CALLED OUT BY
 CALLED OUT BY REPORT RECEIVED BY
 CALLED OUT BY SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
mammouth Hoisting seals	20.9	0	0	BH	OK	None Observed	
M. West Hoisting seals	20.9	0	0	TC BP BH	OK	none obs.	
3rd North Hoisting seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC BP BH	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	none obs.	
Washdown	20.9	0	0	BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8398
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. #

COUNTER SIGNATUR Signature CERT. # 7483

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-27-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:00

AM/PM

END 12:15 AM/PM

Examiners Initials PG

TIME OF EXAMINATION START 1:50

AM/PM

END 1:50 AM/PM

Examiners Initials OS

TIME OF EXAMINATION START _____

AM/PM

END _____ AM/PM

Examiners Initials _____

EXAM. CALLED OUT YES/NO

CALL OUT TIME 1:50 AM/PM

CALLED OUT BY Dale Black

REPORT RECEIVED BY Phil [Signature]
SIGNATURE

CALLED OUT BY _____

CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	OS	ok	None Observed	
Main North ^{SLAB} haulage	20.7	0	0	OS	ok	None observed	
Main West ^{SLAB} haulage	20.7	0	0	PG	ok	cross cut 135 needs dust	working on / done OS
3rd North ^{SLAB} haulage	20.9	0	0	OS	ok	none observed	
1st Right	20.9	0	0	OS	ok	none observed	
Transformers	20.7	0	0	PG	ok	None observed	
chargers	20.7	0	0	PG	ok	None observed	
Storage Area	20.9	0	0	OS	ok	None observed	
washdown	20.9	0	0	OS	ok	None observed	
		0					

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9845
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7483
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 CERT. # 7483

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-26-07 SECTION/AREA Gen mine | |

TIME OF EXAMINATION START 3:52 AM/PM END 5:00 AM/PM Examiners Initials TK
 TIME OF EXAMINATION START 3:46 AM/PM END 5:31 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 3:50 AM/PM END 4:30 AM/PM Examiners Initials BP

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	none obs	
Main North Haulage Seals	20.9	0	0	BH	OK	none obs.	
Main West Haulage Seals	20.9	0	0	TCBP BH	OK	none obs.	
2nd North Haulage Seals	20.9	0	0	BH	OK	none obs.	
1st Right	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	TCBP BH	OK	none obs.	
Chargers	20.9	0	0	TC/BH	OK	none obs.	
Washdown	20.9	0	0	BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9599
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 74183

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-28-07 SECTION/AREA Gen mine

TIME OF EXAMINATION	START <u>7:46</u>	AM/PM <u>AM</u>	END <u>9:40</u>	AM/PM <u>AM</u>	Examiners Initials <u>BH</u>
TIME OF EXAMINATION	START <u>7:50</u>	AM/PM <u>AM</u>	END <u>9:25</u>	AM/PM <u>AM</u>	Examiners Initials <u>TC</u>
TIME OF EXAMINATION	START <u>8:00</u>	AM/PM <u>AM</u>	END <u>8:00</u>	AM/PM <u>AM</u>	Examiners Initials <u>ES</u>

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North ^{Haulage seals}	20.9	0	0	BH	OK	None Observed	
Main West ^{Haulage seals}	20.9	0	0	BH/TC	OK	none obs.	
3 rd North ^{Haulage seals}	20.9	0	0	BH	OK	None Observed	
1 st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC/BH	OK	none obs.	
Chargers	20.9	0	0	BH/	OK	none obs.	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9599
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-29-07

SECTION/AREA Gen mind / /

TIME OF EXAMINATION START 11:00 ~~AM/PM~~
 TIME OF EXAMINATION START 1140 ~~AM/PM~~
 TIME OF EXAMINATION START _____ AM/PM

END 1:00 ~~AM/PM~~
 END 110 ~~AM/PM~~
 END _____ AM/PM

Examiners Initials MC
 Examiners Initials DB
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Areas	20.9	0	ok	DB	Correct	None observed	
Main N. Haulage Seals	20.9	0	ok	DB	Correct	None Observed	
Main W. Haulage Seals	20.9	0	0	MC	OK	none observed	
3 rd N. Haulage Seals	20.9	0	0	MC	OK	none observed	
1 st Right	20.9	0	0	MC	OK	none observed	
Transformers	20.9	0	0	MC	OK	none observed	
Chargers	20.9	0	0	MC	OK	none observed	
Wash down	20.9	0	0	MC	OK	none observed	
Storage Areas	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas Appeared Reasonably safe at Time of pre-shift

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 7325
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7483
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATUR _____ Signature _____ CERT. # 7483

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-30-07

SECTION/AREA Gen minr

TIME OF EXAMINATION START 3:48 ~~AM~~/PM
 TIME OF EXAMINATION START 4:10 ~~AM~~/PM
 TIME OF EXAMINATION START 4:20 ~~AM~~/PM

END 5:29 ~~AM~~/PM
 END 5:14 ~~AM~~/PM
 END 4:50 ~~AM~~/PM

Examiners Initials BH
 Examiners Initials TC
 Examiners Initials BP

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North <small>Haulage Seals</small>	20.9	0	0	BH	OK	None Observed	
Main West <small>Haulage Seals</small>	20.9	0	0	BH/TC/BP	OK	Deep water #2 roadway X-cut 48	Ass men to pump Pumped 7:30:07
3 rd North <small>Haulage Seals</small>	20.9	0	0	BH	OK	None Observed	
1 st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC/BP	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Areas	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 2599
 PRE-SHIFT/MINE EXAMINER CERT. # _____

Signature

COUNTER SIGNATURE CERT. # 4785

2MSHA03129

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-30-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 7:00 AM/PM AM END 8:01 AM/PM PM Examiners Initials PL
 TIME OF EXAMINATION START 7:30 AM/PM PM END 9:40 AM/PM PM Examiners Initials mc/DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing area	20.9	0	0	PL	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	PL	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	mc/DD	OK	none observed	
3 rd North ^{Haulage} seals	20.9	0	0	PL	OK	None Observed	
1 st Right	20.9	0	0	PL	OK	None Observed	
Transformers	20.9	0	0	mc/DD	OK	none observed	
Chargers	20.9	0	0	mc/DD	OK	none observed	
Storage area	20.9	0	0	DD	OK	none observed	
Wash Down	20.9	0	0	mc	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-31-07

SECTION/AREA Ben Mine 1

TIME OF EXAMINATION START 3:58 AM/PM
 TIME OF EXAMINATION START 3:30 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 4:50 AM/PM
 END 3:45 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials DD mc
 Examiners Initials _____

EXAM. CALLED OUT --- YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	DD mc	OK	none obs.	
3 rd North ^{Haulage} seals	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	DD mc	OK	none obs.	
Chargers	20.9	0	0	DD mc	OK	none obs.	
Storage area	20.9	0	0	mc	OK	none obs.	
Wash down	20.9	0	0	DD	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be safe at time of preshift

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 8462
 CERT. # 8058
 CERT. # 7375
 CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4935

2MSHA03132

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7/31/07 SECTION/AREA Gen Mine

TIME OF EXAMINATION START 1200 AM/PM ~~AM/PM~~ END 1246 AM/PM ~~AM/PM~~ Examiners Initials DL
 TIME OF EXAMINATION START 1100 AM/PM ~~AM/PM~~ END 2100 AM/PM ~~AM/PM~~ Examiners Initials DL
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	DL	OK	none observed	
Main North Haulage Seals	20.9	0	0	DL	OK	none observed	
Mill West Haulage Seals	20.9	0	0	KK/LR	OK	none obs	
Trans.	20.9	0	0	LR/KK	OK	none obs	
chargers	20.9	0	0	KK/LR	OK	none obs	
3 North Haulage Seals	20.9	0	0	KK/LR	OK	none obs	
1st right	20.9	0	0	LR/KK	OK	none obs	
Storage area	20.9	0	0	LR	OK	none obs	
Washdown	20.9	0	0	LR	OK	none obs	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appear safe at end of EXAM

PRE-SHIFT/MINE EXAMINER Signature CERT. # 4735
 PRE-SHIFT/MINE EXAMINER CERT. # 7964
 PRE-SHIFT/MINE EXAMINER CERT. # 4375
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 7-31-07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 7:00 AM/PM AM END 8:20 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 7:30 AM/PM AM END 9:40 AM/PM PM Examiners Initials MC/DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21.0	0	0	PC	OK	None Observed	
Main North seals ^{Haulage}	21.0	0	0	PC	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	MC/DD	OK	None observed	
3 rd North Haulage seals	21.0	0	0	PC	OK	None Observed	
1 st Right	21.0	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/DD	OK	None observed	
Chargers	20.9	0	0	PC/DD	OK	None observed	
Storage area	20.9	0	0	DD	OK	None observed	
Wash down	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462 2MSHA03134

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-1-07 SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 4:29 ~~AM~~/PM END 5:31 ~~AM~~/PM Examiners Initials PC
 TIME OF EXAMINATION START 4:35 ~~AM~~/PM END 5:40 ~~AM~~/PM Examiners Initials MC/DD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21.0	0	0	PC	OK	None Observed	
Main North seals ^{Haulage}	21.0	0	0	PC	OK	None Observed	
Main West seals ^{Haulage}	20.9	0	0	MC/DD	OK	none observed	
3 rd North seals ^{Haulage}	21.0	0	0	PC	OK	None Observed	
1 st Right	21.0	0	0	PC	OK	None Observed	
Transfarmers	20.9	0	0	PC MC DD	OK	none observed	
Chargers	20.9	0	0	PC MC DD	OK	none observed	
Storage area	20.9	0	0	MC	OK	none observed	
Wash Down	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 4735

2MSHA03135

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-1-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:45 AM/PM
 END 1:35 AM/PM
 END _____ AM/PM

Examiners Initials RL
 Examiners Initials RJR
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	RL	OK	none observed	
Main North Haulage Seals	21	0	0	RL	OK	none obs.	
Main West Haulage Seals	20.9	0	0	RL/RJR	OK	none obs	
3rd North Haulage Seals	21	0	0	RL	OK	none observed	
1st Right	21	0	0	RL	OK	none observed	
Transformers	20.9	0	0	RL/RJR	OK	none obs	
chargers	20.9	0	0	RL/RJR	OK	none obs	
Storage area	21	0	0	RL	OK	none observed	
Washdown	21	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of EXAM

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 6401
 CERT. # 7454
 CERT. # 43751
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 8462

2MSHA03136

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-1-02 SECTION/AREA Gen 1 Mine 1

TIME OF EXAMINATION START 7:10 AM/PM AM END 8:16 AM/PM PM Examiners Initials PC
 TIME OF EXAMINATION START 7:35 AM/PM AM END 9:33 AM/PM PM Examiners Initials MC/DD
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing area	20.9	0	0	PC	OK	None Observed	
Main North Haulage seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage seals	20.9	0	0	MC/DD	OK	None observed	
3 rd North Haulage seals	20.9	0	0	PC	OK	None Observed	
1 st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC/MC/DD	OK	None observed	
Chargers	20.9	0	0	PC/MC/DD	OK	None observed	
Storage area	20.9	0	0	DD	OK	None observed	
Wash down	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE AT TIME OF PRE-SHIFT

Signature

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7371
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 8462 2MSHA03137

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-2-07

SECTION/AREA Gen 1 Mine

TIME OF EXAMINATION START 4:05
 TIME OF EXAMINATION START 3:35
 TIME OF EXAMINATION START _____

AM/PM END 5:01 AM/PM
 AM/PM END 5:40 AM/PM
 AM/PM END _____ AM/PM

Examiners Initials PL
 Examiners Initials mc/DD
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO
 CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

CALL OUT TIME ----- AM/PM

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None observed	
Main North ^{Haulage} scale	20.9	0	0	PL	OK	None observed	
Main West ^{Haulage} scale	20.9	0	0	mc/DD	OK	none observed	
3 rd North ^{Haulage} scale	20.9	0	0	PL	OK	None observed	
1 st Right	20.9	0	0	PL	OK	None observed	
Transformers	20.9	0	0	PL/mc/DD	OK	none observed	
Chargers	20.9	0	0	PL/mc/DD	OK	none observed	
Storage area	20.9	0	0	mc	OK	none observed	
Wash down	20.9	0	0	DD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 7275
 PRE-SHIFT/MINE EXAMINER CERT. # 8462
 PRE-SHIFT/MINE EXAMINER CERT. # 8055
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 4135

2MSHA03138

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-2-07 SECTION/AREA Con Mines

TIME OF EXAMINATION START 11:30 AM/PM END 12:50 AM/PM Examiners Initials RL
 TIME OF EXAMINATION START 11:00 AM/PM END 1:10 AM/PM Examiners Initials LR/KK
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO Q CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____
 REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	21	0	0	RL	OK	none observed	
North North Haulage Deck	21	0	0	RL	OK	none "	
North West Haulage Deck	20.9	0	0	RL/KK	OK	none "	
3rd North Haulage Deck	21	0	0	RL	OK	none observed	
lat Right	21	0	0	RL	OK	none observed	
Transformers	20.9	0	0	RL/KK	OK	none obs	
chargers	20.9	0	0	RL/KK	OK	none obs	
Storage area	21	0	0	RL	OK	none observed	
Workdown	21	0	0	RL	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at end of exam,

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 6401
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9154
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 43715
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-2-07

SECTION/AREA Gen 1 Mine 1

TIME OF EXAMINATION START 7:10 AM/PM
 TIME OF EXAMINATION START 7:35 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 8:06 AM/PM
 END 9:35 AM/PM
 END _____ AM/PM

Examiners Initials PC
 Examiners Initials PC/DP
 Examiners Initials _____

EXAM. CALLED OUT ---- YES NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PC	OK	None Observed	
Main North Haulage seals	20.9	0	0	PC	OK	None Observed	
Main West Haulage seals	20.9	0	0	MC DD	OK	none observed	
3rd North Haulage seals	20.9	0	0	PC	OK	None Observed	
1st Right	20.9	0	0	PC	OK	None Observed	
Transformers	20.9	0	0	PC MC DD	OK	none observed	
chargers	20.9	0	0	PC MC DD	OK	none observed	
Storage area	20.9	0	0	DD	OK	none observed	
Wash down	20.9	0	0	MC	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared reasonably safe AT Time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 8462

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-3-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:00 AM/PM END 4:44 AM/PM Examiners Initials PL
 TIME OF EXAMINATION START 3:00 AM/PM END 5:40 AM/PM Examiners Initials DD/mc
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO) CALL OUT TIME ----- _____ AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	PL	OK	None observed	
Main North ^{Haulage} seals	20.9	0	0	PL	OK	None observed	
Main West ^{Haulage} seals	20.9	0	0	DD/mc	ok	none obs.	
3 rd North ^{Haulage} seals	20.9	0	0	PL	OK	None Observed	
15 th Right	20.9	0	0	PL	OK	None observed	
Transformers	20.9	0	0	DD/mc	ok	none obs.	
Chargers	20.9	0	0	PL	ok	none observed	
Storage area	20.9	0	0	ml	ok	none obs.	
wash down	20.9	0	0	DD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared to be safe at time of pre-shift

PRE-SHIFT/MINE EXAMINER Signature CERT. # 8462
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 8058
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-307

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START 11:41 AM/PM
 TIME OF EXAMINATION START 11:50 AM/PM

END 12:30 AM/PM
 END 12:56 AM/PM
 END 1:00 AM/PM

Examiners Initials LH
 Examiners Initials LH
 Examiners Initials SW

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LH	ok	none observed	
Main North ^{haulage} SEATS	20.9	0	0	LH	ok	none observed	
Main West ^{haulage} SEATS	20.9	0	0	LH LH	ok	none observed	
3 rd North ^{haulage} SEATS	20.9	0	0	LH	ok	none observed	
1 st Right	20.9	0	0	LH	ok	none observed	
Transformers	20.9	0	0	LH	ok	none observed	
Chargers	21.0	0	0	LH SW	ok	none observed	
Storage Area	20.9	0	0	LH	ok	none observed	
Washdown	20.9	0	0	LH	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appear to be safe at the time of exam

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 8703
 PRE-SHIFT/MINE EXAMINER CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03142

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-3-07 SECTION/AREA Open Mine | |

TIME OF EXAMINATION START 4:05 AM/PM AM END 9:15 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:49 AM/PM PM END 9:38 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START 7:50 AM/PM PM END 9:30 AM/PM PM Examiners Initials BP

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE
 CALLED OUT BY _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Mam Haulage north seals	20.9	0	0	BH	OK	None Observed	
Mam west seals ^{Phut.}	20.9	0	0	TC/ISD BH	OK	none obs.	
3rd north Haulage seals	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	TC/ISD BH	OK	None obs	
Chargers	20.9	0	0	BP BH	OK	none obs.	
Storage Area	20.9	0	0	BH	OK	None Observed	
Wash Down	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at
Time of exam

Signature

PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 9599
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE Signature RT. # 0389

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-4-07

SECTION/AREA Gen mine

TIME OF EXAMINATION START 3:50 AM/PM
 TIME OF EXAMINATION START 3:52 AM/PM
 TIME OF EXAMINATION START 4:00 AM/PM

END 5:35 AM/PM
 END 5:00 AM/PM
 END 5:00 AM/PM

Examiners Initials BH
 Examiners Initials TC
 Examiners Initials BP

EXAM. CALLED OUT ---- YES/NO NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North ^{Harbage} Seals	20.9	0	0	BH	OK	None Observed	
Main west ^{Harbage} Seals	20.9	0	0	BH/TC	OK	None Observed	
3 rd North ^{Harbage} Seals	20.9	0	0	BH	OK	None Observed	
1 st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH/TC	OK	None Observed	
Chargers	20.9	0	0	BH/TC	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 8599
 PRE-SHIFT/MINE EXAMINER CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 7485

2MSHA03144

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-4-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:00 AM/PM AM
 TIME OF EXAMINATION START 12:00 AM/PM PM
 TIME OF EXAMINATION START 12:25 AM/PM PM

END 1:00 AM/PM PM
 END 1:30 AM/PM PM
 END 1:30 AM/PM PM

Examiners Initials SW
 Examiners Initials JD
 Examiners Initials GW

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North ^{SCALS} haulage	21.0	0	0	SW	OK	none observed	
Main West ^{SCALS} haulage	21.0	0	0	SW SW	OK	none observed	
3rd North ^{SCALS} haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW SW	OK	none observed	
chargers	21.0	0	0	SW SW	OK	none observed	
washdown	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9548
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # 7999
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-4-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 9:10 AM/PM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials BH
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	BH	OK	None observed	
Main North ^{Haulage} Seals	20.9	0	0	BH	OK	None observed	
Main West ^{Haulage} Seals	20.9	0	0	BH	OK	None observed	
3 rd North ^{Haulage} Seals	20.9	0	0	BH	OK	None observed	
1 st Right	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	BH	OK	None observed	
Choppers	20.9	0	0	BH	OK	None observed	
Washdown	20.9	0	0	BH	OK	None observed	
Storage Area	20.9	0	0	BH	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature _____

PRE-SHIFT/MINE EXAMINE _____
 PRE-SHIFT/MINE EXAMINE, _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 8395
 CERT. # _____
 CERT. # _____
 CERT. # _____

COUNTER SIGNATURE Signature CERT. # 03892

2MSHA03146

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-5-07 SECTION/AREA Gen Mine 1 1

TIME OF EXAMINATION START 3:30 AM/PM END 4:01 AM/PM Examiners Initials BP
 TIME OF EXAMINATION START 3:46 AM/PM END 5:30 AM/PM Examiners Initials BH
 TIME OF EXAMINATION START 3:07 AM/PM END 3:24 AM/PM Examiners Initials TC

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North Entry	20.9	0	0	BH	OK	None Observed	
Main West Entry	20.9	0	0	BP TC BH	OK	None Observed	
3rd Shift Hoop	20.9	0	0	BH	OK	None Observed	
1st Right	20.9	0	0	BH	OK	None Observed	
Transformed	20.9	0	0	BP TC BH	OK	None Observed	
Changers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Stagg Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 9599
 CERT. # 8395
 CERT. # 9362
 CERT. # _____

COUNTER SIGNATURE _____
 SIGNATURE _____
 RT. # 7480

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-5-07

SECTION/AREA General 1 Mine 1

TIME OF EXAMINATION START 11:00
 TIME OF EXAMINATION START 12:25
 TIME OF EXAMINATION START _____

AM/PM AM END 1:10 AM/PM AM
 AM/PM AM END 1:25 AM/PM AM
 AM/PM _____ END _____ AM/PM _____

Examiners Initials SW
 Examiners Initials LD
 Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO (O)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	21.0	0	0	SW	OK	none observed	
Main North haulage	21.0	0	0	SW	OK	none observed	
Main West haulage	21.0	0	0	SW LD	OK	none observed	
3rd North haulage	21.0	0	0	SW	OK	none observed	
1st Right	21.0	0	0	SW	OK	none observed	
Transformers	21.0	0	0	SW LD	OK	none observed	
Chargers	21.0	0	0	SW LD	OK	none observed	
Washhouse	21.0	0	0	SW	OK	none observed	
Storage Area	21.0	0	0	SW	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Appernd Safe at the time of exam

PRE-SHIFT/MINE EXAMINEF Signature CERT. # 9548
 PRE-SHIFT/MINE EXAMINEF _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINEF _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINEF _____ CERT. # _____

Signature
 CERT. # 7485

COUNTER SIGNATURE

2MSHA03148

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-5-07 SECTION/AREA Gen mine / /

TIME OF EXAMINATION START 7:00 AM/PM AM END 9:13 AM/PM PM Examiners Initials BH
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH	OK	None Observed	
Main North ^{Haulage} seals	20.9	0	0	BH	OK	None Observed	
Main West ^{Haulage} seals	20.9	0	0	BH	OK	None Observed	
3 rd North ^{Haulage} seals	20.9	0	0	BH	OK	None Observed	
1 st Right	20.9	0	0	BH	OK	None Observed	
Transformers	20.9	0	0	BH	OK	None Observed	
Chargers	20.9	0	0	BH	OK	None Observed	
Washdown	20.9	0	0	BH	OK	None Observed	
Storage Area	20.9	0	0	BH	OK	None Observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

PRE-SHIFT/MINE EXAMINER _____ Signature _____ CERT. # 8395
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE _____ Signature _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-6-07

SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 2:28 AM/PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:25 AM/PM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials FMY/MC
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	MC	OK	None observed	
MAIN North haulage seals	20.9	0	0	FMY/MC	OK	None observed	
MAIN West haulage seals	20.9	0	0	FMY/MC	OK	SEE BELOW None observed	
3rd North haulage seals	20.9	0	0	FMY/MC	OK	None observed	
1st Right	20.9	0	0	MC	OK	None observed	
Transformers	20.9	0	0	FMY/MC	OK	SEE BELOW	
chargers	20.9	0	0	MC	OK	None observed	
wash down	20.9	0	0	MC	OK	None observed	
Storage Area	20.9	0	0	MC	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Stoppings #93 in by All Down - temporary
stoppings in place - All other areas appeared reasonably
safe at time of exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 8297
 CERT. # 7375
 CERT. # _____
 CERT. # _____

Signature

Signature

COUNTER SIGNATURE

ERT. # 8462

2MSHA03150

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 4-6-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 7:20 AM/PM AM END 8:35 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:07 AM/PM AM END 8:26 AM/PM PM Examiners Initials BL
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Packing Area	20.9	0	0	TC/BH	OK	None obs.	
Main North Haulage & seals	20.9	0	0	TC/BH	OK	None obs.	
Main West Haulage & seals	20.9	0	0	TC/BH	OK	see below	Working on
3rd North Haulage seals	20.9	0	0	TC/BH	OK	None obs.	
1st Right	20.9	0	0	BH	OK	None obs.	
Transformers	20.9	0	0	TC/BH	OK	see below	
Chargers	20.9	0	0	TC/BH	OK	None obs.	
Wash Down	20.9	0	0	TC	OK	None obs.	
Storage Area	20.9	0	0	TC	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Intake to Belt stoppings out xcs 96, 97, 98, 99, 100, 102, 104, 106, 107, 108, 109, 6 Belt 1, 2, 3, 4
All other Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 8395
 PRE-SHIFT/MINE EXAMINER CERT. # 1450
 PRE-SHIFT/MINE EXAMINER CERT. # 4375

COUNTER SIGNATURE _____ CERT. # _____

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 87-07

SECTION/AREA Gen. Mined / /

TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 3:50 AM/PM
 TIME OF EXAMINATION START 3:45 AM/PM

END 5:30 AM/PM
 END 4:40 AM/PM
 END 5:40 AM/PM

Examiners Initials LR/KK
 Examiners Initials TC
 Examiners Initials BT

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC/BH	OK	none obs.	
Mine North ^{haulage} _{seals}	20.9	0	0	TC/BH	OK	none obs.	
Mine West ^{haulage} _{seals}	20.9	0	0	LR, KK TC/BH	OK	Put in Temporary Cartridges 94, 96, 97 - See below	Working on
3 rd North ^{haulage} _{seals}	20.9	0	0	TC/BH	OK	None	
1 st Right	20.9	0	0	TC	OK	none obs.	
Truss Chambers	20.9	0	0	TC/BH	OK	none obs.	
Chargers	20.9	0	0	TC/KK	OK	none obs.	
Wash down	20.9	0	0	LR/KK	OK	None	
Storage Areas	20.9	0	0	LR	OK	None	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Personnel were moved back to 94 to Rebuild Stoppings.
Intake to Belt Stopping out 94, 96, 97, 98, 99, 100, 102, 104, 105, 109, 6 Belt 4, 2, 3, 4, & all others
Areas approved safe at time of Exam

PRE-SHIFT/MINE EXAMINER: Signature CERT. # 4325
 PRE-SHIFT/MINE EXAMINER: _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER: _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER: _____ CERT. # 8395

Signature

COUNTER SIGNATURE _____ CERT. # 8462

2MSHA03152

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-7-07

SECTION/AREA Gen Mine 1 / /

TIME OF EXAMINATION START 11:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 1:30 AM/PM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials LD
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Prackling Area	20.9	0	0	LD	ok	none observed	
main North ^{seals} Haulage	20.9	0	0	LD	ok	none observed	
main west ^{seals} Haulage	20.9	0	0	LD	ok	stopings See 94, 96, 97 Below	working on Done 8-8-07
3rd North ^{seals} Haulage	20.9	0	0	LD	ok	none observed	
1st Right	20.9	0	0	LD	ok	none observed	
transformers	20.9	0	0	LD	ok	none observed	
chargers	20.9	0	0	LD	ok	none observed	
wash down	20.9	0	0	LD	ok	none observed	
Storage Area	20.9	0	0	LD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Apper-d Safe at the time of exam except as noted above. Done 8-8-07
En date to belt stoping out 94, 96, 97, 98, 99, 100, 102, 104, 108, 109 #6 Belt 1, 2, 3, 4

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03153

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-7-07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 7:35 AM/PM AM
 TIME OF EXAMINATION START 7:37 AM/PM AM
 TIME OF EXAMINATION START 7:25 AM/PM AM

END 8:18 AM/PM AM
 END 8:27 AM/PM AM
 END 8:50 AM/PM AM

Examiners Initials BH
 Examiners Initials TC
 Examiners Initials RLK

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	BH/TC	OK	None observed	
Main North <small>Haulage seals</small>	20.9	0	0	BH/TC	OK	None observed	
Main West <small>Haulage seals</small>	20.9	0	0	BH/TC	OK	None observed	
3 rd North <small>Haulage seals</small>	20.9	0	0	BH/TC	OK	None observed	
1 st Right	20.9	0	0	BH	OK	None observed	
Transformers	20.9	0	0	BH/TC RL	OK	None observed	
Chargers	20.9	0	0	BH	OK	None observed	
Washdown	20.9	0	0	RL	OK	None observed	
Storage Area	20.9	0	0	RL	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas approved Safe at time of Exam

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

Signature

CERT. # 8395
 CERT. # 9362
 CERT. # 4373
 CERT. # 7954

COUNTER SIGNATURE Signature CERT. # 03992

2MSHA03154

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-8-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 3:00 AM/PM END 5:45 AM/PM Examiners Initials TR/KK
 TIME OF EXAMINATION START 3:42 AM/PM END 5:40 AM/PM Examiners Initials TR
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO NO CALL OUT TIME ----- _____ AM/PM

CALLLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	TC	OK	none obs.	
main north Haulage Seals	20.9	0	0	TC	OK	none obs.	
main west Haulage Seals	20.9	0	0	TR/KK LR	OK	none obs.	
350' north Haulage Seals	20.9	0	0	TC	OK	none obs.	
1st Right	20.9	0	0	TC	OK	none obs.	
Transformers	20.9	0	0	TR/KK CR	OK	none obs.	
Chargers	20.9	0	0	TR/KK LR	OK	none obs.	
Wash Down	20.9	0	0	TC	OK	none obs.	
Storage Area	20.9	0	0	TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe at
Time of Exam

PRE-SHIFT/MINE EXAMINER **Signature** CERT. # 9362
 PRE-SHIFT/MINE EXAMINER CERT. # 4375
 PRE-SHIFT/MINE EXAMINER CERT. # 7957
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE _____ CERT. # _____

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-8-07

SECTION/AREA Gen mine 1

TIME OF EXAMINATION START 11:30 AM/PM
 TIME OF EXAMINATION START 11:15 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 12:55 AM/PM
 END 1:30 AM/PM
 END _____ AM/PM

Examiners Initials LD
 Examiners Initials SW
 Examiners Initials _____

EXAM. CALLED OUT YES/NO (NO)

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	OK	none observed	
Main North Haulage Seals	20.9	0	0	SW	OK	none observed	
Main West Haulage Seals	20.9	0	0	LD SW	OK	none observed	
3rd North Haulage Seals	20.9	0	0	SW	OK	none observed	
1st Right	20.9	0	0	SW	OK	none observed	
Transformers	20.9	0	0	LD SW	OK	none observed	
Chargers	20.9	0	0	LD SW	OK	none observed	
Wash down	20.9	0	0	LD	OK	none observed	
Storage Area	20.9	0	0	LD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe to travel at time of exam.

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 9660
 CERT. # 9548
 CERT. # _____
 CERT. # _____

COUNTER SIGNATURE _____
 Signature

CERT. # 7485

2MSHA03156

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-8-07 SECTION/AREA Gen mine

TIME OF EXAMINATION START 7:00 AM/PM AM END 7:23 AM/PM PM Examiners Initials TC
 TIME OF EXAMINATION START 7:07 AM/PM AM END 7:20 AM/PM PM Examiners Initials BR
 TIME OF EXAMINATION START 7:32 AM/PM AM END 7:45 AM/PM PM Examiners Initials KK

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	KK	OK	none observed	
MAIN NORTH Haulage Seals	20.9	0	0	KK	OK	none observed	
north west Haulage Seals	20.9	0	0	TC BR KK	OK	none obs.	
3rd north Haulage Seals	20.9	0	0	KK	OK	none observed	
1st Fight	20.9	0	0	KK	OK	none observed	
Transformers	20.9	0	0	KK	OK	none observed	
chargers	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	
storage Area	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all areas appeared safe at time of pre-shift

Signature _____

CERT. # 8395
 CERT. # 9367
 CERT. # 7959
 CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-9-07

SECTION/AREA Sample 1

TIME OF EXAMINATION START 1:33 AM/PM
 TIME OF EXAMINATION START 4:20 AM/PM
 TIME OF EXAMINATION START 3:50 AM/PM

END 5:25 AM/PM
 END 4:20 AM/PM
 END 4:18 AM/PM

Examiners Initials KK
 Examiners Initials TC
 Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Parking area</u>	<u>20.8</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/BH</u>	<u>OK</u>	<u>none obs</u>	
<u>5th level</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Trams</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/BH</u>	<u>OK</u>	<u>none obs</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared Reasonably safe
At Time of Exam

Signature

PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE
 PRE-SHIFT/MINE EXAMINE

CERT. # 7954
 CERT. # 4362
 CERT. # 8385
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-9-07 SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 11:15 AM/PM PM END 1:30 AM/PM PM Examiners Initials JD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Paroking Area</u>							
<u>Paroking Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>North main ^{Haulage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>M. West ^{Haulage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>3rd North ^{Haulage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>1st Right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>Storage Area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Area 9 appeared safe at the time of exam.

PRE-SHIFT/MINE EXAMINER Signature CERT. # 9660
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-9-07

SECTION/AREA (Gravel) / /

TIME OF EXAMINATION START 7:05 AM/PM
 TIME OF EXAMINATION START 7:50 AM/PM
 TIME OF EXAMINATION START 7:50 AM/PM

END 8:50 AM/PM
 END 8:10 AM/PM
 END 8:05 AM/PM

Examiners Initials KK
 Examiners Initials TL
 Examiners Initials BSH

EXAM. CALLED OUT ---- YES/NO
 CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

CALL OUT TIME ----- AM/PM

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none observed	
M. North Haulage seals	20.9	0	0	KK	OK	none observed	
M. West Haulage seals	20.9	0	0	KK/BSH	OK	none obs.	
3 rd North Haulage seals	20.9	0	0	KK	OK	none observed	
1 st North Haulage	20.9	0	0	KK	OK	none observed	
storage area	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	
Trans.	20.9	0	0	KK/TL	OK	none	
chargers	20.9	0	0	KK/TL	OK	none	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at time of exam

Signature _____

PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954
 CERT. # 9362
 CERT. # 8325
 CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 4735

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-10-07

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:02 AM/PM
 TIME OF EXAMINATION START 4:01 AM/PM
 TIME OF EXAMINATION START 4:10 AM/PM

END 5:15 AM/PM
 END 4:28 AM/PM
 END AM/PM

Examiners Initials KK
 Examiners Initials JC
 Examiners Initials

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	OK	none observed	
M. North Haulage seals	20.9	0	0	KK	OK	none observed	
M. West Haulage seals	20.9	0	0	JC/BH	OK	None obs.	
Trams	20.9	0	0	JC/BH	OK	none obs.	
Chargers	20.9	0	0	JC	OK	none obs.	
Storage area	20.9	0	0	KK	OK	none observed	
Washdown area	20.9	0	0	KK	OK	none observed	
1st East Haulage	20.9	0	0	KK	OK	none observed	
3rd West Haulage seals	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS
9419 main w/s	needs dust in transformer	
	JC	Dustal 8-10-07

PRE-SHIFT REMARKS All areas appeared safe at
Time of exam

Signature _____

PRE-SHIFT/MINE EXAMINE ERT. # 7954
 PRE-SHIFT/MINE EXAMINE ERT. # 9362
 PRE-SHIFT/MINE EXAMINE ERT. # 8395
 PRE-SHIFT/MINE EXAMINE ERT. # _____

Signature _____

COUNTER SIGNATURE CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-10-07 SECTION/AREA Gen Mine / /

TIME OF EXAMINATION START 11:10 AM/PM END 1:35 AM/PM Examiners Initials JD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO _____ CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Praking Area</u>							
<u>Main North ^{Halage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>Main West ^{Halage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>3rd North ^{Halage} Seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>1st Right Halage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>Wash down</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>transformers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>JD</u>	<u>ok</u>	<u>none observed</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Apparent Safe at the time of exam

Signature

PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9660
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature

COUNTER SIGNATURE _____ CERT. # 7485

2MSHA03162

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-10-07

SECTION/AREA General / /

TIME OF EXAMINATION START 7:00 AM/PM
 TIME OF EXAMINATION START 8:20 AM/PM
 TIME OF EXAMINATION START 8:26 AM/PM

END 8:50 AM/PM
 END 9:47 AM/PM
 END 8:42 AM/PM

Examiners Initials KK
 Examiners Initials TC
 Examiners Initials BH

EXAM. CALLED OUT ----- YES/NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	OK	none observed	
M West haulage seals	20.9	0	0	KK	OK	none observed	
3 West haulage seals	20.9	0	0	KK	OK	none observed	
15 right haulage	20.9	0	0	KK	OK	none observed	
Trams	20.9	0	0	TC	OK	none observed	
chargers	20.9	0	0	ISH	OK	None obs.	
M West haulage seals	20.9	0	0	TC	OK	None obs.	
Storage area	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe at
Time of Exam

PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____

CERT. # 7954
 CERT. # 9362
 CERT. # 8395
 CERT. # _____

Signature

Signature

COUNTER SIGNATURE

CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-11-07

SECTION/AREA Ex/Min 1

TIME OF EXAMINATION START 3:06 (A)M/PM
 TIME OF EXAMINATION START 3:53 (A)M/PM
 TIME OF EXAMINATION START 4:10 (A)M/PM

END 5:05 (A)M/PM
 END 5:10 (A)M/PM
 END 4:57 (A)M/PM

Examiners Initials KK
 Examiners Initials BU
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	20.9	0	0	KK	OK	none observed	
M. North Haulage seats	20.9	0	0	KK	OK	none observed	
3rd Haulage seats	20.9	0	0	KK	OK	none observed	
1st right	20.9	0	0	KK	OK	None observed	
Storage area	20.9	0	0	KK	OK	none observed	
Washdown	20.9	0	0	KK	OK	none observed	
M. West Haulage seats	20.9	0	0	KK/BU	OK	None observed	
Trans.	20.9	0	0	KK/BU	OK	None observed	
chargers	20.9	0	0	KK/BU	OK	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All area's appeared reasonably safe at time of exam

Signature _____

PRE-SHIFT/MINE EXAMINE CERT. # 7954
 PRE-SHIFT/MINE EXAMINE CERT. # 8395
 PRE-SHIFT/MINE EXAMINE CERT. # 9362
 PRE-SHIFT/MINE EXAMINE CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03164

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-11-07

SECTION/AREA Gen mine 1 / /

TIME OF EXAMINATION START 11:20 AM/PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 1:50 AM/PM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials JD
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	JD	ok	none observed	
m. North Halage seats	20.9	0	0	JD	ok	none observed	
3rd North Halage seats	20.9	0	0	JD	ok	none observed	
1st Right	20.9	0	0	JD	ok	none observed	
storage area	20.9	0	0	JD	ok	none observed	
wash down	20.9	0	0	JD	ok	none observed	
m west Halage seats	20.9	0	0	JD	ok	Hole in stoping Xc 93	BEING REPAIRED Done JD
transformers	20.9	0	0	JD	ok	none observed	
chargers	20.9	0	0	JD	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas appeared safe at the time of exam except noted above

Signature

PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINEE _____
 PRE-SHIFT/MINE EXAMINER _____

CERT. # 9660
 CERT. # _____
 CERT. # _____
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 7488

2MSHA03165

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-16-07

SECTION/AREA Gen/1102 1 | 1 | 1

TIME OF EXAMINATION START 7:03
 TIME OF EXAMINATION START 7:00
 TIME OF EXAMINATION START 7:04

AM/PM (AM) END 9:05 AM/PM (PM)
 AM/PM (AM) END 7:11 AM/PM (PM)
 AM/PM (AM) END 7:30 AM/PM (PM)

Examiners Initials KK
 Examiners Initials BH
 Examiners Initials TC

EXAM. CALLED OUT ---- YES/NO (NO)

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>Dunking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Main Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>2nd Haulage smooth seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs.</u>	
<u>W. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH/TC</u>	<u>OK</u>	<u>none obs.</u>	
<u>Trans.</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>TC</u>	<u>OK</u>	<u>None obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>BH</u>	<u>OK</u>	<u>None obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS _____

Signature

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954
 CERT. # 8395
 CERT. # 9362
 CERT. # _____

Signature

COUNTER SIGNATURE

CERT. # 03792

2MSHA03166

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-19-01

SECTION/AREA Gen Mine 1

TIME OF EXAMINATION START 3:04 AM/PM
 TIME OF EXAMINATION START 4:15 AM/PM
 TIME OF EXAMINATION START 4:02 AM/PM

END 5:10 AM/PM
 END 4:30 AM/PM
 END 4:25 AM/PM

Examiners Initials KK
 Examiners Initials KK
 Examiners Initials BH

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>3rd North Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>1st right</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none obs</u>	
<u>M. West Haulage seals</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>Tran</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/BH</u>	<u>OK</u>	<u>none obs.</u>	
<u>chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/BH</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All areas appeared safe
at time of exam

Signature _____
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE
 PRE-SHIFT/MINE EXAMINEE

CERT. # 7954
 CERT. # 9362
 CERT. # 8385
 CERT. # _____

Signature _____
 COUNTER SIGNATURE

CERT. # 7485

2MSHA03167

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-12-07 SECTION/AREA Gen mint / /

TIME OF EXAMINATION START 11:00 AM/PM END 1:35 AM/PM Examiners Initials LD
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES NO CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	20.9	0	0	LD	OK	none observed	
Main Nth Haulage Seals	20.9	0	0	LD	OK	none observed	
3rd Nth Haulage Seals	20.9	0	0	LD	OK	none observed	
1st Light	20.9	0	0	LD	OK	none observed	
Storage Area	20.9	0	0	LD	OK	none observed	
Wash Down	20.9	0	0	LD	OK	none observed	
M. West Haulage Seals	20.9	0	0	LD	OK	none observed	
transformers	20.9	0	0	LD	OK	none observed	
chargers	20.9	0	0	LD	OK	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS all Areas Apperend Safe at the time of exam

Signature
 PRE-SHIFT/MINE EXAMINER CERT. # 9660
 PRE-SHIFT/MINE EXAMINER CERT. # _____
 PRE-SHIFT/MINE EXAMINER CERT. # _____
 PRE-SHIFT/MINE EXAMINER CERT. # _____

COUNTER SIGNATURE **Signature** CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-18-07 SECTION/AREA General

TIME OF EXAMINATION START 7:03 AM/PM (AM) END 9:25 AM/PM (AM) Examiners Initials KK
 TIME OF EXAMINATION START 8:10 AM/PM (AM) END 8:40 AM/PM (AM) Examiners Initials TC
 TIME OF EXAMINATION START _____ AM/PM _____ AM/PM _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking lot	20.8	0	0	KK	OK	none obs	
M.W. Haulage seals	20.9	0	0	KK	OK	none obs	
3rd North Haulage seals	20.9	0	0	KK	OK	none obs	
Flight	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs.	
Washdown	20.9	0	0	KK	OK	none obs	
M.W. Haulage seals	20.9	0	0	KK/TC	OK	none obs	
Trans.	20.9	0	0	KK/TC	OK	none obs.	
Chargers	20.9	0	0	KK/TC	OK	none obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Safe
At time of Exam

Signature _____

PRE-SHIFT/MINE EXAMINEE _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # 9690
 PRE-SHIFT/MINE EXAMINEE _____ CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 03892

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-13-07 SECTION/AREA General

TIME OF EXAMINATION START 3:01 (A) AM/PM END 5:15 (A) AM/PM Examiners Initials KK
 TIME OF EXAMINATION START 4:03 (A) AM/PM END 4:30 (A) AM/PM Examiners Initials TC
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO CALL OUT TIME ----- AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
<u>parking area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>M West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>South Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>none observed</u>	
<u>Light</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None observed</u>	
<u>Storage area</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None observed</u>	
<u>Washdown</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK</u>	<u>OK</u>	<u>None observed</u>	
<u>Chargers</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/JN</u>	<u>OK</u>	<u>none obs.</u>	
<u>Tires</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/JN</u>	<u>OK</u>	<u>none obs.</u>	
<u>M West Haulage</u>	<u>20.9</u>	<u>0</u>	<u>0</u>	<u>KK/JN</u>	<u>OK</u>	<u>none obs.</u>	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas appeared safe
AT time of exam

Signature _____

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9362
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9690
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 7485 2MSHA03170

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-13-07 SECTION/AREA Gen Mine | |

TIME OF EXAMINATION START 11:10 AM/PM END 12:00 AM/PM Examiners Initials DD
 TIME OF EXAMINATION START 11:10 AM/PM END 1:05 AM/PM Examiners Initials mc
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM Examiners Initials _____

EXAM. CALLED OUT ----- YES (NO) CALL OUT TIME ----- _____ AM/PM
 CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____ SIGNATURE _____
 CALLED OUT BY _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
HAZ Parking Area	20.9	0	0	DD	ok	none obs.	
main North Haulage-seals	20.9	0	0	DD	ok	none obs.	
main west Haulage-seals	20.9	0	0	DD/mc	ok	none observed	
Storage Area	20.9	0	0	mc	ok	none observed	
Wash down	20.9	0	0	mc	ok	none observed	
3 rd North Haulage seals	20.9	0	0	mc	ok	none observed	
1 st Right	20.9	0	0	mc	ok	none observed	
Trans.	20.9	0	0	DD/mc	ok	none observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS AREAS APPEARED REASONABLY SAFE
AT TIME OF PRE-SHIFT

PRE-SHIFT/MINE EXAMINE Signature CERT. # 8058
 PRE-SHIFT/MINE EXAMINE _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINE _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

COUNTER SIGNATURE Signature CERT. # 7485

2MSHA03171

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-13-87

SECTION/AREA 2nd Mine

TIME OF EXAMINATION START 7:00 AM/PM AM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 9:10 AM/PM AM
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials KK
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT _____ YES/NO

CALL OUT TIME _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking area	80.9	0	0	KK	OK	none obs.	
M. North haulage	90.9	0	0	KK	OK	None obs	
3rd North haulage	90.9	0	0	KK	OK	None obs	
1st North haulage	90.9	0	0	KK	OK	None obs	
Storage area	90.9	0	0	KK	OK	None obs	
Washdown	90.9	0	0	KK	OK	None obs	
M. West haulage	90.9	0	0	KK/JN	OK	None obs.	
Truss	90.9	0	0	KK/JN	OK	None obs.	
chargers	90.9	0	0	KK/JN	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam.

Signature _____

PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER
 PRE-SHIFT/MINE EXAMINER

CERT. # 7954
 CERT. # 4375
 CERT. # 9690
 CERT. # _____

COUNTER SIGNATURE Signature

CERT. # 8358

2MSHA03172

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8/4/07

SECTION/AREA General

TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START 3:00 AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 5:10 AM/PM
 END 5:30 AM/PM
 END _____ AM/PM

Examiners Initials KK
 Examiners Initials ZR/JN
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____

CALLED OUT BY _____

CALLED OUT BY _____

REPORT RECEIVED BY _____

SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	None obs	
North haulage seats	20.9	0	0	KK	OK	None obs	
3rd haulage seats	20.9	0	0	KK	OK	None obs	
1st right	20.9	0	0	KK	OK	None obs	
Storage area	20.9	0	0	KK	OK	None obs	
Washdown	20.9	0	0	KK	OK	None obs	
Midwest haulage seats	20.9	0	0	ZR/JN	OK	None obs.	
Trans.	20.9	0	0	ZR/JN	OK	None obs.	
chargers	20.9	0	0	ZR/JN	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared safe at time of Exam

PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____
 PRE-SHIFT/MINE EXAMINER _____

Signature

CERT. # 7954
 CERT. # 4373
 CERT. # 9690
 CERT. # _____

COUNTER SIGNATURE _____
 Signature _____
 CERT. # 7485

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8.14.07

SECTION/AREA Gen Mine

TIME OF EXAMINATION START 11:00 ~~AM~~/PM
 TIME OF EXAMINATION START _____ AM/PM
 TIME OF EXAMINATION START _____ AM/PM

END 1:15 AM/~~PM~~
 END _____ AM/PM
 END _____ AM/PM

Examiners Initials mc/fm
 Examiners Initials _____
 Examiners Initials _____

EXAM. CALLED OUT ----- YES NO

CALL OUT TIME ----- _____ AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____
 CALLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
Parking Area	209	0	0	FM	CC	None observed	
haulage MAIN North seals	209	0	0	FM MC	CC	None observed	
haulage MAIN West seals	209	0	0	FM MC	CC	None observed	
haulage 3rd North seals	209	0	0	FM MC	CC	None observed	
haulage 1st Right haulage	209	0	0	MC	CC	None observed	
TRANSFORMERS	209	0	0	FM MC	CC	None observed	
chargers	209	0	0	FM MC	CC	None observed	
washdown	209	0	0	MC	CC	None observed	
Storage Area	209	0	0	MC	CC	None observed	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS All Areas Appeared Reasonably Safe At time of exam

Signature _____

PRE-SHIFT/MINE EXAMINER _____ CERT. # 8297
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 7375
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____

COUNTER SIGNATUR _____ CERT. # 7485

2MSHA03174

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-14-07 SECTION/AREA 6m/1100

TIME OF EXAMINATION START 7:00 AM/PM END 8:55 AM/PM Examiners Initials KK
 TIME OF EXAMINATION START 7:00 AM/PM END 9:30 AM/PM Examiners Initials KK/JN
 TIME OF EXAMINATION START _____ AM/PM _____ END _____ AM/PM _____ Examiners Initials _____

EXAM. CALLED OUT ----- YES/NO CALL OUT TIME ----- AM/PM

CALLED OUT BY _____
 CALLED OUT BY _____ REPORT RECEIVED BY _____
 CALLED OUT BY _____ SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	None obs	
North Haulage seals	20.9	0	0	KK	OK	None obs	
South Haulage seals	20.9	0	0	KK	OK	None obs	
1st right	20.9	0	0	KK	OK	None obs	
Storage area	20.9	0	0	KK	OK	None obs	
Washdown	20.9	0	0	KK	OK	None obs	
West Haulage seals	20.9	0	0	KK/JN	OK	None obs	
Trans.	20.9	0	0	KK/JN	OK	None obs	
chargers	20.9	0	0	KK/JN	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Area appeared safe at time of Exam

Signature _____

PRE-SHIFT/MINE EXAMINER _____ CERT. # 7954
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 9690
 PRE-SHIFT/MINE EXAMINER _____ CERT. # 4373
 PRE-SHIFT/MINE EXAMINER _____ CERT. # _____

Signature _____

COUNTER SIGNATURE _____ ERT. # 8308

2MSHA03175

PRE-SHIFT GENERAL MINE

DATE OF EXAMINATION 8-15-07 SECTION/AREA General

TIME OF EXAMINATION START 300 AM PM END 510 AM PM
 TIME OF EXAMINATION START 300 AM PM END 540 AM PM
 TIME OF EXAMINATION START _____ AM/PM END _____ AM/PM

Examiners Initials KK
 Examiners Initials RE/JV
 Examiners Initials _____

EXAM. CALLED OUT ---- YES/NO NO CALL OUT TIME ----- AM/PM

CALLLED OUT BY _____
 CALLLED OUT BY _____
 CALLLED OUT BY _____

REPORT RECEIVED BY _____
 SIGNATURE _____

LOCATIONS	O2	CH4 %	CO	Examiner Initials	CFM/AIR DIRECTION	HAZARD CONDITIONS	ACTION TAKEN
parking area	20.9	0	0	KK	OK	none obs	
Midwest haulage	20.9	0	0	KK	OK	none obs	
South haulage	20.9	0	0	KK	OK	none obs	
15' Right	20.9	0	0	KK	OK	none obs	
Storage area	20.9	0	0	KK	OK	none obs	
Washdown	20.9	0	0	KK	OK	none obs	
trans	20.9	0	0	KK/JN	OK	None obs.	
chargers	20.9	0	0	KK/JN	OK	None obs.	
W. West haulage	20.9	0	0	KK/JN	OK	None obs.	

ON-SHIFT HAZARDS IDENTIFIED

LOCATIONS	HAZARDS	ACTIONS

PRE-SHIFT REMARKS Areas appeared Safe at time of Exam.

Signature _____

PRE-SHIFT/MINE EXAMINER - CERT. # 7954
 PRE-SHIFT/MINE EXAMINER - CERT. # 4325
 PRE-SHIFT/MINE EXAMINER - CERT. # 9690
 PRE-SHIFT/MINE EXAMINER - CERT. # _____

Signature _____

COUNTER SIGNATURE _____ CERT. # 8462

2MSHA03177