

NORTH MAINS

PUMP 5

EXAMINATION OF ELECTRICAL EQUIPMENT

Company PERFORMANCE
Mine UBB
Location WYOMA RALPH WV
Post Office County State

Re-order from
**BJW Printing and
Office Supplies**
P. O. Box 1309
Beckley, W. Va. 25801
Phone (304) 253-7361

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

4-16-08 North Mains Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6 1/2 HP	Hurricane	Located at Mouth of North Mains at #134 Bkt. in Belt Entry			
9 HP	SPS	Located at #12 Bkt. in #4 Entry			
9 HP	Flight	Located at #17 Bkt. in #4 Entry			
5 HP	SPS	Located at #38 Bkt. in #5 Entry			
5 HP	BJM	Located at #40 Bkt. in #4 Entry			
13 HP	Flight	Located at #45-46 Bkt. in #4 Entry			
5 HP	SPS	Located at #53 Bkt. in #5 Entry			
10 HP	Stancor	Located at #78 Bkt. in #4 Entry			

Weekly tests of grounding devices (diodes)

5 HP	Flight	Located at #85 Bkt. in #5 Entry			
5 HP	Flight	Located at #88 Bkt. in #4 Entry			
5 HP	Flight	Located at #105 Bkt. in #4 Entry			
5.5 HP	Flight	Located at #128 Bkt. at Glory Hole			
6.4 HP	Stancor	Located at #128 Bkt. on Glory Belt labeled #2 TRASH PUMP			
6 HP	Stancor	Located at #128 Bkt. on Glory Belt labeled #1 TRASH PUMP			
5 HP	Flight	Located at #130 Bkt. at #7 6' TRK in #4 Entry			
10 HP	Stancor	Located at #137 Bkt. in #3 Entry			
13 HP	Flight	Located in the Belt Entry at the Face of North Mains Section			

NO Dangerous conditions were Found at Time of Examination.
Neil Wheeler

4-250

Neil Wheeler 4-16-08
4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

4-26-08 North Main Pump From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		6 1/2 HP Hunjin Located at #134 BRT at mouth of North Main			
		9 HP SPS Located at #12 BRT in #4 Entry			
		9 HP Flygt Located at #17 BRT in #4 Entry			
		5 HP SPS Located at #38 BRT in #5 Entry			
		5 HP BGM Located at #40 BRT in #4 Entry			
		13 HP Flygt Located at #45-46 BRT in #4 Entry			
		5 HP SPS Located at #53 BRT in #5 Entry			
		10 HP Starcor Located at #78 BRT in #4 Entry			
		5 HP Flygt Located at #85 BRT in #5 Entry			
		5 HP Flygt Located at #88 BRT in #4 Entry			
		5 HP Flygt Located at #105 BRT in #4 Entry			
		58 HP Flygt Located at #128 BRT at Wagon Hole			
		6.4 HP Starcor Located at #128 BRT on Wagon Belt Labeled #2 TRASH PUMP			
		6 HP Starcor Located at #128 BRT on Wagon Belt Labeled #1 TRASH PUMP			
		5 HP Flygt Located at #130 BRT at #7-6' TAIL			

NO DANGEROUS
 CONDITIONS WERE
 FOUND AT TIME OF EXAMINATION
 JIM WOODS
 4-25-08 - 4-26-08

Examinations of low- medium-voltage power circuit breakers (monthly)

10 HP Starcor Located at #137 BRT in #3 Entry
 13 HP Flygt Located in the Belt Entry
 OF THE FACE OF NORTH MAIN

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

5-2-08 North Mine's Pumps From Mouth to Face.

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		0 1/2 HP Handia Located at Mouth of North Mine at #134 Belt			
		9 HP SPS Located at #12 Bkt in #4 Entry			
		9 HP Flygt Located at #17 Bkt in #4 Entry			
		5 HP SPS Located at #38 Bkt in #5 Entry			
		5 HP BSM Located at #40 Bkt in #4 Entry			
		13 HP Flygt Located at #45-40 Bkt in #4 Entry			
		5 HP SPS Located at #53 Bkt in #5 Entry			
		10 HP Stmcar. Located at #78 Bkt in #4 Entry			

No Dangerous conditions were found at time of Examination
 Paul McLean
 5-2-08 4:25

Weekly tests of grounding devices (diodes)

		5 HP Flygt located at #85 Bkt in #5 Entry			
		5 HP Flygt located at #88 Bkt in #4 Entry			
		5 HP Flygt located at #105 Bkt in #4 Entry			
		5.5 HP Flygt located at #128 Bkt at along Hole.			
		6.4 HP Stmcar located at #128 Bkt on along belt labeled #2 TRASH PUMP			
		6.0 HP Stmcar located at #128 Bkt on along belt labeled #1 TRASH PUMP			
		5 HP Flygt located at #130 Bkt in #4 Entry at #7-6' TH' C			
		10 HP Stmcar. located at #137 Bkt in #3 Entry			
		13 HP Flygt located in the Belt Entry of Face of North Mine's section			

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

5-9-08 North MAIR'S PUMPS FROM MOUTH TO FACE

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6 1/2 HP Motor	Located at Mouth of North MAIR'S	at #134 Bkt			
9 HP SPS	Located at #12 Bkt in #4 Entry				
9 HP Flygt	Located at #17 Bkt in #4 Entry				
5 HP SPS	Located at #38 Bkt in #5 Entry				
5 HP BSM	Located at #40 Bkt in #4 Entry				
13 HP Flygt	Located at #45-46 Bkt in #4 Entry				
5 HP SPS	Located at #53 Bkt in #5 Entry				
10 HP Stacor	Located at #78 Bkt in #4 Entry				
5 HP Flygt	Located at #85 Bkt in #5 Entry				
5 HP Flygt	Located at #88 Bkt in #4 Entry				
5 HP Flygt	Located at #105 Bkt in #4 Entry				
58 HP Flygt	Located at #125 Bkt at Glory Hole				
6.4 HP Stacor	Located at #128 Bkt on Glory Belt	Labeled #2 Trash Pump			
6 HP Stacor	Located at #128 Bkt on Glory Belt	Labeled #1 Trash Pump			
5 HP Flygt	Located at #130 Bkt	at #130 Bkt			
		at #7-6' Tail Piece			
Examinations of low-medium-voltage power circuit breakers (monthly)					
10 HP Stacor	Located at #137 Bkt in #3 Entry				
13 HP Flygt	Located in the Belt Entry of the FACE of North MAIR'S				

No Dangerous Conditions were Found at Time of Examination
 and Under 4250

EXAMINATION OF ELECTRICAL EQUIPMENT

5-16-08 North Mines Pumps FROM MOUTH TO FACE

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6 1/2 HP	Harder	Located at Mouth of North Mines at #134 BTK			
9 HP	SPS	Located at #12 BTK in #4 Entry			
9 HP	Flygt	Located at #17 BTK in #4 Entry			
5 HP	SPS	Located at #38 BTK in #5 Entry			
5 HP	BSM	Located at #40 BTK in #4 Entry			
13 HP	Flygt	Located at #45-46 BTK in #4 Entry			
5 HP	SPS	Located at #53 BTK in #6 Entry			
10 HP	Stator	in AS Remove FROM 75 BTK and took to Gallery Belt			

No Dangerous Conditions
were found at time of
EXAMINATION -
T.M. Miller 4-250

Weekly tests of grounding devices (diodes)

5 HP	Flygt	Located at #95 BTK in #5 Entry			
5 HP	Flygt	Located at # 95 BTK in #4 Entry			
5 HP	Flygt	Located at #105 BTK in #4 Entry			
5.8 HP	Flygt	Located at #125 BTK at Gallery Hole			
10 HP	Stator	Located at #128 BTK on Gallery Belt Labeled Heavy Pump			
6 HP	Stator	Located at #128 BTK on Gallery Belt Labeled #1 Trip Pump			
5 HP	Flygt	Located at #130 BTK at #7-6' Tail Piece in #4 Entry			
10 HP	Stator	Located at #137 BTK in #3 Entry			
13 HP	Flygt	Located at the FACE OF North Mines Section in the Belt Entry			

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-22-08	North	MAIN'S	FROM	North to Face	
		6 1/2 HP Run In Located at North of north end			
		9 HP SPS Located at #12 Brk in #4 Entry			
		9 HP Flygt Located at #17 Brk in #4 Entry			
		5 HP SPS Located at #38 Brk in #5 Entry			
		5 HP B5M Located at #40 Brk in #4 Entry			
		13 HP Flygt Located at #45-46 in #4 Entry			
		5 HP SPS Located at #53 Brk in #5 Entry			
		5 HP Flygt Located at #85 Brk in #5 Entry			
		5 HP Flygt Located at #88 Brk in #4 Entry			
		5 HP Flygt Located at #105 Brk in #4 Entry			
		5 HP Flygt Located at #125 Brk at delay Ho'le			
		10 HP Stator Located at #125 Brk on Gary belt + labeled HERR PUMP			
		6 HP Stator Located at #125 Brk on Gary belt LABEL #1 TRIST PUMP			
		5 HP Flygt Located at #130 Brk at #7-6' TRIL in #4 Entry			
		10 HP Stator Located at #137 Brk in #3 Entry			

No Dangerous
Conditions were
Found at Time of
Examination.
M. J. Williams
4-250

Examinations of low-medium-voltage power circuit breakers (monthly)

13 HP Flygt Located at the Face of North
MAIN'S Section in The Belt Entry

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-30-08	North	MAIN'S Pumps	From Mouth to Face		
		6 1/2 HP Hand Pk Located at mouth of North Main at #134 Bkt			
		9 HP SPS Located at #12 Bkt in #4 Entry			
		9 HP Flygt Located at #17 Bkt in #4 Entry			
		5 HP SPS Located at #35 Bkt in #5 Entry			
		5 HP D/M Located at #40 Bkt in #4 Entry			
		13 HP Flygt Located at #45-46 Bkt in #4 Entry			
		5 HP SPS Located at #53 Bkt in #5 Entry			
		5 HP Flygt Located at #85 Bkt in #5 Entry			
		Weekly tests of grounding devices (diodes)			
		5 HP Flygt Located at #88 Bkt in #4 Entry			
		5 HP Flygt Located at #105 Bkt in #4 Entry			
		55 HP Flygt Located at #120 Bkt at Glory Hole			
		10 HP Stancer Located at #128 Bkt on Glory Belt Labeled Head Pump			
		6 HP Stancer Located at #128 Bkt on Glory Belt Labeled #1 Trash Pump			
		5 HP Flygt Located at #130 Bkt at #7-6' Tail in #4 Entry			
		10 HP Stancer Located at #137 Bkt in #3 Entry			
		13 HP Flygt Located in #4 Entry O.F. to Face of North Main's Section			

No Dangerous conditions were Found at Time of Examination.

W. J. [Signature] 4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

6-6-08 N. Mills Pump 9 From Mouth to Spere

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SPS Located at #12 Brk in #4 Entry			
		9HP Flygt Located at #17 Brk in #4 Entry			
		5HP SPS Located at #38 Brk in #5 Entry			
		5HP BSM Located at #40 Brk in #4 Entry			
		13HP Flygt Located at #45-46 Brk in #4 Entry			
		5HP SPS Located at #53 Brk in #5 Entry			
		5HP Flygt Located at #89 Brk in #5 Entry			
		5HP Flygt Located at #98 Brk in #4 Entry			
		5HP Flygt Located at #105 Brk in #4 Entry			
		50HP Flygt Located at #126 Brk at Glory Hole			
		10HP Stancor Located at #28 Brk on Glory Belt Labeled Head Pul			
		6HP Stancor Located at #128 Brk on Glory Belt Labeled #1 Trash Pul			
		5HP Flygt Located at #130 Brk in #4 Entry at #7-6' TAIL			
		10HP Stancor Located at #137 Brk in #3 Entry			
		13HP Flygt Located in the Face of North Bridge in the Belt Entry			

No Dangerous conditions were found at time of Examination
 Will Hudson
 U-250

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

6-13-05

Examination of electrical equipment (weekly)

North Mains Pump's From South to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP SPS Located at #12 BRT in #4 Entry
- 9HP Flight Located at #17 BRT in #4 Entry
- 5HP SPS Located at #38 BRT in #5 Entry
- 5HP BJM Located at #40 BRT in #4 Entry
- 13HP Flight Located at #45 & #40 BRT in #4 Entry
- 5HP SPS Located at #53 BRT in #5 Entry

Weekly tests of grounding devices (diodes)

- 5HP Flight Located at #85 BRT in #5 Entry
- 5HP Flight Located at #95 BRT in #4 Entry
- 5HP Flight Located at #105 BRT in #4 Entry
- 58HP Flight Located at #128 BRT at Long Hole
- 10HP Station Located at #128 RR on Long Belt at belted Head Road
- 6HP ~~Station~~ Station Located at #28 RR ~~on Long Belt~~ on Long Belt
- 5HP Flight Located at #130 BRT in #4 Entry at #7-6 TAIL
- 10HP Station Located at #137 BRT in #3 Entry
- 17HP Flight Located in the FACE OF the Belt Entry OF North Mains section

No Dangerous conditions were Found at Time of Examination

Tom Wagon
4-25-05
6-13-05

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-18-08	9HPSPS #12 BK	#4 Entry NM		OK	
	9HP Flight #17 BK	#4 " "		OK	
	5HP SPS #39 BK	#5 " "		OK	
	5HP BSM #40 BK	#4 Entry NM		OK	
	13HP Flight #45 BK	#4 " "		OK	
	5HP SPS #53 BK	#5 " "		OK	
	5HP Flight #85 BK	#5 " "		OK	
	5HP Flight #84 BK	#4 " "		OK	
	58HP Flight #128 BK	on Glory Hole belt head pump		OK	
	10HP Stencore #128 BK	on Glory Hole belt (head pump)		OK	
	6HP Stencore #128 BK	on Glory Hole belt (#1 trash pump)		OK	
	5HP Flight #130 BK	#7 in belt tail		OK	
	10HP Stencore #137 BK	#3 Entry		OK	
	13HP Flight	in face of NM in belt entry		OK	

T.C. Sauer 8-31

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

6-28-08

North MARINE PUMPS FROM MOUTH TO FACE

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP 3PS	located at #12 BRT	in #4 Entry			
9HP Flight	located at #17 BRT	in #4 Entry			
5HP 4PS	located at #38 BRT	in #5 Entry			
5HP 15M	located at #40 BRT	in #4 Entry			
13HP Flight	located at #45-46 BRT	in #4 Entry			
5HP 5PS	located at #53 BRT	in #5 Entry			
5HP Flight	located at #85 BRT	in #5 Entry			
5HP Flight	located at #85 BRT	in #4 Entry			

No Dangerous conditions were found at time of Examination.

Serial Number 4-250 6-28-08

Weekly tests of grounding devices (diodes)

5HP Flight	located at #105 BRT	in #4 Entry
5HP Flight	located at #125 BRT	at Glory Hole
10HP STANCO	located at #125 BRT	on Glory Belt LABELED Dead Pump
6HP STANCO	located at #125 BRT	on Glory Belt LABELED #1 Trash Pump
5HP Flight	located at #130 BRT	at #7-6' Tail Piece in #4 Entry
10HP STANCO	located at #137 BRT	in #3 Entry
13HP Flight	located in the Belt Entry	of the Face of old North MARINE section.

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

7-3-08 North MAIN PUMPS From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	9PS	Located at # 12 BRT in # 4 Entry			
9HP	Flight	Located at # 17 BRT in # 4 Entry			
5HP	9PS	Located at # 38 BRT in # 5 Entry			
5HP	BSM	Located at # 40 BRT in # 4 Entry			
13HP	Flight	Located at # 45-46 BRT in # 4 Entry			
5HP	9PS	Located at # 53 BRT in # 5 Entry			
5HP	Flight	Located at # 85 BRT in # 5 Entry			
5HP	Flight	Located at # 88 BRT in # 4 Entry			
5HP	Flight	Located at # 105 BRT in # 4 Entry			
58HP	Plant	Located at # 128 BRT at Glory Hole			
10HP	Stacon	Located at # 128 BRT on Glory Belt labeled # End Pump			
6HP	Stacon	Located at # 128 BRT on Glory Belt labeled # 1 Trash Pump			
5HP	Flight	Located at # 130 BRT in # 4 Entry at # 7-6' Tail			
10HP	Stacon	Located at # 137 BRT in # 3 Entry			
13HP	Flight	Located in the Face of North Mains section in the Belt Entry			

No Dangerous conditions were found at Time of Examination
 Paul Nielsen
 4250
 7-3-08

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

7-11-08 North MAIN'S PUMPS FROM Mouth to FINE.

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SPS Located at # 12 BRT in # 4 Entry			
		9HP Flygt Located at # 17 BRT in # 4 Entry			
		5HP SPS Located at # 38 BRT in # 5 Entry			
		5HP Flygt Located at # 40 BRT in # 4 Entry			
		13HP Flygt Located at # 45-46 BRT in # 4 Entry			
		5HP SPS Located at # 53 BRT in # 5 Entry.			
		5HP Flygt Located at # 55 BRT in # 5 Entry			
		5HP Flygt Located at # 88 BRT in # 4 Entry			

no Dangerous conditions were found at time of Examination
 Mail Number 4-250

Weekly tests of grounding devices (diodes)

5HP Flygt Located at # 105 BRT in # 4 Entry
 5.5HP Flygt Located at # 128 BRT at Wagon Hole
 10HP Starcon Located at # 128 BRT on Wagon belt Labeled Head Pump
 6HP Starcon Located at # 128 BRT on Wagon belt Labeled #1 TRASH PUMP
 5HP Flygt Located at # 130 BRT in # 4 Entry at # 7-6' TAIL
 10HP Starcon Located at # 137 BRT in # 3 Entry ~~at # 7-6' TAIL~~
 13HP Flygt Located at the Face of North MAIN'S in the Belt Entry (out of service, no power)

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-18-08	North main's	Pumps	From Mouth to Face		
		9HP SP5 located at # 12 BRK in # 4 Entry			
		9HP Flygt located at # 17 BRK in # 4 Entry			
		5HP SP5 located at # 35 BRK in # 5 Entry			
		5HP BSM located at # 40 BRK in # 4 Entry			
		13HP Flygt located at # 45-46 BRK in # 4 Entry			
		5HP SP5 located at # 53 BRK in # 5 Entry			
		5HP Flygt located at # 85 BRK in # 5 Entry			
		5HP Flygt located at # 88 BRK in # 4 Entry			
		5HP Flygt located at # 105 BRK in # 4 Entry			
		98HP Flygt located at # 125 BRK at Clary Hole			
		10HP Stator located at # 128 BRK on 6-long belt covered Road Pump			
		6HP Flygt located at # 128 BRK on 6-long belt covered #1 TRM Pump			
		5HP Flygt located at # 130 BRK in # 4 Entry at # 7-6' TRIL			
		10HP Stator located at # 137 BRK in # 3 Entry			
		13HP Flygt located in the Belt Entry			

No Dangerous conditions were found at time of Examination
sent Michael
6-250

Examinations of low- medium-voltage power circuit breakers (monthly)

OR the Face of North side section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

7-25-08 North Mine 3 Pumps From Mouth to Face.

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SP5 Located at #12 Bnk in #4 Entry	NO Dangerous conditions were found at time of Examination	No Dangerous conditions were found at time of Examination	April Washburn 4-25-08
		9HP Flygt Located at #17 Bnk in #4 Entry			
		5HP SP5 Located at #35 Bnk in #5 Entry			
		5HP D5M Located at #40 Bnk in #4 Entry			
		13HP Flygt Located at #45-46 Bnk in #4 Entry			
		5HP SP5 Located at #53 Bnk in #5 Entry			
		5HP Flygt Located at #83 Bnk in #5 Entry			
		5HP Flygt Located at #83 Bnk in #4 Entry			

Weekly tests of grounding devices (diodes)

		5HP Flygt Located at #105 Bnk in #4 Entry
		5BHP Flygt Located at #125 Bnk at Glory Hole
		10HP Gt Accor. Located at #125 Bnk on Glory Bent labeled Head Pump
		6HP Gt Accor. Located at #125 Bnk on Glory Bent labeled #1 Tail Pump
		3HP Flygt Located at #130 Bnk in #4 Entry at #7-6' Tail
		10HP Gt Accor. Located at #137 Bnk in #3 Entry
		13HP Flygt Located at the Face of North Mine's in the Belt Entry.

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

8-1-08 North Mains Pumps From Mouth to Face

Date

Location

Equipment examined and/or tested

Dangerous conditions

Action taken

Examiner

9HP PPS Located at #12 Bkt in #4 Entry
 9HP Flygt Located at #17 Bkt in #4 Entry
 6HP Starcor Located at #37 Bkt in old #1 section Right Return
 9HP PPS Located at #40 Bkt in old #1 section Right Return
 5HP PPS Located at #38 Bkt in #5 Entry
 5HP DSM Located at #40 Bkt in #4 Entry
 13HP Flygt Located at #45-46 Bkt in #4 Entry
 5HP PPS Located at #53 Bkt in #5 Entry
 5HP Flygt Located at #55 Bkt in #5 Entry
 5HP Flygt Located at #88 Bkt in #4 Entry
 5HP Flygt Located at #105 Bkt in #4 Entry
 58HP Flygt Located at #125 Bkt at along hole
 10HP Starcor Located at #125 Bkt on along belt labeled Head Pump
 6HP Starcor Located at #125 Bkt on along belt labeled #1 Trash Pump
 5HP Flygt Located at #130 Bkt in #4 Entry at #7-6' Tail

No Dangerous conditions were found at time of Examination
 Mark W. ...
 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

10 HP Starcor Located at #137 Bkt in #3 Entry
 13HP Flygt Located at the Face of North Mains Section in the best Entry

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

8-8-08

North MAIR'S PUMP FROM NORTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9 HP PPS	Located at # 12 BRT in # 4 Entry				
9 HP Flight	located at # 17 BRT in # 4 Entry				
6 HP STANCON	Located at # 37 BRT in old # 1 section Right Return				
9 HP SPS	located at # 40 BRT in old # 1 section Right Return				
5 HP SPS	Located at # 38 BRT in # 5 Entry				
5 HP BSM	Located at # 40 BRT in # 4 Entry				
13 HP Flight	Located at # 45-46 BRT in # 4 Entry				
5 HP SPS	Located at # 53 BRT in # 5 Entry				
Weekly tests of grounding devices (diodes)					
5 HP Flight	Located at # 85 BRT in # 5 Entry				
5 HP Flight	Located at # 88 BRT in # 4 Entry				
5 HP Flight	Located at # 105 BRT in # 4 Entry				
58 HP Flight	Located at # 128 BRT At 6-10y Hole				
10 HP STANCON	Located at # 128 BRT on Wing bolt labeled Head Pump				
6 HP STANCON	Located at # 128 BRT on Wing bolt labeled #1 Thrust Pad				
5 HP Flight	Located at # 130 BRT in # 4 Entry at # 7-6' TAIL				
10 HP STANCON	Located at # 137 BRT in # 3 Entry				
13 HP Flight	Located in the Belt Entry of the Face of old North MAIR'S section				

NO DANGEROUS
 CONDITIONS WERE FOUND
 AT TIME OF EXAMINATION
 Next week
 8-23-08

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

8-15-08 North MAIN'S Pumps From mouth to face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SPS Located at #12 BRT in #4 Entry			
		9HP Flygt Located at #17 BRT in #4 Entry			
		6HP Starcor Located at #37 BRT on old #1 section in Right Return			
		9HP SPS Located at #40 BRT on old #1 section in Right Return			
		5HP SPS Located at #35 BRT in #5 Entry			
		5HP BTM Located at #40 BRT in #4 Entry			
		13HP Flygt Located at #45-46 BRT in #4 Entry			
		5HP SPS Located at #53 BRT in #5 Entry			
		5HP Flygt Located at #55 BRT in #5 Entry			
		5HP Flygt Located at #88 BRT in #4 Entry			
		5HP Flygt Located at #105 BRT in #4 Entry			
		56HP Flygt Located at #128 BRT at Wagon Hole			
		10HP Starcor Located at #128 BRT on Wagon Belt Labeled Bend Pump			
		6HP Starcor Located at #128 BRT on Wagon Belt Labeled #1 Turn Pump			
		5HP Flygt Located at #130 BRT in #4 Entry at #7-6' TRAIL			

No Dangerous
 → conditions were
 found at time
 of Examination
 Not Sub U-250

Examinations of low- medium-voltage power circuit breakers (monthly)

10HP Starcor Located at #137 BRT in #3 Entry
 13HP Flygt Located in the Belt Entry on
 the FACE of old North MAIN'S section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

8-29-08

NORTH MAIN'S PUMPS FROM MONTH TO FACA

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9 HP GPS Located at # 12 BAK in the # 4 Entry
- 9 HP Flygt Located at # 17 BAK in # 4 Entry
- 6 HP Staccor Located at # 37 BAK on old # 1 section in Right Return
- 9 HP GPS Located at # 40 BAK on old # 1 section in Right Return
- 5 HP GPS Located at # 38 BAK in # 5 Entry
- 5 HP BTM Located at # 40 BAK in # 4 Entry
- 13 HP Flygt Located at # 45-46 BAK in # 4 Entry
- 5 HP GPS Located at # 53 BAK in # 5 Entry

No Dangerous Conditions
were Found at
Time of Examination.
Jill Neel
4-250

Weekly tests of grounding devices (diodes)

- 9 HP Flygt Located at # 74 BAK on old # 1 section Right Return
- 5 HP Flygt Located at # 85 BAK in # 5 Entry
- 5 HP Flygt Located at # 85 BAK in # 4 Entry
- 5 HP Flygt Located at # 105 BAK in # 4 Entry
- 5.8 HP Flygt Located at # 125 BAK at Colony Hole
- 10 HP Staccor Located at # 125 BAK on Colony Belt Labeled Head Pump
- 6 HP Staccor Located at # 128 BAK on Colony Belt Labeled # 1 Trash Pump
- 5 HP Flygt Located at # 130 BAK in # 4 Entry at # 7-6' TAIL
- 10 HP Staccor Located at # 137 BAK in # 3 Entry
- 13 HP Flygt Located at the FINE OF old North main's section in the Belt Entry

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-5-08	North	MINNIS PUMP; FROM MONTH TO FACE			
		9HP SPS Located at # 12 BRT in # 4 Entry			
		9HP Flygt Located at # 17 BRT in # 4 Entry			
		6HP Starcor Located at # 37 BRT ON old # 1 section in Right Return			
		9HP SPS Located at # 40 BRT on old # 1 section in Right Return			
		5HP SPS Located at # 38 BRT in # 5 Entry			
		5HP BSM Located at # 40 BRT in # 4 Entry			
		13HP Flygt Located at # 45, 46 BRT in # 4 Entry			
		5HP SPS Located at # 53 BRT in # 5 Entry			
		9HP Flygt Located at # 94 BRT on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BRT in # 5 Entry			
		5HP Flygt Located at # 85 BRT in # 4 Entry			
		5HP Flygt Located at # 105 BRT in # 4 Entry			
		58HP Flygt Located at # 128 BRT at Glory Hole			
		10HP Starcor Located at # 128 BRT on 6-1/2" Belt Labeled Head Pump			
		6HP Starcor Located at # 128 BRT on 6-1/2" Belt Labeled #1 Push Pump			
Examinations of low- medium-voltage power circuit breakers (monthly)					
		5HP Flygt Located at # 130 BRT in # 4 Entry at # 7-6' TAIL			
		10HP Starcor Located at # 137 BRT in # 3 Entry			
		13HP Flygt Located in the FACE of North Minnis in the Belt Entry.			

NO DANGEROUS CONDITIONS
 → were Found at time of
 Exam. at 4:25 PM

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

9-12-09

North Mines Pumps From North to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP SPS Located at # 12 Bkt in # 4 Entry			
		9 HP Flygt Located at # 17 Bkt in # 4 Entry			
		6 HP STANCO Located at # 37 Bkt on old # 1 section in Right Return			
		9 HP SPS Located at # 40 Bkt on old # 1 section in Right Return			
		5 HP SPS Located at # 38 Bkt in # 5 Entry			
		5 HP SPS Located at # 40 Bkt in # 4 Entry			
		13 HP Flygt Located at # 45-46 Bkt in # 4 Entry			
		5 HP SPS Located at # 53 Bkt in # 5 Entry			

No dangerous conditions were found at time of examination.
 Put under 4-250

Weekly tests of grounding devices (diodes)

		9 HP Flygt Located at # 74 Bkt on old # 1 section in Right Return			
		5 HP Flygt Located at # 85 Bkt in # 5 Entry			
		5 HP Flygt Located at # 88 Bkt in # 4 Entry			
		5 HP Flygt Located at # 105 Bkt in # 4 Entry			
		5 HP Flygt Located at # 125 Bkt on Old # 1 Bkt			
		10 HP STANCO Located at # 125 Bkt on Old # 1 Bkt labeled Head Pump			
		6 HP STANCO Located at # 125 Bkt on Old # 1 Bkt labeled # 1 Truss Pump			
		5 HP Flygt Located at # 130 Bkt in # 4 Entry at # 7-6 Tail			
		10 HP STANCO Located at # 137 Bkt in # 3 Entry			
		13 HP Flygt Located at the FACE OF North Mines Section in the Belt Entry			

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

9-19-09 North MAIR'S PUMPS FROM MOUNTS TO FACE

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SPS Located at # 12 BRK in # 4 Entry			
		9HP Flight Located at # 17 BRK in # 4 Entry (Repaired main breaker)			
		6HP Stancor Located at # 37 BRK on old # 1 section in right return			
		9HP SPS Located at # 40 BRK on old # 1 section in right return			
		5HP BSM SPS Located at # 39 BRK in # 5 Entry			
		5HP BSM Located at # 40 BRK in # 5 Entry			
		13HP Flight Located at # 45-46 BRK in # 4 Entry			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flight Located at # 74 BRK on old # 1 section in right return			
		5HP Flight Located at # 85 BRK in # 5 Entry			
		5HP Flight Located at # 88 BRK in # 4 Entry			
		5HP Flight Located at # 105 BRK in # 4 Entry			
		58 HP Flight Located at # 128 BRK at the Clough Hole			
		10 HP Stancor Located at # 128 BRK on Clough Belt Loop of Head Pump			
		6 HP Stancor Located at # 128 BRK on Clough Belt Loop of Head Pump			

No Dangerous conditions
 were found at time of
 Examination

[Signature]
 4/25/00

Examinations of low- medium-voltage power circuit breakers (monthly)

5 HP Flight Located at # 130 BRK in # 4 Entry at # 7-6 Tail
 10 HP Stancor Located at # 137 BRK in # 3 Entry
 13 HP Flight Located at the Face of old north
 MAIR'S section in the Belt Entry

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

9-26-08 North MAIN'S PUMP'S FROM MOUTH TO FACE

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

9HP SPS Located at # 12 BRK in # 4 Entry
 9HP Flyght Located at # 17 BRK in # 4 Entry
 6HP Stancor Located at # 37 BRK on old # 1 section in Right Return
 9HP SPS Located at # 40 BRK on old # 1 section in Right Return
 5HP SPS Located at # 38 BRK in # 5 Entry
 5HP BSM Located at # 40 BRK in # 4 Entry
 13HP Flyght located at # 45-46 BRK in # 4 Entry
 5HP SPS Located at # 53 BRK in # 5 Entry

NO Dangerous Conditions
 were found at Time
 of Examination
 Rich Nelson
 4-29-08

Weekly tests of grounding devices (diodes)

9HP Flyght Located at # 74 BRK on old # 1 section in Right Return
 5HP Flyght located at # 85 BRK in # 5 Entry
 5HP Flyght located at # 88 BRK in # 4 Entry
 5HP Flyght Located at # 105 BRK in # 4 Entry
 53HP Flyght located at # 128 BRK at along Hole
 10HP Stancor Located at # 128 BRK on Glory Belt labeled Hard Pump
 6HP Stancor Located at # 128 BRK on Glory Belt labeled # 1 TRASH PUMP
 5HP Flyght Located at # 130 BRK in # 4 Entry AT # 7-6' TAIL
 10HP Stancor Located at # 137 BRK in # 3 Entry
 13HP Flyght Located in the Belt Entry OF THE FACE
 OF OLD NORTH MAIN'S SECTION.

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

10-3-08 NORTH MAIN'S PUMPS FROM MOUTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP SPS Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP Stator Located at # 37 BRK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BRK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BRK in # 5 Entry			
		5HP BSM Located at # 40 BRK in # 4 Entry		NO DANGEROUS CONDITIONS	
		13HP Flygt Located at # 45-46 BRK in # 4 Entry		repair found at	
		5HP SPS Located at # 53 BRK in # 5 Entry		Time of Exam.	
		9HP Flygt Located at # 74 BRK on old # 1 section in Right Return		Oil Under	
		5HP Flygt Located at # 85 BRK in # 5 Entry		U-250	
		5HP Flygt Located at # 88 BRK in # 4 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		58HP Flygt Located at # 128 BRK at U long hole			
		10HP Stator Located at # 128 BRK on along belt labeled Head Pump			
		6HP Stator Located at # 128 BRK on along belt labeled #1 TANK PUMP			

Examinations of low- medium-voltage power circuit breakers (monthly)

		5HP Flygt Located at # 130 BRK at # 7-6 Tail in # 4 Entry			
		10HP Stator Located at # 137 BRK in # 3 Entry			
		13HP Flygt Located at the Face of North Main's section in the Belt Entry			

EXAMINATION OF ELECTRICAL EQUIPMENT

10-11-08 North Main's Pumps From Mouth to Face

Examination of electrical equipment (weekly)

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

9HP SPS Located at # 12 BTK in #4 Entry
 9HP Flygt Located at # 17 BTK in # 4 Entry
 6HP Stancer Located at # 37 BTK on old #1 section in Right Return
 9HP SPS Located at # 40 BTK on old #1 section in Right Return
 5HP SPS Located at # 38 BTK in # 5 Entry
 5HP Dsm Located at # 40 BTK in # 4 Entry
 13HP Flygt Located at # 45-46 BTK in # 4 Entry
 5 HP SPS Located at # 53 BTK in # 5 Entry

Weekly tests of grounding devices (diodes)

9HP Flygt Located at # 74 BTK on old #1 section in Right Return
 5HP Flygt Located at # 95 BTK in # 5 Entry
 5HP Flygt Located at # 85 BTK in # 4 Entry
 5HP Flygt Located at # 105 BTK in # 4 Entry
 58HP Flygt Located at # 125 BTK at Wlody Hole
 10HP Stancer Located at # 128 BTK on Wlody Belt around Road Pump
 6HP Stancer Located at # 126 BTK on Wlody Belt Labeled # 1 TMS H Pump
 5HP Flygt Located at # 130 BTK at # 7-6 Tail in # 4 Entry
 10HP Stancer Located at # 137 BTK in # 3 Entry
 13HP Flygt Located in the Face of North Main's section in the Belt Entry

→ No Dangerous Conditions were Found at Time of Examination
 Neil M. ...
 4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

10-25-06

North MAIR'S PUMP'S FROM MOUTH TO FACE

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9 HP SPS Located at # 12 Bkt in # 4 Entry
- 9 HP Flygt Located at # 17 Bkt in # 4 Entry
- 6 HP Stancor Located at # 37 Bkt on old #1 section in Right Return
- 9 HP SPS Located at # 40 Bkt on old #1 section in Right Return
- 5 HP SPS Located at # 34 Bkt in # 5 Entry
- 5 HP BJM Located at # 40 Bkt in # 4 Entry
- 13 HP Flygt Located at # 45-46 Bkt in # 4 Entry
- 5 HP SPS Located at # 53 Bkt in # 5 Entry

NO Dangerous
conditions were found
At Time of Examination
Not needed
4-250.

Weekly tests of grounding devices (diodes)

- 9 HP Flygt Located at # 74 Bkt on old #1 section in Right Return
- 5 HP Flygt Located at # 85 Bkt in # 5 Entry
- 5 HP Flygt Located at # 89 Bkt in # 4 Entry
- 5 HP Flygt Located at # 105 Bkt in # 4 Entry
- 58 HP Flygt Located at # 128 Bkt at Wagon Hole
- 10 HP Stancor Located at # 128 Bkt on Wagon Belt Labeled Head Pump
- 6 HP Stancor Located at # 128 Bkt on Wagon Belt Labeled #1 Trash Pump
- 5 HP Flygt Located at # 130 Bkt at # 7-6' Tail in # 4 Entry
- 10 HP Stancor Located at # 137 Bkt in # 3 Entry
- 13 HP Flygt Located at the Face of North MAIR'S section in the Belt Entry

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

11-1-08 North MAIN'S Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flight Located at #12 Brk in #4 Entry (new pump)			
		9HP Flight Located at #17 Brk in #4 Entry			
		6HP Starcor Located at #37 Brk on old #1 section in Right Return			
		9HP SPS Located at #40 Brk on old #1 section in Right Return			
		5HP SPS Located at #38 Brk in #5 Entry			
		5HP BSM Located at #40 Brk in #4 Entry			
		13HP Flight Located at #45-46 Brk in #4 Entry			
		5HP SPS Located at #53 Brk in #5 Entry			
		9HP Flight Located at #74 Brk on old #1 section in Right Return			
		5HP Flight Located at #85 Brk in #5 Entry			
		5HP Flight Located at #88 Brk in #4 Entry			
		5HP Flight Located at #105 Brk in #4 Entry			
		58HP Flight Located at #128 Brk at Wagon Hole			
		10HP Starcor Located at #128 Brk on Wagon Belt Labeled Head Pump			
		6HP Starcor Located at #128 Brk on Wagon Belt Labeled #1 Trash Pump			

NO DANGEROUS
 conditions were
 found at time of
 examination
 J. J. [unclear]
 4/25/08

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flight Located at #130 Brk in #4 Entry at #7-6 Tail
 10HP Starcor Located at #137 Brk in #3 Entry
 13HP Flight Located in the Belt Entry of
 the Face of old North MAIN'S section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

11-8-08

North MAIN'S PUMP? From north to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flygt Located at # 12 BAK in # 4 Entry
- 9HP Flygt Located at # 17 BAK in # 4 Entry
- 6HP STANOR Located at # 37 BAK or old # 1 section in Right Return
- 9HP SPS Located at # 40 BAK or old # 1 section in Right Return
- 5HP SPS Located at # 38 BAK in # 5 Entry
- 5HP BSM Located at # 40 BAK in # 4 Entry
- 13HP Flygt Located at # 45-46 BAK in # 4 Entry
- 5HP SPS Located at # 53 BAK in # 5 Entry

No Dangerous Conditions were found at

A time of Examination

Unit Number: 4250

Weekly tests of grounding devices (diodes)

- 9HP Flygt Located at # 74 BAK or old # 1 section in Right Return
- 5HP Flygt Located at # 85 BAK in # 5 Entry
- 5HP Flygt Located at # 88 BAK in # 4 Entry
- 5HP Flygt Located at # 105 BAK in # 4 Entry
- 58HP Flygt Located at # 128 BAK at Glory Hole
- 10HP STANOR Located at # 128 BAK or Glory Belt labeled Head Pump
- 6HP STANOR Located at # 128 BAK or Glory Belt labeled # 1 Tank Pump
- 5HP Flygt Located at # 130 BAK in # 4 Entry at # 7-6' TAIL
- 10HP STANOR Located at # 137 BAK in # 3 Entry
- 13HP Flygt. Located in the BEL Entry of the Face of the old north MAIN'S section

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

11-15-08 North MAIN'S PUMP? FROM MOUTH TO FACE.

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP Starcor Located at # 37 BRK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BRK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BRK in # 5 Entry			
		5HP BDM Located at # 40 BRK in # 4 Entry			
		13HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flygt Located at # 74 BRK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BRK in # 5 Entry			
		5HP Flygt Located at # 88 BRK in # 4 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		55HP Flygt Located at # 128 BRK at along Hole			
		10HP Starcor Located at # 128 BRK on along Belt 7 labeled Head Pump			
		6HP Starcor Located at # 128 BRK on along Belt labeled # 17056 Pump			

No Dangerous Conditions
Were Found At Time
OF EXAMINATION.

4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt	Located at # 130 BRK in # 4 Entry at # 7-6' TRAIL
10HP Starcor	Located at # 137 BRK in # 3 Entry
13HP Flygt	Located in the Belt Entry OF THE FACE OF old North MAIN'S SECTION

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

11-21-08

North Main's Pump, From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRT in # 4 Entry			
		9HP Flygt Located at # 17 BRT in # 4 Entry			
		6HP Starcon Located at # 37 BRT on old # 1 section in Right Return			
		9HP SP5 Located at # 40 BRT on old # 1 section in Right Return			
		5HP SP5 Located at # 38 BRT in # 5 Entry			
		5HP BSM Located at # 40 BRT in # 4 Entry			
		13HP Flygt Located at # 45-46 BRT in # 4 Entry			
		5HP SP5 Located at # 53 BRT in # 5 Entry			

NO Dangerous Conditions were found at time of Examination.

Weekly tests of grounding devices (diodes)

		9HP Flygt Located at # 74 BRT on old # 1 section in Right Return			Thal. Number 4-250
		5HP Flygt Located at # 85 BRT in # 5 Entry			
		5HP Flygt Located at # 96 BRT in # 4 Entry			
		5HP Flygt Located at # 105 BRT in # 4 Entry			
		58HP Flygt Located at # 128 BRT at Worry Hole			
		10HP Starcon Located at # 128 BRT on Worry Belt Labeled Head Pump			
		6HP Starcon Located at # 128 BRT on Worry Belt Labeled # 1 Trash Pump			
		5HP Flygt Located at # 130 BRT in # 4 Entry at # 7-6' trail			
		10HP Starcon Located at # 137 BRT in # 2 Entry			
		13HP Flygt Located in Face of old North Main's section in the Belt Entry			

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

11-28-06 North Main's Pumps From North to Face
 Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flygt Located at # 12 Bkt in # 4 Entry
- 9HP Flygt Located at # 17 Bkt in # 4 Entry
- 6HP Starcor Located at # 37 Bkt on old # 1 section in Right Return
- 9HP G.P.S. Located at # 40 Bkt on old # 1 section in Right Return
- 5HP G.P.S. Located at # 38 Bkt in # 5 Entry
- 5HP P.S.M. Located at # 40 Bkt in # 4 Entry
- 13HP Flygt Located at # 45-46 Bkt in # 4 Entry
- 5HP G.P.S. Located at # 53 Bkt in # 5 Entry
- 9HP Flygt Located at # 74 Bkt on old # 1 section in Right Return
- 5HP Flygt Located at # 85 Bkt in # 5 Entry
- 5HP Flygt Located at # 88 Bkt in # 4 Entry
- 5HP Flygt Located at # 105 Bkt in # 4 Entry
- 58HP Flygt Located at # 128 Bkt at Wlogy Hole
- 10HP Starcor Located at # 129 Bkt on Wlogy Belt Labeled Head Pump
- 6HP Starcor Located at # 128 Bkt on Wlogy Belt Labeled #1 Trash Pump

→ No dangerous conditions were found at time of Examination
 Phil Wilson
 11-25-06

Examinations of low- medium-voltage power circuit breakers (monthly)

- 9HP Flygt Located at # 130 Bkt in # 4 Entry at # 7-6' Tail
- 10HP Starcor Located at # 137 Bkt in # 2 Entry
- 13HP Flygt Located in the Belt Entry of North Main's old section in the Face

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

12-12-08

North mines Pumps From North to FICO

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Flygt	Located at #12 BAK in #4 Entry			
9HP	Flygt	Located at #17 BAK in #4 Entry			
6HP	Stanco	Located at #37 BAK on old #1 section in Right Return			
9HP	SPS	Located at #40 BAK on old #1 section in Right Return			
5HP	SPS	Located at #38 BAK in #5 Entry			
5HP	BUM	Located at #40 BAK in #4 Entry			
13HP	Flygt	Located at #45-46 BAK #4 Entry			
5HP	SPS	Located at #53 BAK in #5 Entry			

No Dangerous Conditions were found at time of Examination. *W. J. [Signature]*

Weekly tests of grounding devices (diodes)

9HP	Flygt	Located at #74 BAK on old #1 section in Right Return
5HP	Flygt	Located at #85 BAK in #5 Entry
5HP	Flygt	Located at #85 BAK in #4 Entry
5HP	Flygt	Located at #105 BAK in #4 Entry
5HP	Flygt	Located at #125 BAK AT Glary Hole
10HP	Stanco	Located at #128 BAK on Glary Belt Labeled Hand Pump
6HP	Stanco	Located at #128 BAK on Glary Belt Labeled #1 Thrust Pump
5HP	Flygt	Located at #130 BAK in #4 Entry AT #7-6' THIL
10HP	Stanco	Located at #137 BAK in #2 Entry
13HP	Flygt	Located at the face of old North mine's section in the Belt Entry

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-20-08	North Main's	Pumps	From north to Face		
		9HP Pump Located at #12 BAK in #4 Entry			
		9HP Pump Located at #17 BAK in #4 Entry			
		6HP Stator Located at #37 BAK on old #1 section in Right Return			
		9HP GFS Located at #40 BAK on old #1 section in Right Return			
		5HP GFS Located at #38 BAK in #5 Entry			
		5HP PTM Located at #40 BAK in #4 Entry			
		13HP Pump Located at #45-46 BAK in #4 Entry			
		5HP GFS Located at #53 BAK in #5 Entry			
		9HP Pump Located at #74 BAK on old #1 section in Right Return			
		5HP Pump Located at #85 BAK in #5 Entry			
		5HP Pump Located at #88 BAK in #4 Entry			
		7HP Pump Located at #105 BAK in #4 Entry			
		5.5HP Pump Located at #128 BAK at W Long Hole			
		10HP Stator Located at #128 BAK on W Long Belt Labeled Head Pump			
		6HP Stator Located at #128 BAK on W Long Belt Labeled #1 Trash Pump			

No dangerous conditions were found at time of Exam. Don. Seal Under 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Pump	Located at #130 BAK in #4 Entry	at #7-6' THL
10HP Stator	Located at #137 BAK in #2 Entry	
13HP Pump	Located on the belt Entry in the	
Face of North Main's section old section out of service (No Power)		

EXAMINATION OF ELECTRICAL EQUIPMENT

1-3-09

Examination of electrical equipment (weekly)

~~North~~ North

Mains

Pumps

From

North to Face

Date

Location

Equipment examined and/or tested

Dangerous conditions

Action taken

Examiner

- 9 HP Flight Located At # 12 Bnk in # 4 Entry
- 9 HP Flight Located At # 17 Bnk in # 4 Entry
- 6 HP Starcor Located At # 37 Bnk on old # 1 section in Right Return
- 9 HP SPS Located At # 46 Bnk on old # 1 section in North Return
- 5 HP SPS Located At # 38 Bnk in # 5 Entry
- 5 HP BSM Located At # 40 Bnk in # 4 Entry
- 13 HP Flight Located At # 45-46 Bnk in # 4 Entry
- 5 HP SPS Located At # 53 Bnk in # 5 Entry

no dangerous conditions were found at time of Examination

Pat Walker
4-250
1-3-09

Weekly tests of grounding devices (diodes):

- 9 HP Flight Located At # 74 Bnk on old # 1 section in Right Return
- 5 HP Flight Located At # 85 Bnk in # 5 Entry
- 5 HP Flight Located At # 85 Bnk in # 4 Entry
- 5 HP Flight Located At # 105 Bnk in # 4 Entry
- 5 HP Flight Located At # 128 Bnk at Glory Hole
- 10 HP Starcor Located At # 128 Bnk on along belt labeled Head Pump
- 6 HP Starcor Located At # 128 Bnk on along belt labeled # 1 Tail Pump
- 5 HP Flight Located At # 130 Bnk in # 4 Entry At # 7-6' Tail
- 10 HP Starcor Located At # 137 Bnk in # 2 Entry
- 13 HP Flight Located in the Face of old North main section in the Belt Entry. (Out of service no power.)

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

1-10-09

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9AP Flygt Located #12 Bnk in #4 Entry			
		2AP Flygt Located #17 Bnk in #4 Entry			
		6AP Starcor Located # 37 Bnk on old #1 section in Right Return			
		9AP SPS Located #40 Bnk on old #1 section in Right Return			
		5AP APC Located #38 Bnk in #5 Entry			
		5AP BTM Located #40 Bnk in #4 Entry			
		13AP Flygt Located at # 45-46 Bnk in #4 Entry			
		3AP SPS Located at # 53 Bnk in #5 Entry			
		9AP Flygt Located at # 74 Bnk on old #1 section in Right Return			
		5AP Flygt Located at # 85 Bnk in #5 Entry			
		5AP Flygt Located at # 85 Bnk in #4 Entry			
		5AP Flygt Located at # 105 Bnk in #4 Entry			
		55AP Flygt located at #128 Bnk at Albany Hole			
		10AP Starcor Located at #128 Bnk on long belt Label Head Pump			
		6AP Starcor Located at #128 Bnk on long belt Labeled #1 Trash Pump			

no dangerous
conditions were found
at Time of Examination
Paul Miller
4-250
1-10-09

Examinations of low- medium-voltage power circuit breakers (monthly)

5AP Flygt Located at #130 Bnk in #4 Entry at #7-6 TRIL
 10AP Starcor Located at #137 Bnk in #2 Entry
 13AP Flygt located in the belt Entry of the Face
 of old North Main's Section.
 This PUMP is out of service - no power

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

1-16-09 North MAIN PUMPS From mouth to FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Flyght	Located at #12 BAK in #4 Entry			
9HP	Flyght	located at #17 BAK in #4 Entry			
6HP	Starcon	Located at #37 BAK on old #1 section in Right Return			
9HP	SPS	Located at #40 BAK on old #1 section in Right Return			
5HP	SPS	Located at #38 BAK in #5 Entry			
5HP	DJM	Located at #46 BAK in #4 Entry			
13HP	Flyght	Located at #45-46 BAK in #4 Entry			
5HP	SPS	Located at #53 BAK in #5 Entry			

NO Dangerous Conditions were Found at Time of Examination
Paul Nicolau
4-250

Weekly tests of grounding devices (diodes)

9HP	Flyght	Located at #74 BAK on old #1 section in Right Return			
5HP	Flyght	Located at #85 BAK in #5 Entry			
5HP	Flyght	Located at #88 BAK in #4 Entry			
5HP	Flyght	Located at #105 BAK in #4 Entry			
58HP	Flyght	Located at #128 BAK in Long Hole			
10HP	Starcon	Located at #128 BAK on Gray belt LABELED Head Pump			
6HP	Starcon	Located at #128 BAK on Gray belt LABELED #1 TRASH PUMP			
5HP	Flyght	Located at #130 BAK in #4 Entry at #7-6' tail			
10HP	Starcon	Located at #137 BAK in #2 Entry			
13HP	Flyght	Located in the belt Entry in the FACE on old north main's section.			

(This pump is out of service)
no power

Monthly examinations of methane monitors

Paul Nicolau
4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

1-24-09 North Mains Pumps from mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		4HP Flygt Located at # 12 Bnk in # 4 Entry			
		7HP Flygt. Located at # 17 Bnk in # 4 Entry			
		6HP Stator Located at # 37 Bnk on old # 1 Section in Right Return			
		9HP SPS Located at # 40 Bnk on old # 1 Section in Right Return			
		5HP SPS Located at # 38 Bnk in # 5 Entry			
		5HP BSM Located at # 40 Bnk in # 4 Entry			
		13HP Flygt Located at # 45-46 Bnk in # 4 Entry			
		5HP SPS Located at # 53 Bnk in # 5 Entry			
		9HP Flygt Located at # 74 Bnk on old # 1 Section in Right Return			
		5HP Flygt Located at # 85 Bnk in # 5 Entry			
		5HP Flygt Located at # 88 Bnk in # 4 Entry			
		5HP Flygt Located at # 105 Bnk in # 4 Entry			
		78HP Flygt Located at # 128 Bnk at Alog Hole			
		10HP Stator Located at # 128 Bnk on Alog Belt Labeled Head Pump			
		6HP Stator Located at # 128 Bnk on Alog Belt Labeled # 1 Trash Pump			

No Dangerous Load at-at's were found at time of Examination.
 Examiners
 Date 1-24-09
 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt	Located at # 130 Bnk in # 4 Entry at # 7-6 TAIL
10HP Stator	Located at # 137 Bnk in # 2 Entry
13HP Flygt	Located at The Face of old North mains section at the Belt Entry. (This pump is out of service no power.)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

1-30-09

North Mines Pump From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9AP	Flight	Located at # 12 BRT in # 4 Entry			
9AP	Flight	Located at # 17 BRT in # 4 Entry			
6AP	Starcor	Located at # 37 BRT on old # 1 section in Right Return			
9AP	SPS	Located at # 40 BRT on old # 1 section in Right Return			
5AP	SPS	Located at # 38 BRT in # 5 Entry			
5AP	BJM	Located at # 40 BRT in # 4 Entry			
13AP	Flight	Located at # 45 BRT in # 4 Entry			
5AP	SPS	Located at # 53 BRT in # 5 Entry			

no Dangerous Conditions were found at Time of Examination
 Not Under 4250

Weekly tests of grounding devices (diodes)

9AP	Flight	Located at # 74 BRT on old # 1 section in Right Return			
5AP	Flight	Located at # 85 BRT in # 5 Entry			
5AP	Flight	Located at # 88 BRT in # 4 Entry			
5AP	Flight	Located at # 105 BRT in # 4 Entry			
58AP	Flight	Located at # 128 BRT at Glory Hole			
10AP	Starcor	Located at # 128 BRT on Glory Belt Labeled Head Pump			
6AP	Starcor	Located at # 128 BRT on Glory Belt Labeled # 1 Trash Pump			
5AP	Flight	Located at # 130 BRT in # 4 Entry at # 7-6 Tail			
10AP	Starcor	Located at # 137 BRT in # 2 Entry			
13AP	Flight	Located at the Face of North Mines Section in the Belt Entry. This Pump is out of service			

Monthly examinations of methane monitors

NO P.M.E.O.

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-6-09	North Main	Pump P. Floor	North to Face		
		9HP Flygt Located at #12 Bkt in #4 Entry			
		9HP Flygt Located at #17 Bkt in #4 Entry			
		6HP Stancer Located at #37 Bkt on old #1 section in Right Return			
		9HP SPS Located at #40 Bkt on old #1 section in Right Return			
		5HP SPS Located at #38 Bkt in #5 Entry			
		5HP BJM Located at #40 Bkt in #4 Entry			
		13HP Flygt Located at #45-46 Bkt in #4 Entry			
		5HP SPS Located at #53 Bkt in #5 Entry			
		9HP Flygt Located at #74 Bkt on old #1 section in Right Return			
		5HP Flygt Located at #85 Bkt in #5 Entry			
		5HP Flygt Located at #98 Bkt in #4 Entry			
		5HP Flygt Located at #105 Bkt in #4 Entry			
		58HP Flygt Located at #128 Bkt at Glory Hole			
		10HP Stancer Located at #128 Bkt on Glory Belt Labeled Head Pump			
		6HP Stancer Located at #128 Bkt on Glory Belt Labeled #1 Trash Pump			

No Dangerous Conditions were Found At time of Examination

Number Visited
250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt	Located at 130 Bkt in #4 Entry at #7-6' Tail
10HP Stancer	Located at #137 Bkt in #2 Entry
13HP Flygt	Located in the Face of old North Main's section in the #4 Entry.

This Pump is still out of service due to no Power - P. Adams

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

2-14-09 North MAIN'S PUMPS FROM MOUTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 BRT in # 4 Entry			
		9 HP Flygt Located at # 17 BRT in # 4 Entry			
		6 HP Stancor Located at # 37 BRT on old # 1 section in Right Return			
		9 HP SPS Located at # 40 BRT on old # 1 section in Right Return			
		5 HP SPS Located at # 38 BRT in # 5 Entry			
		5 HP BJM Located at # 40 BRT in # 4 Entry			
		13 HP Flygt Located at # 45-46 BRT in # 4 Entry			
		5 HP SPS Located at # 53 BRT in # 5 Entry			

No Dangerous Conditions were found at Time of Examination.
Neil Winder

Weekly tests of grounding devices (diodes)

		9 HP Flygt Located at # 74 BRT on old # 1 section in Right Return			
		5 HP Flygt Located at # 95 BRT in # 5 Entry			
		5 HP Flygt Located at # 88 BRT in # 4 Entry			
		5 HP Flygt Located at # 105 BRT in # 4 Entry			
		58 HP Flygt Located at # 128 BRT at Glory Hole			
		10 HP Stancor Located at # 128 BRT on Glory Belt Labeled Head Pump			
		6 HP Stancor Located at # 128 BRT on Glory Belt Labeled # 1 Trash Pump			
		5 HP Flygt Located at # 130 BRT in # 4 Entry at # 26 Tail			
		10 HP Stancor Located at # 137 BRT in # 2 Entry			

4-250

13 HP Flygt Located in the Face of the Belt Entry on old North MAIN'S section. This pump is still out of service due to no power

Monthly examinations of methane monitors

Neil Winder 4-256
2-14-09

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

2-25-09 North MAINS Pumps From MOUTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP Stancor Located at # 37 BRK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BRK on old # 1 section in Right Return			
		5HP SPS Located at # 33 BRK in # 5 Entry			
		5HP DJM Located at # 40 BRK in # 4 Entry			
		13HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flygt Located at # 74 BRK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BRK in # 5 Entry			
		5HP Flygt Located at # 88 BRK in # 4 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		53HP Flygt Located at # 128 BRK at along Hole sump			
		10HP Stance Located at # 128 BRK on along Belt Labeled Head Pump			
		6HP Stancor Located at # 128 BRK on along Belt Labeled # 1 TRASH Pump			

No Dangerous
Conditions were
Found At Time of EXAM.
Said under
4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt Located at # 130 BRK in # 4 Entry at # 7-6' TAIL

10HP Stancor Located at # 137 BRK in # 2 Entry

13HP Flygt Located in the Belt Entry in the FACE
OF OLD NORTH MAINS SECTION

This PUMP is OUT OF SERVICE DUE TO NO POWER

2-25-09
4-250
Said under

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

3-6-09 North mine pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 BRK in # 4 Entry			
		9 HP Flygt Located at # 17 BRK in # 4 Entry			
		6 HP STARCOR Located at # 37 BRK on old #1 section in Right Return			
		9 HP SPS Located at # 40 BRK on old #1 section in Right Return			
		5 HP SPS Located at # 38 BRK in # 5 Entry			
		5 HP BTM Located at # 40 BRK in # 4 Entry			
		13 HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5 HP SPS Located at # 53 BRK in # 5 Entry			

no Dangerous conditions were found at time of Examination
 just Visual
 4-250

Weekly tests of grounding devices (diodes)

		9 HP Flygt Located at # 74 BRK on old #1 section in Right Return
		5 HP Flygt Located at # 55 BRK in # 5 Entry
		5 HP Flygt Located at # 85 BRK in # 4 Entry
		5 HP Flygt Located at # 105 BRK in # 4 Entry
		5 HP Flygt Located at # 128 BRK at Worg Hole
		10 HP STARCOR Located at # 125 BRK on Worg belt labeled Head Pump
		6 HP STARCOR Located at # 128 BRK on Worg belt labeled #1 Trash Pump
		5 HP Flygt Located at # 130 BRK in # 4 Entry at # 7-6' This view
		10 HP STARCOR Located at # 137 BRK in # 12 Entry
		13 HP Flygt Located in the face of the 15' old Entry on old North mine's section

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

3-13-09 North MAIN Pumps From mouth to Race

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at #12 Bkt in #4 Entry			
		9HP Flygt Located at #17 Bkt in #4 Entry			
		6HP Stacor Located at #37 Bkt. on old #1 section in Right Return			
		9HP SPS Located at #40 Bkt on old #1 section in Right Return			
		5HP SPS Located at #40 Bkt in #4 Entry			
		5HP SPS Located at #38 Bkt in #5 Entry			
		13HP Flygt Located at #45-46 Bkt in #4 Entry			
		5HP SPS Located at #53 Bkt in #5 Entry			
		9HP Flygt Located at #74 Bkt on old #1 section in Right Return			
		5HP Flygt Located at #85 Bkt in #5 Entry			
		5HP Flygt Located at #85 Bkt in #4 Entry			
		5HP Flygt Located at #105 Bkt in #4 Entry			
		58HP Flygt Located at #128 Bkt at Wagon Hole			
		10HP Stacor Located at #128 Bkt on Wagon Belt LABELED Head Pump			
		6HP Stacor Located at #128 Bkt on Wagon Belt LABELED #1 Trash Pump			

NO Dangerous conditions were found at

Time of Examination
see index
4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt	located at #130 Bkt in #4 Entry at #7-6' Tail
10HP Stacor	located at #137 Bkt in #2 Entry
13HP Flygt	located in the Belt Entry of the FACE OF old North MAIN'S SECTION

EXAMINATION OF ELECTRICAL EQUIPMENT

3-20-09 North MAIRS Pumps From Mouth to Face

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Flyght	Located at #12 BRT in #4 Entry			
9HP	Flyght	Located at #17 BRT in #4 Entry			
6HP	Stanco	Located at #37 BRT on old #1 section in Light Return			
9HP	S.P.S	Located at #40 BRT on old #1 section in Light Return			
5HP	S.P.S	located at #38 BRT in #5 Entry			
5HP	B5M	Located at #40 BRT in #4 Entry			
13HP	Flyght	Located at #45-46 BRT in #4 Entry			
5HP	S.P.S	Located at #53 BRT in #5 Entry			

No Dangerous Conditions
 Conditions were found at Time of Exam.

Weekly tests of grounding devices (diodes)

9HP	Flyght	Located at #74 BRT on old #1 section in Light Return
5HP	Flyght	Located at #85 BRT in #5 Entry
5HP	Flyght	Located at #88 BRT in #4 Entry
5HP	Flyght	Located at #105 BRT in #4 Entry
58HP	Flyght	Located at #128 BRT at Along Hole
10HP	Stanco	Located at #128 BRT on Along Belt Labeled Head Pump
6HP	Stanco	Located at #128 BRT on Along Belt Labeled #1 Trash Pump
5HP	Flyght	Located at #130 BRT at #7-6' TRIC in #4 Entry
10HP	Stanco	Located at #137 BRT in #2 Entry
13HP	Flyght	Located at in the Belt Entry of the Face of old North MAIRS section

Paul Vidler
 4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

3-27-09

North MAIN'S PUMPS FROM MOUTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flyant located at # 12 BRK			
		9 HP Flyant located at # 17 BRK			
		6 HP STANCON located at # 37 BRK on old #1 section in Right Return			
		5 HP BJM located at # 40 BRK in # 4 Entry			
		5 HP SPS located at # 38 BRK in # 5 Entry			
		13 HP Flyant located at # 45-46 BRK in # 4 Entry			
		5 HP SPS located at # 53 BRK in # 5 Entry			
		9 HP Flyant located at # 74 BRK on old #1 section in Right Return			
		5 HP Flyant located at # 85 BRK in # 5 Entry			
		5 HP Flyant located at # 88 BRK in # 4 Entry			
		5 HP Flyant located at # 105 BRK in # 4 Entry			
		5 HP Flyant located at # 128 BRK at 10' long table			
		10 HP STANCON located at # 128 BRK on Wagon Belt labeled Head Pump			
		6 HP STANCON located at # 128 BRK on Wagon Belt labeled #1 Trough Pump			
		5 HP Flyant located at # 130 BRK at # 7-6 Tail Piece.			

No Dangerous conditions were found at time of Examination.

Not Made 4:50

Examinations of low- medium-voltage power circuit breakers (monthly)

10 HP STANCON located at # 137 BRK in # 2 Entry
 13 HP Flyant located in the Belt Entry of the old north main's section in the Face.

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

4-4-09

North Main's Pumps From Mouth to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flight Located at # 12 BRK in # 4 Entry
- 9HP Flight Located at # 17 BRK in # 4 Entry
- 6HP Starcor Located at # 37 BRK on old # 1 section in Right Return
- 9HP SPS Located at # 40 BRK on old # 1 section in Right Return
- 5HP SPS Located at # 38 BRK in # 5 Entry
- 5HP BSM Located at # 40 BRK in # 4 Entry
- 13HP Flight Located at # 45-46 BRK in # 4 Entry
- 5HP SPS Located at # 53 BRK in # 5 Entry

No Dangerous conditions were Found at Time of Examination

J. W. Miller
4-25-09

Weekly tests of grounding devices (diodes)

- 9HP Flight Located at # 74 BRK on old # 1 section in Right Return
- 5HP Flight Located at # 85 BRK in # 5 Entry
- 5HP Flight Located at # 88 BRK in # 4 Entry
- 5HP Flight Located at # 105 BRK in # 4 Entry
- 50HP Flight Located at # 128 BRK at Glory Hole
- 10HP Starcor Located at # 128 BRK on Glory Belt Labeled Head Pump
- 6HP Starcor Located at # 128 BRK on Glory Belt Labeled # 1 Trash Pump
- 5HP Flight Located at # 130 BRK at # 7-6' Tail Piece
- 10HP Starcor Located at # 137 BRK in # 2 Entry
- 13HP Flight Located in the FACE OF the Belt Entry on old North Main's section

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

4-18-09 North MAIN'S Pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 BRT in # 4 Entry			
		9 HP Flygt Located at # 17 BRT in # 4 Entry			
		6 HP Stator Located at # 37 BRT on old # 1 section in Right Return			
		9 HP SPS Located at # 40 BRT on old # 1 section in Right Return on old # 5 section in Right Return			
		5 HP SPS Located at # 38 BRT in # 5 Entry			
		5 HP BDM Located at # 40 BRT in # 4 Entry			
		13 HP Flygt Located at # 45-46 BRT in # 4 Entry			
		5 HP SPS Located at # 53 BRT in # 5 Entry			
		9 HP Flygt Located at # 74 BRT on old # 1 section in Right Return 4-257			
		5 HP Flygt Located at # 85 BRT in # 5 Entry			
		5 HP Flygt Located at # 88 BRT in # 4 Entry			
		5 HP Flygt Located at # 105 BRT in # 4 Entry			
		55 HP Flygt Located at # 128 BRT at Along Hole			
		10 HP Stator Located at # 128 BRT on Along belt Labeled Head Pump			
		6 HP Stator Located at # 128 BRT on Along belt Labeled # 1 Trash Pump			

No dangerous conditions were found at Time of Examination

Examinations of low- medium-voltage power circuit breakers (monthly)

		5 HP Flygt Located at # 130 BRT at # 7-6' Tail			
		10 HP Stator Located at # 137 BRT at # 127 BRT Entry			
		13 HP Flygt Located in the Face of North MAIN'S old Section Belt Entry			

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

4-24-09 North Main's Pump's From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9AP	Flyght	Located at #12 BTK in #4 Entry			
9AP	Flyght	Located at #17 BTK in #4 Entry			
6AP	Starcon	Located at #37 BTK on old #1 section in Right Return			
9AP	S.P.S	Located at #40 BTK on old #1 section in Right Return			
5AP	S.P.S	Located at # 38 38 BTK in #5 Entry			
5AP	B3M	Located at #40 BTK in #4 Entry			
13AP	Flyght	Located at #45-46 BTK in #4 Entry			
5AP	S.P.S	Located at #53 BTK in #5 Entry			
9AP					
Weekly tests of grounding devices (diodes)					
	Flyght	Located at #74 BTK on old #1 section in Right Return			
5AP	Flyght	Located at #85 BTK in #5 Entry			
5AP	Flyght	Located at #88 BTK in #4 Entry			
5AP	Flyght	Located at #105 BTK in #4 Entry			
15AP	Flyght	Located at #125 BTK at a long hole			
10AP	Starcon	Located at #128 BTK on a long belt labeled Head Pump			
6AP	Starcon	Located at #128 BTK on a long belt labeled #1 Trash Pump			
5AP	Flyght	Located at #130 BTK in #4 Entry at #7-6' TIC			
10AP	Starcon	Located at #137 BTK in #2 Entry			
13AP	Flyght	Located at North Main's Face of the Belt Entry			

No Dangerous Conditions were found at time of Examination.
 Paul Mader
 4-25-09

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

5-1-09

WORK MARKS PUMPS FROM NORTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flyabt Located at # 12 BAK in # 4 Entry			
		9HP Flyabt Located at # 17 BAK in # 4 Entry			
		6HP stator Located at # 37 BAK on old # 1 section in Right Return			
		9HP SPS Located at # 37 BAK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BAK in # 5 Entry			
		5HP PUM Located at # 40 BAK in # 4 Entry			
		13HP Flyabt Located at # 45-46 BAK in # 4 Entry			
		5HP SPS Located at # 53 BAK in # 5 Entry			
		9HP Flyabt Located at # 74 BAK on old # 1 section in Right Return			
		5HP Flyabt Located at # 95 BAK in # 5 Entry			
		5HP Flyabt Located at # 88 BAK in # 4 Entry			
		5HP Flyabt Located at # 105 BAK in # 4 Entry			
		58HP Flyabt Located at # 128 BAK at along Hole			
		10HP stator Located at # 128 BAK on along Belt labeled Head Pump			
		6HP stator Located at # 128 BAK on along Belt labeled # 1 Tail Pump			

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flyabt Located at # 130 BAK at # 7-6 Tail
10HP stator Located at # 137 BAK in # 2 Entry
13HP Flyabt Located at the FACE OF THE BELT ENTRY on old north mines section.

↑
 Tail Motor
 No Dangerous Conditions
 were Found at Time of
 Examination 4-25-09

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

5-8-09

North Man's Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
------	----------	----------------------------------	----------------------	--------------	----------

9 AP Flygt Located at # 12 BRT in # 4 Entry

9 AP Flygt Located at # 17 BRT in # 4 Entry

6 AP Stator Located at # 37 BRT on old # 1 section in Right Return

9 AP SPS Located at # 40 BRT on old # 1 section in Right Return

5 AP SPS Located at # 38 BRT in # 5 Entry

5 AP BJM Located at # 40 BRT in # 4 Entry

13 AP Flygt Located at # 45-46 BRT in # 4 Entry

5 AP SPS Located at # 53 BRT in # 5 Entry

Weekly tests of grounding devices (diodes)

9 AP Flygt Located at # 74 BRT on old # 1 section in Right Return

5 AP Flygt Located at # 85 BRT in # 5 Entry

5 AP Flygt Located at # 105 BRT in # 4 Entry

5 AP Flygt Located at # 128 BRT at Glory Hole

10 AP Flygt Located at # 128 BRT on along belt (out of service?)

5 AP Flygt Located at # 130 BRT at # 7-6' TRIC

10 AP Stator Located at # 137 BRT in # 2 Entry

13 AP Flygt Located at the Face in the belt Entry

OF old North man's sections

9

NO Dangerous Conditions
were Found at
Time of Examination
5-8-09
not needed
4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

5-16-09 North Main's Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 Bkt in # 4 Entry			
		9HP Flygt Located at # 17 Bkt in # 4 Entry			
		6HP Stator Located at # 37 Bkt or old #1 section in Right Return			
		9HP SPS Located at # 40 Bkt or old #1 section in Right Return			
		5HP SPS Located at # 38 Bkt in # 5 Entry			
		5HP BSM Located at # 40 Bkt in # 4 Entry			
		13HP Flygt (Took out of service Pump covered new one on order) Located at 45-46 Bkt in # 4 Entry			
		5HP SPS Located at # 53 Bkt in # 5 Entry			
		9HP Flygt Located at # 74 Bkt or old #1 section in Right Return			
		5HP Flygt Located at # 85 Bkt in # 5 Entry			
		5HP Flygt Located at # 105 Bkt in # 4 Entry			
		58HP Flygt Located at # 128 Bkt at Clay Hole			
		10HP Stator Located at # 128 Bkt or 6-Long Belt Labeled Head Pump			
		5HP Flygt Located at # 130 Bkt at # 7-6 Tail Piece			

Examinations of low- medium-voltage power circuit breakers (monthly)

10HP ~~Stator~~ Located at # 137 Bkt in # 2 Entry

13HP Flygt Located in the Face of the belt Entry or old North Main's section

No Dangerous
Conditions were
Found at Time
of Examination
5-16-09
Paul Mular

EXAMINATION OF ELECTRICAL EQUIPMENT


Examination of electrical equipment (weekly)

5-21-09 North Mains Pump From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 AP Flyght Located at # 12 BAK in # 4 Entry			
		9 AP Flyght Located at # 17 BAK in # 4 Entry			
		6 AP Starcor Located at # 37 BAK on old # 1 section in Right Return			
		9 AP SPS Located at # 40 BAK on old # 1 section in Right Return			
		5 AP SPS located at # 38 BAK in # 5 Entry			
		5 AP BSM located at # 40 BAK in # 4 Entry			
		(13 AP Flyght This Pump still out of service)			
		5 AP SPS located at # 53 BAK in # 5 Entry			

Weekly tests of grounding devices (diodes)

		9 AP Flyght Located at # 74 BAK on old # 1 section in Right Return			
		5 AP Flyght Located at # 85 BAK in # 5 Entry			
		5 AP Flyght Located at # 105 BAK in # 4 Entry			
		5 AP Flyght Located at # 128 BAK at Along Hole			
		10 AP Starcor Located at # 128 BAK on Along belt labeled Road Pump			
		5 AP Flyght Located at # 130 BAK in # 4 Entry at # 7-6 Tail			
		10 AP Starcor Located at # 137 BAK in # 2 Entry			
		13 AP Flyght Located in the Face of the Belt Entry of old North Mains section			



Monthly examinations of methane monitors

NO Dangerous conditions were found at time of examination.

W. J. ...
4250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

5-29-09 north main's kumps from south to face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt located at # 12 BAK in # 4 Entry			
		9HP Flygt located at # 17 BAK in # 4 Entry			
		6HP Stator located at # 37 BAK on old # 1 section in right Return			
		9HP G.P.S located at # 40 BAK on old # 1 section in right Return			
		5HP G.P.S located at # 38 BAK in # 5 Entry			
		5HP B.S.M located at # 40 BAK in # 4 Entry			
		13HP Flygt located at # 45-46 BAK in # 4 Entry			
		5HP G.P.S located at # 53 BAK in # 5 Entry			
		9HP Flygt located at # 74 BAK on old # 1 section in right Return			
		5HP Flygt located at # 85 BAK in # 5 Entry			
		5HP Flygt located at # 105 BAK in # 4 Entry			
		55HP Flygt located at # 128 BAK at blow hole			
		10HP Stator located at # 128 BAK on blow belt labeled Head Pump			
		5HP Flygt located at # 130 BAK at # 7-6' TALK in # 4 Entry			
		10HP Stator located at # 137 BAK in # 2 Entry			

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Flygt located in the FACE of the Belt Entry of old north main's section

No Dangerous conditions were found at Time of Examination.

ant nuclear

4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

6-5-09 North MAINS PUMPS From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9AP	Flggt	Located at # 12 BAK in # 4 Entry			
9AP	Flggt	Located at # 17 BAK in # 4 Entry			
6AP	STANCON	Located at # 37 BAK on old # 15 section in Right Return			
9AP	SFS	located at # 40 BAK on old # 15 section in Right Return			
5AP	SFS	located at # 38 BAK in # 5 Entry			
5AP	B5M	located at # 40 BAK in # 4 Entry			
13AP	Flggt	located at # 45-46 BAK in # 4 Entry			
5AP	SFS	located at # 33 BAK in # 5 Entry			

No Dangerous conditions were found at Time of Examination

Weekly tests of grounding devices (diodes)

9AP	Flggt	located at # 74 BAK on old # 15 section in Right Return			
5AP	Flggt	located at # 85 BAK in # 5 Entry			
5AP	Flggt	located at # 105 BAK in # 4 Entry			
5AP	Flggt	located at # 128 BAK at Glory Hole			
10AP	STANCON	located at # 128 BAK on Glory Belt LABELED HEAD PUMP			
5AP	Flggt	located at # 130 BAK AT # 7-6' TAIL in # 4 Entry			
10AP	STANCON	located at # 137 BAK in # 2 Entry			
13AP	Flggt	located in the Belt Entry of the Face of old North Mains Section			

4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

6-12-09 North Mines Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP Stator Located at # 37 BRK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BRK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BRK in # 5 Entry			
		5HP BRK Located at # 40 BRK in # 4 Entry			
		13HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flygt Located at # 74 BRK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BRK in # 5 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		58HP Flygt Located at # 128 BRK at Blary Hole			
		10HP Stator Located at # 125 BRK on 6" Wdg belt coupled Head Pump			
		5HP Flygt Located at # 130 BRK at # 7-6' TOL in # 4 Entry			
		10HP Stator Located at # 137 BRK in # 2 Entry			

→ No Dangerous Conditions were Found at Time of Examination
 Not Under
 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Flygt Located in the Face of the Belt Entry on old North Mines section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

6-20-09

North mines Pump Room Floor month to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Flygt	Located at #12 BAK in #4 Entry			
9HP	Flygt	Located at #17 BAK in #4 Entry			
6HP	Starcon	Located at #37 BAK on old #1 section in Right Return			
9HP	SPS	Located at #40 BAK on old #1 section in Right Return			
5HP	SPS	Located at #38 BAK in #5 Entry			
5HP	BJM	Located at #40 BAK in #4 Entry			
13HP	Flygt	Located at #45-46 BAK in #4 Entry			
5HP	SPS	Located at #53 BAK in #5 Entry			

Weekly tests of grounding devices (diodes)

9HP	Flygt	Located at #74 BAK on old #1 section in Right Return			
5HP	Flygt	Located at #85 BAK in #5 Entry			
5HP	Flygt	Located at #105 BAK in #4 Entry			
5HP	Flygt	Located at #128 BAK at 6-Long Hole			
10HP	Starcon	Located at #128 BAK on along Belt Labeled Head Pump			
5HP	Flygt	Located at #130 BAK at #7-6' Tail in #4 Entry			
10HP	Starcon	Located at #137 BAK in #2 Entry			
13HP	Flygt	Located in the Face of the Belt Entry on old North mine's section			

No Dangerous conditions were found at time of Examination.
 Not Under 4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

6-27-09 North Main's Pump From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BTK in # 4 Entry			
		9HP Flygt Located at # 17 BTK in # 4 Entry			
		6HP Starcon Located at # 37 BTK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BTK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BTK in # 5 Entry			
		Found Power Cable Cut. Repaired Immediately			
		5HP BSM Located at # 40 BTK in # 4 Entry			
		13HP Flygt Located at # 45-46 BTK in # 4 Entry			
		5HP SPS Located at # 53 BTK in # 5 Entry			
		9HP Flygt Located at # 74 BTK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BTK in # 5 Entry			
		5HP Flygt Located at # 105 BTK in # 4 Entry			
		58HP Flygt Located at # 128 BTK at Along Hole			
		10HP Starcon Located at # 128 BTK on Along belt labeled Head Pump			
		5HP Flygt Located at # 130 BTK at # 7-6' TAIL in # 4 Entry			

Examinations of low- medium-voltage power circuit breakers (monthly)

10HP Starcon Located at # 137 BTK in # 2 Entry
 13HP Flygt Located in the Belt Entry on the
 Face of old North Main's section

✓

Other than # 38 BTK Pump
 No other Dangerous conditions
 were found at time of Examination
 Neil Nelson

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

7-4-09

North MAIR'S Pumps From Mouth to Face.

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner	
		9HP Flygt Located at # 12 BRT in # 4 Entry				
		9HP Flygt Located at # 17 BRT in # 4 Entry				
		6HP Stancer Located at # 37 BRT on old # 1 section in Right Return.				
		9HP SPS Located at # 40 BRT on old # 1 section in Right Return.				
		5HP SPS Located at # 38 BRT in # 5 Entry				
		5HP BSM Located at # 40 BRT in # 4 Entry				
		13HP Flygt Located at # 45-46 BRT in # 4 Entry				
		5HP SPS Located at # 53 BRT in # 5 Entry				
		Weekly tests of grounding devices (diodes)				
		9HP Flygt Located at # 74 BRT on old # 1 section in Right Return				
		5HP Flygt Located at # 85 BRT in # 5 Entry				
		5HP Flygt Located at # 105 BRT in # 4 Entry				
		58HP Flygt Located at # 128 BRT at Wavy Hole				
		10HP Stancer Located at # 128 BRT on Wavy Belt Labeled Head Pump				
		5HP Flygt Located at # 130 BRT at # 7-6' TAIL in # 4 Entry				
		10HP Stancer Located at # 137 BRT in # 2 Entry				
		13HP Flygt Located in the belt entry in the Face of old North MAIR'S section				

all Dangerous conditions were found at time of Examination and resolved
 U-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

7-11-09 North Manie's Pumps From North to Face

Date

Location

Equipment examined and/or tested

Dangerous conditions

Action taken

Examiner

- 9HP Flygt Located at # 12 BAK in # 4 Entry
- 9HP Flygt Located at # 17 BAK in # 4 Entry
- 6HP Stancor Located at # 37 BAK or old # 1 section in Right Return
- 9HP SPS Located at # 40 BAK or old # 1 section in Right Return
- 5HP SPS Located at # 38 BAK in # 5 Entry
- 5HP BSM Located at # 40 BAK in # 4 Entry
- 13HP Flygt Located at # 45-46 BAK in # 4 Entry
- 5HP SPS Located at # 53 BAK in # 5 Entry
- 9HP Flygt Located at # 74 BAK or old # 1 section in Right Return
- 5HP Flygt Located at # 85 BAK in # 5 Entry
- 5HP Flygt Located at # 105 BAK in # 4 Entry
- 58HP Flygt Located at # 128 BAK at Along Hole
- 10HP Stancor Located at # 128 BAK or Along belt labeled Head Pump
- 5HP Flygt Located at # 130 BAK at # 9-6' Tail in # 4 Entry
- 10HP Stancor Located at # 137 BAK in # 2 Entry

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Flygt located in the belt Entry of the Face of old North Manie's section

NO DANGEROUS CONDITIONS
WERE FOUND ON THESE
PUMPS AT TIME
OF EXAMINATION.

Sub Number 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

7-22-09 North Mines Pumps from Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Flygt	Located at #12 BRT in #4 Entry			
9HP	Flygt	Located at #17 BRT in #4 Entry			
6HP	Stator	Located at #37 BRT on old #1 section in Right Return			
9HP	SPS	Located at #40 BRT on old #1 section in Right Return			
5HP	SPS	Located at #38 BRT in #5 Entry			
5HP	Bsm	Located at #40 BRT in #4 Entry			
13HP	Flygt	Located at #45-46 BRT in #4 Entry			
5HP	SPS	Located at #53 BRT in #5 Entry			

Weekly tests of grounding devices (diodes)

9HP	Flygt	Located at #74 BRT on old #1 section in Right Return			
5HP	Flygt	Located at #85 BRT in #5 Entry			
5HP	Flygt	Located at #105 BRT in #4 Entry			
58HP	Flygt	Located at #128 BRT at Glory Hole			
10HP	Stator	Located at #128 BRT on a clay belt around Head Pump			
5HP	Flygt	Located at #130 BRT at #7-6' Tail in #4 Entry			
10HP	Stator	Located at #137 BRT in #4 Entry			
13HP	Flygt	Located in the Face of the Belt Entry on old north mines section			

Monthly examinations of methane monitors

No Dangerous
Conditions were
Found at Time of
Examination

W. M. Miller
4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

7-31-09

North Mains Panel 9 From Meters to Bus

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt located at #126 BK in #4 Entry		No Dangerous conditions were found at time of Examination.	Paul Miska 4-250
		9HP Flygt located at #176 BK in #4 Entry			
		6HP Stancore located at #97 BK on old #1 section in right return			
		9HP SPS located at #40 BK on old #1 section in right return			
		5HP SPS located at #36 BK in #5 Entry			
		5HP SPS located at #40 BK in #4 Entry			
		13HP Flygt located at #45-46 BK in #4 Entry			
		5HP SPS located at #53 BK in #5 Entry			
		9HP Flygt located at #74 BK on old #1 section in right return			
		5HP Flygt located at #85 BK in #5 Entry			
		58HP Flygt is down & out of service at #128 BK at along 170 lb 3 wood			
		10HP Stancore located at #128 BK on along belt OK	No Dangerous conditions observed.		Paul Miska 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

5HP Flygt located at #130 BK
 10HP Stancore located at #137 BK
 13HP Flygt located in the Face of
 North Mains Section

All three pumps are out of service. No power in area.
 Paul Miska
 4-250

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

8-8-09	North Main	Pumps	From mouth to Face	
Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken / Examiner
		9HP Flygt Located at #12 Bnk in #4 Entry		
		9HP Flygt Located at #17 Bnk in #4 Entry		
		6HP Starcor Located at #37 Bnk on old #1 section in Right Return		
		9HP SPS Located at #40 Bnk on old #1 section in Right Return		
		5HP SPS Located at #38 Bnk in #5 Entry		
		5HP DS in Located at #40 Bnk in #4 Entry		
		13HP Flygt Located at #45-46 Bnk in #4 Entry		
		5HP SPS Located at #53 Bnk in #5 Entry		
				NO Dangerous conditions were found at time of Examination JIM NICOLA 4-250

Weekly tests of grounding devices (diodes)

		9HP Flygt Located at #74 Bnk on old #1 section in Right Return		
		5HP Flygt Located at #55 Bnk in #5 Entry		
		55HP Flygt Located at #128 Bnk at Glory Hole Pump		
		10HP Starcor Located at #128 Bnk on Glory Belt		

		5HP Flygt Located at #130 Bnk		
		10HP Starcor Located at #137 Bnk		
		13HP Flygt Located at # of the Face		
		of North Main's section		
				All of these pumps are out of service due to no power in area JIM NICOLA 4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

8-20-09

North Main

Pumps

from the Month to the Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BAK in # 4 Entry			
		9HP Flygt Located at # 17 BAK in # 4 Entry			
		6HP Stancore Located at # 37 BAK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BAK on Old # 1 section in Right Return			
		5HP SPS Located at # 38 BAK in # 5 Entry			
		5HP BSM Located at # 40 BAK in # 4 Entry			
		13HP Flygt Located at # 45-46 BAK in # 4 Entry			
		5HP SPS Located at # 53 BAK in # 5 Entry			
		9HP Flygt Located at # 74 BAK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BAK in # 5 Entry			
		55HP Flygt Located at # 128 BAK at Old bag Hole 3402			
		10HP Stancore Located at # 128 BAK on Old bag Belt			
		15HP Flygt Located at # 130 BAK at # 7-6 Tail Piece			
		10HP Stancore Located at # 137 BAK in # 2 Entry			
		13HP Flygt Located at the Face of old			

Examinations of low- medium-voltage power circuit breakers (monthly)

North Main's section in the Belt Entry

No Dangerous
Conditions were
found at time
of Examination

David Walker 4-250


EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

8-25-09

NORTH MAINS PUMPS FROM MOUTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flyght Located at # 12 Bnk in # 4 Entry			
		9HP Flyght Located at # 17 Bnk in #			
		6HP Stator Located at # 37 Bnk on old # 1 section in right return			
		9HP SPS Located at # 40 Bnk on old # 1 section in right return			
		5HP SPS Located at # 38 Bnk in # 5 Entry			
		5HP SPS Located at # 40 Bnk in # 4 Entry			
		13HP Flyght Located at # 45-46 Bnk in # 4 Entry			
		5HP SPS Located at # 53 Bnk in # 5 Entry			
		2HP Flyght Located at # 74 Bnk on old # 1 section in right return			
		5HP Flyght Located at # 85 Bnk in # 5 Entry			
		5HP Flyght Located at # 105 Bnk in # 4 Entry			
		5HP Flyght Located at # 125 Bnk at Glory Hole			
		10HP Stator Located at # 125 Bnk on along Belt			
		5HP Flyght Located at # 130 Bnk at # 7-6' Tail Piece			
		10HP Stator Located at # 137 Bnk in # 2 Entry			
		13HP Flyght Located in the FACE OF the Belt Entry on old north MAINS section			



No Dangerous conditions were found at time of Examination.

J. J. Miller

Weekly tests of grounding devices (diodes)

4-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

9-5-09 North Main Street from North to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Plant located at # 12 Bnk in # 4 Entry			
		9HP Plant located at # 17 Bnk in # 4 Entry			
		6HP station located at # 37 Bnk on old #1 section in right return			
		9HP SPS located at # 40 Bnk on old #1 section in right return			
		5HP SPS located at # 38 Bnk in # 5 Entry			
		5HP BSM located at # 40 Bnk in # 4 Entry			
		13HP Plant located at # 45-46 Bnk in # 4 Entry			
		5HP SPS located at # 53 Bnk in # 5 Entry			
		9HP Plant located at # 74 Bnk on old #1 section in right return			
		5HP Plant located at # 85 Bnk in # 5 Entry			
		8HP Plant located at # 109 Bnk in # 4 Entry			
		58HP Plant located at # 128 Bnk on Long Dale Street (Flooded)			
		10 HP station located at # 128 Bnk on Long Dale Street			
		5HP Plant located at # 130 Bnk in # 4 Entry			
		10 HP station located at # 137 Bnk in # 2 Entry			

No Dangerous conditions were found at time of examination.

4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Plant located in the face of old north main section in the belt entry

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

9-12-09

NORTH MAIN PUMPS FROM NORTH TO FACE

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at #12 BAK in #4 Entry			
		9 HP Flygt Located at #17 BAK in #4 Entry			
		6 HP Starvac Located at #37 BAK on old #1 section, in right return			
		9 HP SPS Located at #44 BAK on old #1 section in right return			
		5 HP SPS Located at #38 BAK in #5 Entry			
		5 HP STM Located at #40 BAK in #4 Entry			
		13 HP Flygt Located at #45-46 BAK in #4 Entry			
		5 HP SPS Located at #53 BAK in #5 Entry			
		Weekly tests of grounding devices (diodes)			
		9 HP Flygt Located at #74 BAK on old #1 section in right return			
		5 HP Flygt Located at #85 BAK in #5 Entry			
		5 HP Flygt Located at #105 BAK in #4 Entry			
		55 HP Flygt Located at #128 BAK at Glory Hole Sump			
		10 HP Starvac Located at #128 BAK on a long belt			
		5 HP Flygt Located at #130 BAK at #7-6' TAIL in #4 Entry			
		10 HP Starvac Located at #137 BAK in #2 Entry			
		13 HP Flygt Located at the FACE OF old north main section in the Belt Entry			

NO Dangerous Conditions were Found at Time of Examination and Under 4250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

9-25-09 North Mains Pumps From Mouth to Face

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP STANCON Located at # 37 BRK on old # 1 section in Right Return		No other Dangerous conditions were	
		9HP SPS Located at # 40 BRK on old # 1 section in Right Return		Found at time of	
		5HP SPS Located at # 38 BRK in # 5 Entry		Examination	
		5HP BSM Located at # 40 BRK in # 4 Entry			
		13HP Flygt Located at # 45-46 BRK in # 4 Entry (see bottom of page)			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flygt Located at # 74 BRK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BRK in # 5 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		5HP Flygt Located at # 128 BRK at Along Hole pump			
		10HP STANCON Located at # 128 BRK on Along Belt			
		5HP Flygt Located at # 130 BRK at # 7-6' 7 1/2" Pipe in # 4 Entry			
		10HP STANCON Located at # 137 BRK in # 2 Entry			

Not Under
4-25-0
9-25-09

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Flygt located in the Belt Entry on the Face of old North MHA section

(45-46 BRK Pump was Found to Have cable pulled out of starter Box. Cable was Re-Insulated and ReEntered in starter Box)

Not Under
4-25-0
9-25-09

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

10-3-09

North Main's Pumps From North to Five

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BAK in # 4 Entry			
		9HP Flygt Located at # 17 BAK in # 4 Entry			
		6HP Stancer Located at # 37 BAK on old # 1 section in Right Return			
		9HP SPS Located at # 40 BAK on old # 1 section in Right Return			
		5HP SPS Located at # 38 BAK in # 5 Entry			
		5HP BSA Located at # 40 BAK in # 4 Entry			
		13HP Flygt Located at # 45-46 BAK in # 4 Entry			
		5HP SPS Located at # 53 BAK in # 5 Entry			

No Dangerous Conditions
were found at time
of Examination

Paul Maslow
4-250
10-3-09

Weekly tests of grounding devices (diodes)

		9HP Flygt Located at # 74 BAK on old # 1 section in Right Return
		5HP Flygt Located at # 85 BAK in # 5 Entry
		5HP Flygt Located at # 105 BAK in # 4 Entry
		5HP Flygt Located at # 128 BAK at Wagon Hole sump
		10HP Stancer Located at # 128 BAK on Glory belt
		5HP Flygt Located at # 130 BAK at # 7 - 6' Tail piece in # 4 Entry
		10HP Stancer Located at # 137 BAK in # 2 Entry
		13HP Flygt Located in the belt Entry in the Face of old North main's section

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

10-10-09 North Main's Pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 BRT in # 4 Entry			
		9 HP Flygt Located at # 17 BRT in # 4 Entry			
		6 HP Stator Located at # 37 BRT on old #1 section in right return			
		9 HP SPS Located at # 40 BRT on old #1 section in right return			
		5 HP SPS Located at # 38 BRT in # 5 Entry			
		5 HP BSM Located at # 40 BRT in # 4 Entry			
		13 HP Flygt Located at # 45-46 BRT in # 4 Entry			
		5 HP SPS Located at # 53 BRT in # 5 Entry			
		9 HP Flygt Located at # 74 BRT on old #1 section in right return			
		5 HP Flygt Located at # 85 BRT in # 5 Entry			
		5 HP Flygt Located at # 105 BRT in # 4 Entry			
		5 HP Flygt Located at # 128 BRT at Glory Hole ramp			
		10 HP Stator Located at # 128 BRT on Glory Belt			
		5 HP Flygt Located at # 130 BRT at # 7-6' Tail Piece			
		10 HP Stator Located at # 137 BRT in # 2 Entry			

No dangerous conditions were found at time of examination

Paul Jackson
4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

13 HP Flygt Located at in Face of the Belt Entry or the old West mine's section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

10-17-09

North mine's Panels From mouth to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flygt Located at # 12 BAK in #4 Entry
- 9HP Flygt Located at # 17 BAK in #4 Entry
- 6HP Stator Located at # 37 BAK on old #1 section in Right return
- 9HP SPS Located at # 40 BAK on old #1 section in Right return
- 5HP SPS Located at # 39 BAK in #5 Entry
- 5HP BSM Located at # 40 BAK in #4 Entry
- 13HP Flygt Located at # 45-46 BAK in #4 Entry
- 5HP SPS Located at # 53 BAK in #5 Entry

No Dangerous conditions were found at TIME OF EXAMINATION

Weekly tests of grounding devices (diodes)

- 9HP Flygt + Located at # 74 BAK on old #1 section in Right return
- 5HP Flygt Located at # 85 BAK in #5 Entry
- 5HP Flygt Located at # 105 BAK in #5 Entry
- 75HP Flygt Located at # 125 BAK at Wagon Hole
- 10HP Stator Located at # 128 BAK on Wagon belt
- 5HP Flygt Located at # 130 BAK at # 7-6' TAIL piece
- 10HP Stator Located at # 137 BAK in #2 Entry
- 13HP Flygt Located at the face of old North mine's section located in the Belt Entry.

Handwritten
U-250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

10-24-09

North MAINS Panel From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 Bkt in # 4 Entry			
		9HP Flygt Located at # 17 Bkt in # 4 Entry			
		6HP Stancer Located at # 37 Bkt on old # 1 section in Right Return			
		9HP GRS Located at # 40 Bkt on old # 1 section in Right Return			
		5HP GRS Located at # 38 Bkt in # 5 Entry			
		5HP BSM Located at # 40 Bkt in # 4 Entry			
		13HP Flygt Located at # 45-46 Bkt in # 4 Entry			
		5HP GRS Located at # 3 Bkt in # 5 Entry			
		9HP Flygt Located at # 7 Bkt on old # 1 section in Right Return			
		5HP Flygt Located at # 35 Bkt in # 5 Entry			
		5HP Flygt Located at # 10 Bkt in # 4 Entry			
		58HP Flygt Located at # 128 Bkt at Along Hole Supp			
		10HP Stancer Located at # 128 Bkt on Along Hole Belt			
		5HP Flygt Located at # 130 Bkt at # 7-6 Tail in # 4 Entry			
		10HP Stancer Located at # 137 Bkt in # 2 Entry			

No Dangerous Conditions
 → were Found at
 Time of Examination
 and under
 4-250
 10-24-09

Examinations of low- medium-voltage power circuit breakers (monthly)

13HP Flygt Located in the Face of the Belt
 Entry of old North MAINS section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

10-29-09

NORTH MAINS PUMPS FROM NORTH TO FACE

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flygt Located at # 12 BRK in # 4 Entry
- 9HP Flygt Located at # 17 BRK in # 4 Entry
- 6HP Stinson Located at # 37 BRK on old #1 section in Right Return
- 9HP SPS Located at # 40 BRK on old #1 section in Right Return
- 5HP SPS Located at # 35 BRK in # 5 Entry
- 5HP BTM Located at # 40 BRK in # 4 Entry
- 13HP Flygt Located # 45-46 BRK in # 4 Entry
- 5HP SPS Located at # 53 BRK in # 5 Entry

No Dangerous Conditions
were Found at
Time of Examination
M. J. ... 4-250
10-29-09

Weekly tests of grounding devices (diodes)

- 9HP Flygt Located at # 74 BRK on old #1 section in Right Return
- 5HP Flygt Located at # 85 BRK in # 5 Entry
- 5HP Flygt Located at # 105 BRK in # 4 Entry
- 5.5HP Flygt Located at # 128 BRK at the Old Long Hole Pump
- 10HP Stinson Located at # 128 BRK on Old Long Hole belt
- 5HP Flygt Located at # 130 BRK at # 7-6' TAIL in # 4 Entry
- 10HP Stinson Located at # 137 BRK in # 2 Entry
- 13HP Flygt Located at the Belt Entry at Old North Mains section in the Face.

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

11-7-09 North Main Panel's From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 Bnk in # 4 Entry			
		9 HP Flygt Located at # 17 Bnk in # 4 Entry			
		6 HP Stator Located at # 27 Bnk on old # 1 section in Right Return			
		9 HP SPS Located at # 26 Bnk on old # 1 section in Right Return			
		5 HP SPS Located at # 38 Bnk in # 5 Entry			
		5 HP D5M Located at # 40 Bnk in # 4 Entry			
		13 HP Flygt Located at # 45-46 Bnk in # 4 Entry			
		5 HP SPS Located at # 53 Bnk in # 5 Entry			
		9 HP Flygt Located at # 74 Bnk on old # 1 section in Right Return			
		5 HP Flygt Located at # 85 Bnk in # 5 Entry			
		5 HP Flygt Located at # 105 Bnk in # 4 Entry			
		5.5 HP Flygt Located at # 128 Bnk at Along Hole			
		10 HP Stator Located at # 128 Bnk on old # 1 section (out of service)			
		5 HP Flygt Located at # 130 Bnk at # 7-6' Tail in # 4 Entry			
		10 HP Stator Located at # 137 Bnk in # 2 Entry			

no. Dangerous conditions were found at time of examination
 Pub. Under 4250

Examinations of low-medium-voltage power circuit breakers (monthly)

13 HP Flygt Located in the Belt Entry of old North Main's section.

To: Memo 33359

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

11-21-09

North Water Pumps From Mouth to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

9AP Plant Located at # 12 BAK in # 4 Entry
 9AP Plant Located at # 17 BAK in # 4 Entry
 6AP Stator Located at # 37 BAK on old # 1 section in Right Return
 9AP SPS Located at # 40 BAK on old # 1 section in Right Return
 5AP BSM Located at # 40 BAK in # 4 Entry
 5AP SPS Located at # 38 BAK in # 5 Entry
 13AP Plant Located at # 45-46 BAK in # 4 Entry
 5AP SPS Located at # 53 BAK in # 5 Entry

no dangerous
 conditions were
 found at time of
 examination

Weekly tests of grounding devices (diodes)

9AP Plant Located at # 74 BAK on old # 1 section in Right Return
 5AP Plant Located at # 85 BAK in # 5 Entry
 5AP Plant Located at # 105 BAK in # 4 Entry
 5AP Plant Located at # 128 BAK at Wagon Hove
 5AP Plant Located at # 130 BAK at # 7-6' Tail in # 4 Entry
 10AP SPS Located at # 137 BAK in # 2 Entry
 13AP Plant Located at the Face of North # 4 section
 located in the Belt Entry

Paul Miller
 4-250

Monthly examinations of methane monitors

T. Moore 33359

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

11-28-09

North MAIR's Pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BRK in # 4 Entry			
		9HP Flygt Located at # 17 BRK in # 4 Entry			
		6HP Starcon Located at # 37 BRK on old # 1 section in right Return			
		9HP SPS Located at # 40 BRK on old # 1 section in right Return			
		5HP SPS Located at # 38 BRK in # 5 Entry			
		5HP SPS Located at # 40 BRK in # 4 Entry			
		13HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5HP SPS Located at # 53 BRK in # 5 Entry			
		9HP Flygt Located at # 74 BRK on old # 1 section in right return			
		5HP Flygt Located at # 85 BRK in # 5 Entry			
		5HP Flygt Located at # 105 BRK in # 4 Entry			
		58HP Flygt Located at # 128 BRK at Glory Hole Sump.			
		5HP Flygt Located at # 130 BRK at # 7-6 TAIL in # 4 Entry			
		10HP Starcon Located at # 137 BRK in # 2 Entry			
		13HP Flygt Located at the Face of the belt Entry			

NO Dangerous conditions were found at Time of Examination. Not applicable

4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

OF OLD North MAIR's section

T. Moore 33359

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

12-4-09

north MAINS Panels From Mouth to Face

Date Location Equipment examined and/or tested Dangerous conditions Action taken Examiner

- 9HP Flygt Located at #12 brk in #4 Entry
- 9HP Flygt Located at #17 brk in #4 Entry
- 6HP Stator Located at #37 brk on old #1 section in Right return
- 9HP GRS Located at #40 brk on old #1 section in Right return
- 5HP ~~GRS~~ GRS Located at #38 brk in #5 Entry
- 5HP '65M Located at #40 brk in #4 Entry
- 13HP Flygt Located at #45-46 brk in #4 Entry
- 5HP GRS Located at #53 brk in #5 Entry

No dangerous conditions were found at time of Examination.

Weekly tests of grounding devices (diodes)

Not needed
4-250

- 9HP Flygt Located at #74 brk on old #1 section in Right return
- 5HP Flygt Located at #95 brk in #5 Entry
- 5HP Flygt Located at #105 brk in #4 Entry
- 58HP Flygt Located at #128 brk at Wagon Hole ramp
- 5HP Flygt Located at #130 brk at #7-6 Tail
- 10HP Stator Located at #137 brk in #2 Entry
- 13HP Flygt Located in the best Entry of the Face of old north MAINS section

Monthly examinations of methane monitors

T. P. Name 33339

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

92-11-09 North Mines Pined's From Meats to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Plant located at # 12 bar in # 4 Entry			
		9HP Plant located at # 17 bar in # 4 Entry			
		6HP STACOR located at # 37 bar on old # 1 section in Right Return			
		9HP SP5 located at # 40 bar on old # 1 section in Right Return			
		5HP SP5 located at # 38 bar in # 5 Entry			
		5HP P5M located at # 40 bar in # 4 Entry			
		13HP Plant located between # 45-46 bar in # 4 Entry			
		5HP SP5 located at # 53 bar in # 5 Entry			
		9HP Plant located at # 74 bar on old # 1 section in Right Return			
		5HP Plant located at # 95 bar in # 5 Entry			
		5HP Plant located at # 105 bar in # 4 Entry			
		5.5HP Plant located at # 128 bar at Long Hole 3 amp			
		5HP Plant located at # 130 bar at # 7-6 Tail in # 4 Entry			
		10HP STACOR located at # 137 bar in # 2 Entry			
		13HP Plant located in the belt Entry of			

NO Dangerous conditions were found at time of Examination
 and Miller
 4250

Examinations of low- medium-voltage power circuit breakers (monthly)

Old North Mines section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-29-09	North mains	#126 9 HP Flight	None found		
	North mains	#176 9 HP Flight	None found		
	North mains	#37 9 HP Stamped	None found		
	North mains	#40 9 HP	None found		
	North mains	#38 5 HP	None found		
	North mains	#45 13 HP	None found		
	North mains	#53 5 HP	None found		
	North mains	#74 9 HP	None found		

Weekly tests of grounding devices (diodes)

North mains	#85 5 HP	None found		
North mains	#105 5 HP	None found		
North mains	#128 5 HP	None found		
North mains	#130 5 HP	None found		
North mains	#137 10 HP	None found		
North mains	13 HP	danger out	wrong size breaker in starter	Virgil Bowman 4-249

12-30-09 North mains 13 HP pump The proper breaker has been installed
Virgil Bowman
4-249

Monthly examinations of methane monitors

T. Wilson 33389

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

1-9-10 North Mills Pump's From month to PJC &

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flgnt Located at #12 Bk in #4 Entry			
		9HP Flgnt Located at #17 Bk in #4 Entry			
		6HP Strcon Located at #37 Bk on old #1 section in Right Entry			
		9HP SPS Located at #40 Bk on old #1 section in Right Entry			
		5HP SPS Located at #38 Bk in #5 Entry			
		5HP BSM Located at #40 Bk in #4 Entry			
		13HP Flgnt Located at #45-46 Bk in #4 Entry			
		5HP SPS Located at #53 Bk in #5 Entry			
		9HP Flgnt Located at #74 Bk on old #1 section in Right Entry			
		5HP Flgnt Located at #55 Bk in #5 Entry			
		5HP Flgnt Located at #105 Bk in #4 Entry			
		5HP Flgnt Located at #128 Bk at Wry Hole			
		5HP Flgnt Located at #130 Bk at #7-6 TAIL			
		10HP Strcon Located at #137 Bk in #2 Entry			
		13HP Flgnt Located in the best Entry of old North Mills section			

No Dangerous Conditions
were found at time
of Examination.

WJL
4-25-0

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

1-16-10 North Mines Pumps From Mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9AP Flygt Located at # 12 BTK in # 4 Entry			
		9AP Flygt Located at # 17 BTK in # 4 Entry			
		6AP Staircase Located at # 37 BTK on old # 1 section in Right Return			
		9AP SPS Located at # 40 BTK on old # 1 section in Right Return			
		5AP SPS Located at # 38 BTK in # 5 Entry			
		5AP BSM Located at # 40 BTK in # 4 Entry			
		13AP Flygt Located at # 45-46 BTK in # 4 Entry			
		5AP SPS Located at # 53 BTK in # 5 Entry			
		Weekly tests of grounding devices (diodes)			
		9AP Flygt Located at # 74 BTK on old # 1 section in Right Return			
		5AP Flygt Located at # 85 BTK in # 5 Entry			
		5AP Flygt Located at # 105 BTK in # 4 Entry			
		5AP Flygt Located at # 128 BTK at 6' long hole			
		5AP Flygt Located at # 130 BTK at # 7-6' TAIL			
		10AP Staircase Located at # 137 BTK in # 2 Entry			
		13AP Flygt Located at the Face of old North mine's section in the Belt Entry			

No Dangerous Conditions
were Found at Time
of Examination
not under
4250

Monthly examinations of methane monitors

T. Moore 33389

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-23-10	N OAH	MAIN'S PUMPS	FROM MOUTH TO FACE		
		9 HP Flygt Located at # 12 Bnk in # 4 Entry			
		9 HP Flygt Located at # 17 Bnk in # 4 Entry			
		6 HP Stator Located at # 37 Bnk on old # 1 section in Right Entry			
		9 HP SPS Located at # 40 Bnk on old # 1 section in Right Entry			
		5 HP SPS Located at # 38 Bnk in # 5 Entry			
		5 HP BSM Located at # 40 Bnk in # 4 Entry			
		13 HP Flygt Located at # 45-46 Bnk in # 4 Entry			
		5 HP SPS Located at # 53 Bnk in # 5 Entry			
		9 HP Flygt Located at # 74 Bnk on old # 1 section in Right Entry			
		5 HP Flygt Located at # 95 Bnk in # 5 Entry			
		5 HP Flygt Located at # 105 Bnk in # 5 Entry			
		5 HP Flygt Located at # 106 Bnk in # 4 Entry			
		5 HP Flygt Located at # 128 Bnk at along hole			
		5 HP Flygt Located at # 130 Bnk at # 7-6' Tail in # 4 Entry			
		10 HP Stator Located at # 137 Bnk in # 2 Entry			

No Dangerous conditions were found at time of Examination
 J. A. F. Examiner
 Neil Walker
 4-250

Examinations of low- medium-voltage power circuit breakers (monthly)

13 HP Flygt Located in the West Entry of old West MAIN'S section.

EXAMINATION OF ELECTRICAL EQUIPMENT

1-30-10 North Mains Pump's From Mouth to Face

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9 HP Flygt Located at # 12 BRK in # 4 Entry			
		9 HP Flygt Located at # 17 BRK in # 4 Entry			
		6 HP STARCOR Located at # 37 BRK on old # 1 section in Right Entry			
		9 HP SPS Located at # 40 BRK on old # 1 section in Right Entry			
		5 HP SPS Located at # 38 BRK in # 5 Entry			
		5 HP BDM Located at # 40 BRK in # 4 Entry			
		13 HP Flygt Located at # 45-46 BRK in # 4 Entry			
		5 HP SPS Located at # 53 BRK in # 5 Entry			

No Dangerous Conditions
Were Found at Time
of Examination

Paul Niska
4-25-0

Weekly tests of grounding devices (diodes)

		9 HP Flygt Located at # 74 BRK in Right Entry of old # 1 section
		5 HP Flygt Located at # 85 BRK in # 5 Entry
		5 HP Flygt Located at # 105 BRK in # 4 Entry
		5 HP Flygt Located at # 128 BRK at along Hole
		5 HP Flygt Located at # 130 BRK at # 7-6' trail
		10 HP STARCOR Located at # 137 BRK in # 2 Entry
		13 HP Flygt located in the Belt Entry of old North Mains section.

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

2-6-10 North main's Panels From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 BAK in # 4 Entry			
		9HP Flygt Located at # 17 BAK in # 4 Entry			
		6HP Stator Located at # 37 BAK on old # 1 section in Right Entry			
		9HP SPS Located at # 40 BAK on old # 1 section in Right Entry			
		5HP SPS Located at # 38 BAK in # 5 Entry			
		5HP BTM Located at # 40 BAK in # 4 Entry		no Dangerous conditions were found at time of examination.	
		13HP Flygt Located at # 45-46 BAK in # 4 Entry			
		5HP SPS Located at # 53 BAK in # 5 Entry			
		9HP Flygt Located at # 74 BAK on old # 1 section in Right Return			
		5HP Flygt Located at # 85 BAK in # 5 Entry			
		5HP Flygt Located at # 105 BAK in # 4 Entry			
		58HP Flygt Located at # 125 BAK at along Pole second			
		5HP Flygt Located at # 130 BAK at # 7-6' TAIL			
		10HP Stator Located at # 137 BAK in # 2 Entry			
		13HP Flygt Located at the Face of the Belt Entry on old port main's section.			

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

2-13-10 North MAIR'S Pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP Flygt	Located at #12	BREAK in #4 Entry			
9HP Flygt	Located at #17	BREAK in #4 Entry			
6HP Strega	Located at #37	BANK on old #1 section in Right Returns			
9HP SP5	Located at #40	BANK on old #1 section in Right Entry			
5HP SP5	Located at #38	BANK in #5 Entry			
5HP PSM	Located in #4 Entry	at #40 bank (out of service)			
3HP Flygt	Located at #45-46	BANK in #4 Entry			
5HP SP5	Located at #53	BANK in #5 Entry			
Weekly tests of grounding devices (diodes)					
9HP Flygt	Located at #74	BANK on old #1 section in Right Returns			
5HP Flygt	Located at #85	BANK in #5 Entry			
5HP Flygt	Located at #105	BANK in #4 Entry			
55HP Flygt	Located at #128	BANK at Wagon Hole 5400P			
5HP Flygt	Located at #130	BANK at #7-6 Tail Piece in #4 Entry			
NO HP Strega	Located at #137	BANK in #2 Entry			
13HP Flygt	Located in the Belt Entry	OF the Face of old North MAIR'S section.			

No Dangerous conditions were found at Time of Examination
 4-250

2-13-10

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

2-20-10 North Mine's Pumps From mouth to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt Located at # 12 Bnk in # 4 Entry			
		9HP Flygt Located at # 17 Bnk in # 4 Entry			
		6HP Stancor Located at # 31 Bnk on old # 1 section in Right Entry			
		9HP SPS Located at # 40 Bnk on old # 1 section in Right Entry			
		5HP SPS Located at # 38 Bnk in # 5 Entry			
		5HP B3M Located at # 40 Bnk in # 4 Entry (out of service)			
		13HP Flygt Located at # 45-46 Bnk in # 4 Entry			
		5HP SPS Located at # 53 Bnk in # 5 Entry			
		9HP Flygt Located at # 74 Bnk on old # 1 section in Right Entry			
		5HP Flygt Located at # 85 Bnk in # 5 Entry			
		5HP Flygt Located at # 105 Bnk in # 4 Entry			
		5.5HP Flygt Located at # 128 Bnk at Glory Hole sum			
(2)		13HP Flygt Located at the 130 130 Bnk # 76' TA's Piece where Mother Drive is being set (Need Rock Plug at Pump.)			

No Dangerous Condition was Found at time of Examination
 that didn't
 U-250

Examinations of low- medium-voltage power circuit breakers (monthly)

10 HP Stancor Located at # 137 Bnk in # 2 Entry
 13 HP Flygt Located at the Face of old North Mine's section in the Best Entry

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-26-10	North	North	North	North	North
		9HP Flgnt Located at #12 BAK in #4 Entry			
		9HP Flgnt Located at #17 BAK in #4 Entry			
		6HP Stancer Located at #37 BAK on old #1 section in Right Entry			
		9HP 51% Located at #40 BAK on old #1 section in Right Entry			
		5HP SP5 Located at #38 BAK in #5 Entry			
		5HP BSM Located at #40 BAK in #4 Entry (Coat of smoke)			
		13HP Flgnt Located at #45-46 BAK in #4 Entry			
		5HP 51% Located at #53 BAK in #5 Entry			
		Weekly tests of grounding devices (diodes)			
		9HP Flgnt Located at #74 BAK on old #1 section in Right Entry			
		5HP Flgnt Located at #85 BAK in #5 Entry			
		5HP Flgnt Located at #105 BAK in #4 Entry			
		55HP Flgnt Located at #125 BAK at Glang Hole			
		83HP Flgnt Located at #130 BAK at #7-6' Tail Piece			
		10 HP Stancer Located at #137 BAK in #2 Entry			
		8 HP Flgnt Located in the Belt Entry of			
		0.12 North Main's section in the Entry			

NO Dangerous conditions were found at time of Examination
 Subscribed
 4250

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

3-6-10 North Maines Panels from Month to Face

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9HP	Plant	Located at # 12 BAK in # 4 Entry			
9HP	Plant	Located at # 17 BAK in # 4 Entry			
6HP	Stator	Located at # 37 BAK on old # 1 section in Right Entry		No Dangerous	
9HP	SPS	Located at # 40 BAK on old # 1 section in Right Entry		A condition's was	
5HP	SPS	Located at # 38 BAK in # 5 Entry		Found at Time of Exam	
5HP	SPS	Located at # 40 BAK in # 4 Entry (out of service)		and visible	
13HP	Plant	Located at # 45-46 BAK in # 4 Entry			4-250
5HP	SPS	Located at # 53 BAK in # 5 Entry			
9HP	Plant	Located at # 74 BAK on old # 1 section in Right Return			
5HP	Plant	Located at # 85 BAK in # 5 Entry			
5HP	Plant	Located at # 105 BAK in # 4 Entry			
53HP	Plant	Located at # 120 BAK at along Hole Summit			
13HP	Plant	Located at # 130 BAK at # 7-6' Bend THL			
10HP	Stator	Located at # 37 BAK in # 2 Entry			
13HP	Plant	Located at the Face in the Belt Entry			

Examinations of low- medium-voltage power circuit breakers (monthly)

OF old North Maines Section

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

3-15-10

North Main Pumps From Mouth to FAC

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
		9HP Flygt located at # 12 BAK in # 4 Entry			
		9HP Flygt located at # 17 BAK in # 4 Entry			
		6HP Flygt located at # 37 BAK in Right Entry on old # 1 section			
		9HP SPS located at # 40 BAK on old # 1 section in Right Entry			
		5HP SPS located at # 38 BAK in # 5 Entry			
		5HP DSM located at # 40 BAK in # 4 Entry (out of service)			
		13HP Flygt located at # 45-46 BAK in # 4 Entry			
		5HP SPS located at # 53 BAK in # 5 Entry			
		Weekly tests of grounding devices (diodes)			
		9HP Flygt located at # 74 BAK on old # 1 section in Right Entry			
		5HP Flygt located at # 85 BAK in # 5 Entry			
		5HP Flygt located at # 105 BAK in # 4 Entry			
		5HP Flygt located at # 125 BAK at Glory Hole well			
		13HP Flygt located at # 130 BAK at # 7-6' Tail Piece			
		10HP Stand located at # 137 BAK in # 2 Entry			
		13HP Flygt located at the Best Entry of the File of Old North Main's section			
			NO Dangerous Conditions were found at Time of Examination		APR 15 1956

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)


Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-24-10	12 Bk	ok AT Time of Exam	None	Reported	J. Smith
	17 Bk	ok AT Time of Exam	None	Reported	J. Smith
	37 Bk	ok AT Time of Exam	None	Reported	J. Smith
	45 Bk	ok AT Time of Exam	None	Reported	J. Smith
	42 Bk	ok AT Time of Exam	None	Reported	J. Smith
	53 Bk	ok AT Time of Exam	None	Reported	J. Smith
	85 Bk	ok AT Time of Exam	None	Reported	J. Smith
	128 Bk	ok AT Time of Exam isolated pump	None	Report	J. Smith
Weekly tests of grounding devices (diodes)					
	130 Bk	ok AT Time of Exam	None	Reported	J. Smith
	137 Bk	ok AT Time of Exam	None	Reported	J. Smith
	North Mains Pump	ok AT Time of Exam	None	Reported	J. Smith

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-30-10	12 Bk	ok AT Time of Exam	None	Reported	
3-30-10	17 Bk	ok AT Time of Exam	None		
3-30-10	37 Bk	ok AT Time of Exam	None		
3-30-10	45 Bk	ok AT Time of Exam	None		
3-31-10	42 Bk	ok AT Time of check	None		
3-31-10	53 Bk	ok AT Time of check	None		
3-31-10	85 Bk	ok AT Time of check	None		
3-31-10	128 Bk	ok AT Time of check	None		
3-31-10	130 Bk	ok AT Time of Exam	None		
3-31-10	137 Bk	ok AT Time of Exam	None		
3-31-10	N main	ok AT Time of Exam	None		



 A. J. [Signature]

 3-31-10

Examinations of low- medium-voltage power circuit breakers (monthly)