

Bleeder

# PRESHIFT - ONSHIFT and DAILY REPORT

Full

Company Performance Coal

Mine W. B. B.

SECTION ~~#67~~ #672 Bleeder Area

LOCATION Naoma Raleigh W.V.  
Post Office County State

Form 6-1489  
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 8-25-09 20 Section or Area Examined 4 Section  
 Time of Examination: from 1:00 a.m. or p.m. to 2:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Steve Harsch Time 3:20 P.M.  
 Report received by Rick Foster  
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location

Violation or Hazardous Condition

Action Taken

1.	<u>Mining Section</u>		
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location

CFM

Location

CFM

<u>left L.O. X cut</u>	<u>20,202</u>
<u>right L.O. X cut</u>	<u>24,078</u>

Remarks: 20.8% O<sub>2</sub>, 0% ch<sub>4</sub>, 0% CO<sub>2</sub>, track, trackways, power cables, scrap chargin clear at time of exam.

Outby chargin OK at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Steve Harsch Freshift-Mine Examiner Certificate No. 1658A Assistant Foreman Certificate No. 1658A  
 Countersigned \_\_\_\_\_ Mine Manager—Mine Foreman  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/8 20 10 Section or Area Examined Bleeder  
 Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time      A.M.      P.M.  
 Report received by      (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brd to 131 brd ch<sup>4</sup>0.0%</u>	<u>Water in various places and in various entries</u>	<u>Pumpings</u>
2. <u>    </u>	<u>    </u>	<u>    </u>
3. <u>    </u>	<u>    </u>	<u>    </u>
4. <u>    </u>	<u>    </u>	<u>    </u>
5. <u>    </u>	<u>    </u>	<u>    </u>
6. <u>    </u>	<u>    </u>	<u>    </u>
7. <u>    </u>	<u>    </u>	<u>    </u>
8. <u>    </u>	<u>    </u>	<u>    </u>
9. <u>    </u>	<u>    </u>	<u>    </u>
10. <u>    </u>	<u>    </u>	<u>    </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>

Remarks: ch<sup>4</sup>0.0% co<sup>2</sup>0.0% o<sup>2</sup>20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1759-A Certificate No.       
 Assistant Foreman [Signature] 1759-A Certificate No.       
 Countersigned [Signature] 33759  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11/8 Section or Area Examined Bleeder  
Time of Examination: from 1200 a.m. or 3:00 p.m. to 3:00 a.m. or 3:00 p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time          A.M.          P.M.  
Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brt</u>	<u>ch<sup>4</sup> 0.0% O<sub>2</sub> 23" at Point of measure</u>	<u>Pumpins</u>
2. <u>100 brt #1 #2 #3</u>	<u>Water Down</u>	<u>none</u>
3. <u>#4</u>	<u>22" of water at Point of measure</u>	<u>pumpins</u>
4. <u>118 brt #4</u>	<u>24" of water at Point of measure</u>	<u>pumpins</u>
5. <u>122 brt #1 #2</u>	<u>water Down</u>	<u>none</u>
6. <u>#3</u>	<u>5" at Point of measure</u>	<u>pumpins</u>
7. <u>#4</u>	<u>27" w R Pump 4 pump 30"</u>	<u>pumpins</u>
8. <u>125 brt #4</u>	<u>37" at Point of measure</u>	<u>Pumpins</u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam  
Track, travel way clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By [Signature] Preshift-Mine Examiner Certificate No. 1259-D  
Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 3225-7  
Assistant Foreman  
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 119 2010 Section or Area Examined Bleeder  
 Time of Examination: from 8:00 a.m. or p.m. to 10:30 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk to 131 brk ch<sup>4</sup> 0.0%</u>	<u>Water in Various Places</u>	<u>Pumping</u>
2. <u>        </u>	<u>        </u>	<u>        </u>
3. <u>        </u>	<u>        </u>	<u>        </u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Dir movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam

Track travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1759-D Certificate No.  
 Preshift-Mine Examiner Assistant Foreman  
 Countersigned [Signature] 3339  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1-9 2010 Section or Area Examined Bleeder Area  
Time of Examination: from 1200 a.m. or 00 p.m. to 3:00 a.m. or 00 p.m.  
Was this report phoned to outside: Yes no  
By whom Brought out Time --- A.M. --- P.M.  
Report received by --- (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk to 88 brk ch<sup>4</sup>ado</u>	<u>24" of water at Point of measure</u>	<u>pumpins</u>
2. <u>100 brk #1 #2 #3</u>	<u>Water Down</u>	<u>none</u>
3. <u>#4</u>	<u>21" of water at Point of measure</u>	<u>pumpins</u>
4. <u>118 brk #4</u>	<u>23" of water at Point of measure</u>	<u>pumpins</u>
5. <u>122 brk #1 #2</u>	<u>water Down</u>	<u>None</u>
6. <u>#3</u>	<u>5" at Point of measure</u>	<u>pumpins</u>
7. <u>#4</u>	<u>R pump 25 1/2" L pump 29"</u>	<u>pumpins</u>
8. <u>125 brk #4</u>	<u>36 1/2" at Point of measure</u>	<u>pumpins</u>
9. <u>#2</u>	<u>water Down</u>	<u>none</u>
10. <u>---</u>	<u>---</u>	<u>---</u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>

Remarks: ch<sup>4</sup> 0.0% CO 0% O<sup>2</sup> 20.8% at time of exam

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.  
Signed By [Signature] Preshift-Mine Examiner Certificate No. 1759-A  
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33354  
Assistant Foreman Certificate No. \_\_\_\_\_  
Superintendent or Assistant \_\_\_\_\_

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant



Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11/11/20 Section or Area Examined Breeder  
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85 brk to 131 brk	at 0.0% water in various places	Pumping
2. 123 brk	ch <sup>4</sup> 0.05%	
3. <u>        </u>	<u>        </u>	<u>        </u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: Ch<sup>4</sup> 0.0% CO 0.0% O<sub>2</sub> 20.8% at time of exam.  
123 brk #3 entry ch<sup>4</sup> 0.05%  
Tract, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 17597D  
 Preshift Mine Examiner  
 Countersigned [Signature] Certificate No. 17597D  
 Mine Manager—Mine Foreman  
[Signature] Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1112 20<sup>th</sup> Section or Area Examined Bleeder Area  
 Time of Examination: from 9:00 a.m. or p.m. to 10:45 a.m. or p.m.  
 Was this report phoned to outside: Yes  No   
 By whom Brought Out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk to 131 brk ch<sup>4</sup> o<sub>2</sub> water in various places</u>		<u>Pumps</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam  
Tracks travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1759-A  
 Countersigned [Signature] Mine Manager—Mine Foreman Assistant Foreman Certificate No. 1759-B  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/12 20 10 Section or Area Examined Bleeder
Time of Examination from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding air measurements and water issues.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: 'Good Air Movement'.

Remarks: ch 0.090 CO 0.8 O2 20.8% at time of exam
122 # 3 brk 0.05% ch4

Tract, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 17524
Countersigned [Signature] Mine Manager-Mine Foreman Assistant Foreman Certificate No. 33359
Assistant Foreman Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1/13 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 8:30 a.m. or p.m. to 10:30 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Bright Time --- A.M. --- P.M.  
 Report received by --- (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk to 131 brk ch<sup>o</sup> 0.05% water in various places</u>		<u>Pumping</u>
2. <u>122 ch<sup>o</sup> 0.05%</u>		
3. _____		
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

Location	Air Measurements		Location	CFM
	CFM	CFM		
<u>Good Air movement</u>				
_____				
_____				
_____				
_____				
_____				
_____				
_____				
_____				
_____				

Remarks: ch<sup>o</sup> 0.090 co 0.8 0<sup>2</sup> 20.8% at time of exam.  
Powercenter, travelways, track clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1752-A  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 1752-A  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1113 Section or Area Examined Bleeder
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 8 rows of handwritten entries regarding water levels and pumping actions at various locations like 85-88 brd, 100 brd, etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: CH4 0.0% CO2 20.8% at time of exam.
122 brd CH4 0.05%
Track Travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman
Certificate No. 1259-A 26241

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11/4 2010 Section or Area Examined Bleeder
Time of Examination: from 9:00 a.m. or p.m. to 10:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85brt to 131brt, Water in Various Places, Pumps. Row 2: 122 brt ch%0.05%, Water in #3 and #4 entry, Pumps.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement, blank, blank, blank.

Remarks: ch%0.0% CO%0% O2 20.8% at time of exam.
122brt ch%0.05%
Track, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1755A
Countersigned [Signature] Mine Foreman Certificate No. 26041
Assistant Foreman

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_



Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/14 2010 Section or Area Examined Bleeder
Time of Examination: from 12:00 a.m. or 6:00 a.m. to 3:00 a.m. or 6:00 a.m.
Was this report phoned to outside Yes no
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding water levels and pumping actions at various points of measure.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: Ch 0.09% CO 0% O2 20.8% at time of exam.
Q2 brk # 3 entry ch 0.05%
Track, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1253A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 26241
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

\_\_\_\_\_  
 Assistant Mine Foreman-Mine Manager Certificate No. \_\_\_\_\_ Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1115 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 8:00 a.m. or p.m. to 10:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brk ch<sup>4</sup> 0.0%</u>	<u>Water in various places</u>	<u>Pumping</u>
2. <u>122 brk ch<sup>4</sup> 0.05%</u>		
3. <u>        </u>		
4. <u>        </u>		
5. <u>        </u>		
6. <u>        </u>		
7. <u>        </u>		
8. <u>        </u>		
9. <u>        </u>		
10. <u>        </u>		

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			
<u>        </u>			

Remarks: ch<sup>4</sup> 0.0% co 0% o<sup>2</sup> 20.8% at time of exam.  
ch<sup>4</sup> 0.05% at 122 brk #3 entry  
Track, travel way clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1255-12 Assistant Foreman [Signature] 1259-12  
 Countersigned [Signature] 55327 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination \_\_\_\_\_ 20\_\_\_\_ Section or Area Examined \_\_\_\_\_
Time of Examination: from \_\_\_\_\_ a.m. or p.m. to \_\_\_\_\_ a.m. or p.m.
Was this report phoned to outside: Yes \_\_\_\_\_ no \_\_\_\_\_
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M \_\_\_\_\_ P.M.
Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various locations like 85-88 brd, 100 brd #1 #2, #3, #4, 122 brd #1 #2, #3, #4, 125 brd.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: Good Air Movement.

Remarks: Ch 0.0% CO 0% O2 20.8% at time of exam.
122 brd #3 entry ch 40.05%
Track, travel ways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 17597
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/16/10 Section or Area Examined Bleeder Area
Time of Examination: from 8:00 a.m. or p.m. to 9:45 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 brk to 131 brk ch4 0.09 water in various places pumping. Row 2: 122 brk ch4 0.05%

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air movement

Remarks: ch4 0.09 co2 20.8% at time of exam.
122 brk #3 entry ch4 0.05%
Traced travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 1755-A
Countersigned To [Signature] Mine Manager - Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/16/09 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or (a.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various boreholes (85-88 brd, 100 brd #1-3, 118 brd #4, 122 brd #1-2, 125 brd #4) and their water levels or conditions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: CH4 0.9% to 0.9% or 20.8% in all entries but at 122 brd #3 entry CH4 0.05%
Track travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 139-D
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 3332
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11/18/2010 Section or Area Examined Bleeder Area
Time of Examination: from 7:00 a.m. or p.m. to 9:10 a.m. or p.m.
Was this report phoned to outside: Yes No
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 brk & 131 brk ch4 & water in various places, Pumping. Row 2: 122 brk ch4 0.05%

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement

Remarks: ch4 0.06 0.08 0.22 0.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1759-A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33329
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/18/81 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or 3:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries such as '85 to 88 brd', '19" of water at Point of measure', 'Pumping'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: Ch4 0.0% CO 0% O2 20.8% at time of exam

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1159-A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certified by \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1119 20 Section or Area Examined Bleeder Area
Time of Examination: from 9:00 a.m. or p.m. to 10:30 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 brk to 131 brk ch4.0% water in various places Pumping

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement

Remarks: ch4 0.0% CO 0% O2 20.8% at time of exam.
Track travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] 1759-A Certificate No. 33355
Countersigned [Signature] Mine Manager-Mine Foreman
Assistant Foreman [Signature] 1759-B Certificate No.
Superintendent or Assistant



Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11/19 2010 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding water levels and pumping actions in various bleeder areas.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains one handwritten entry: 'Good Air Movement'.

Remarks: Ch 0.0% CO 0% O2 20.8% at time of exam

Track, travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 15912 Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33389
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 5 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 5 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/20/20 Section or Area Examined Bleeder Area
Time of Examination: from 7:00 a.m. or p.m. to 9:30 a.m. or p.m.
Was this report phoned to outside Yes no
By whom Brought Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 brt - 131 brt, Water in Various Places, Pumping.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: CH4 0.0% CO2 0.208% at time of exam.

Tract, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1255-D
Countersigned T. Moore Mine Manager - Mine Foreman Certificate No. 38359
Assistant Foreman [Signature] Certificate No. 1255-D
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11/20 Section or Area Examined Bleeder
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding water levels and pumping actions at various locations.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: ch 0.08 CO 0.6 O2 20.8% at time of exam.

Track clear at time of exam.

86 brd on travelway needs sand tracks set (Loose Bolt)

76 brd on travelway needs sand track set (Loose Bolt)

Other parts of travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 1759-A
Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Certificate No. 5555
Assistant Foreman Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/21 2010 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten observations and actions.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: CH2O.0% CO2.0% O2 20.8% at Time of exam.

Traffic, travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1259-A
Countersigned T. Moore Mine Manager-Mine Foreman Certificate No. 33257
Assistant Foreman
Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/22/20 Section or Area Examined Bleeder
Time of Examination: from 12:00 a.m. or 6:00 p.m. to 3:00 a.m. or 6:00 p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for water levels and pumping actions at various locations like 85 brk to 88 brk, 100 brk #1, #2, #3, etc.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: CH4 0.0% CO2 0.2% 20.8% at time of exam

Track, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshfield Mine Examiner Certificate No. 17597
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 55559
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent of Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1/25 2010 Section or Area Examined Bleeder
Time of Examination: from 8:00 a.m. or p.m. to 10:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location

Violation or Hazardous Condition

Action Taken

- 1. 85 brt to 131 brt ch 0.0% Water in Various Places Pumps
2.
3.
4.
5.
6.
7.
8.
9.
10.

Air Measurements

Location

CFM

Location

CFM

Good Air Movement

Remarks: ch 4.0% co 0% o2 20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant

Use Indefinible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1/25 2010 Section or Area Examined Bleeder  
 Time of Examination: from 12:00 a.m. or PM to 3:00 a.m. or PM  
 Was this report phoned to outside: Yes no  
 By whom Brought Out Time AM P.M.  
 Report received by \_\_\_\_\_ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85-88 brk	ch <sup>4</sup> 0.09% of water at Point of measure	Pumping
2. 100 brk #1, #2, #3	no water at time of exam	none
3. #4	7" of water at Deepest Point	Pumping
4. 118 brk #4	29" of water at Point of measure	Pumping
5. 122 brk #1, #2	no water	none
6. #3	3" at Point of measure	Pumping
7. #4	R pump 25" L pump 30" of water	Pumping
8. 125 brk #4	36" of water at Point of measure	Pumping
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: ch<sup>4</sup> 0.0% CO<sub>2</sub> 0.208% at time of exam.

Track, travel ways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1397 Assistant Foreman \_\_\_\_\_ Certificate No. \_\_\_\_\_  
 Countersigned [Signature] Mine Manager—Mine Foreman \_\_\_\_\_  
 \_\_\_\_\_ Assistant Foreman  
 \_\_\_\_\_ Superintendent or Assistant

Use Indefinible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1126 20 10 Section or Area Examined Bleeder  
 Time of Examination: from 900 a.m. or p.m. to 1100 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought Out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location

Violation or Hazardous Condition

Action Taken

1. 85 brt to 131 brt ch<sup>4</sup> & water in various places Pumps
2.
3.
4.
5.
6.
7.
8.
9.
10.

Air Measurements

Location

CFM

Location

CFM

Location	CFM	Location	CFM
<u>Good Air Movement</u>			

Remarks: ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam.

Track, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 17557A Certificate No.           
 Shift-Mine Examiner Assistant Foreman  
 Countersigned [Signature] 83352 Certificate No. 17557A  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1126 2010 Section or Area Examined Bleeder
Time of Examination: from 12:00 a.m. or 6:00 a.m. to 3:00 a.m. or 6:00 a.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding water levels and pumping actions at various locations.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: ch 0.09% CO2 0.20.8% at time of exam
Track, trackway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 1789-A Assistant Foreman
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 20769 Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_  
\_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_  
\_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1/27 Section or Area Examined Bleeder Area  
 Time of Examination: from 12:00 a.m. or 3:00 p.m. to 3:00 a.m. or 6:00 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85-88 brd	Ch <sup>4</sup> O <sub>2</sub> 18" of water at Point of measure	Pumping
2. 100 brd #1, #2, #3	no water	none
3. #4	3" at Deepest Point	Pumping
4. 118 brd #4	24" at Point of measure	Pumping
5. 122 brd #1, #2, #3	no water	none
6. #3	3" of water at Point of measure	Pumping
7. #4	R pump 26" L Pump 29 1/2"	Pumping
8. 125 brd #4	35 1/2" of water at Point of measure	Pumping
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: Ch<sup>4</sup> 0.0% CO<sub>2</sub> 2.20% at time of exam.  
Track, travel ways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759A  
 Countersigned [Signature] Mine Manager—Mine Foreman  
[Signature] Assistant Foreman Certificate No. 5957  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 11/28 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 8:00 a.m. or p.m. to 10:30 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brt to B1 brt of water in various places</u>		<u>Pumps</u>
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: CH<sub>4</sub> 0.0% CO 0.0% O<sub>2</sub> 20.8% at time of exam.

Track travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1755-A  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 1755-A  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1/28 2010 Section or Area Examined Bleeder Area
Time of Examination: from 1200 a.m. or 00 p.m. to 300 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains 10 rows of handwritten entries regarding water levels and pumping actions at various bit locations.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: CH 0.0% CO 0% O2 20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1739-A Assistant Foreman
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant



Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_  
\_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_  
\_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 11/29/20 Section or Area Examined Bleeder Area
Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Braught JH Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 bkt to 131 bkt ch4.0% Water in Various Places Pumping

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement

Remarks: ch4.0% CO2 0.20.8% at time of exam.
Tract, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33757
Assistant Foreman
Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 1/29 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 12:00 a.m. or 3:00 p.m. to 3:00 a.m. or 3:00 p.m.  
 Was this report phoned to outside: Yes no no no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brk</u>	<u>Ch<sup>4</sup> 0.008% of water in Various Places</u>	<u>Pumpins</u>
2. <u>100 brk #1, #2, #3</u>	<u>no water</u>	<u>None</u>
3. <u>#4</u>	<u>3' of water at Deepest Point</u>	<u>Pumpins</u>
4. <u>118 brk #4</u>	<u>23' of water at Point of measure</u>	<u>Pumpins</u>
5. <u>122 brk #1, #2</u>	<u>No water</u>	<u>None</u>
6. <u>#3</u>	<u>5 1/2' of water at Point of measure</u>	<u>Pumpins</u>
7. <u>#4</u>	<u>R pump 25' L pump 30"</u>	<u>Pumpins</u>
8. <u>125 brk #4</u>	<u>36' of water at Point of measure</u>	<u>Pumpins</u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: Ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam

Track, travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 189-A Assistant Foreman Certificate No.           
 Countersigned [Signature] 3337 Mine Manager—Mine Foreman Certificate No.           
         Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1/30 2010 Section or Area Examined Bleeder Area
Time of Examination: from 8:00 a.m. or p.m. to 10:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought Out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 856rd to 131 brd Ch 1/8" water in various places Pumping

Air Measurements

CFM

Location

CFM

Table for Air Measurements with columns for Location and CFM. Entry: Good Air Movement

Remarks: Ch 1/8" CO 0% O2 20.8% at time of exam.
Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33359
Assistant Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

Violations and other Hazardous Conditions Observed and Reported  
Violation or Hazardous Condition

Location

Action taken

- 1. \_\_\_\_\_
- 2. \_\_\_\_\_
- 3. \_\_\_\_\_
- 4. \_\_\_\_\_
- 5. \_\_\_\_\_
- 6. \_\_\_\_\_
- 7. \_\_\_\_\_
- 8. \_\_\_\_\_

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 11/30 Section or Area Examined Bleeder Area  
 Time of Examination: from 1200 a.m. or 00 p.m. to 300 a.m. or 00 p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85-88 brk	CH <sub>4</sub> 0.07 1/2" of water at Point of measure	Pumping
2. 100 #1, #2, #3	no water	none
3. #4	5" of water at Point of measure	Pumping
4. 118 brk #4	23" of water at Point of measure	Pumping
5. 121 #1, #2	no water	none
6. #3	6" at Point of measure	Pumping
7. #4	L Pump 21" R pump 24"	Pumping
8. 125 brk	35 1/2" of water at Point of measure	Pumping
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: CH<sub>4</sub> 0.0% CO<sub>2</sub> 0.2 20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1755-19  
 Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 3330-9  
 Assistant Foreman           
 Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2/1/10 Section or Area Examined Bleeder Area
Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: 85 brd to #31 brd, Abol water in various places, Pumping.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: CH4 0.0% CO 0% O2 20.8% at time of exam.

Treat, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 1759-A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33351
Assistant Foreman [Signature] Assistant Foreman Certificate No. 1159-A
Superintendent or Assistant [Signature]

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2/11 Section or Area Examined Bleeder Area  
 Time of Examination: from 12:00 or P.M. to 3:00 or A.M.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85-88 brk	0'0" of water at Point of measure	Pumping
2. 100 brk #1 #2 #3 #4	NO water	none
3. 118 brk #4	23" of water at Point of measure	Pumping
4. 122 brk #1 #2	NO water	none
5. #3	0'0" of water at Point of measure	Pumping
6. #4	0'0" of water at Point of measure	Pumping
7. 125 brk #4	35 1/2" of water at Point of Measure	Pumping
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: Ch<sup>4</sup> 0.0% CO 0.9% O<sub>2</sub> 20.8% at time of exam  
Ch<sup>4</sup> 0.05% at 122 brk #3 entry at time of exam  
Track, travel way clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Assistant Foreman Certificate No. 1759-A  
 Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33357  
         Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 2/2/10 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought Out Time      A.M.      P.M.  
 Report received by      (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brk to 131 brk ch<sup>o</sup> of water</u>	<u>in various places</u>	<u>Pumping</u>
2. <u>    </u>	<u>    </u>	<u>    </u>
3. <u>    </u>	<u>    </u>	<u>    </u>
4. <u>    </u>	<u>    </u>	<u>    </u>
5. <u>    </u>	<u>    </u>	<u>    </u>
6. <u>    </u>	<u>    </u>	<u>    </u>
7. <u>    </u>	<u>    </u>	<u>    </u>
8. <u>    </u>	<u>    </u>	<u>    </u>
9. <u>    </u>	<u>    </u>	<u>    </u>
10. <u>    </u>	<u>    </u>	<u>    </u>

#### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>
<u>    </u>	<u>    </u>	<u>    </u>	<u>    </u>

Remarks: ch<sup>o</sup> 0.0% O<sub>2</sub> 20.8% CO 0% at time of exam

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 139-D Assistant Foreman [Signature] 1769-D  
Preshift Mine Examiner Certificate No. Assistant Foreman Certificate No.  
 Countersigned [Signature] 33359  
Mine Manager—Mine Foreman Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2/2 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 12:00 a.m. or 3:00 p.m. to 3:00 a.m. or 3:00 p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

## Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brk</u>	<u>CH<sup>4</sup> 0.07% at point of measure</u>	<u>Pumping</u>
2. <u>100 brk #1-#4</u>	<u>no water</u>	<u>none</u>
3. <u>118 brk #4</u>	<u>22 1/2" of water at point of measure</u>	<u>Pumping</u>
4. <u>122 brk #1, #2</u>	<u>no water</u>	<u>None</u>
5. <u>#3</u>	<u>5" at point of measure</u>	<u>Pumping</u>
6. <u>#4</u>	<u>R pump 24" L Pump 21"</u>	<u>Pumping</u>
7. <u>125 brk #4</u>	<u>35" of water at point of measure</u>	<u>Pumping</u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

## Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: CH<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam

Track, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 125914 Assistant Foreman  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33719  
 Assistant Foreman  
 Superintendent or Assistant



Use Indefinible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible  
Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 213 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

## Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 brd to 131 brd <sup>ch<sup>y</sup></sup></u>	<u>0.0% water in various places</u>	
2. <u>        </u>	<u>        </u>	<u>        </u>
3. <u>        </u>	<u>        </u>	<u>        </u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

## Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>			
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: ch<sup>y</sup> 0.0% CO<sub>2</sub> 0.2% O<sub>2</sub> 20.8% at time of exam.

Track, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 175977  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33339  
[Signature] Assistant Foreman  
         Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Use Indelible  
Pencil or Ink

### PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 213 20 10 Section or Area Examined Bleeder Area  
 Time of Examination: from 2:00 a.m. or p.m. to 3:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time --- A.M. --- P.M.  
 Report received by --- (Signed)

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85-88 brk	Ch <sup>4</sup> 0.0% / 6" of water at Point of measure	Pumping
2. 100 brk #1, 2, 3, 4	NO water	None
3. 118 brk #4	22" at Point of measure	pumping
4. 122 brk #1, #2	NO water	None
5. #3	3" of water at Point of measure	Pumping
6. #4	R pump 24" L pump 29"	Pumping
7. 125 brk	35" of water at Point of measure	Pumping
8. -----	-----	-----
9. -----	-----	-----
10. -----	-----	-----

#### Air Measurements

Location	CFM	Location	CFM
Good Air Movement	---	---	---
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----

Remarks: Ch<sup>4</sup> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam  
 Tract, travelways clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759A Assistant Foreman  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 33329  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2/4 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 7:00 a.m. or p.m. to 10:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time --- A.M. --- P.M.  
 Report received by --- (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85 brt to B1 brt	CH <sub>4</sub> 0.0% Water in Various Places	Pumpings
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----
9. -----	-----	-----
10. -----	-----	-----

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	---	---	---
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----
-----	-----	-----	-----

Remarks: CH<sub>4</sub> 0.0% CO 0% O<sub>2</sub> 20.8% at time of exam.  
Treat travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1755-10  
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 1759-H  
[Signature] Assistant Foreman  
[Signature] Superintendent or Assistant

Use Indelible  
Pencil or Ink

# DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2/4 20 10 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various bleeder areas and water measurements.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: Ch 0.09% CO2 20.8% at time of exam.
Tract, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift-Mine Examiner Certificate No. 17894
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33359
Assistant Foreman
Superintendent or Assistant



Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine \_\_\_\_\_ Certificate No. \_\_\_\_\_ Mine Foreman-Mine Manager \_\_\_\_\_ Certificate No. \_\_\_\_\_ Superintendent or Assistant \_\_\_\_\_

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination: 215 Section or Area Examined: Bleeder Area  
 20. 10  
 Time of Examination: from 7:00 a.m. or p.m. to 12:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  No   
 By whom: Brought Out Time          A.M.          P.M.  
 Report received by          (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 to 131</u>	<u>but ch<sup>4</sup> 0.0% water in various places</u>	<u>Pumping</u>
2. <u>        </u>	<u>        </u>	<u>        </u>
3. <u>        </u>	<u>        </u>	<u>        </u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: Ch<sup>4</sup> 0.0% CO 0% O<sup>2</sup> 20.8% at time of exam.  
Track travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1759-A  
 Preshift-Mine Examiner  
 Countersigned [Signature] Certificate No. 1759-A  
 Mine Manager—Mine Foreman  
 Assistant Foreman

Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 215 Section or Area Examined Bleeder Area  
 Time of Examination: from 1200 a.m. or 10 p.m. to 215 a.m. or 0 p.m.  
 Was this report phoned to outside: Yes Brought out no OUT Time          A.M.          P.M.  
 By whom           
 Report received by          (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85-88 brk</u>	<u>13 1/2" of water at Point of measure</u>	<u>Pumping</u>
2. <u>100 brk #1, #2, #3, #4</u>	<u>NO water</u>	<u>None</u>
3. <u>118 brk</u>	<u>22 1/2" of water at Point of measure</u>	<u>Pumping</u>
4. <u>122 brk #1, #2</u>	<u>NO water</u>	<u>None</u>
5. <u>#3</u>	<u>3" of water at Point of measure</u>	<u>Pumping</u>
6. <u>#4</u>	<u>R pump 24" L Pump 29"</u>	<u>Pumping</u>
7. <u>125 brk</u>	<u>35 1/2" of water at Point of measure</u>	<u>Pumping</u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: OH 0.09% CO 0% O<sub>2</sub> 20.8% at time of exam.

Track, travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1759 A  
 Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 3339  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2/6/10 Section or Area Examined Bleeder Area  
 Time of Examination: from 8:00 a.m. or p.m. to 10:00 a.m. or p.m.  
 Was this report phoned to outside: Yes no  
 By whom Brought out Time          A.M.          P.M.  
 Report received by          (Signed)

## Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. 85 brk to 131 brk	Water in various places	Pumping
2. <del>85</del> 122 brk #3	ch <sup>4</sup> 0.05%	
3. 100 brk #4	ch <sup>4</sup> 0.10%	
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

## Air Measurements

Location	CFM	Location	CFM
Good Air Movement			
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: ch<sup>4</sup> 0.09% co<sub>2</sub> 0% o<sub>2</sub> 20.8% at time of exam  
 ch<sup>4</sup> at 100 brk #4 entry is 0.05%  
 122 brk at #3 entry is 0.10% ch<sup>4</sup>  
 Tract travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1758-A  
 Preshift-Mine Examiner  
 Countersigned [Signature] Certificate No. 1759-A  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

### DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

#### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

#### Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

#### Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2/6 20 10 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or p.m. to 2:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for various boreholes (85, 100, 118, 122, 125) and their water levels and actions taken (Pumping, None).

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: Good Air Movement.

Remarks: CH4 0.0% CO 0% O2 20.8% at time of exam
100 bdr #4 entry CH4 0.10% 122 bdr #3 entry is CH4 0.05%
Treat travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1969A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 33389
Assistant Foreman
Superintendent or Assistant



Use Indefilble  
Pencil or Ink

**DAILY AND ONSHIFT REPORT**  
**MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant
----------------	-----------------	---------------------------	-----------------	-----------------------------

Use Indelible Pencil or Ink

# PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 218 2010 Section or Area Examined Bleeder Area  
 Time of Examination: from 7:00 a.m. or p.m. to 9:00 a.m. or p.m.  
 Was this report phoned to outside: Yes  no   
 By whom Brought Out Time          A.M.          P.M.  
 Report received by          (Signed)

### Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>85 to 131 brk</u>	<u>Good Water in Various Places</u>	<u>Pumpings</u>
2. <u>        </u>	<u>        </u>	<u>        </u>
3. <u>        </u>	<u>        </u>	<u>        </u>
4. <u>        </u>	<u>        </u>	<u>        </u>
5. <u>        </u>	<u>        </u>	<u>        </u>
6. <u>        </u>	<u>        </u>	<u>        </u>
7. <u>        </u>	<u>        </u>	<u>        </u>
8. <u>        </u>	<u>        </u>	<u>        </u>
9. <u>        </u>	<u>        </u>	<u>        </u>
10. <u>        </u>	<u>        </u>	<u>        </u>

### Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>
<u>        </u>	<u>        </u>	<u>        </u>	<u>        </u>

Remarks: CH<sub>4</sub> 0% CO 0% O<sub>2</sub> 20.8% at time of exam

Track, travelway clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 1057-A Certificate No.  
 Preshift-Mine Examiner  
 Countersigned [Signature] 3335-9  
 Mine Manager—Mine Foreman  
 Assistant Foreman  
 Superintendent or Assistant

Use Indelible  
Pencil or Ink

**DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT**

Report shall be  
signed when made

Date \_\_\_\_\_ Shift \_\_\_\_\_ Area or Section \_\_\_\_\_

*Violations and other Hazardous Conditions Observed and Reported*

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

*Examinations for Methane in Working Places*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

*Examinations for Methane in Return Aircourses*

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_  
Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2/8/10 Section or Area Examined Bleeder Area
Time of Examination: from 12:00 a.m. or p.m. to 2:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Brought out Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for locations 85 to 125 brk and actions like Pumping, None.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry: Good Air Movement.

Remarks: CH4 0.0% CO 0% O2 20.8% at time of exam.
122 brk #9 ent 0.05% CH4
Tract, travelway clear at time of exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Preshift Mine Examiner Certificate No. 1789-A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 33329
Assistant Foreman
Superintendent or Assistant