

LBB Construction 52 to 62 BK PRESHIFT - ONSHIFT and DAILY REPORT STARTED 1-21-10

Company PERFORMANCE COAL

Mine UBB

SECTION LBB CONSTRUCTION

LOCATION NAOMA RALEIGH WV
Post Office County State

FINISHED 2-6-10

Budget No. 42-1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. Do not mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-21 20 10 Section or Area Examined LBB Construction
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	Work Area	0%	NONE OBSERVED	NONE
2.	CHARGER	0%	NONE OBSERVED	NONE
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 0% CO 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor 37002
 Preshift-Mine Examiner Certificate No.
 Countersigned R.R. [unclear] 28734
 Mine Manager—Mine Foreman
[Signature] 29011
 Assistant Foreman
 Superintendent or Assistant

Use Indefinible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-21 2010 Section or Area Examined LBB Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: Work Area 07044, none observed, none. Row 2: Charge 07044, none observed, none.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks:

No. of defects 02 20.8 or 00020
Tracks & Tranchways clean at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 2973
[Signature] Assistant Foreman Certificate No. 29611
[Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-22 2010 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought outside Time A.M. P.M.
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area O2CH4</u>	<u>none observed</u>	<u>none</u>
2. <u>Changun O2CH4</u>	<u>none observed</u>	<u>none</u>
3. <u> </u>	<u> </u>	<u> </u>
4. <u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: NoCH4 Sect. O2 20.5 or 0026
Track + Tranchung clear of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 29611
 Countersigned [Signature] Mine Manager--Mine Foreman Certificate No. 2823
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-22 2010 Section or Area Examined LBB Construction
 Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	Work Area	0%	NONE observed	NONE
2.	CHARGER	0%	NONE observed	NONE
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄ 0% CO 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37002 Assistant Foreman Certificate No. _____
 Countersigned [Signature] 28252 Mine Manager—Mine Foreman Certificate No. _____
 _____ Assistant Foreman
 _____ Superintendent or Assistant

12/22/10 cd 1947-A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-22 20: Section or Area Examined KBB construction
 Time of Examination: from 8:30 a.m. or 11:30 a.m. or 0 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄ O ₂	Violation or Hazardous Condition	Action Taken
1.	work Area	0%	None observed	None
2.	Charge	0%	None observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄, 20.8% O₂, 0ppm C.O. Detected
Track, Travel ways, OK At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 1047A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 2073L
 _____ Assistant Foreman
 _____ Superintendent or Assistant

978

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date: 10/10/2010 Shift: 8:00-4:00 Area or Section: 10-85-1

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Contains handwritten entries for violations and actions.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Contains handwritten data for 20 methane examinations.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Contains handwritten data for 10 methane examinations in return aircourses.

Number of Bolts Tested: 10. Number of Bolts Torqued Above Range: 0. Below Range: 0.

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken.

Remarks (Statement as to General Conditions of Mine or Area of Mine):

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-23-10 Section or Area Examined LBB construction
Time of Examination: from 9:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: WORK AREA, none observed, none. Row 2: charger, none observed, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air movement.

Remarks: 0% CH4, 20.8% O2, 0ppm C.O. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 1947-A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 25734
Assistant Foreman
Superintendent or Assistant [Signature] 39199

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-23 2010 Section or Area Examined LBB construction
 Time of Examination: from 1200 a.m. or p.m. to 400 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Bright outside
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>work AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>CHARGER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 0% CO, 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Faylon 37002
 Preshift-Mine Examiner Certificate No.
 Countersigned Rich [Signature] 28231
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.
 Assistant Foreman

Mez cd 1947-A

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-23-10 Section or Area Examined LBB Construction

Time of Examination: from 8:30 a.m. or 0 p.m. to 11:30 a.m. or 0 p.m.

Was this report phoned to outside: Yes no

By whom _____ Time _____ A.M. _____ P.M.

Report received by Brought out

(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	WORK AREAS	0%	NONE OBSERVED	NONE
2.	CHARGER	0%	NONE OBSERVED	NONE
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH₄, 20.8% O₂, 0PPM C.O. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature]
Preshift-Mine Examiner

447-A
Certificate No.

Assistant Foreman

Certificate No.

Countersigned _____
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-24-10 2010 Section or Area Examined LBB construction
Time of Examination: from 8:00 a.m. or 6 p.m. to 11:30 a.m. or 6 p.m.
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows 1-10. Row 1: Work Area, 0%, None observed, None. Row 2: Charger, 0%, None observed, None. Row 3-10: VOID

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air movement. Row 2-10: VOID

Remarks:

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Mine Manager-Mine Foreman Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

FRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-24-10 20 Section or Area Examined LBB construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Blought out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air movement.

Remarks: 0% ch4, 20.8% O2, 0ppm C.O. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1947A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28782
Assistant Foreman

Laury Stewart 39199 Superintendent or Assistant George Curry 27429

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination: 1-24 2010 Section or Area Examined: LBB Construction
 Time of Examination: from 12 a.m. or PM to 3 a.m. or PM
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought Out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u> <u>0% CH₄</u>	<u>NONE observed</u>	<u>NONE</u>
2. <u>Charger</u> <u>0% CH₄</u>	<u>NONE observed</u>	<u>NONE</u>
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks:

0% CH₄, 0% CO₂, 20.8% O₂

Track, Travelway clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jacq Stewart 39199 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned Rich Baker 9872 Certificate No. _____
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____
M. Mes Cal. 1941-A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-24-20 Section or Area Examined LBB Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by brought out side (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: Work Area 070CH4, none observed, none. Row 2: Changers 070CH4, none observed, none.

Air Measurements

Location CFM Location CFM
Good air movement

Remarks: NOCH4 def. O2 20.80 CO2
Tracks Franchways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 29732
[Signature] Assistant Foreman Certificate No. 29611
[Signature] Superintendent or Assistant Certificate No. 27429

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-23 2010 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u> <u>Rochny</u>	<u>none observed</u>	<u>none</u>
2. <u>Chargers</u> <u>Rochny</u>	<u>none observed</u>	<u>none</u>
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
	<u>Good air movement</u>		
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Rochny Sect. 02 20:50 or 00:00
Track & Traveler way clean at exam.

This is to certify that: (a) This section of the mine was properly examined by me; (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Ray Peterson 2964 Assistant Foreman Certificate No. _____
Preshift-Mine Examiner
 Countersigned Rich Foster 2872 Mine Manager—Mine Foreman Certificate No. _____
Mine Manager—Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination ²⁵ 1-26-10 20: Section or Area Examined *L.B.B. construction*
 Time of Examination: from *12:00* a.m. or *3:00* p.m. to *3:00* a.m. or *3:00* p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.	<i>Work area clear at time of exam</i>	
2.		
3.	<i>20.8% O₂ O₂ & D₂CO</i>	
4.		
5.	<i>Track, truckpass power center, scoop chaper clear at time of exam.</i>	
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
<i>Good air movement</i>			

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By *George Curry* *27429* Assistant Foreman Certificate No.
 Countersigned *Paul Tate* *28232* Mine Manager - Mine Foreman Certificate No.
Paul Tate *29611* Assistant Foreman
 Superintendent or Assistant
Jan 26 1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-25 10 Section or Area Examined LBB Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed) brought outside

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: work area clear at time of exam none Rep.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: good air movement

Remarks:

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 2964 Assistant Foreman Certificate No.
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 2873
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No. _____

Mine Foreman-Mine Manager

Certificate No. _____

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-26 2010 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought outside
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>work area clear at time of exam - none</u>	<u>none</u>	<u>none</u>
2. <u>No CH4 det. 0% 20.80 CO2</u>		
3. <u>changes 0% CH4</u>	<u>none found</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: No CH4 det. 0% 20.80 CO2
Tracks & Trenchways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Myleton 29611
 Preshift-Mine Examiner Certificate No.
 Countersigned Reed Foster 28736
 Mine Manager—Mine Foreman Assistant Foreman Certificate No.
Myleton 29611
 Assistant Foreman
George C. ... 27429
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-26 2010 Section or Area Examined LBB Construction
Time of Examination: from 12:00 a.m. or 0 p.m. to 4:00 a.m. or 0 p.m.
Was this report phoned to outside: Yes no no 2
By whom Brought outside Time A.M. P.M.
Report received by Brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area 0/0CH₄</u>	<u>none observed</u>	<u>none</u>
2. <u>CHARGERS 0/0CH₄</u>	<u>seen at exam</u>	<u>none</u>
3. <u> </u>	<u> </u>	<u> </u>
4. <u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 0/0CH₄, 0/0CO, 20.8% O₂ tracks - travelways clear at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By George Carr 2729 Certificate No. 28732
 Countersigned Mike Pitts Mine Manager - Mine Foreman
Ray Johnson Assistant Foreman
 2904
 Assistant Foreman
 Certificate No. 1654A
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-26 2010 Section or Area Examined LPB Construction

Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes no

By whom _____ Time _____ A.M. _____ P.M.

Report received by Brought outside _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area 02044</u>	<u>none observed</u>	<u>none</u>
2. <u>charge 02044</u>	<u>none observed</u>	<u>none</u>
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	<u>good air movement</u>	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 02044 deck. 0% 20.50 CO2
Tracks & traweways clean at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1659A
 Countersigned [Signature] Mine Manager - Mine Foreman Assistant Foreman Certificate No. 2828
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-27 20 10 Section or Area Examined LBB Construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Report received by Thought outside (Signed) Time A.M. P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Row 1: Work Area O2, none observed, none. Row 2: Chaugun O2, none observed, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: good air movement.

Remarks: Rocky sect. O2 20.8 or 20.0% tracks & travelways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 28734
Assistant Foreman

Superintendent or Assistant George Curry 27429

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 1-27-10 Shift Day Area or Section L.B.B. Construction

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>300ft</u>	<u>breached 200ft</u>	<u>200ft</u>
4. <u>300ft</u>	<u>breached 200ft</u>	<u>200ft</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. <u>Belt entry</u>	<u>10:00</u>	<u>0%</u>	11. _____	_____	_____
2. <u>Truck entry</u>	<u>12:00</u>	<u>0%</u>	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-27 20 10 Section or Area Examined Longwall Construction
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes _____ no ✓
By whom _____ Time _____ A.M. _____ P.M.
Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>CHARGER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 0% CO 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37602 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned Bob Baker Mine Manager - Mine Foreman _____
Roy Peterson Assistant Foreman _____
 _____ 29611 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-27 20 19 Section or Area Examined LBB Construction
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by brought outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u> <u>O₂CH₄</u>	<u>none observed</u>	<u>none</u>
2. <u>Charger</u> <u>O₂CH₄</u>	<u>none observed</u>	<u>none</u>
3. <u>Plc</u> <u>O₂CH₄</u>	<u>none observed</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: O₂CH₄ Def. 06 20.50 CO₂
Tracks & haulways clean at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 29611 Assistant Foreman Certificate No. _____
 Countersigned [Signature] 28236 Mine Manager—Mine Foreman Certificate No. _____
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-28 10 Section or Area Examined LBB Construction
Time of Examination: from 3:00 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M P.M.
Report received by brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Work Area, Charge, and P/C, all with 'none observed' and 'none' action.

Air Measurements

Location CFM Location CFM

Good air movement

Remarks: Noisy dust. 8 1/2 20.5oz CO2
Tracks & Trunkways clear at exam.

This is to certify that: (a) this section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Certificate No. 28230
Assistant Foreman
Superintendent or Assistant: Jim Sawyer 32261, Larry Stewart 39199

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

<i>Location</i>	<i>Time</i>	<i>Methane Content</i>	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-28 Section or Area Examined LBS Construction
Time of Examination: from 1200 a.m. or p.m. to 300 a.m. or p.m.
Was this report phoned to outside: Yes no X
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for 'WORLD AREA', 'CHARGER', and 'POWER ROOM' with 'NONE OBSERVED' and 'NONE'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'GOOD AIR MOVEMENT'.

Remarks: 0% CH4, 20.8% O2, 0% CO
TRUCK & TRAVELWAYS CLEAR AT TOE.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1659-A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 28734
[Signature] Assistant Foreman
[Signature] Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-28 2010 Section or Area Examined LBB Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by Brought outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area O2 44</u>	<u>none observed</u>	<u>none</u>
2. <u>Charges O2</u>	<u>none observed</u>	<u>none</u>
3. <u>Lower Center O2</u>	<u>none observed</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Rock dust 0.20.802 CO2
Tracks + tranelways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Preshift Mine Examiner Assistant Foreman Certificate No. _____
Countersigned [Signature] Certificate No. 28736
Mine Manager - Mine Foreman Assistant Foreman Certificate No. _____
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-29 2010 Section or Area Examined LBB Construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Report received by (Signed) handit outside Time A.M P.M.

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Work Area, Chaper, and P/C, all with 'none observed' and 'none' action taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good air movement'.

Remarks: Noisy deck of 20,000 CO2 track & travelway & clear at exam.

This is to certify that (a) this section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
Signed By [Signature] Certificate No. 29011
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28736
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 1-29-10 Shift Day Area or Section L.B.L. construction

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Stuck</u>	<u>brake shoe</u>	<u>rest shoe</u>
4. <u>Stuck</u>	<u>brake shoe</u>	<u>rest shoe</u>
5. <u>Stuck</u>	<u>brake shoe</u>	<u>rest shoe</u>
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____
Mine Foreman-Mine Manager Rick Pata Certificate No. 28236
Superintendent or Assistant _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-29 2010 Section or Area Examined LBB Construction

Time of Examination: from 12:00 a.m. or 09 p.m. to 3:00 a.m. or 09 p.m.

Was this report phoned to outside: Yes no

By whom _____ Time _____ A.M. _____ P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>CHARGER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>POWER CENTER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 0% CO 20.8% O₂

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor Certificate No. 37002
 Countersigned Rich [Signature] Mine Manager—Mine Foreman Certificate No. 28734
[Signature] Assistant Foreman Certificate No. 16594
[Signature] Superintendent or Assistant

Mus Co. 1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-29-10 Section or Area Examined LBB construction

Time of Examination: from 8:30 a.m. or 11:30 a.m. or 2 p.m.

Was this report phoned to outside: Yes no

By whom Time A.M. P.M.

Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 4 columns: Location, CH4, Violation or Hazardous Condition, Action Taken. Rows include Work Area, Charger, Power center.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten note 'Good Air movement'.

Remarks: 0% ch4, 20.8% O2, 0 PPM C.O. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 1947A Assistant Foreman Certificate No.

Countersigned [Signature] Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 1-30-10 20. Section or Area Examined LBB Condu
 Time of Examination: from 3:00 a.m. or 6:00 p.m. to 6:00 a.m. or 3:00 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Location	Violations and other Hazardous Conditions Observed and Reported	Action Taken
1. <u>work Area</u>	<u>CH₄ 0%</u>	<u>None observed</u>
2. <u>Charger</u>	<u>0%</u>	<u>None observed</u>
3. <u>Power Center</u>	<u>0%</u>	<u>None observed</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Location	Air Measurements	Location	CFM
<u>Good air movement</u>	<u>CFM</u>	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 0% CO 20.8% O₂ detected
track & travelways safe at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947-A
 Countersigned [Signature] Mine Manager / Mine Foreman Certificate No. 2873L
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	<i>Location</i>	<i>Violation or Hazardous Condition</i>	<i>Action taken</i>
1.	_____	_____	_____
2.	_____	_____	_____
3.	_____	_____	_____
4.	_____	_____	_____
5.	_____	_____	_____
6.	_____	_____	_____
7.	_____	_____	_____
8.	_____	_____	_____

Examinations for Methane in Working Places

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	11.	_____	_____	_____
2.	_____	_____	_____	12.	_____	_____	_____
3.	_____	_____	_____	13.	_____	_____	_____
4.	_____	_____	_____	14.	_____	_____	_____
5.	_____	_____	_____	15.	_____	_____	_____
6.	_____	_____	_____	16.	_____	_____	_____
7.	_____	_____	_____	17.	_____	_____	_____
8.	_____	_____	_____	18.	_____	_____	_____
9.	_____	_____	_____	19.	_____	_____	_____
10.	_____	_____	_____	20.	_____	_____	_____

Examinations for Methane in Return Aircourses

	<i>Location</i>	<i>Time</i>	<i>Methane Content</i>		<i>Location</i>	<i>Time</i>	<i>Methane Content</i>
1.	_____	_____	_____	6.	_____	_____	_____
2.	_____	_____	_____	7.	_____	_____	_____
3.	_____	_____	_____	8.	_____	_____	_____
4.	_____	_____	_____	9.	_____	_____	_____
5.	_____	_____	_____	10.	_____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-30 2010 Section or Area Examined LBB Construction
Time of Examination: from 1200 a.m. or (P.M.) to 300 a.m. or (P.M.)
Was this report phoned to outside: Yes no
By whom _____ Time _____ A.M. _____ P.M.
Report received by Brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include work area, charger, power center, and empty rows 4-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Includes handwritten entry 'Good Air Movement'.

Remarks: 0% CH4, 0% CO, 20.8% O2, track, travelways safe at level

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor Preshift Mine Examiner Certificate No. 37002
Countersigned Rick Kula Mine Manager-Mine Foreman Certificate No. 28736
Assistant Foreman Superintendent or Assistant

Muesch 1947-A

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 1-30 2010 Section or Area Examined LBB Construction
 Time of Examination: from 8:30 a.m. or 6 p.m. to 11:30 a.m. or 6 p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken	
1.	Work Area	CH ₄ 0%	None observed	None
2.	Charger	0%	None observed	None
3.	Powercent	0%	None observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: Track, Travelways, clear At Time OF exam
0% CH₄, 20.8% O₂, 0.1ppm C.O. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By M. J. Cole Preshift Mine Examiner Certificate No. 1947-A
 Countersigned Rick Foster Mine Manager—Mine Foreman Certificate No. 2273
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-30 20 10 Section or Area Examined LBB Construction
Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by Brought Outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Work Area (0% CH4), Changer (0%), and Powercenter (0%), all with 'NONE observed' and 'NONE' action taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: Truck, Trackage clean at exam
0% CH4, 0% CO, 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947A
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28236

Assistant Foreman
Superintendent or Assistant
Joan Stewart 39199

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested _____ Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-30 2010 Section or Area Examined LBB Construction
Time of Examination: from 12 a.m. or 00 to 3 a.m. or 03
Was this report phoned to outside: Yes no
By whom Brought Out Time A.M P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries for Work Area, Changer, and Powercenter, all with 'None Observed' and 'None' action.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Contains handwritten entry 'Good Air Movement'.

Remarks: Track, Travelway clear at exam
0% CH4, 0% CO, 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Jay Stewart 39199 Certificate No. 28232
Countersigned Rick Foster 29611
Assistant Foreman Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested _____ Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Certificate No. Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 1-31 2010 Section or Area Examined LBB Construction
Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Work Area, Charger, Power Center, and empty rows 4-10.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1 contains 'Good AIR movement'.

Remarks: 0% CH4, 20.9% O2, dppm C.O. Detected
Track, Travelways, Clear AT exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947A
Countersigned [Signature] Mine Manager-Mine Foreman Certificate No. 28736
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2-1 2010 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no Time A.M. P.M.
 By whom Brought over
 Report received by Brought over (Signed)

	Location	Violations and other Hazardous Conditions Observed and Reported	Action Taken
1.	Work Area	CH ₄ 0% None observed	None
2.	Charger	0% None observed	None
3.	Powercenter	0% None observed	None
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Location	Air Measurements	Location	CFM
Good Air movement			

Remarks: 0% CH₄, 20.5% O₂, 0 PPM C.O. Detected
Track, Travelways, clear At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 2873L
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-1-2010 Section or Area Examined LBB Const
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by Brought outside (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Row 1: work AREA 0% ch4, none observed, none. Row 2: charger 0% ch4, none observed, none. Row 3: power center 0% ch4, none observed, none.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Row 1: Good Air Movement.

Remarks: 0% ch4, 0% CO, 20.8% O2, tracks, travelways clear at rear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By George Curran 27429 Certificate No. Assistant Foreman
Countersigned Mike Tala 23736 Certificate No. Mine Foreman
Assistant Foreman 29611
Superintendent or Assistant

JUN 26 1947-A

Use Indefible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-1 Section or Area Examined LBB Construction
 Time of Examination: from 8:30 a.m. or 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u>	<u>0%</u>	<u>none observed</u>	<u>None</u>
2. <u>Chargers</u>	<u>0%</u>	<u>none observed</u>	<u>None</u>
3. <u>e/c</u>	<u>0%</u>	<u>none observed</u>	<u>None</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0ppm C.O. Detected
Tracks, Travel ways, clear At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner
 Countersigned [Signature] Mine Manager—Mine Foreman
 Assistant Foreman _____
 Superintendent or Assistant _____

Certificate No. 6474
 Assistant Foreman _____
 Certificate No. _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-2 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. Work Area	0%	None observed	None
2. Charger	0%	None observed	None
3. Powercenter	0%	None observed	None
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0 PPM C.O.
Track, Travelways, clear AT TIME OF exam

[Signature] 29611
 This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.
 Signed By [Signature] Preshift Mine Examiner Certificate No. 1947A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 2873C
 _____ Assistant Foreman

Superintendent or Assistant
[Signature] 27429

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 2-27-10 Shift Day Area or Section L.B.B. Construction

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1.	<u>Set Timbers in belt head area</u>	
2.	<u>Rollal load ribs in belt head area</u>	
3.		
4.		
5.		
6.		
7.		
8.		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.			13.		
4.			14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Reck Foster 28734
Assistant Mine Certificate No.

Reck Foster 28734
Mine Foreman-Mine Manager Certificate No. Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-2 2010 Section or Area Examined UBB Construction
 Time of Examination: from 1200 a.m. or (p.m.) to 300 a.m. or (p.m.)
 Was this report phoned to outside: Yes no Time _____ A.M. _____ P.M.
 By whom _____
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>WORK AREA 0% CH₄</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>POWER CENTER 0% CH₄</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>CLIPPERS 0% CH₄</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>GOOD AIR MOVEMENT</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0% CO
TRACK AND FRAMES ARE CLEAR AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charley Taylor 37002 Assistant Foreman Certificate No. _____
 Countersigned Rich Baker Mine Manager—Mine Foreman Certificate No. 28736
Ray Peterson Assistant Foreman Certificate No. 29611 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-2 2010 Section or Area Examined LBB Construction
 Time of Examination: from 6:30 a.m. or 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out (Signed)

Location	Violations and other Hazardous Conditions Observed and Reported	Action Taken
1. <u>Work Area</u>	<u>CH₄ 0%</u> <u>None observed</u>	<u>None</u>
2. <u>Pic</u>	<u>0%</u> <u>None observed</u>	<u>None</u>
3. <u>Changers</u>	<u>0%</u> <u>None observed</u>	<u>None</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Location	CFM	Air Measurements	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Remarks: 0% CH₄, 20.8% O₂, 0 PPM CO₂ Detected
Track, Travelways, Clear At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner 2947A Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager—Mine Foreman 2536
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-3 2010 Section or Area Examined LBB CONSTRUCTION
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by brought outside
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>Work Area</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
2. <u>PC's</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
3. <u>charger</u>	<u>0%</u>	<u>none observed</u>	<u>none</u>
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: NoCH₄ det. 0% 20.8oz
Track + Tranchways clean at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Freshift Mine Examiner Certificate No. 19617A
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 23734
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2-3 2010 Section or Area Examined LBB Construction
Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.
Was this report phoned to outside: Yes no. 1
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows include Work Area, Power Center, and Charger, all with 'NONE OBSERVED' and 'NONE' action taken.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: Good Air Movement.

Remarks: 0% CH4 0% CO 20-8 % O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor 37002 Assistant Foreman Certificate No.
Countersigned Paul [Signature] 28232 Mine Manager - Mine Foreman
Assistant Foreman 29611 Superintendent or Assistant

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-3 2010 Section or Area Examined LBB Construction
 Time of Examination: from 8:30 a.m. or p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no Time A.M. P.M.
 By whom Brought out side
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area 0%</u>	<u>none observed</u>	<u>none</u>
2. <u>Power Center 0%</u>	<u>none observed</u>	<u>none</u>
3. <u>Charger 0%</u>	<u>none observed</u>	<u>none</u>
4. <u> </u>	<u> </u>	<u> </u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: No eye sect. 0% 20.00 CO2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Preshift Mine Examiner Certificate No. 22736
 Countersigned Rich Tolles Mine Manager—Mine Foreman Assistant Foreman Certificate No.
 Assistant Foreman Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-4 1960 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought outside
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area 0% CH4</u>	<u>none observed</u>	<u>none</u>
2. <u>Power Center 0%</u>	<u>none observed</u>	<u>none</u>
3. <u>Charger 0%</u>	<u>none observed</u>	<u>none</u>
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: No CH4 det. 0% 20.8oz CO2
Tracks & Tranehways clear at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 29611
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 28236
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 7-4 Section or Area Examined CBS Construction
 Time of Examination: from 12:30 a.m. or 2:00 p.m. to 2:00 a.m. or 2:00 p.m.
 Was this report phoned to outside: Yes no Time A.M. P.M.
 By whom
 Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Power central</u> <u>0% CH₄</u>	<u>None observed</u>	<u>None</u>
2. <u>Work Area</u> <u>0% CH₄</u>	<u>None observed</u>	<u>None</u>
3. <u>Chairs</u> <u>0% CH₄</u>	<u>None observed</u>	<u>None</u>
4. <u>D-Box</u> <u>0% CH₄</u>	<u>None observed</u>	<u>None</u>
5. <u> </u>	<u> </u>	<u> </u>
6. <u> </u>	<u> </u>	<u> </u>
7. <u> </u>	<u> </u>	<u> </u>
8. <u> </u>	<u> </u>	<u> </u>
9. <u> </u>	<u> </u>	<u> </u>
10. <u> </u>	<u> </u>	<u> </u>

Air Measurements

CFM

Location

CFM

Location	CFM	Location	CFM
<u>good AIR movement</u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

Remarks: 0% CH₄, 0% O₂, 20.8% O₂, 0% CO
Track and travel ways clean AT T.O.E.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor Certificate No. 37002 Assistant Foreman Certificate No.
 Countersigned Bob Foster Mine Manager - Mine Foreman Certificate No. 28734
 Assistant Foreman Certificate No. 29611 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-4 20 10 Section or Area Examined LBB Construction
 Time of Examination: from 8:30 a.m. or 11:00 p.m. to 11:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by brought outside
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. <u>Work Area O₂ CH₄</u>	<u>none observed</u>	<u>none</u>
2. <u>plc O₂ CH₄</u>	<u>none observed</u>	<u>none</u>
3. <u>changer O₂ CH₄</u>	<u>none observed</u>	<u>none</u>
4. <u>D. Box O₂ CH₄</u>	<u>none observed</u>	<u>none</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Rocky dirt. O₂ 20.5 or 20.0
Track & haulways clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 24611
 Countersigned [Signature] Mine Manager—Mine Foreman Certificate No. 28236
 Assistant Foreman _____ Certificate No. _____
 Superintendent or Assistant _____

Use Indefilble
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2-5 2010 Section or Area Examined LBB Construction
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes no
By whom
Report received by (Signed) brought out side

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Rows 1-10. Locations include Work Area, Plc, charger, D. Box. All violations listed as 'none observed' and actions as 'none'.

Air Measurements

Table with 4 columns: Location, CFM, Location, CFM. Entry: good air movement.

Remarks: No ch4 det. O2 20.5 on COO2. Tracks & roadways clean at exam.

This is to certify that: (a) this section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 29611
Countersigned [Signature] Mine Manager - Mine Foreman Certificate No. 28236
Assistant Foreman
Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 2-5-10 Shift Day Area or Section L.B.B. Cont.

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. <u>Cleaned up in work area.</u>	_____	_____
6. <u>Set ends</u>	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Rick Foster
Assistant Mine

2823
Certificate No.

Rick Foster
Mine Foreman-Mine Manager

2823
Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-5 2010 Section or Area Examined LBB CONSTRUCTION
 Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
 Was this report phoned to outside: Yes _____ no ✓ Time _____ A.M. _____ P.M.
 By whom _____
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	CH ₄	Violation or Hazardous Condition	Action Taken
1. <u>WORK AREA</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
2. <u>POWER CENTER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
3. <u>CHARGER</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
4. <u>D. BOX</u>	<u>0%</u>	<u>NONE OBSERVED</u>	<u>NONE</u>
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% CH₄ 0% CO 20.8%

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Harley Taylor Certificate No. 37002
 Preshift-Mine Examiner Assistant Foreman Certificate No.
 Countersigned Rich Carter Certificate No. 23732
 Mine Manager—Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

M.L. 1027 10474

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-5 2010 Section or Area Examined LBB construction
 Time of Examination: from 8:20 a.m. or 6 a.m. to 11:30 a.m. or 6 p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH ₄	Violation or Hazardous Condition	Action Taken
1.	work Area	0%	none observed	None
2.	Power Center	0%	none observed	None
3.	Charger	0%	none observed	None
4.	D-Box	0%	none observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch₄, 20.4% O₂, 0 ppm c.o. Detected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mary Cole Preshift-Mine Examiner Certificate No. 6947-A
 Countersigned Rick Jula Mine Manager—Mine Foreman Certificate No. 2822
 Assistant Foreman _____ Certificate No. _____
 Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date ----- Shift ----- Area or Section -----

Violations and other Hazardous Conditions Observed and Reported		
Location	Violation or Hazardous Condition	Action taken
1. -----	-----	-----
2. -----	-----	-----
3. -----	-----	-----
4. -----	-----	-----
5. -----	-----	-----
6. -----	-----	-----
7. -----	-----	-----
8. -----	-----	-----

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	11. -----	-----	-----
2. -----	-----	-----	12. -----	-----	-----
3. -----	-----	-----	13. -----	-----	-----
4. -----	-----	-----	14. -----	-----	-----
5. -----	-----	-----	15. -----	-----	-----
6. -----	-----	-----	16. -----	-----	-----
7. -----	-----	-----	17. -----	-----	-----
8. -----	-----	-----	18. -----	-----	-----
9. -----	-----	-----	19. -----	-----	-----
10. -----	-----	-----	20. -----	-----	-----

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. -----	-----	-----	6. -----	-----	-----
2. -----	-----	-----	7. -----	-----	-----
3. -----	-----	-----	8. -----	-----	-----
4. -----	-----	-----	9. -----	-----	-----
5. -----	-----	-----	10. -----	-----	-----

Number of Bolts Tested -----
Number of Bolts Torqued Above Range ----- Below Range -----

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken -----

Remarks (Statement as to General Conditions of Mine or Area of Mine) -----

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 2-6 Section or Area Examined LBB Construction
 Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
 Was this report phoned to outside: Yes _____ no ✓
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Chy	Violation or Hazardous Condition	Action Taken
1. Work Area	0%	none observed	none
2. Power center	0%	none observed	none
3. Charger	0%	none observed	none
4. D-Boxes	0%	none observed	none
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____

Air Measurements

Location	CFM	Location	CFM
Good Air Movement	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: 0% Chy, 20.8% O₂, 0ppm C.O Detected
Track, Travelways ok At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 1947-A
 Countersigned Rick Foster Mine Manager—Mine Foreman Certificate No. 2373
 Assistant Foreman _____ Certificate No. _____
 Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant