

*Move book Postal/Bureau*

*Started 3-18-10*

# PRESHIFT - ONSHIFT and DAILY REPORT

Company *Performance Coal*  
Mine *V. B. B.*  
SECTION *Move book*  
LOCATION *Naoma* *Raleigh* *N.C.*  
Post Office County State

Form 6-1489  
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible  
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be  
signed when made

Date of Examination 3-18-70 20. Section or Area Examined Plumley to 61 X cut  
Time of Examination: from 2:30 a.m. or P.M. to 5:00 a.m. or P.M.  
Was this report phoned to outside: Yes no  
By whom \_\_\_\_\_ Time \_\_\_\_\_ A.M. \_\_\_\_\_ P.M.  
Report received by \_\_\_\_\_  
(Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.	<u>Track clear from Plumley switch to 61 X cut on mainline. 20.8% O<sub>2</sub>, 0% CH<sub>4</sub>, 0% CO</u>	
2.		
3.		
4.		
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
<u>Track end</u>	<u>20,000</u>	<u>CFM</u>	

Remarks: 20.8% O<sub>2</sub>, 0% CH<sub>4</sub>, 0% CO, track clear prior to moving equipment scoop

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Rick Foster 28736 Assistant Foreman Certificate No.  
Countersigned Rick Foster 28736 Mine Manager—Mine Foreman  
Assistant Foreman  
Superintendent or Assistant

Use Indefilible  
Pencil or Ink

DAILY AND ONSHIFT REPORT  
MINE FOREMAN OR ASSISTANT

Report shall be  
signed when made

Date 3-19-70 Shift Day Area or Section Phenolite C1X4000

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	Moved maintenance side between shifts.	_____
3. _____	_____	_____
4. _____	Track clear after moving maintenance side	_____
5. _____	20.8% O <sub>2</sub> O <sub>2</sub> C <sub>1</sub> C <sub>2</sub>	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested \_\_\_\_\_

Number of Bolts Torqued Above Range \_\_\_\_\_ Below Range \_\_\_\_\_

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken \_\_\_\_\_

Remarks (Statement as to General Conditions of Mine or Area of Mine) \_\_\_\_\_

Asst. M  
Assistant Mine

28736  
Certificate No.

Asst. M  
Mine Foreman-Mine Manager

28736  
Certificate No.

Superintendent or Assistant