

Move Book

3 & 4

PRE-SHIFT - ONSHIFT and DAILY REPORT

Company UBB
Mine Performance
SECTION 3 & 4
LOCATION Naoma Raleigh WV
Post Office County State

Re-order from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, WV 25801

Phone (304) 253-7361

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 9-30-09 20 Section or Area Examined 4
 Time of Examination: from 800 (a.m. or p.m.) to 900 (a.m. or p.m.)
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed) _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Moved Scoop from #4 section to</u>	_____	_____
4. <u>out side</u>	_____	_____
5. _____	_____	_____
6. <u>Track Clear from 815:40 900 AM</u>	_____	_____
7. _____	_____	_____
8. <u>Track Clear after move 900 AM</u>	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
<u>CH4-0%</u>	_____	_____	_____
<u>O2-20.8%</u>	_____	_____	_____
<u>CO-0%</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager/Foreman _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 9-30-09 20 Section or Area Examined 3 section
 Time of Examination: from 9:30 a.m. or p.m. to 10:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Roadway Clear</u>	<u>Going in south Portal</u>	
4. <u>up by motor Barn up to</u>	<u>12 Brk</u>	
5. <u>CH₄-0%, CO-0%, O₂-20.8%</u>	<u>4</u>	<u>31222</u>
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 31222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] 31222 Mine Manager Mine Foreman _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

**DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT**

Report shall be
signed when made

Date 9-30-09 Shift Day Area or Section South portal to 3 section

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	Moved 2 10 stairs from outside to	_____
4. _____	12 Bk going in south portal	_____
5. _____	_____	_____
6. _____	Everything clear after move.	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman [Signature] Certificate No. 37222
 Mine Foreman-Mine Manager [Signature] Certificate No. [Signature]
 Superintendent or Assistant [Signature]

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10-01-09 20 Section or Area Examined 3
 Time of Examination: from 8:30 a.m. or p.m. to 9:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	Travel way from outside up motor barn	_____
4. _____	entry to 12 Bk everything clear	_____
5. _____	_____	_____
6. _____	CO-0%, O2-20.8%, CH4-0%	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift Mine Examiner Certificate No. 37222 Assistant Foreman Certificate No. _____
 Countersigned [Signature] Mine Manager or Mine Foreman _____
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 10-2-09 Shift Day Area or Section South

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.		
3.	<u>moved 2 skars 10 BIK to 19</u>	
4.	<u>Area Clear after 5/cars moved</u>	
5.		
6.		
7.	<u>230 PM - 300 PM</u>	<u>guy</u>
8.		
9.		
10.		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.	<u>Good Air</u>		13.		
4.	<u>Movement</u>		14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

[Signature]
Assistant Mine Foreman

37222
Certificate No. Mine Foreman-Mine Manager

[Signature]
Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10/9-09 20 08B-3 Section or Area Examined
 Time of Examination: from 1200 a.m. or p.m. to 1240 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Traveled from outside on south side from motor Barn Entry up 10 Biks Everything Clear

CH₄ 0%
 CO 0%
 O₂ 20.8%

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager Mine Foreman 37060000
 _____ Assistant Foreman _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 10-8-09 Shift Day Area or Section UBA-3

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. <u>No Power didn't move nothing</u>	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

[Handwritten signature]
390000

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10-9-09 Section or Area Examined VRA-3
 Time of Examination: from 600 a.m. or p.m. to 630 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>CH₄ 0%</u>	<u>Traveled from outside south side to 17 Bik in motor Barn entry. everything clear</u>	_____
4. <u>O₂ 20.8%</u>		_____
5. <u>CO 0%</u>		_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 37222 Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager _____ Mine Foreman _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 10-9-09 Shift Day Area or Section 3 section side

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.		
3.	Took 1212 miner in from outside	
4.	up #5 Entry to 12 Bik	
5.		
6.	Took R Bolter from outside up to	
7.	11 Bik.	
8.		
9.	Fire Bossed after took equipment in	
10.	every thing Clear. Guy 33222 900AM	

Examinations for Methane in Working Places

10-9-09

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.			13.		
4.			14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested

Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Guy 33222 Assistant Mine Foreman Certificate No.

Cook Mine Foreman-Mine Manager

3506000 Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 10-11-09 20 Section or Area Examined 3 sect
 Time of Examination: from 6:00 a.m. or p.m. to 6:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.	from outside south side to #1 Brk in	
3.	#5 Entry going in Motor Barn Entry	
4.	clear at time of exam.	
5.		
6.	CH ₄ -0% O ₂ -20.8% CO-0%	
7.	/	
8.	/	
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager Mine Foreman 390600 _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 10-12-09 Shift Day Area or Section 3 side

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.	From outside to 21 Bk going in #5 Entry	
3.		
4.	took 12-12 mmer in threw motor Bern Entry	
5.		
6.	Area Clear after 9-26AM 10-12-09	
7.		
8.		
9.		
10.		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.			13.		
4.			14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Examinations for Methane in Return Aircourses



Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

 Assistant Mine Foreman
37222 Certificate No.
 Mine Foreman-Mine Manager
 Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10-20-09 20 Section or Area Examined U B B 4 section
 Time of Examination: from 600 a.m. or p.m. to 700 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Track clear at time of exam</u>	_____	_____
4. _____	_____	_____
5. <u>CH₄ 0%, O₂ 20.8%, CO 0%</u>	_____	_____
6. _____	_____	_____
7. <u>from section to outside</u>	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: everything clear.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 3722 _____
 Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned [Signature] 28736 _____
 Mine Manager Mine Foreman

 Assistant Foreman

 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 10-20-09 Shift Day Area or Section U B B-4 section

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.	Brought scoop from section to outside	
3.		
4.		
5.		
6.		
7.	700-745 AM	
8.		
9.		
10.		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.			13.		
4.	Good Air movement		14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Examinations for Methane in Return Aircourses


Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____


Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____


Assistant Mine Foreman

37221
Certificate No.


Mine Foreman-Mine Manager

28236
Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10-20-09 20 Section or Area Examined UAB-4 section
 Time of Examination: from 7:30 a.m. or p.m. to 8:00 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom Brought out Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Track clear</u>	<u>after scoop was brought out</u>	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>g</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: CO-0%, CH4-0%, O2-20.8%

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Manager Mine Foreman 28736 _____
 Assistant Foreman _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 10-20-79 20 Section or Area Examined UAB-3 Section
 Time of Examination: from 8:00 a.m. or p.m. to 8:20 a.m. or p.m.
 Was this report phoned to outside; Yes no
 By whom Brought out Time 8:30 A.M. P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. <u>Motor Barn entry south side up to 17 BIK</u>	_____	_____
3. <u>everything clear.</u>	_____	_____
4. _____	_____	_____
5. <u>#1 Move Box</u>	<u>OK</u>	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: CO-0%, O2-20.8%, CH4-0%
Travel ways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Preshift-Mine Examiner Certificate No. 37222
 Countersigned [Signature] Mine Manager / Mine Foreman Certificate No. 28726
[Signature] Assistant Foreman Certificate No. 30539
 _____ Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date 10-26-09 Shift Day Area or Section VAA-3 Section

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.	Moved 12-72 mmmer from 8 Brk south side	
3.	to 3 section 17 Brk	
4.	Moved 10 scar from 16 Brk to 18 Brk south side	
5.		
6.	Moved staker feeder from outside to 8 Brk	
7.	south side	
8.		
9.		
10.		

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1.			11.		
2.			12.		
3.			13.		
4.			14.		
5.			15.		
6.			16.		
7.			17.		
8.			18.		
9.			19.		
10.			20.		

Coal Air movement
Everything clear.

Examinations for Methane in Return Aircourses




Location	Time	Methane Content	Location	Time	Methane Content
1.			6.		
2.			7.		
3.			8.		
4.			9.		
5.			10.		

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

 37222 Certificate No.
 Certificate No.
 Certificate No.
 Assistant Mine Foreman Mine Foreman-Mine Manager Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 10-21-09 20 3 Section or Area Examined Section South 4
 Time of Examination: from 2:45 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Travel way clear after equipment move</u>	_____	_____
4. <u>CH-0%</u>	_____	_____
5. <u>07-20-0%</u>	_____	_____
6. <u>00-0%</u>	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Move Boxes disconnected

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Certificate No. _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] Mine Foreman 08736
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-2-09 20 UBB-3 Section or Area Examined South Portal
 Time of Examination: from 900 a.m. or p.m. to 1000 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.	Area from state outside on south portal	
3.	up to 17 Brk Area Clear at time	
4.	of exam. 1000 AM 11-2-09 JY	
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: CO-0%, O2-20.8%, CH4-0%
Move boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37222 Assistant Foreman Certificate No. _____
 Countersigned [Signature] 2878 Mine Manager Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 11-2-09 Shift Day Area or Section UAD-3 South 4 Portal

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Area Clear</u>	_____	_____
4. <u>Moved Feeder, Roof Bolter from 7 Bik to</u>	_____	_____
5. <u>16 Bik. Everything clear after move</u>	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. <u>Good Air movement</u>	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

[Signature] 37222 Assistant Mine Foreman Certificate No. 37222
[Signature] Mine Foreman-Mine Manager Certificate No. 2873
 Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 11-2-09 20 Section or Area Examined UAB-3 South
 Time of Examination; from 100 a.m. or p.m. to 200 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. <u>3 section south side from # 3 motor Bank to 17 Bk</u>	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: ch 4-0%, O₂ 20 8/10 - 02, CO-0%
Everything clear after move.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 3722 _____ Assistant Foreman _____ Certificate No. _____
 Countersigned [Signature] _____ Mine Manager _____ Mine Foreman _____ Certificate No. 28736
 _____ Assistant Foreman _____
 _____ Superintendent or Assistant _____

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-16-09 20 Section or Area Examined UAB 3 side
 Time of Examination: from 1000 a.m. or p.m. to 1100 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>3 section south side from portal</u>	_____	_____
4. <u>up to 18 Bik at Cut throw.</u>	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. <u>Area Clear at time of exam.</u>	_____	_____
8. _____	_____	_____
9. <u>CH₄-0%, O₂-20.8%, CO-0%</u>	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
_____	_____	_____	_____
<u>Coal Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: Move Box - OK R. Stueffer

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] Certificate No. 37222
 Preshift-Mine Examiner Assistant Foreman Certificate No. _____
 Countersigned _____
 Mine Manager Mine Foreman _____
 Assistant Foreman _____
 Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date 11-16-09 Shift Day Area or Section UBB-3 side

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action Taken. Contains handwritten entries: 3. Moved -498-1735R Maintand supp from outside to top of Hill at D-Deer's; 6. Moved 2/scar from top of Hill down to BIK toward outside.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content (repeated). Contains 20 numbered rows for recording methane examination data.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content (repeated). Contains 10 numbered rows for recording methane examination data in return aircourses.

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

37222

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 11-16-09 20 Section or Area Examined UHB-3 south side
 Time of Examination: from 130 a.m. or p.m. to 230 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. <u>Area from outside to top of Hill at O-Doors</u>	<u>Clear after g/car and scoop move.</u>	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. <u>CO 0%</u>	<u>CH4 0%</u>	_____
9. <u>O2 20.8%</u>	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
<u>Good Air Movement</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [Signature] 37227 _____
 Preshift Mine Examiner Certificate No. Assistant Foreman Certificate No.
 Countersigned _____
 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 11-19-09 20 Section or Area Examined 4 section to 3 section
 Time of Examination: from 6:00 a.m. or p.m. to 7:30 a.m. or p.m.
 Was this report phoned to outside: Yes no
 By whom _____ Time _____ A.M. _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1.		
2.		
3.	<u>Moved Fanchel 35-C scoop from 4 section to</u>	
4.	<u>3 section. All trackways clear after move</u>	
5.		
6.		
7.		
8.	<u>20.3% O₂, 0.9% H₂, 0% CO</u>	
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
<u>Good air movement</u>			

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the W. Va. Mining Laws and the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Buck Foster 28736 Assistant Foreman Certificate No. _____
 Preshift-Mine Examiner
 Countersigned Buck Foster 28736 Mine Manager Mine Foreman
 Assistant Foreman
 Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine Foreman

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant