

STARTED 1-10-10

Daily
EXAMINATION
OF
GAS VALVES
AT
SEALS

Company Name: PERFORMANCE COAL Mine Name: UBB

Date Book Started: JAN. 10, 2010 Date Book Completed: _____

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 10, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-10-10	5	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 2					
1-10-10	10	GAS VALVE CHECK (IND GASING)				Jay Stewart	39199
		Set 3					
1-10-10	13	GAS VALVE CHECK (IND GASING)				Jay Stewart	39199
		Set 4					
1-10-10	21	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 5					
1-10-10	26	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 6					
1-10-10	33	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 7					
1-10-10	38	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 8					
1-10-10	43	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 9					
1-10-10	44	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 10					
1-10-10	47	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 11					
1-10-10	50	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 12					
1-10-10	53	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 13					
1-10-10	56	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 14					
1-10-10	62	GAS VALVE CHECK (IND GASING)				George Curry	27429
		Set 15					
1-10-10	63	GAS VALVE CHECK (IND GASING)				George Curry	27429
		BAROMETER READING 30.1					

Signature _____

Rich Foster
Mine Foreman

2873

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 11, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
1-11-10	5	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 2					
1-11-10	10	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 3					
1-11-10	13	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 4					
1-11-10	21	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 5					
1-11-10	26	GAS VALVE CHECK (IN GASING)				George Curry	27429
		SET 6					
1-11-10	33	GAS VALVE CHECK (OUT GASING)	1.8	12.8		George Curry	27429
		SET 7					
1-11-10	38	GAS VALVE CHECK (OUT GASING)	.75	17.2		George Curry	27429
		SET 8					
1-11-10	43	GAS VALVE CHECK (OUT GASING)		19.5		George Curry	27429
		SET 9					
1-11-10	44	GAS VALVE CHECK (OUT GASING)		18.6		George Curry	27429
		SET 10					
1-11-10	47	GAS VALVE CHECK (IN GASING)				George Curry	27429
		SET 11					
1-11-10	50	GAS VALVE CHECK (OUT GASING)		14.9		George Curry	27429
		SET 12					
1-11-10	53	GAS VALVE CHECK (OUT GASING)		19.5		George Curry	27429
		SET 13					
1-11-10	56	GAS VALVE CHECK (IN GASING)				George Curry	27429
		SET 14					
1-11-10	62	GAS VALVE CHECK (OUT GASING)		17.7		George Curry	27429
		SET 15					
1-11-10	63	GAS VALVE CHECK (IN GASING)				George Curry	27429
		BAROMETER READING 29.9					

Signature Reid Zehr
Mine Foreman

28730
Certificate No.

Signature _____
Superintendent

Remarks Gas Tube in need of Repair #5 Seal.

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 12, 2010

DAILY Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-12-10	5	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 2					
1-12-10	10	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 3					
1-12-10	13	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 4					
1-12-10	21	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 5					
1-12-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-12-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-12-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-12-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-12-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-12-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-12-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-12-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-12-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-12-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-12-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.1					

Signature _____

Rick Foster
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

REMARKS Gas tube repaired #5 Seal 1-12-10 Jim Boyer 32261

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 13, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-13-10	5	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 2					
1-13-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
1-13-10	13	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 4					
1-13-10	21	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 5					
1-13-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-13-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-13-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-13-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-13-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-13-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-13-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-13-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-13-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-13-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-13-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.1					

Signature _____

Rich Foster
Mine Foreman

28236
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 14, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-14-10	5	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 2					
1-14-10	10	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 3					
1-14-10	13	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 4					
1-14-10	21	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 5					
1-14-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-14-10	33	GAS VALVE CHECK (OUT GASING)	6	5.5	0	Harley Taylor	37002
		Set 7					
1-14-10	38	GAS VALVE CHECK (OUT GASING)	1	16.9	0	Harley Taylor	37002
		Set 8					
1-14-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-14-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-14-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-14-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-14-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-14-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-14-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-14-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.0					

Signature _____

Mine Foreman

28734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 15, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
1-15-10	5	Set 1 GAS VALVE check (IN GASING)				Jay Stewart	39199
1-15-10	10	Set 2 GAS VALVE check (IN GASING)				Jay Stewart	39199
1-15-10	13	Set 3 GAS VALVE check (IN GASING)				Jay Stewart	39199
1-15-10	21	Set 4 GAS VALVE check (IN GASING)				Jay Stewart	39199
1-15-10	26	Set 5 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	33	Set 6 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	38	Set 7 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	43	Set 8 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	44	Set 9 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	47	Set 10 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	50	Set 11 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	53	Set 12 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	56	Set 13 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	62	Set 14 GAS VALVE check (IN GASING)				Harley Taylor	37002
1-15-10	63	Set 15 GAS VALVE check (IN GASING)				Harley Taylor	37002
		Barometer Reading 30.1					

Signature _____

Rick Foster
Mine Foreman

28734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 16, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-16-10	5	GAS VALVE CHECK (IN GASING)				Jacy Stewart	39199
		Set 2					
1-16-10	10	GAS VALVE CHECK (IN GASING)				Jacy Stewart	39199
		Set 3					
1-16-10	13	GAS VALVE CHECK (IN GASING)				Jacy Stewart	39199
		Set 4					
1-16-10	21	GAS VALVE CHECK (IN GASING)				Jacy Stewart	39199
		Set 5					
1-16-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-16-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-16-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-16-10	43	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 9					
1-16-10	44	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 10					
1-16-10	47	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 11					
1-16-10	50	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 12					
1-16-10	53	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 13					
1-16-10	56	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 14					
1-16-10	62	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 15					
1-16-10	63	GAS VALVE CHECK (IN GASING)				George Curry	27429
		BAROMETER READING 30.0					

Signature _____

Mine Foreman

Rick Foster

Certificate No.

28736

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 17, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-17-10	5	GAS VALVE CHECK (In Gasing)				Jay Stewart	39199
		Set 2					
1-17-10	10	GAS VALVE CHECK (OUT GASING)	.2	10.1		George Curry	27429
		Set 3					
1-17-10	13	GAS VALVE CHECK (In Gasing)				Jay Stewart	39199
		Set 4					
1-17-10	21	GAS VALVE CHECK (In Gasing)				George Curry	27429
		Set 5					
1-17-10	26	GAS VALVE CHECK (OUT GASING)	.2	19.8		George Curry	27429
		Set 6					
1-17-10	33	GAS VALVE CHECK (OUT GASING)	3.0	13.1		George Curry	27429
		Set 7					
1-17-10	38	GAS VALVE CHECK (OUT GASING)	.7	15		George Curry	27429
		Set 8					
1-17-10	43	GAS VALVE CHECK (OUT GASING)	.1	16.5		George Curry	27429
		Set 9					
1-17-10	44	GAS VALVE CHECK (OUT GASING)	.1	16.8		George Curry	27429
		Set 10					
1-17-10	47	GAS VALVE CHECK (OUT GASING)	.05	13.1		George Curry	27429
		Set 11					
1-17-10	50	GAS VALVE CHECK (OUT GASING)	.1	10.8		George Curry	27429
		Set 12					
1-17-10	53	GAS VALVE CHECK (OUT GASING)	.3	12.7		George Curry	27429
		Set 13					
1-17-10	56	GAS VALVE CHECK (OUT GASING)	.1	16.1		George Curry	27429
		Set 14					
1-17-10	62	GAS VALVE CHECK (OUT GASING)	.6	9.9		George Curry	27429
		Set 15					
1-17-10	63	GAS VALVE CHECK (In Gasing)				George Curry	27429
		BAROMETER READING 29.8					

Signature _____

Mine Foreman

Rick Foster

Certificate No.

28734

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 18, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-18-10	5	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 2					
1-18-10	10	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 3					
1-18-10	13	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 4					
1-18-10	21	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 5					
1-18-10	26	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 6					
1-18-10	33	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 7					
1-18-10	38	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 8					
1-18-10	43	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 9					
1-18-10	44	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 10					
1-18-10	47	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 11					
1-18-10	50	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 12					
1-18-10	53	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 13					
1-18-10	56	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 14					
1-18-10	62	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 15					
1-18-10	63	GAS VALVE CHECK (NO GASING)				George Curry	27429
		BAROMETER READING 29.8					

Signature _____

Rick Foster
Mine Foreman

29734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 19, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-19-10	5	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 2					
1-19-10	10	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 3					
1-19-10	13	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 4					
1-19-10	21	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 5					
1-19-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-19-10	33	GAS VALVE CHECK (OUT GASING)	7	53	0	Harley Taylor	37002
		Set 7					
1-19-10	38	GAS VALVE CHECK (OUT GASING)	1	14.5	0	Harley Taylor	37002
		Set 8					
1-19-10	43	GAS VALVE CHECK (OUT GASING)	0	19.3	0	Harley Taylor	37002
		Set 9					
1-19-10	44	GAS VALVE CHECK (OUT GASING)	0	19.3	0	Harley Taylor	37002
		Set 10					
1-19-10	47	GAS VALVE CHECK (OUT GASING)	0	20.2	0	Harley Taylor	37002
		Set 11					
1-19-10	50	GAS VALVE CHECK (OUT GASING)	0	16.9	0	Harley Taylor	37002
		Set 12					
1-19-10	53	GAS VALVE CHECK (OUT GASING)	0	20.1	0	Harley Taylor	37002
		Set 13					
1-19-10	56	GAS VALVE CHECK (OUT GASING)	0	20.6	0	Harley Taylor	37002
		Set 14					
1-19-10	62	GAS VALVE CHECK (OUT GASING)	0	20.6	0	Harley Taylor	37002
		Set 15					
1-19-10	63	GAS VALVE CHECK (OUT GASING)	0	20.7	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 20, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-20-10	5	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 2					
1-20-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
1-20-10	13	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 4					
1-20-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 5					
1-20-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-20-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-20-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-20-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-20-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-20-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-20-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-20-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-20-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-20-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-20-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

2873
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 21, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-21-10	5	Gas Valve check (IN Gasing)				Jacy Stewart	39199
		Set 2					
1-21-10	10	Gas Valve check (IN Gasing)				Jacy Stewart	39199
		Set 3					
1-21-10	13	Gas Valve check (IN Gasing)				Jacy Stewart	39199
		Set 4					
1-21-10	21	Gas Valve check (IN Gasing)				Jacy Stewart	39199
		Set 5					
1-21-10	26	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 6					
1-21-10	33	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 7					
1-21-10	38	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 8					
1-21-10	43	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 9					
1-21-10	44	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 10					
1-21-10	47	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 11					
1-21-10	50	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 12					
1-21-10	53	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 13					
1-21-10	56	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 14					
1-21-10	62	Gas Valve check (IN Gasing)				Harley Taylor	37002
		Set 15					
1-21-10	63	Gas Valve check (IN Gasing)				Harley Taylor	37002
		BAROMETER Reading 29.6					

Signature _____

Reck Jantz

Mine Foreman

28736

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 22, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-22-10	5	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 2					
1-22-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
1-22-10	13	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 4					
1-22-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 5					
1-22-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-22-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-22-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-22-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-22-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-22-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-22-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-22-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-22-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-22-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-22-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN-23, 2010

DAILY Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-23-10	5	GAS VALVE CHECK (IN GASING)				Boony Curry	27429
		Set 2					
1-23-10	10	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 3					
1-23-10	13	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 4					
1-23-10	21	GAS VALVE CHECK (IN GASING)				Boony Curry	27429
		Set 5					
1-23-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-23-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-23-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-23-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-23-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-23-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-23-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-23-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-23-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-23-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-23-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING					

Signature _____

Rebecca
Mine Foreman

28736

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 24, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-24-10	5	GAS VALVE CHECK (OUT GASING)	.85	19.7		Jay Stewart	39199
		Set 2					
1-24-10	10	GAS VALVE CHECK (OUT GASING)	.1	2.5		George Curry	27429
		Set 3					
1-24-10	13	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 4					
1-24-10	21	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 5					
1-24-10	26	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 6					
1-24-10	33	GAS VALVE CHECK (OUT GASING)	.75	9.4		George Curry	27429
		Set 7					
1-24-10	38	GAS VALVE CHECK (OUT GASING)	.8	16.0		George Curry	27429
		Set 8					
1-24-10	43	GAS VALVE CHECK (OUT GASING)	.2	17.8		George Curry	27429
		Set 9					
1-24-10	44	GAS VALVE CHECK (OUT GASING)	.1	16.8		George Curry	27429
		Set 10					
1-24-10	47	GAS VALVE CHECK (OUT GASING)		18.5		George Curry	27429
		Set 11					
1-24-10	50	GAS VALVE CHECK (OUT GASING)	.2	12.5		George Curry	27429
		Set 12					
1-24-10	53	GAS VALVE CHECK (OUT GASING)	.8	13.3		George Curry	27429
		Set 13					
1-24-10	56	GAS VALVE CHECK (.20	16.9		Jay Stewart	39199
		Set 14					
1-24-10	62	GAS VALVE CHECK (OUT GASING)	.2	11.3		George Curry	27429
		Set 15					
1-24-10	63	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Barometer Reading (29.5)					

Signature Rich Forte
Mine Foreman

2823
Certificate No.

Signature _____
Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 25, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-25-10	5	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 2					
1-25-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
1-25-10	13	GAS VALVE CHECK (IN GASING)				Joey Stewart	39199
		Set 4					
1-25-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 5					
1-25-10	26	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 6					
1-25-10	33	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 7					
1-25-10	38	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 8					
1-25-10	43	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 9					
1-25-10	44	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 10					
1-25-10	47	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 11					
1-25-10	50	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 12					
1-25-10	53	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 13					
1-25-10	56	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 14					
1-25-10	62	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 15					
1-25-10	63	GAS VALVE CHECK (NO GASING)				George Curry	27429
		BAROMETER READING (29.8)					

Signature _____

Mine Foreman

Certificate No. 0873

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 26, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-26-10	5	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 2					
1-26-10	10	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 3					
1-26-10	13	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 4					
1-26-10	21	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 5					
1-26-10	26	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 6					
1-26-10	33	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 7					
1-26-10	38	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 8					
1-26-10	43	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 9					
1-26-10	44	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 10					
1-26-10	47	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 11					
1-26-10	50	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 12					
1-26-10	53	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 13					
1-26-10	56	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 14					
1-26-10	62	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 15					
1-26-10	63	GAS VALVE check (IN GASING)				Harley Taylor	37002
		BAROMETER Reading 29.7					

Signature _____

Rich Foster
Mine Foreman

28236
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 27, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-27-10	5	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 2					
1-27-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
1-27-10	13	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 4					
1-27-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 5					
1-27-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
1-27-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
1-27-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
1-27-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
1-27-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
1-27-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
1-27-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
1-27-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
1-27-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
1-27-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
1-27-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.1					

Signature _____

Rick Foster
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 28, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
1-28-10	5	GAS VALVE CHECK (IN GASING)				Jaeg Stewart	39199
		SET 2					
1-28-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		SET 3					
1-28-10	13	GAS VALVE CHECK (IN GASING)				Jaeg Stewart	39199
		SET 4					
1-28-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		SET 5					
1-28-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 6					
1-28-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 7					
1-28-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 8					
1-28-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 9					
1-28-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 10					
1-28-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 11					
1-28-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 12					
1-28-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 13					
1-28-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 14					
1-28-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 15					
1-28-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.0					

Signature _____

Rick Ester
Mine Foreman

28732

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 29, 2010

Daily Examinations - Week-Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
1-29-10	5	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 2					
1-29-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		SET 3					
1-29-10	13	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 4					
1-29-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		SET 5					
1-29-10	26	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 6					
1-29-10	33	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 7					
1-29-10	38	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 8					
1-29-10	43	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 9					
1-29-10	44	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 10					
1-29-10	47	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 11					
1-29-10	50	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 12					
1-29-10	53	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 13					
1-29-10	56	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 14					
1-29-10	62	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		SET 15					
1-29-10	63	GAS VALVE CHECK (IN GASING)				Charley Taylor	37002
		BAROMETER READING 30.2					

Signature _____

Rick Foster
Mine Foreman

28731
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

JAN. 30, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-30-10	5	GAS VALVE check (IN Gasing)				Jay Stewart	39199
		Set 2					
1-30-10	10	GAS VALVE check (IN Gasing)				Jim Boyer	32261
		Set 3					
1-30-10	13	GAS VALVE check (IN Gasing)				Jay Stewart	39199
		Set 4					
1-30-10	21	GAS VALVE check (IN Gasing)				Jim Boyer	32261
		Set 5					
1-30-10	26	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		Set 6					
1-30-10	33	GAS VALVE check (OUT Gasing)	7	5.5	0	Harley Taylor	37002
		Set 7					
1-30-10	38	GAS VALVE check (OUT Gasing)	1	16.3	0	Harley Taylor	37002
		Set 8					
1-30-10	43	GAS VALVE check (OUT Gasing)	0	17.7	0	Harley Taylor	37002
		Set 9					
1-30-10	44	GAS VALVE check (OUT Gasing)	0.1	17.5	0	Harley Taylor	37002
		Set 10					
1-30-10	47	GAS VALVE check (OUT Gasing)	0.1	20.7	0	Harley Taylor	37002
		Set 11					
1-30-10	50	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		Set 12					
1-30-10	53	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		Set 13					
1-30-10	56	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		Set 14					
1-30-10	62	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		Set 15					
1-30-10	63	GAS VALVE check (IN Gasing)				Harley Taylor	37002
		BAROMETER Reading 29.8					

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

JAN. 31, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-31-10	5	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 2					
1-31-10	10	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 3					
1-31-10	13	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 4					
1-31-10	21	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 5					
1-31-10	26	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 6					
1-31-10	33	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 7					
1-31-10	38	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 8					
1-31-10	43	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 9					
1-31-10	44	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 10					
1-31-10	47	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 11					
1-31-10	50	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 12					
1-31-10	53	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 13					
1-31-10	56	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 14					
1-31-10	62	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		Set 15					
1-31-10	63	GAS VALVE CHECK (TIO GASING)				George Curry	27429
		BAROMETER READING (30.0)					

Signature _____

Rick Foster
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 2, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
2-2-10	5	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 2					
2-2-10	10	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 3					
2-2-10	13	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 4					
2-2-10	21	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 5					
2-2-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		SET 6					
2-2-10	33	GAS VALVE CHECK (OUT GASING)	7	5.8	0	Harley Taylor	37002
		SET 7					
2-2-10	38	GAS VALVE CHECK (OUT GASING)	1	15.8	0	Harley Taylor	37002
		SET 8					
2-2-10	43	GAS VALVE CHECK (OUT GASING)	0	18.0	0	Harley Taylor	37002
		SET 9					
2-2-10	44	GAS VALVE CHECK (OUT GASING)	0	17.6	0	Harley Taylor	37002
		SET 10					
2-2-10	47	GAS VALVE CHECK (OUT GASING)	0	18.0	0	Harley Taylor	37002
		SET 11					
2-2-10	50	GAS VALVE CHECK (OUT GASING)	0	12.7	0	Harley Taylor	37002
		SET 12					
2-2-10	53	GAS VALVE CHECK (OUT GASING)	1	15.4	5	Harley Taylor	37002
		SET 13					
2-2-10	56	GAS VALVE CHECK (OUT GASING)	0	18.3	0	Harley Taylor	37002
		SET 14					
2-2-10	62	GAS VALVE CHECK (OUT GASING)	1	11.7	0	Harley Taylor	37002
		SET 15					
2-2-10	63	GAS VALVE CHECK (OUT GASING)	0	19.7	0	Harley Taylor	37002
		BAROMETER READING 28.0					

Signature _____

Rick Foster
Mine Foreman

28732

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 3, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-3-10	5	GAS VALVE CHECK (IN GASING)				Jim Beymer	32261
		Set 2					
2-3-10	10	GAS VALVE CHECK (IN GASING)				Jim Beymer	32261
		Set 3					
2-3-10	13	GAS VALVE CHECK (IN GASING)				Jim Beymer	32261
		Set 4					
2-3-10	21	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 5					
2-3-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
2-3-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
2-3-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
2-3-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
2-3-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
2-3-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
2-3-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
2-3-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
2-3-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
2-3-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
2-3-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.0					

Signature _____

Rick Zetter
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 4, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-4-10	5	GAS VALVE check (IN GASING)				Jaay Stewart	39199
		Set 2					
2-4-10	10	GAS VALVE check (IN GASING)				Jim Bayner	32261 32261
		Set 3					
2-4-10	13	GAS VALVE check (IN GASING)				Jaay Stewart	39199
		Set 4					
2-4-10	21	GAS VALVE check (IN GASING)				Jim Bayner	32261
		Set 5					
2-4-10	26	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 6					
2-4-10	33	GAS VALVE check (OUT GASING)	6	6.1	0	Harley Taylor	37002
		Set 7					
2-4-10	38	GAS VALVE check (OUT GASING)	1	16.8	0	Harley Taylor	37002
		Set 8					
2-4-10	43	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 9					
2-4-10	44	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 10					
2-4-10	47	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 11					
2-4-10	50	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 12					
2-4-10	53	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 13					
2-4-10	56	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 14					
2-4-10	62	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 15					
2-4-10	63	GAS VALVE check (IN GASING)				Harley Taylor	37002
		BAROMETER READING 30.0					

Signature _____

Rick Foster
Mine Foreman

28734

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 5, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-5-10	5	GAS VALVE check (In Gasing)				Jacy Stewart	39199
		Set 2					
2-5-10	10	GAS VALVE check (In Gasing)				Jacy Stewart	39199
		Set 3					
2-5-10	13	GAS VALVE check (In Gasing)				Jacy Stewart	39199
		Set 4					
2-5-10	21	GAS VALVE check (In Gasing)				Jacy Stewart	39199
		Set 5					
2-5-10	26	GAS VALVE check (OUT GASING)	0	20.3	0	Harley Taylor	37002
		Set 6					
2-5-10	33	GAS VALVE check (OUT GASING)	7	5.1	0	Harley Taylor	37002
		Set 7					
2-5-10	38	GAS VALVE check (OUT GASING)	1	15.7	0	Harley Taylor	37002
		Set 8					
2-5-10	43	GAS VALVE check (OUT GASING)	0	18.0	0	Harley Taylor	37002
		Set 9					
2-5-10	44	GAS VALVE check (OUT GASING)	0	17.0	0	Harley Taylor	37002
		Set 10					
2-5-10	47	GAS VALVE check (OUT GASING)	0	17.7	0	Harley Taylor	37002
		Set 11					
2-5-10	50	GAS VALVE check (OUT GASING)	0	11.6	0	Harley Taylor	37002
		Set 12					
2-5-10	53	GAS VALVE check (OUT GASING)	3	9.4	7	Harley Taylor	37002
		Set 13					
2-5-10	56	GAS VALVE check (OUT GASING)	0	16.5	0	Harley Taylor	37002
		Set 14					
2-5-10	62	GAS VALVE check (OUT GASING)	1	10.5	0	Harley Taylor	37002
		Set 15					
2-5-10	63	GAS VALVE check (OUT GASING)	0	18.1	0	Harley Taylor	37002
		BAROMETER Reading 29.5					

Signature _____

Rick Zil
Mine Foreman

2823
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 6, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-6-10	5	GAS VALVE check (IN GASING)				Jim Beynen	32261
		Set 2					
2-6-10	10	GAS VALVE check (IN GASING)				Jim Beynen	32261
		Set 3					
2-6-10	13	GAS VALVE check (IN GASING)				Jim Beynen	32261
		Set 4					
2-6-10	21	GAS VALVE check (IN GASING)				Jim Beynen	32261
		Set 5					
2-6-10	26	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 6					
2-6-10	33	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 7					
2-6-10	38	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 8					
2-6-10	43	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 9					
2-6-10	44	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 10					
2-6-10	47	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 11					
2-6-10	50	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 12					
2-6-10	53	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 13					
2-6-10	56	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 14					
2-6-10	62	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 15					
2-6-10	63	GAS VALVE check (IN GASING)				Harley Taylor	37002
		BAROMETER READING 29.5					

Signature Rich Zita
Mine Foreman

28732
Certificate No.

Signature _____
Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 7, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-7-10	5	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 2					
2-7-10	10	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 3					
2-7-10	13	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 4					
2-7-10	21	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 5					
2-7-10	26	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 6					
2-7-10	33	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 7					
2-7-10	38	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 8					
2-7-10	43	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 9					
2-7-10	44	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 10					
2-7-10	47	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 11					
2-7-10	50	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 12					
2-7-10	53	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 13					
2-7-10	56	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 14					
2-7-10	62	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Set 15					
2-7-10	63	GAS VALVE CHECK (NO GASING)				George Curry	27429
		Barometer Reading 30.0					

Signature _____

Rick Foster
Mine Foreman

28736

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 8, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-8-10	5	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 2					
2-8-10	10	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 3					
2-8-10	13	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 4					
2-8-10	21	GAS VALVE CHECK (IN GASING)				Jim Boyer	32261
		Set 5					
2-8-10	26	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 6					
2-8-10	33	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 7					
2-8-10	38	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 8					
2-8-10	43	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 9					
2-8-10	44	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 10					
2-8-10	47	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 11					
2-8-10	50	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 12					
2-8-10	53	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 13					
2-8-10	56	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 14					
2-8-10	62	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 15					
2-8-10	63	GAS VALVE CHECK (IN GASING)				George Curry	27429
		BAROMETER READING 30.0					

Signature _____

Rick Post
Mine Foreman

28752
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 9, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-9-10	5	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 2					
2-9-10	10	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 3					
2-9-10	13	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 4					
2-9-10	21	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 5					
2-9-10	26	GAS VALVE check (IN GASING)				Harley Taylor	37002
		Set 6					
2-9-10	33	GAS VALVE check (OUT GASING)	11	4.9	0	Harley Taylor	37002
		Set 7					
2-9-10	38	GAS VALVE check (OUT GASING)	1	14.7	0	Harley Taylor	37002
		Set 8					
2-9-10	43	GAS VALVE check (OUT GASING)	0	18.2	0	Harley Taylor	37002
		Set 9					
2-9-10	44	GAS VALVE check (OUT GASING)	0	17.2	0	Harley Taylor	37002
		Set 10					
2-9-10	47	GAS VALVE check (OUT GASING)	0	16.8	0	Harley Taylor	37002
		Set 11					
2-9-10	50	GAS VALVE check (OUT GASING)	0	12.7	0	Harley Taylor	37002
		Set 12					
2-9-10	53	GAS VALVE check (OUT GASING)	1	17.3	5	Harley Taylor	37002
		Set 13					
2-9-10	56	GAS VALVE check (OUT GASING)	0	17.2	0	Harley Taylor	37002
		Set 14					
2-9-10	62	GAS VALVE check (OUT GASING)	1	9.8	0	Harley Taylor	37002
		Set 15					
2-9-10	63	GAS VALVE check (OUT GASING)	0	19.3	0	Harley Taylor	37002
		BAROMETER READING 29.6					

Signature _____

Rick Foster
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 10, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-10-10	5	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 2					
2-10-10	10	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 3					
2-10-10	13	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 4					
2-10-10	21	GAS VALVE CHECK (IN GASING)				Jay Stewart	39199
		Set 5					
2-10-10	26	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 6					
2-10-10	33	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 7					
2-10-10	38	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 8					
2-10-10	43	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 9					
2-10-10	44	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 10					
2-10-10	47	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 11					
2-10-10	50	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 12					
2-10-10	53	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 13					
2-10-10	56	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 14					
2-10-10	62	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Set 15					
2-10-10	63	GAS VALVE CHECK (IN GASING)				Harley Taylor	37002
		Barometer Reading 29.6					

Signature _____

Rick Foster
Mine Foreman

23732

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Feb. 11, 2010 North West & North Mains Seals

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
2-11-10	5	GAS VALVE CHECK (IN GASING)				Jaeger Stewart	39199
		SET 2					
2-11-10	10	GAS VALVE CHECK (IN GASING)				Jim Boygen	32261
		SET 3					
2-11-10	13	GAS VALVE CHECK (IN GASING)				Jim Boygen	32261
		SET 4					
2-11-10	21	GAS VALVE CHECK (IN GASING)				Jaeger Stewart	39199
		SET 5					
2-11-10	26	GAS VALVE CHECK (IN GASING)	0	20.0	0	Harley Taylor	37002
		SET 6					
2-11-10	33	GAS VALVE CHECK (OUT GASING)	6	5.9	5	Harley Taylor	37002
		SET 7					
2-11-10	38	GAS VALVE CHECK (OUT GASING)	1	15.6	0	Harley Taylor	37002
		SET 8					
2-11-10	43	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
		SET 9					
2-11-10	44	GAS VALVE CHECK (IN GASING)	0	20.9	0	Harley Taylor	37002
		SET 10					
2-11-10	47	GAS VALVE CHECK (IN GASING)	0	20.9	0	Harley Taylor	37002
		SET 11					
2-11-10	50	GAS VALVE CHECK (IN GASING)	0	20.9	0	Harley Taylor	37002
		SET 12					
2-11-10	53	GAS VALVE CHECK (IN GASING)	0	20.9	0	Harley Taylor	37002
		SET 13					
2-11-10	56	GAS VALVE CHECK (IN GASING)	0	20.8	0	Harley Taylor	37002
		SET 14					
2-11-10	62	GAS VALVE CHECK (IN GASING)	1	10.7	0	Harley Taylor	37002
		SET 15					
2-11-10	63	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
	*	BARDMETER READING 29.9					

WEEKLY EXAMINATION OF SEALS

Feb. 12, 2010

Rt. 4 + MRS Seals

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
2-12-10	5	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 2					
2-12-10	10	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 3					
2-12-10	13	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 4					
2-12-10	21	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		SET 5					
2-12-10	26	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		SET 6					
2-12-10	33	GAS VALVE CHECK (IN GASING)	6	5.7	0	Harley Taylor	37002
		SET 7					
2-12-10	38	GAS VALVE CHECK (OUT GASING)	1	15.6	0	Harley Taylor	37002
		SET 8					
2-12-10	43	GAS VALVE CHECK (IN GASING)	0.1	19.4	0	Harley Taylor	37002
		SET 9					
2-12-10	44	GAS VALVE CHECK (IN GASING)	0	18.9	0	Harley Taylor	37002
		SET 10					
2-12-10	47	GAS VALVE CHECK (IN GASING)	0.1	19.7	0	Harley Taylor	37002
		SET 11					
2-12-10	50	GAS VALVE CHECK (IN GASING)	0	16.1	0	Harley Taylor	37002
		SET 12					
2-12-10	53	GAS VALVE CHECK (IN GASING)	0	20.4	0	Harley Taylor	37002
		SET 13					
2-12-10	56	GAS VALVE CHECK (IN GASING)	0	20.8	0	Harley Taylor	37002
		SET 14					
2-12-10	62	GAS VALVE CHECK (OUT GASING)	0	16.9	0	Harley Taylor	37002
		SET 15					
2-12-10	63	GAS VALVE CHECK (OUT GASING)	0	19.4	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28736

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 13, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-13-10	5	GAS VALVE check (NO GASING)				George Curry	27429
		Set 2					
2-13-10	10	GAS VALVE check (NO GASING)				George Curry	27429
		Set 3					
2-13-10	13	GAS VALVE check (NO GASING)				George Curry	27429
		Set 4					
2-13-10	21	GAS VALVE check (NO GASING)				George Curry	27429
		Set 5					
2-13-10	26	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 6					
2-13-10	33	GAS VALVE check (IN GASING)	6	5.9	5	Harley Taylor	37002
		Set 7					
2-13-10	38	GAS VALVE check (IN GASING)	1	15.6	0	Harley Taylor	37002
		Set 8					
2-13-10	43	GAS VALVE check (IN GASING)	0.1	19.5	0	Harley Taylor	37002
		Set 9					
2-13-10	44	GAS VALVE check (IN GASING)	0	18.7	0	Harley Taylor	37002
		Set 10					
2-13-10	47	GAS VALVE check (IN GASING)	0.1	20.0	0	Harley Taylor	37002
		Set 11					
2-13-10	50	GAS VALVE check (IN GASING)	0	20.7	0	Harley Taylor	37002
		Set 12					
2-13-10	53	GAS VALVE check (IN GASING)	1	16.8	9	Harley Taylor	37002
		Set 13					
2-13-10	56	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 14					
2-13-10	62	GAS VALVE check (IN GASING)	0	18.3	0	Harley Taylor	37002
		Set 15					
2-13-10	63	GAS VALVE check (IN GASING)	0	20.1	0	Harley Taylor	37002
		BAROMETER Reading 29.7					

Signature Rick Foster Mine Foreman Certificate No. 28731 Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 14, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-14-10	5	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		Set 2					
2-14-10	10	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 3					
2-14-10	13	GAS VALVE CHECK (IN GASING)				Jacq Stewart	39199
		Set 4					
2-14-10	21	GAS VALVE CHECK (IN GASING)				George Curry	27429
		Set 5					
2-14-10	26	GAS VALVE CHECK (IN GASING)	0	20.4	0	George Curry	27429
		Set 6					
2-14-10	33	GAS VALVE CHECK (OUT GASING)	0	16.4	0	George Curry	27429
		Set 7					
2-14-10	38	GAS VALVE CHECK (OUT GASING)	1.77	15.7	0	George Curry	27429
		Set 8					
2-14-10	43	GAS VALVE CHECK (IN GASING)	0	20.6	0	George Curry	27429
		Set 9					
2-14-10	44	GAS VALVE CHECK (IN GASING)	0	18.2	0	George Curry	27429
		Set 10					
2-14-10	47	GAS VALVE CHECK (IN GASING)	0	20.1	0	George Curry	27429
		Set 11					
2-14-10	50	GAS VALVE CHECK (IN GASING)	0	18.5	0	George Curry	27429
		Set 12					
2-14-10	53	GAS VALVE CHECK (IN GASING)	1.4	18.4	0	George Curry	27429
		Set 13					
2-14-10	56	GAS VALVE CHECK (IN GASING)	0	20.4	0	George Curry	27429
		Set 14					
2-14-10	62	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 15					
2-14-10	63	GAS VALVE CHECK (IN GASING)	0	20.3	0	George Curry	27429
		BAROMETER READING 29.8					

Signature Rick Jones
Mine Foreman

28734
Certificate No.

Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 15, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-15-10	5	GAS VALVE CHECK (IN BASING)	0	20.8	0	George Curry	27429
		Set 2					
2-15-10	10	GAS VALVE CHECK (IN BASING)	0	20.8	0	George Curry	27429
		Set 3					
2-15-10	13	GAS VALVE CHECK (IN BASING)	0	20.8	0	George Curry	27429
		Set 4					
2-15-10	21	GAS VALVE CHECK (IN BASING)	0	20.8	0	George Curry	27429
		Set 5					
2-15-10	26	GAS VALVE CHECK (IN BASING)	0	20.8	0	Jacy Stewart	39199
		Set 6					
2-15-10	33	GAS VALVE CHECK (OUT BASING)	0.06	16.5	0	George Curry	27429
		Set 7					
2-15-10	38	GAS VALVE CHECK (OUT BASING)	0	19.5	0	George Curry	27429
		Set 8					
2-15-10	43	GAS VALVE CHECK (OUT BASING)	0	20.1	0	George Curry	27429
		Set 9					
2-15-10	44	GAS VALVE CHECK (OUT BASING)	0	18.1	0	George Curry	27429
		Set 10					
2-15-10	47	GAS VALVE CHECK (OUT BASING)	0	19.8	0	George Curry	27429
		Set 11					
2-15-10	50	GAS VALVE CHECK (OUT BASING)	0	18.2	0	George Curry	27429
		Set 12					
2-15-10	53	GAS VALVE CHECK (OUT BASING)	0	18.5	0	George Curry	27429
		Set 13					
2-15-10	56	GAS VALVE CHECK (OUT BASING)	0	20.2	0	George Curry	27429
		Set 14					
2-15-10	62	GAS VALVE CHECK (OUT BASING)	0	19.2	0	George Curry	27429
		Set 15					
2-15-10	63	GAS VALVE CHECK (IN BASING)	0	20.8	0	George Curry	27429
		BAROMETER READING 29.5					

Signature _____

Rick Tate
Mine Foreman

28736

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 16, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-16-10	5	Gas Valve check (IN GASING)	0.4	4.9	0	Harley Taylor	37002
		Set 2					
2-16-10	10	Gas Valve check (IN GASING)	0.4	6.3	0	Harley Taylor	37002
		Set 3					
2-16-10	13	Gas Valve check (IN GASING)	0	20.8	0	Harley Taylor	37002
		Set 4					
2-16-10	21	Gas Valve check (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 5					
2-16-10	26	Gas Valve check (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 6					
2-16-10	33	Gas Valve check (IN GASING)	0	20.9	0	Harley Taylor	37002
		Set 7					
2-16-10	38	Gas Valve check (IN GASING)	0	21.0	0	Harley Taylor	37002
		Set 8					
2-16-10	43	Gas Valve check (IN GASING)	0.1	19.7	0	Harley Taylor	37002
		Set 9					
2-16-10	44	Gas Valve check (IN GASING)	0.1	18.8	0	Harley Taylor	37002
		Set 10					
2-16-10	47	Gas Valve check (IN GASING)	0.1	19.7	0	Harley Taylor	37002
		Set 11					
2-16-10	50	Gas Valve check (IN GASING)	0.1	18.0	0	Harley Taylor	37002
		Set 12					
2-16-10	53	Gas Valve check (IN GASING)	1	17.9	0	Harley Taylor	37002
		Set 13					
2-16-10	56	Gas Valve check (IN GASING)	0.1	19.9	0	Harley Taylor	37002
		Set 14					
2-16-10	62	Gas Valve check (IN GASING)	0.2	19.0	0	Harley Taylor	37002
		Set 15					
2-16-10	63	Gas Valve check (IN GASING)	0.1	20.0	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Zosta
Mine Foreman

28734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 17, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-17-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 2					
2-17-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 3					
2-17-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 4					
2-17-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 5					
2-17-10	26	GAS VALVE CHECK (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 6					
2-17-10	33	GAS VALVE CHECK (IN GASING)	5	6.9	0	Harley Taylor	37002
		Set 7					
2-17-10	38	GAS VALVE CHECK (IN GASING)	1	16.3	0	Harley Taylor	37002
		Set 8					
2-17-10	43	GAS VALVE CHECK (IN GASING)	0	20.1	0	Harley Taylor	37002
		Set 9					
2-17-10	44	GAS VALVE CHECK (IN GASING)	1	18.6	0	Harley Taylor	37002
		Set 10					
2-17-10	47	GAS VALVE CHECK (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 11					
2-17-10	50	GAS VALVE CHECK (IN GASING)	0	18.3	0	Harley Taylor	37002
		Set 12					
2-17-10	53	GAS VALVE CHECK (IN GASING)	1	18.2	0	Harley Taylor	37002
		Set 13					
2-17-10	56	GAS VALVE CHECK (IN GASING)	0	20.5	0	Harley Taylor	37002
		Set 14					
2-17-10	62	GAS VALVE CHECK (IN GASING)	1	19.0	0	Harley Taylor	37002
		Set 15					
2-17-10	63	GAS VALVE CHECK (IN GASING)	0	20.2	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature Rick Foster Mine Foreman Certificate No. 23731 Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 18, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
2-18-10	5	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		SET 2					
2-18-10	10	GAS VALVE check (IN GASING)	0	20.5	0	Jim Boyer	32261
		SET 3					
2-18-10	13	GAS VALVE check (IN GASING)	0	20.5	0	Jim Boyer	32261
		SET 4					
2-18-10	21	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		SET 5					
2-18-10	26	GAS VALVE check (IN GASING)	0	20.4	0	Harley Taylor	37002
		SET 6					
2-18-10	33	GAS VALVE check (IN GASING)	5	8.1	0	Harley Taylor	37002
		SET 7					
2-18-10	38	GAS VALVE check (IN GASING)	1	15.9	0	Harley Taylor	37002
		SET 8					
2-18-10	43	GAS VALVE check (IN GASING)	0	20.1	0	Harley Taylor	37002
		SET 9					
2-18-10	44	GAS VALVE check (IN GASING)	1	19.3	0	Harley Taylor	37002
		SET 10					
2-18-10	47	GAS VALVE check (IN GASING)	0	20.0	0	Harley Taylor	37002
		SET 11					
2-18-10	50	GAS VALVE check (IN GASING)	0	18.4	0	Harley Taylor	37002
		SET 12					
2-18-10	53	GAS VALVE check (IN GASING)	1	18.8	0	Harley Taylor	37002
		SET 13					
2-18-10	56	GAS VALVE check (IN GASING)	0	20.8	0	Harley Taylor	37002
		SET 14					
2-18-10	62	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		SET 15					
2-18-10	63	GAS VALVE check (IN GASING)	0	20.2	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Rick Zota
Mine Foreman

2873C
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 19, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-19-10	5	GAS VALVE check (IN GASING)	0	20.8	0	Joey Stewart	39199
		Set 2					
2-19-10	10	GAS VALVE check (IN GASING)	0	20.8	0	Jim Sawyer	32261
		Set 3					
2-19-10	13	GAS VALVE check (IN GASING)	0	20.8	0	Joey Stewart	39199
		Set 4					
2-19-10	21	GAS VALVE check (IN GASING)	0	20.8	0	Jim Sawyer	32261
		Set 5					
2-19-10	26	GAS VALVE check (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 6					
2-19-10	33	GAS VALVE check (IN GASING)	6	5.9	0	Harley Taylor	37002
		Set 7					
2-19-10	38	GAS VALVE check (IN GASING)	4	18.6	0	Harley Taylor	37002
		Set 8					
2-19-10	43	GAS VALVE check (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 9					
2-19-10	44	GAS VALVE check (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 10					
2-19-10	47	GAS VALVE check (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 11					
2-19-10	50	GAS VALVE check (IN GASING)	0	18.9	0	Harley Taylor	37002
		Set 12					
2-19-10	53	GAS VALVE check (IN GASING)	2	19.9	0	Harley Taylor	37002
		Set 13					
2-19-10	56	GAS VALVE check (IN GASING)	0	20.9	0	Harley Taylor	37002
		Set 14					
2-19-10	62	GAS VALVE check (IN GASING)	0	20.5	0	Harley Taylor	37002
		Set 15					
2-19-10	63	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Rich Miller
Mine Foreman

28236
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 20, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-20-10	5	GAS VALVE check (NO GASING)	0	20.8	0	George Curry	27429
		Set 2					
2-20-10	10	GAS VALVE check (NO GASING)	0	20.8	0	George Curry	27429
		Set 3					
2-20-10	13	GAS VALVE check (NO GASING)	0	20.8	0	George Curry	27429
		Set 4					
2-20-10	21	GAS VALVE check (NO GASING)	0	20.8	0	George Curry	27429
		Set 5					
2-20-10	26	GAS VALVE check (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 6					
2-20-10	33	GAS VALVE check (IN GASING)	6	67	0	Harley Taylor	37002
		Set 7					
2-20-10	38	GAS VALVE check (IN GASING)	0	20.5	0	Harley Taylor	37002
		Set 8					
2-20-10	43	GAS VALVE check (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 9					
2-20-10	44	GAS VALVE check (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 10					
2-20-10	47	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 11					
2-20-10	50	GAS VALVE check (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 12					
2-20-10	53	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 13					
2-20-10	56	GAS VALVE check (IN GASING)	0	20.9	0	Harley Taylor	37002
		Set 14					
2-20-10	62	GAS VALVE check (IN GASING)	0	20.7	0	Harley Taylor	37002
		Set 15					
2-20-10	63	GAS VALVE check (IN GASING)	0	20.7	0	Harley Taylor	37002
		BAROMETER READING 30.0					

Signature _____

Rick Foster
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 21, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-21-10	5	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 2					
2-21-10	10	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 3					
2-21-10	13	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 4					
2-21-10	21	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 5					
2-21-10	26	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 6					
2-21-10	33	GAS VALVE CHECK (OUT GASING)	10.0	16.2	0	George Curry	27429
		Set 7					
2-21-10	38	GAS VALVE CHECK (OUT GASING)	5.5	17.5	0	George Curry	27429
		Set 8					
2-21-10	43	GAS VALVE CHECK (NO GASING)	0	19.9	0	George Curry	27429
		Set 9					
2-21-10	44	GAS VALVE CHECK (NO GASING)	0	19.6	0	George Curry	27429
		Set 10					
2-21-10	47	GAS VALVE CHECK (NO GASING)	0	20.6	0	George Curry	27429
		Set 11					
2-21-10	50	GAS VALVE CHECK (NO GASING)	0	19.1	0	George Curry	27429
		Set 12					
2-21-10	53	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 13					
2-21-10	56	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 14					
2-21-10	62	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		Set 15					
2-21-10	63	GAS VALVE CHECK (NO GASING)	0	20.7	0	George Curry	27429
		BAROMETER READING 20.8					

Signature _____

Rick Foster
Mine Foreman

25736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 22, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-22-10	5	GAS VALVE CHECK (IN BASING)	0	20.8	0	Jim Boyer	32261
		Set 2					
2-22-10	10	GAS VALVE CHECK (IN BASING)	0	20.8	0	Jack Stuart	39199
		Set 3					
2-22-10	13	GAS VALVE CHECK (IN BASING)	0	20.8	0	Jack Stuart	39199
		Set 4					
2-22-10	21	GAS VALVE CHECK (IN BASING)	0	20.8	0	Jim Boyer	32261
		Set 5					
2-22-10	26	GAS VALVE CHECK (OUT BASING)	0	20.2	0	George Curry	27429
		Set 6					
2-22-10	33	GAS VALVE CHECK (OUT BASING)	1.0	7.0	0	George Curry	27429
		Set 7					
2-22-10	38	GAS VALVE CHECK (OUT BASING)	1.6	17.0	0	George Curry	27429
		Set 8					
2-22-10	43	GAS VALVE CHECK (OUT BASING)	0	20.1	0	George Curry	27429
		Set 9					
2-22-10	44	GAS VALVE CHECK (OUT BASING)	0	20.1	0	George Curry	27429
		Set 10					
2-22-10	47	GAS VALVE CHECK (OUT BASING)	0	19.1	0	George Curry	27429
		Set 11					
2-22-10	50	GAS VALVE CHECK (OUT BASING)	.05	17.2	0	George Curry	27429
		Set 12					
2-22-10	53	GAS VALVE CHECK (OUT BASING)	.75	17.1	0	George Curry	27429
		Set 13					
2-22-10	56	GAS VALVE CHECK (OUT BASING)	0	20.3	0	George Curry	27429
		Set 14					
2-22-10	62	GAS VALVE CHECK (IN BASING)	0	20.7	0	George Curry	27429
		Set 15					
2-22-10	63	GAS VALVE CHECK (IN BASING)	0	20.7	0	George Curry	27429
		BAROMETER READING 29.4					

Signature _____

Paul Zelen
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 23, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION
		Set 1					
2-23-10	5	GAS VALVE check (IN GASING)	0.4	3.0	0	Harley Taylor	37002
		Set 2					
2-23-10	10	GAS VALVE check (IN GASING)	0.3	5.2	0	Harley Taylor	37002
		Set 3					
2-23-10	13	GAS VALVE check (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 4					
2-23-10	21	GAS VALVE check (IN GASING)	0	18.6	0	Harley Taylor	37002
		Set 5					
2-23-10	26	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 6					
2-23-10	33	GAS VALVE check (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 7					
2-23-10	38	GAS VALVE check (IN GASING)	1	16.7	0	Harley Taylor	37002
		Set 8					
2-23-10	43	GAS VALVE check (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 9					
2-23-10	44	GAS VALVE check (IN GASING)	0.1	19.2	0	Harley Taylor	37002
		Set 10					
2-23-10	47	GAS VALVE check (IN GASING)	0.1	19.1	0	Harley Taylor	37002
		Set 11					
2-23-10	50	GAS VALVE check (IN GASING)	0.1	16.1	0	Harley Taylor	37002
		Set 12					
2-23-10	53	GAS VALVE check (IN GASING)	1	14.7	0	Harley Taylor	37002
		Set 13					
2-23-10	56	GAS VALVE check (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 14					
2-23-10	62	GAS VALVE check (IN GASING)	0.2	17.2	0	Harley Taylor	37002
		Set 15					
2-23-10	63	GAS VALVE check (IN GASING)	0.2	19.0	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28732

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 24, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		SET 1					
2-24-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		SET 2					
2-24-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		SET 3					
2-24-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		SET 4					
2-24-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	George Curry	27429
		SET 5					
2-24-10	26	GAS VALVE CHECK (IN GASING)	0	20.2	0	Harley Taylor	37002
		SET 6					
2-24-10	33	GAS VALVE CHECK (IN GASING)	6	4.9	0	Harley Taylor	37002
		SET 7					
2-24-10	38	GAS VALVE CHECK (IN GASING)	1	15.9	0	Harley Taylor	37002
		SET 8					
2-24-10	43	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		SET 9					
2-24-10	44	GAS VALVE CHECK (OUT GASING)	0	18.8	0	Harley Taylor	37002
		SET 10					
2-24-10	47	GAS VALVE CHECK (OUT GASING)	0	19.7	0	Harley Taylor	37002
		SET 11					
2-24-10	50	GAS VALVE CHECK (OUT GASING)	0	17.5	0	Harley Taylor	37002
		SET 12					
2-24-10	53	GAS VALVE CHECK (OUT GASING)	1	17.4	0	Harley Taylor	37002
		SET 13					
2-24-10	56	GAS VALVE CHECK (OUT GASING)	0	19.5	0	Harley Taylor	37002
		SET 14					
2-24-10	62	GAS VALVE CHECK (OUT GASING)	0	19.8	0	Harley Taylor	37002
		SET 15					
2-24-10	63	GAS VALVE CHECK (OUT GASING)	0	18.4	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Beta
Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 25, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-25-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 2					
2-25-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 3					
2-25-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 4					
2-25-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 5					
2-25-10	26	GAS VALVE CHECK (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 6					
2-25-10	33	GAS VALVE CHECK (IN GASING)	6	5.0	0	Harley Taylor	37002
		Set 7					
2-25-10	38	GAS VALVE CHECK (IN GASING)	1	15.7	0	Harley Taylor	37002
		Set 8					
2-25-10	43	GAS VALVE CHECK (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 9					
2-25-10	44	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 10					
2-25-10	47	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 11					
2-25-10	50	GAS VALVE CHECK (IN GASING)	0	18.0	0	Harley Taylor	37002
		Set 12					
2-25-10	53	GAS VALVE CHECK (IN GASING)	1	18.4	0	Harley Taylor	37002
		Set 13					
2-25-10	56	GAS VALVE CHECK (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 14					
2-25-10	62	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 15					
2-25-10	63	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 26, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-26-10	5	GAS VALVE check (IN GASING)	0	0	0	Jack Stewart	39199
		Set 2					
2-26-10	10	GAS VALVE check (IN GASING)	0	0	0	Jack Stewart	39199
		Set 3					
2-26-10	13	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 4					
2-26-10	21	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 5					
2-26-10	26	GAS VALVE check (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 6					
2-26-10	33	GAS VALVE check (OUT GASING)	6	5.1	0	Harley Taylor	37002
		Set 7					
2-26-10	38	GAS VALVE check (IN GASING)	1	15.6	0	Harley Taylor	37002
		Set 8					
2-26-10	43	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 9					
2-26-10	44	GAS VALVE check (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 10					
2-26-10	47	GAS VALVE check (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 11					
2-26-10	50	GAS VALVE check (IN GASING)	0	18.7	0	Harley Taylor	37002
		Set 12					
2-26-10	53	GAS VALVE check (IN GASING)	2	19.4	0	Harley Taylor	37002
		Set 13					
2-26-10	56	GAS VALVE check (IN GASING)	0	20.5	0	Harley Taylor	37002
		Set 14					
2-26-10	62	GAS VALVE check (IN GASING)	0	20.2	0	Harley Taylor	37002
		Set 15					
2-26-10	63	GAS VALVE check (IN GASING)	0	20.0	0	Harley Taylor	37002
		BAROMETER READING 29.6					

Signature

Rick Foster
Mine Foreman

2873
Certificate No.

Signature

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Feb. 27, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-27-10	5	GAS VALVE check (IN GASING)	0	20.8	0	Jay Stewart	39199
		Set 2					
2-27-10	10	GAS VALVE check (IN GASING)	3	4.2	0	Harley Taylor	37002
		Set 3					
2-27-10	13	GAS VALVE check (IN GASING)	0	20.8	0	Jay Stewart	39199
		Set 4					
2-27-10	21	GAS VALVE check (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 5					
2-27-10	26	GAS VALVE check (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 6					
2-27-10	33	GAS VALVE check (IN GASING)	6	5.1	0	Harley Taylor	37002
		Set 7					
2-27-10	38	GAS VALVE check (IN GASING)	1	16.3	0	Harley Taylor	37002
		Set 8					
2-27-10	43	GAS VALVE check (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 9					
2-27-10	44	GAS VALVE check (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 10					
2-27-10	47	GAS VALVE check (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 11					
2-27-10	50	GAS VALVE check (IN GASING)	0	18.6	0	Harley Taylor	37002
		Set 12					
2-27-10	53	GAS VALVE check (IN GASING)	2	19.8	0	Harley Taylor	37002
		Set 13					
2-27-10	56	GAS VALVE check (IN GASING)	1	19.8	0	Harley Taylor	37002
		Set 14					
2-27-10	62	GAS VALVE check (IN GASING)	1	17.6	0	Harley Taylor	37002
		Set 15					
2-27-10	63	GAS VALVE check (IN GASING)	0	20.1	0	Harley Taylor	37002
		BAROMETER Reading 29.6					

Signature Rick Foster
Mine Foreman

25232
Certificate No.

Signature _____
Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Feb. 28, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-28-10	5	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		Set 2					
2-28-10	10	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		Set 3					
2-28-10	13	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		Set 4					
2-28-10	21	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		Set 5					
2-28-10	26	GAS VALUE check (In Gassing)	0	20.8	0	Jay Stewart	39199
		Set 6					
2-28-10	33	GAS VALUE check (OUT GASING)	6.0	5.2	0	George Curry	27429
		Set 7					
2-28-10	38	GAS VALUE check (OUT GASING)	1.85	16.0	0	George Curry	27429
		Set 8					
2-28-10	43	GAS VALUE check (NO GASING)	0	19.5	0	George Curry	27429
		Set 9					
2-28-10	44	GAS VALUE check (NO GASING)	0	19.5	0	George Curry	27429
		Set 10					
2-28-10	47	GAS VALUE check (NO GASING)	0	19.8	0	George Curry	27429
		Set 11					
2-28-10	50	GAS VALUE check (OUT GASING)	0	17.7	0	George Curry	27429
		Set 12					
2-28-10	53	GAS VALUE check (OUT GASING)	1.53	18.4	0	George Curry	27429
		Set 13					
2-28-10	56	GAS VALUE check (NO GASING)	0	20.3	0	George Curry	27429
		Set 14					
2-28-10	62	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		Set 15					
2-28-10	63	GAS VALUE check (NO GASING)	0	20.7	0	George Curry	27429
		BAROMETER Reading 29.7					

Signature: _____

Mine Foreman

Certificate No.

Signature: _____

Superintendent

Rich Foster

28736

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 1, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-1-10	5	GAS VALVE check (In Gasms)	0	20.8	0	Jacy Stewart	39199
		Set 2					
3-1-10	10	GAS VALVE check	0	20.8	0	Jim Sawyer	32261
		Set 3					
3-1-10	13	GAS VALVE check	0	20.8	0	Jim Sawyer	32261
		Set 4					
3-1-10	21	GAS VALVE check (In Gasms)	0	20.8	0	Jacy Stewart	39199
		Set 5					
3-1-10	26	GAS VALVE check (In Gasms)	0	20.3	0	George Curry	27429
		Set 6					
3-1-10	33	GAS VALVE check (Out Gasms)	L.D	5.5	0	George Curry	27429
		Set 7					
3-1-10	38	GAS VALVE check (Out Gasms)	1.83	15.8	0	George Curry	27429
		Set 8					
3-1-10	43	GAS VALVE check (In Gasms)	0	19.6	0	George Curry	27429
		Set 9					
3-1-10	44	GAS VALVE check (In Gasms)	0	19.3	0	George Curry	27429
		Set 10					
3-1-10	47	GAS VALVE check (In Gasms)	0	19.9	0	George Curry	27429
		Set 11					
3-1-10	50	GAS VALVE check (Out Gasms)	0	18.2	0	George Curry	27429
		Set 12					
3-1-10	53	GAS VALVE check (Out Gasms)	.31	19.2	0	George Curry	27429
		Set 13					
3-1-10	56	GAS VALVE check (In Gasms)	0	20.3	0	George Curry	27429
		Set 14					
3-1-10	62	GAS VALVE check (In Gasms)	0	20.2	0	George Curry	27429
		Set 15					
3-1-10	63	GAS VALVE check (In Gasms)	0	20.2	0	George Curry	27429
		BAROMETER Reading					

Signature _____

Rich Zetter
Mine Foreman

28737
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 2, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-2-10	5	GAS VALVE check (IN GASING)	0.4	3.1	0	Harley Taylor	37002
		Set 2					
3-2-10	10	GAS VALVE check (IN GASING)	0.4	3.0	0	Harley Taylor	37002
		Set 3					
3-2-10	13	GAS VALVE check (IN GASING)	0	20.1	0	Harley Taylor	37002
		Set 4					
3-2-10	21	GAS VALVE check (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 5					
3-2-10	26	GAS VALVE check (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 6					
3-2-10	33	GAS VALVE check (OUT GASING)	6	5.4	0	Harley Taylor	37002
		Set 7					
3-2-10	38	GAS VALVE check (OUT GASING)	1	15.8	0	Harley Taylor	37002
		Set 8					
3-2-10	43	GAS VALVE check (OUT GASING)	0	19.5	0	Harley Taylor	37002
		Set 9					
3-2-10	44	GAS VALVE check (OUT GASING)	0	19.1	0	Harley Taylor	37002
		Set 10					
3-2-10	47	GAS VALVE check (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 11					
3-2-10	50	GAS VALVE check (OUT GASING)	0	18.6	0	Harley Taylor	37002
		Set 12					
3-2-10	53	GAS VALVE check (OUT GASING)	0.1	19.8	0	Harley Taylor	37002
		Set 13					
3-2-10	56	GAS VALVE check (OUT GASING)	0	20.2	0	Harley Taylor	37002
		Set 14					
3-2-10	62	GAS VALVE check (OUT GASING)	0.4	11.7	0	Harley Taylor	37002
		Set 15					
3-2-10	63	GAS VALVE check (OUT GASING)	0	20.0	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28224
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 3, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-3-10	5	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 2					
3-3-10	10	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 3					
3-3-10	13	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 4					
3-3-10	21	GAS VALVE check (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 5					
3-3-10	26	GAS VALVE check (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 6					
3-3-10	33	GAS VALVE check (IN GASING)	6	5.2	0	Harley Taylor	37002
		Set 7					
3-3-10	38	GAS VALVE check (IN GASING)	1	16.2	0	Harley Taylor	37002
		Set 8					
3-3-10	43	GAS VALVE check (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 9					
3-3-10	44	GAS VALVE check (IN GASING)	0	18.7	0	Harley Taylor	37002
		Set 10					
3-3-10	47	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 11					
3-3-10	50	GAS VALVE check (IN GASING)	0.1	15.3	0	Harley Taylor	37002
		Set 12					
3-3-10	53	GAS VALVE check (IN GASING)	1	16.7	0	Harley Taylor	37002
		Set 13					
3-3-10	56	GAS VALVE check (IN GASING)	0.1	18.9	0	Harley Taylor	37002
		Set 14					
3-3-10	62	GAS VALVE check (IN GASING)	0.4	11.7	0	Harley Taylor	37002
		Set 15					
3-3-10	63	GAS VALVE check (IN GASING)	0	20.1	0	Harley Taylor	37002
		Barometer Reading 29.7					

Signature _____

Rick Foster
Mine Foreman

28732

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 4, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-4-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 2					
3-4-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 3					
3-4-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 4					
3-4-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Boyer	32261
		Set 5					
3-4-10	26	GAS VALVE CHECK (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 6					
3-4-10	33	GAS VALVE CHECK (IN GASING)	6	4.9	0	Harley Taylor	37002
		Set 7					
3-4-10	38	GAS VALVE CHECK (IN GASING)	1	16.2	0	Harley Taylor	37002
		Set 8					
3-4-10	43	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 9					
3-4-10	44	GAS VALVE CHECK (IN GASING)	0.1	18.5	0	Harley Taylor	37002
		Set 10					
3-4-10	47	GAS VALVE CHECK (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 11					
3-4-10	50	GAS VALVE CHECK (IN GASING)	0	18.0	0	Harley Taylor	37002
		Set 12					
3-4-10	53	GAS VALVE CHECK (IN GASING)	1	17.5	0	Harley Taylor	37002
		Set 13					
3-4-10	56	GAS VALVE CHECK (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 14					
3-4-10	62	GAS VALVE CHECK (IN GASING)	0.1	18.0	0	Harley Taylor	37002
		Set 15					
3-4-10	63	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Rick Foster
Mine Foreman

28232
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 5, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-5-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jack Smart	39199
		Set 2					
2-5-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 3					
2-5-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jack Smart	39199
		Set 4					
2-5-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Beynon	32261
		Set 5					
2-5-10	26	GAS VALVE CHECK (IN GASING)	0	20.1	0	Harley Taylor	37002
		Set 6					
2-5-10	33	GAS VALVE CHECK (IN GASING)	6	4.9	0	Harley Taylor	37002
		Set 7					
2-5-10	38	GAS VALVE CHECK (IN GASING)	1	16.4	0	Harley Taylor	37002
		Set 8					
2-5-10	43	GAS VALVE CHECK (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 9					
2-5-10	44	GAS VALVE CHECK (IN GASING)	0	19.1	0	Harley Taylor	37002
		Set 10					
2-5-10	47	GAS VALVE CHECK (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 11					
2-5-10	50	GAS VALVE CHECK (IN GASING)	0	18.4	0	Harley Taylor	37002
		Set 12					
2-5-10	53	GAS VALVE CHECK (IN GASING)	2	19.3	0	Harley Taylor	37002
		Set 13					
2-5-10	56	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 14					
2-5-10	62	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 15					
2-5-10	63	GAS VALVE CHECK (IN GASING)	0	19.8	0	Harley Taylor	37002
		BAROMETER READING 30.1					

Signature _____

Mine Foreman

Rick Foster

Certificate No.

28736

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 6, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
2-6-10	5	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Bryan	32261
		Set 2					
2-6-10	10	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jacy Stewart	39199
		Set 3					
2-6-10	13	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jacy Stewart	39199
		Set 4					
2-6-10	21	GAS VALVE CHECK (IN GASING)	0	20.8	0	Jim Bryan	32261
		Set 5					
2-6-10	26	GAS VALVE CHECK (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 6					
2-6-10	33	GAS VALVE CHECK (IN GASING)	6	5.4	0	Harley Taylor	37002
		Set 7					
2-6-10	38	GAS VALVE CHECK (IN GASING)	1	17.2	0	Harley Taylor	37002
		Set 8					
2-6-10	43	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 9					
2-6-10	44	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 10					
2-6-10	47	GAS VALVE CHECK (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 11					
2-6-10	50	GAS VALVE CHECK (IN GASING)	0	18.8	0	Harley Taylor	37002
		Set 12					
2-6-10	53	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 13					
2-6-10	56	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 14					
2-6-10	62	GAS VALVE CHECK (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 15					
2-6-10	63	GAS VALVE CHECK (IN GASING)	0	20.1	0	Harley Taylor	37002
		BAROMETER READING 30.1					

Signature _____

Rick Jones
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 7, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-7-10	5	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 2					
3-7-10	10	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 3					
3-7-10	13	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 4					
3-7-10	21	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 5					
3-7-10	26	GAS VALVE CHECK (IN GASING)	0	20.1	0	George Curry	27429
		Set 6					
3-7-10	33	GAS VALVE CHECK (IN GASING)	4.32	8.8	0	George Curry	27429
		Set 7					
3-7-10	38	GAS VALVE CHECK (IN GASING)	1.5	17.8	0	George Curry	27429
		Set 8					
3-7-10	43	GAS VALVE CHECK (IN GASING)	0	19.7	0	George Curry	27429
		Set 9					
3-7-10	44	GAS VALVE CHECK (IN GASING)	0	19.2	0	George Curry	27429
		Set 10					
3-7-10	47	GAS VALVE CHECK (IN GASING)	0	20.1	0	George Curry	27429
		Set 11					
3-7-10	50	GAS VALVE CHECK (IN GASING)	0	19.0	0	George Curry	27429
		Set 12					
3-7-10	53	GAS VALVE CHECK (IN GASING)	0	20.7	0	George Curry	27429
		Set 13					
3-7-10	56	GAS VALVE CHECK (IN GASING)	0	20.3	0	George Curry	27429
		Set 14					
3-7-10	62	GAS VALVE CHECK (IN GASING)	0	20.1	0	George Curry	27429
		Set 15					
3-7-10	63	GAS VALVE CHECK (IN GASING)	0	20.4	0	George Curry	27429
		BAROMETER READING 30.0					

Signature _____

Rich Zetter
Mine Foreman

25736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 8, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-8-10	5	GAS VALVE CHECK (IN GASING)	1.0	3.5	0	Jim Boyer	32261
		Set 2					
3-8-10	10	GAS VALVE CHECK (IN GASING)	0	4.6	0	Jim Boyer	32261
		Set 3					
3-8-10	13	GAS VALVE CHECK (IN GASING)	0	20.5	0	Jim Boyer	32261
		Set 4					
3-8-10	21	GAS VALVE CHECK (IN GASING)	0	20.0	0	Jim Boyer	32261
		Set 5					
3-8-10	26	GAS VALVE CHECK (IN GASING)	0	20.3	0	George Curry	27429
		Set 6					
3-8-10	33	GAS VALVE CHECK (IN GASING)	5.0	6.8	0	George Curry	27429
		Set 7					
3-8-10	38	GAS VALVE CHECK (IN GASING)	0	19.5	0	George Curry	27429
		Set 8					
3-8-10	43	GAS VALVE CHECK (IN GASING)	0	19.3	0	George Curry	27429
		Set 9					
3-8-10	44	GAS VALVE CHECK (IN GASING)	0	19.0	0	George Curry	27429
		Set 10					
3-8-10	47	GAS VALVE CHECK (IN GASING)	0	20.0	0	George Curry	27429
		Set 11					
3-8-10	50	GAS VALVE CHECK (IN GASING)	0	18.6	0	George Curry	27429
		Set 12					
3-8-10	53	GAS VALVE CHECK (IN GASING)	0	20.0	0	George Curry	27429
		Set 13					
3-8-10	56	GAS VALVE CHECK (IN GASING)	0	20.2	0	George Curry	27429
		Set 14					
3-8-10	62	GAS VALVE CHECK (IN GASING)	0	20.1	0	George Curry	27429
		Set 15					
3-8-10	63	GAS VALVE CHECK (IN GASING)	0	20.0	0	George Curry	27429
		BAROMETER READING 29.9					

Signature _____

Rick Foster
Mine Foreman

25234
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 9, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-9-10	5	GAS VALVE CHECK (IN GASING)	0.3	3.5	0	Harley Taylor	37002
		Set 2					
3-9-10	10	GAS VALVE CHECK (IN GASING)	0.3	4.6	0	Harley Taylor	37002
		Set 3					
3-9-10	13	GAS VALVE CHECK (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 4					
3-9-10	21	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 5					
3-9-10	26	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 6					
3-9-10	33	GAS VALVE CHECK (OUT GASING)	6	5.4	0	Harley Taylor	37002
		Set 7					
3-9-10	38	GAS VALVE CHECK (OUT GASING)	1	17.6	0	Harley Taylor	37002
		Set 8					
3-9-10	43	GAS VALVE CHECK (OUT GASING)	0	19.4	0	Harley Taylor	37002
		Set 9					
3-9-10	44	GAS VALVE CHECK (OUT GASING)	0	19.1	0	Harley Taylor	37002
		Set 10					
3-9-10	47	GAS VALVE CHECK (OUT GASING)	0	19.6	0	Harley Taylor	37002
		Set 11					
3-9-10	50	GAS VALVE CHECK (OUT GASING)	0	17.4	0	Harley Taylor	37002
		Set 12					
3-9-10	53	GAS VALVE CHECK (OUT GASING)	0.3	18.7	0	Harley Taylor	37002
		Set 13					
3-9-10	56	GAS VALVE CHECK (OUT GASING)	0	19.8	0	Harley Taylor	37002
		Set 14					
3-9-10	62	GAS VALVE CHECK (OUT GASING)	0.1	18.1	0	Harley Taylor	37002
		Set 15					
3-9-10	63	GAS VALVE CHECK (OUT GASING)	0	20.0	0	Harley Taylor	37002
		BAROMETER READING 29.8					

Signature _____

Rich [Signature]
Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 10, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-10-10	5	GAS VALVE CHECK (IN GASING)	0	3.0	0	Jim Boyer	32261
		Set 2					
3-10-10	10	GAS VALVE CHECK (IN GASING)	0	3.7	0	Jim Boyer	32261
		Set 3					
3-10-10	13	GAS VALVE CHECK (IN GASING)	0	20.3	0	Jim Boyer	32261
		Set 4					
3-10-10	21	GAS VALVE CHECK (IN GASING)	0	20.6	0	Jim Boyer	32261
		Set 5					
3-10-10	26	GAS VALVE CHECK (IN GASING)	0	19.1	0	Harley Taylor	37002
		Set 6					
3-10-10	33	GAS VALVE CHECK (IN GASING)	6	4.9	0	Harley Taylor	37002
		Set 7					
3-10-10	38	GAS VALVE CHECK (IN GASING)	1	17.3	0	Harley Taylor	37002
		Set 8					
3-10-10	43	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 9					
3-10-10	44	GAS VALVE CHECK (IN GASING)	0	18.8	0	Harley Taylor	37002
		Set 10					
3-10-10	47	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 11					
3-10-10	50	GAS VALVE CHECK (IN GASING)	0	16.9	0	Harley Taylor	37002
		Set 12					
3-10-10	53	GAS VALVE CHECK (IN GASING)	1	17.7	0	Harley Taylor	37002
		Set 13					
3-10-10	56	GAS VALVE CHECK (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 14					
3-10-10	62	GAS VALVE CHECK (OUT GASING)	0.3	11.8	0	Harley Taylor	37002
		Set 15					
3-10-10	63	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28032
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 11, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-11-10	5	GAS VALVE CHECK (IN GASING)	0	2.8	0	Jim Sawyer	32261
		Set 2					
3-11-10	10	GAS VALVE CHECK (IN GASING)	0	3.9	0	Jim Sawyer	32261
		Set 3					
3-11-10	13	GAS VALVE CHECK (IN GASING)	0	20.1	0	Jim Sawyer	32261
		Set 4					
3-11-10	21	GAS VALVE CHECK (IN GASING)	0	20.7	0	Jim Sawyer	32261
		Set 5					
3-11-10	26	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 6					
3-11-10	33	GAS VALVE CHECK (OUT GASING)	6	4.4	0	Harley Taylor	37002
		Set 7					
3-11-10	38	GAS VALVE CHECK (OUT GASING)	1	16.8	0	Harley Taylor	37002
		Set 8					
3-11-10	43	GAS VALVE CHECK (OUT GASING)	0	19.3	0	Harley Taylor	37002
		Set 9					
3-11-10	44	GAS VALVE CHECK (IN GASING)	0	18.9	0	Harley Taylor	37002
		Set 10					
3-11-10	47	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 11					
3-11-10	50	GAS VALVE CHECK (IN GASING)	0	16.1	0	Harley Taylor	37002
		Set 12					
3-11-10	53	GAS VALVE CHECK (IN GASING)	1	16.9	0	Harley Taylor	37002
		Set 13					
3-11-10	56	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 14					
3-11-10	62	GAS VALVE CHECK (IN GASING)	1	16.3	0	Harley Taylor	37002
		Set 15					
3-11-10	63	GAS VALVE CHECK (IN GASING)	0	18.8	0	Harley Taylor	37002
		BAROMETER READING 29.6					

Signature _____

Rick Baker
Mine Foreman

28732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 12, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-12-10	5	GAS VALUE CHECK (In Gasing)	1	2.4	0	Jacy Stewart	39199
		Set 2					
3-12-10	10	GAS VALUE CHECK (In Gasing)	1	3.0	0	Jacy Stewart	39199
		Set 3					
3-12-10	13	GAS VALUE CHECK (In Gasing)	0	20.5	0	Jacy Stewart	39199
		Set 4					
3-12-10	21	GAS VALUE CHECK (In Gasing)	0	19.7	0	Jacy Stewart	39199
		Set 5					
3-12-10	26	GAS VALUE CHECK (In Gasing)	0	19.1	0	Harley Taylor	37002
		Set 6					
3-12-10	33	GAS VALUE CHECK (Out Gasing)	6	4.3	0	Harley Taylor	37002
		Set 7					
3-12-10	38	GAS VALUE CHECK (Out Gasing)	1	16.4	0	Harley Taylor	37002
		Set 8					
3-12-10	43	GAS VALUE CHECK (Out Gasing)	0	19.2	0	Harley Taylor	37002
		Set 9					
3-12-10	44	GAS VALUE CHECK (Out Gasing)	0	18.9	0	Harley Taylor	37002
		Set 10					
3-12-10	47	GAS VALUE CHECK (Out Gasing)	0	19.2	0	Harley Taylor	37002
		Set 11					
3-12-10	50	GAS VALUE CHECK (Out Gasing)	0.1	16.4	0	Harley Taylor	37002
		Set 12					
3-12-10	53	GAS VALUE CHECK (Out Gasing)	1	17.2	0	Harley Taylor	37002
		Set 13					
3-12-10	56	GAS VALUE CHECK (Out Gasing)	0	19.3	0	Harley Taylor	37002
		Set 14					
3-12-10	62	GAS VALUE CHECK (Out Gasing)	0	18.3	0	Harley Taylor	37002
		Set 15					
3-12-10	63	GAS VALUE CHECK (Out Gasing)	0	19.0	0	Harley Taylor	37002
		BAROMETER READING 29.5					

Signature _____

Rick Foster
Mine Foreman

2874
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 13, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-13-10	5	GAS VALVE check (IN GASING)	0	10.3	0	George Curry	27429
		Set 2					
3-13-10	10	GAS VALVE check (IN GASING)	0	19.1	0	George Curry	27429
		Set 3					
3-13-10	13	GAS VALVE check (IN GASING)	0	20.3	0	George Curry	27429
		Set 4					
3-13-10	21	GAS VALVE check (IN GASING)	0	20.1	0	George Curry	27429
		Set 5					
3-13-10	26	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 6					
3-13-10	33	GAS VALVE check (OUT GASING)	6	4.1	0	Harley Taylor	37002
		Set 7					
3-13-10	38	GAS VALVE check (OUT GASING)	1	16.5	0	Harley Taylor	37002
		Set 8					
3-13-10	43	GAS VALVE check (OUT GASING)	0	19.3	0	Harley Taylor	37002
		Set 9					
3-13-10	44	GAS VALVE check (OUT GASING)	0	18.7	0	Harley Taylor	37002
		Set 10					
3-13-10	47	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 11					
3-13-10	50	GAS VALVE check (OUT GASING)	0	14.9	0	Harley Taylor	37002
		Set 12					
3-13-10	53	GAS VALVE check (OUT GASING)	4	5.3	0	Harley Taylor	37002
		Set 13					
3-13-10	56	GAS VALVE check (OUT GASING)	0	15.5	0	Harley Taylor	37002
		Set 14					
3-13-10	62	GAS VALVE check (OUT GASING)	1	9.7	0	Harley Taylor	37002
		Set 15					
3-13-10	63	GAS VALVE check (OUT GASING)	0	19.3	0	Harley Taylor	37002
		BAROMETER Reading 29.3					

Signature _____

Rick Foster
Mine Foreman

25736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 14, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-14-10	5	GAS VALVE CHECK (IN GASING)	.27	4.4	0	George Curry	27429
		Set 2					
3-14-10	10	GAS VALVE CHECK (IN GASING)	.22	4.8	0	George Curry	27429
		Set 3					
3-14-10	13	GAS VALVE CHECK (IN GASING)	0	19.9	0	George Curry	27429
		Set 4					
3-14-10	21	GAS VALVE CHECK (IN GASING)	0	19.7	0	George Curry	27429
		Set 5					
3-14-10	26	GAS VALVE CHECK (IN GASING)	0	20.6	0	George Curry	27429
		Set 6					
3-14-10	33	GAS VALVE CHECK (IN GASING)	6.0	6.7	0	George Curry	27429
		Set 7					
3-14-10	38	GAS VALVE CHECK (IN GASING)	1.82	15.9	0	George Curry	27429
		Set 8					
3-14-10	43	GAS VALVE CHECK (IN GASING)	0	17.9	0	George Curry	27429
		Set 9					
3-14-10	44	GAS VALVE CHECK (IN GASING)	0	17.2	0	George Curry	27429
		Set 10					
3-14-10	47	GAS VALVE CHECK (IN GASING)	0	18.9	0	George Curry	27429
		Set 11					
3-14-10	50	GAS VALVE CHECK (IN GASING)	0	13.0	0	George Curry	27429
		Set 12					
3-14-10	53	GAS VALVE CHECK (OUT GASING)	4.0	5.9	0	George Curry	27429
		Set 13					
3-14-10	56	GAS VALVE CHECK (OUT GASING)	0	15.6	0	George Curry	27429
		Set 14					
3-14-10	62	GAS VALVE CHECK (OUT GASING)	1.47	10.5	0	George Curry	27429
		Set 15					
3-14-10	63	GAS VALVE CHECK (OUT GASING)	1.23	16.8	0	George Curry	27429
		BAROMETER READING 29.9					

Signature _____

Rick Foster
Mine Foreman

28236
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 15, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-15-10	5	GAS VALVE CHECK (IN GASING)	0	3.5	0	Jacy Stewart	39199
		Set 2					
3-15-10	10	GAS VALVE CHECK (IN GASING)	0	4.9	0	Jacy Stewart	39199
		Set 3					
3-15-10	13	GAS VALVE CHECK (IN GASING)	0	20.1	0	Jacy Stewart	39199
		Set 4					
3-15-10	21	GAS VALVE CHECK (IN GASING)	0	19.7	0	Jacy Stewart	39199
		Set 5					
3-15-10	26	GAS VALVE CHECK (IN GASING)	0	20.5	0	George Curry	27429
		Set 6					
3-15-10	33	GAS VALVE CHECK (OUT GASING)	7.0	3.8	0	George Curry	27429
		Set 7					
3-15-10	38	GAS VALVE CHECK (OUT GASING)	1.9	14.6	0	George Curry	27429
		Set 8					
3-15-10	43	GAS VALVE CHECK (OUT GASING)	0	19.0	0	George Curry	27429
		Set 9					
3-15-10	44	GAS VALVE CHECK (IN GASING)	0	17.9	0	George Curry	27429
		Set 10					
3-15-10	47	GAS VALVE CHECK (IN GASING)	0	19.3	0	George Curry	27429
		Set 11					
3-15-10	50	GAS VALVE CHECK (IN GASING)	0	14.0	0	George Curry	27429
		Set 12					
3-15-10	53	GAS VALVE CHECK (IN GASING)	1.74	11.4	0	George Curry	27429
		Set 13					
3-15-10	56	GAS VALVE CHECK (IN GASING)	0	17.1	0	George Curry	27429
		Set 14					
3-15-10	62	GAS VALVE CHECK (IN GASING)	.14	16.3	0	George Curry	27429
		Set 15					
3-15-10	63	GAS VALVE CHECK (IN GASING)	.18	17.1	0	George Curry	27429
		BAROMETER READING	29.8				

Signature _____

Rick Foster
Mine Foreman

24736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 16, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-16-10	5	GAS VALVE CHECK (IN GASING)	0.1	4.1	0	Harley Taylor	37002
		Set 2					
3-16-10	10	GAS VALVE CHECK (IN GASING)	0.2	5.3	0	Harley Taylor	37002
		Set 3					
3-16-10	13	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 4					
3-16-10	21	GAS VALVE CHECK (IN GASING)	0.2	19.4	0	Harley Taylor	37002
		Set 5					
3-16-10	26	GAS VALVE CHECK (IN GASING)	0.2	19.6	0	Harley Taylor	37002
		Set 6					
3-16-10	33	GAS VALVE CHECK (IN GASING)	6	5.5	0	Harley Taylor	37002
		Set 7					
3-16-10	35	GAS VALVE CHECK (IN GASING)	1	15.1	0	Harley Taylor	37002
		Set 8					
3-16-10	43	GAS VALVE CHECK (IN GASING)	0.2	19.7	0	Harley Taylor	37002
		Set 9					
3-16-10	44	GAS VALVE CHECK (IN GASING)	0.1	18.9	0	Harley Taylor	37002
		Set 10					
3-16-10	47	GAS VALVE CHECK (IN GASING)	0.2	19.9	0	Harley Taylor	37002
		Set 11					
3-16-10	50	GAS VALVE CHECK (IN GASING)	0.1	16.6	0	Harley Taylor	37002
		Set 12					
3-16-10	53	GAS VALVE CHECK (IN GASING)	1	16.9	0	Harley Taylor	37002
		Set 13					
3-16-10	56	GAS VALVE CHECK (IN GASING)	0.1	19.5	0	Harley Taylor	37002
		Set 14					
3-16-10	62	GAS VALVE CHECK (IN GASING)	0	17.0	0	Harley Taylor	37002
		Set 15					
3-16-10	63	GAS VALVE CHECK (IN GASING)	0	19.0	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Mine Foreman

Rick Foster 2873L

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 17, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-17-10	5	GAS VALVE CHECK (IN GASING)	0	4.0	0	Jim Boyer	32261
		Set 2					
3-17-10	10	GAS VALVE CHECK (IN GASING)	1%	4.3	0%	Jim Boyer	32261
		Set 3					
3-17-10	13	GAS VALVE CHECK (IN GASING)	0	20.6	0	Jim Boyer	32261
		Set 4					
3-17-10	21	GAS VALVE CHECK (IN GASING)	0	19.7	0	Jim Boyer	32261
		Set 5					
3-17-10	26	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 6					
3-17-10	33	GAS VALVE CHECK (IN GASING)	6	5.7	0	Harley Taylor	37002
		Set 7					
3-17-10	38	GAS VALVE CHECK (OUT GASING)	1	15.8	0	Harley Taylor	37002
		Set 8					
3-17-10	43	GAS VALVE CHECK (OUT GASING)	2	19.9	0	Harley Taylor	37002
		Set 9					
3-17-10	44	GAS VALVE CHECK (OUT GASING)	2	19.4	0	Harley Taylor	37002
		Set 10					
3-17-10	47	GAS VALVE CHECK (OUT GASING)	2	20.2	0	Harley Taylor	37002
		Set 11					
3-17-10	50	GAS VALVE CHECK (OUT GASING)	2	19.1	0	Harley Taylor	37002
		Set 12					
3-17-10	53	GAS VALVE CHECK (OUT GASING)	0	19.2	0	Harley Taylor	37002
		Set 13					
3-17-10	56	GAS VALVE CHECK (OUT GASING)	2	20.2	0	Harley Taylor	37002
		Set 14					
3-17-10	62	GAS VALVE CHECK (OUT GASING)	2	19.6	0	Harley Taylor	37002
		Set 15					
3-17-10	63	GAS VALVE CHECK (OUT GASING)	2	20.1	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature Rick Pata Mine Foreman Certificate No. 28732 Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 18, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-18-10	5	GAS VALVE CHECK (IN GASING)	0	3.8	0	Jim Boyer	32261
		Set 2					
3-18-10	10	GAS VALVE CHECK (IN GASING)	1	4.1	0	Jim Boyer	32261
		Set 3					
3-18-10	13	GAS VALVE CHECK (IN GASING)	0	20.4	0	Jim Boyer	32261
		Set 4					
3-18-10	21	GAS VALVE CHECK (IN GASING)	0	19.6	0	Jim Boyer	32261
		Set 5					
3-18-10	26	GAS VALVE CHECK (IN GASING)	1	19.5	0	Harley Taylor	37002
		Set 6					
3-18-10	33	GAS VALVE CHECK (OUT GASING)	6	5.3	0	Harley Taylor	37002
		Set 7					
3-18-10	38	GAS VALVE CHECK (OUT GASING)	1	6.5	0	Harley Taylor	37002
		Set 8					
3-18-10	43	GAS VALVE CHECK (IN GASING)	1	20.0	0	Harley Taylor	37002
		Set 9					
3-18-10	44	GAS VALVE CHECK (IN GASING)	1	19.1	0	Harley Taylor	37002
		Set 10					
3-18-10	47	GAS VALVE CHECK (IN GASING)	1	20.1	0	Harley Taylor	37002
		Set 11					
3-18-10	50	GAS VALVE CHECK (IN GASING)	1	18.3	0	Harley Taylor	37002
		Set 12					
3-18-10	53	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 13					
3-18-10	56	GAS VALVE CHECK (IN GASING)	2	20.2	0	Harley Taylor	37002
		Set 14					
3-18-10	62	GAS VALVE CHECK (IN GASING)	2	18.5	0	Harley Taylor	37002
		Set 15					
3-18-10	63	GAS VALVE CHECK (IN GASING)	2	20.1	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rick Foster
Mine Foreman

28734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 19, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-19-10	5	GAS VALVE check (IN GASING)	0	3.9	0	Jim Boyer	32261
		Set 2					
3-19-10	10	GAS VALVE check (IN GASING)	1	4.7	0	Jack Stuart	39199
		Set 3					
3-19-10	13	GAS VALVE check (IN GASING)	0	20.3	0	Jack Stuart	39199
		Set 4					
3-19-10	21	GAS VALVE check (IN GASING)	0	19.6	0	Jack Stuart	39199
		Set 5					
3-19-10	26	GAS VALVE check (IN GASING)	2	19.3	0	Harley Taylor	37002
		Set 6					
3-19-10	33	GAS VALVE check (IN GASING)	6	4.7	0	Harley Taylor	37002
		Set 7					
3-19-10	38	GAS VALVE check (IN GASING)	1	16.3	0	Harley Taylor	37002
		Set 8					
3-19-10	43	GAS VALVE check (IN GASING)	1	19.9	0	Harley Taylor	37002
		Set 9					
3-19-10	44	GAS VALVE check (IN GASING)	1	19.5	0	Harley Taylor	37002
		Set 10					
3-19-10	47	GAS VALVE check (IN GASING)	1	19.9	0	Harley Taylor	37002
		Set 11					
3-19-10	50	GAS VALVE check (IN GASING)	1	18.1	0	Harley Taylor	37002
		Set 12					
3-19-10	53	GAS VALVE check (IN GASING)	0	19.7	0	Harley Taylor	37002
		Set 13					
3-19-10	56	GAS VALVE check (IN GASING)	1	20.0	0	Harley Taylor	37002
		Set 14					
3-19-10	62	GAS VALVE check (IN GASING)	1	19.1	0	Harley Taylor	37002
		Set 15					
3-19-10	63	GAS VALVE check (IN GASING)	2	20.3	0	Harley Taylor	37002
		BAROMETER Reading 29.9					

Signature _____

Mine Foreman

Rick Foster 2873C

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 20, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-20-10	5	GAS VALVE check (NO GASING)	0	21.6	0	George Curry	27429
		Set 2					
3-20-10	10	GAS VALVE check (NO GASING)	0	21.8	0	George Curry	27429
		Set 3					
3-20-10	13	GAS VALVE check (NO GASING)	0	20.5	0	George Curry	27429
		Set 4					
3-20-10	21	GAS VALVE check (NO GASING)	0	19.6	0	George Curry	27429
		Set 5					
3-20-10	26	GAS VALVE check (IN GASING)	.2	19.4	0	Harley Taylor	37002
		Set 6					
3-20-10	33	GAS VALVE check (IN GASING)	.6	4.7	0	Harley Taylor	37002
		Set 7					
3-20-10	38	GAS VALVE check (IN GASING)	.1	16.5	0	Harley Taylor	37002
		Set 8					
3-20-10	43	GAS VALVE check (IN GASING)	.1	19.8	0	Harley Taylor	37002
		Set 9					
3-20-10	44	GAS VALVE check (IN GASING)	.1	19.9	0	Harley Taylor	37002
		Set 10					
3-20-10	47	GAS VALVE check (IN GASING)	.2	20.0	0	Harley Taylor	37002
		Set 11					
3-20-10	50	GAS VALVE check (IN GASING)	.2	18.4	0	Harley Taylor	37002
		Set 12					
3-20-10	53	GAS VALVE check (NO GASING)	0	20.4	0	George Curry	27429
		Set 13					
3-20-10	56	GAS VALVE check (NO GASING)	0	20.8	0	George Curry	27429
		Set 14					
3-20-10	62	GAS VALVE check (NO GASING)	0	20.3	0	George Curry	27429
		Set 15					
3-20-10	63	GAS VALVE check (NO GASING)	0	20.4	0	George Curry	27429
		BAROMETER Reading 29.9					

Signature _____

Rick Zetter
Mine Foreman

25231

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 21, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-21-10	5	GAS VALVE CHECK (TWO GASINGS)	.12	4.2	0	George Curry	27429
		Set 2					
3-21-10	10	GAS VALVE CHECK (TWO GASINGS)	.22	4.8	0	George Curry	27429
		Set 3					
3-21-10	13	GAS VALVE CHECK (TWO GASINGS)	0	19.9	0	George Curry	27429
		Set 4					
3-21-10	21	GAS VALVE CHECK (TWO GASINGS)	0	19.3	0	George Curry	27429
		Set 5					
3-21-10	26	GAS VALVE CHECK (TWO GASINGS)	0	19.6	0	George Curry	27429
		Set 6					
3-21-10	33	GAS VALVE CHECK (TWO GASINGS)	6.2	5.1	0	George Curry	27429
		Set 7					
3-21-10	38	GAS VALVE CHECK (TWO GASINGS)	1.57	16.7	0	George Curry	27429
		Set 8					
3-21-10	43	GAS VALVE CHECK (TWO GASINGS)	.1	19.7	0	George Curry	27429
		Set 9					
3-21-10	44	GAS VALVE CHECK (TWO GASINGS)	0	19.7	0	George Curry	27429
		Set 10					
3-21-10	47	GAS VALVE CHECK (TWO GASINGS)	0	20.1	0	George Curry	27429
		Set 11					
3-21-10	50	GAS VALVE CHECK (TWO GASINGS)	.1	19.5	0	George Curry	27429
		Set 12					
3-21-10	53	GAS VALVE CHECK (TWO GASINGS)	0	20.3	0	George Curry	27429
		Set 13					
3-21-10	56	GAS VALVE CHECK (TWO GASINGS)	0	20.5	0	George Curry	27429
		Set 14					
3-21-10	62	GAS VALVE CHECK (TWO GASINGS)	0	20.4	0	George Curry	27429
		Set 15					
3-21-10	63	GAS VALVE CHECK (TWO GASINGS)	0	20.1	0	George Curry	27429
		BAROMETER READING 29.8					

Signature _____

Rick Foster
Mine Foreman

29732
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 22, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-22-10	5	GAS VALVE check (I/O GASING)	0	21.7	0	George Curry	27429
		Set 2					
3-22-10	10	GAS VALVE check (I/O GASING)	0	3.5	0	George Curry	27429
		Set 3					
3-22-10	13	GAS VALVE check (I/O GASING)	0	20.1	0	Jay Stewart	39199
		Set 4					
3-22-10	21	GAS VALVE check (I/O GASING)	0	19.4	0	George Curry	27429
		Set 5					
3-22-10	26	GAS VALVE check (I/O GASING)	0	19.6	0	George Curry	27429
		Set 6					
3-22-10	33	GAS VALVE check (O/LT GASING)	6.0	16.7	0	George Curry	27429
		Set 7					
3-22-10	38	GAS VALVE check (O/LT GASING)	1.0	16.8	0	George Curry	27429
		Set 8					
3-22-10	43	GAS VALVE check (I/O GASING)	0	20.0	0	George Curry	27429
		Set 9					
3-22-10	44	GAS VALVE check (I/O GASING)	0	19.6	0	George Curry	27429
		Set 10					
3-22-10	47	GAS VALVE check (I/O GASING)	0	20.5	0	George Curry	27429
		Set 11					
3-22-10	50	GAS VALVE check (I/O GASING)	0	18.7	0	George Curry	27429
		Set 12					
3-22-10	53	GAS VALVE check (I/O GASING)	0	20.3	0	George Curry	27429
		Set 13					
3-22-10	56	GAS VALVE check (I/O GASING)	0	19.4	0	George Curry	27429
		Set 14					
3-22-10	62	GAS VALVE check (I/O GASING)	0	19.8	0	George Curry	27429
		Set 15					
3-22-10	63	GAS VALVE check (I/O GASING)	0	20.5	0	George Curry	27429
		BAROMETER READING 29.21					

Signature _____

Rick Foster
Mine Foreman

22731

Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 23, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-23-10	5	GAS VALVE check (IN GASING)	0.1	3.3	0	Harley Taylor	37002
		Set 2					
3-23-10	10	GAS VALVE check (IN GASING)	0.1	4.5	0	Harley Taylor	37002
		Set 3					
3-23-10	13	GAS VALVE check (IN GASING)	0.2	19.8	0	Harley Taylor	37002
		Set 4					
3-23-10	21	GAS VALVE check (IN GASING)	0.2	18.9	0	Harley Taylor	37002
		Set 5					
3-23-10	26	GAS VALVE check (IN GASING)	0.2	19.1	0	Harley Taylor	37002
		Set 6					
3-23-10	33	GAS VALVE check (IN GASING)	6	4.6	0	Harley Taylor	37002
		Set 7					
3-23-10	38	GAS VALVE check (IN GASING)	0.2	20.2	0	Harley Taylor	37002
		Set 8					
3-23-10	43	GAS VALVE check (IN GASING)	0.2	19.3	0	Harley Taylor	37002
		Set 9					
3-23-10	44	GAS VALVE check (IN GASING)	0.1	18.7	0	Harley Taylor	37002
		Set 10					
3-23-10	47	GAS VALVE check (IN GASING)	0.2	19.2	0	Harley Taylor	37002
		Set 11					
3-23-10	50	GAS VALVE check (IN GASING)	0.2	20.3	0	Harley Taylor	37002
		Set 12					
3-23-10	53	GAS VALVE check (IN GASING)	2	13.2	0	Harley Taylor	37002
		Set 13					
3-23-10	56	GAS VALVE check (IN GASING)	0.1	18.8	0	Harley Taylor	37002
		Set 14					
3-23-10	62	GAS VALVE check (IN GASING)	0	16.3	0	Harley Taylor	37002
		Set 15					
3-23-10	63	GAS VALVE check (IN GASING)	0	18.5	0	Harley Taylor	37002
		BAROMETER READING 29.7					

Signature _____

Rock Zito
Mine Foreman

28724
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 24, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-24-10	5	GAS VALVE check (In Gasing)	0	3.9	0	Jacq Stewart	39199
		Set 2					
3-24-10	10	GAS VALVE check (In Gasing)	0	5.5	0	Jacq Stewart	39199
		Set 3					
3-24-10	13	GAS VALVE check (In Gasing)	0	20.1	0	Jacq Stewart	39199
		Set 4					
3-24-10	21	GAS VALVE check (In Gasing)	0	19.4	0	Jacq Stewart	39199
		Set 5					
3-24-10	26	GAS VALVE check (IN GASING)	0.2	18.9	0	Harley Taylor	37002
		Set 6					
3-24-10	33	GAS VALVE check (IN GASING)	0.6	4.4	0	Harley Taylor	37002
		Set 7					
3-24-10	38	GAS VALVE check (IN GASING)	1	16.2	0	Harley Taylor	37002
		Set 8					
3-24-10	43	GAS VALVE check (IN GASING)	0.2	19.6	0	Harley Taylor	37002
		Set 9					
3-24-10	44	GAS VALVE check (IN GASING)	0.2	19.1	0	Harley Taylor	37002
		Set 10					
3-24-10	47	GAS VALVE check (IN GASING)	0.2	19.2	0	Harley Taylor	37002
		Set 11					
3-24-10	50	GAS VALVE check (IN GASING)	0.2	19.0	0	Harley Taylor	37002
		Set 12					
3-24-10	53	GAS VALVE check (IN GASING)	1	18.2	0	Harley Taylor	37002
		Set 13					
3-24-10	56	GAS VALVE check (IN GASING)	0.1	19.1	0	Harley Taylor	37002
		Set 14					
3-24-10	62	GAS VALVE check (IN GASING)	0.1	19.1	0	Harley Taylor	37002
		Set 15					
3-24-10	63	GAS VALVE check (IN GASING)	0.2	20.4	0	Harley Taylor	37002
		BAROMETER Reading 29.9					

Signature _____

Mine Foreman

Rick Foster

Certificate No.

29734

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 26, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-26-10	5	GAS VALVE CHECK (IN GASING)	0	4.9	0	Joey Stewart	39199
		Set 2					
3-26-10	10	GAS VALVE CHECK (IN GASING)	0	5.1	0	Joey Stewart	39199
		Set 3					
3-26-10	13	GAS VALVE CHECK (IN GASING)	0	20.4	0	Joey Stewart	39199
		Set 4					
3-26-10	21	GAS VALVE CHECK (IN GASING)	0	19.7	0	Joey Stewart	39199
		Set 5					
3-26-10	26	GAS VALVE CHECK (IN GASING)	0.2	19.0	0	Harley Taylor	37002
		Set 6					
3-26-10	33	GAS VALVE CHECK (IN GASING)	6	5.3	0	Harley Taylor	37002
		Set 7					
3-26-10	38	GAS VALVE CHECK (IN GASING)	0.1	18.6	0	Harley Taylor	37002
		Set 8					
3-26-10	43	GAS VALVE CHECK (IN GASING)	0.2	18.9	0	Harley Taylor	37002
		Set 9					
3-26-10	44	GAS VALVE CHECK (IN GASING)	0.1	18.5	0	Harley Taylor	37002
		Set 10					
3-26-10	47	GAS VALVE CHECK (IN GASING)	0.2	20.1	0	Harley Taylor	37002
		Set 11					
3-26-10	50	GAS VALVE CHECK (IN GASING)	0.2	18.4	0	Harley Taylor	37002
		Set 12					
3-26-10	53	GAS VALVE CHECK (IN GASING)	1	17.8	0	Harley Taylor	37002
		Set 13					
3-26-10	56	GAS VALVE CHECK (IN GASING)	0.2	20.1	0	Harley Taylor	37002
		Set 14					
3-26-10	62	GAS VALVE CHECK (IN GASING)	0.1	18.3	0	Harley Taylor	37002
		Set 15					
3-26-10	63	GAS VALVE CHECK (IN GASING)	0	17.8	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Rick Zota
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 27, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-27-10	5	GAS VALVE CHECK (IN GASING)	.3%	20.1%	0%	<i>Jim Wilton</i>	1659-A
		Set 2					
3-27-10	10	GAS VALVE CHECK (IN GASING)	.3%	20.1%	0%	<i>Jim Wilton</i>	1659-A
		Set 3					
3-27-10	13	GAS VALVE CHECK (IN GASING)	.3%	19.9%	0%	<i>Jim Wilton</i>	1659-A
		Set 4					
3-27-10	21	GAS VALVE CHECK (IN GASING)	.3%	20.0%	0%	<i>Jim Wilton</i>	1659-A
		Set 5					
3-27-10	26	GAS VALVE CHECK (IN GASING)	.3%	19.4%	0%	<i>Jim Wilton</i>	1659-A
		Set 6					
3-27-10	33	GAS VALVE CHECK (IN GASING)	.6%	19.9%	0%	<i>Jim Wilton</i>	1659-A
		Set 7					
3-27-10	38	GAS VALVE CHECK (IN GASING)	1%	17.8%	0%	<i>Jim Wilton</i>	1659-A
		Set 8					
3-27-10	43	GAS VALVE CHECK (IN GASING)	.2%	19.4%	0%	<i>Jim Wilton</i>	1659-A
		Set 9					
3-27-10	44	GAS VALVE CHECK (IN GASING)	.2%	19.1%	0%	<i>Jim Wilton</i>	1659-A
		Set 10					
3-27-10	47	GAS VALVE CHECK (IN GASING)	.3%	20.0%	0%	<i>Jim Wilton</i>	1659-A
		Set 11					
3-27-10	50	GAS VALVE CHECK (IN GASING)	.2%	17.9%	0%	<i>Jim Wilton</i>	1659-A
		Set 12					
3-27-10	53	GAS VALVE CHECK (IN GASING)	.4%	18.1%	0%	<i>Jim Wilton</i>	1659-A
		Set 13					
3-27-10	56	GAS VALVE CHECK (IN GASING)	.2%	20.3%	0%	<i>Jim Wilton</i>	1659-A
		Set 14					
3-27-10	62	GAS VALVE CHECK (IN GASING)	.1%	18.5%	0%	<i>Jim Wilton</i>	1659-A
		Set 15					
3-27-10	63	GAS VALVE CHECK (IN GASING)	0%	18.5%	0%	<i>Jim Wilton</i>	1659-A
		BAROMETER READING 30.0%					

Signature _____

Rick Pata
Mine Foreman

28736
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 28, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-28-10	5	GAS VALUE check (IN GASING)	0%	38%	0%	Jim Williams	1659-A
		Set 2					
3-28-10	10	GAS VALUE check (IN GASING)	.2%	27%	0%	Jim Williams	1659-A
		Set 3					
3-28-10	13	GAS VALUE check (IN GASING)	.2%	19.1%	0%	Jim Williams	1659-A
		Set 4					
3-28-10	21	GAS VALUE check (IN GASING)	.2	18.8%	0%	Jim Williams	1659-A
		Set 5					
3-28-10	26	GAS VALUE check (OUT GASING)	0	19.6	0	George Curry	27429
		Set 6					
3-28-10	33	GAS VALUE check (OUT GASING)	5.0	16.1	0	George Curry	27429
		Set 7					
3-28-10	38	GAS VALUE check (OUT GASING)	1.0	16.4	0	George Curry	27429
		Set 8					
3-28-10	43	GAS VALUE check (OUT GASING)	0	20.3	0	George Curry	27429
		Set 9					
3-28-10	44	GAS VALUE check (OUT GASING)	0	19.8	0	George Curry	27429
		Set 10					
3-28-10	47	GAS VALUE check (OUT GASING)	0	20.6	0	George Curry	27429
		Set 11					
3-28-10	50	GAS VALUE check (OUT GASING)	0	18.9	0	George Curry	27429
		Set 12					
3-28-10	53	GAS VALUE check (OUT GASING)	0	19.1	0	George Curry	27429
		Set 13					
3-28-10	56	GAS VALUE check (OUT GASING)	0	20.8	0	George Curry	27429
		Set 14					
3-28-10	62	GAS VALUE check (OUT GASING)	0	19.7	0	George Curry	27429
		Set 15					
3-28-10	63	GAS VALUE check (OUT GASING)	0	19.5	0	George Curry	27429
		BAROMETER READING 29.6					

Signature _____

Beck Foster
Mine Foreman

2873
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 29, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-29-10	5	GAS VALVE CHECK (IN GASING)	0	0	2.9	Joey Stewart	39199
		Set 2					
3-29-10	10	GAS VALVE CHECK (IN GASING)	1	0	3.9	Joey Stewart	39199
		Set 3					
3-29-10	13	GAS VALVE CHECK (IN GASING)	0	0	19.9	Joey Stewart	39199
		Set 4					
3-29-10	21	GAS VALVE CHECK (IN GASING)	0	0	19.4	Joey Stewart	39199
		Set 5					
3-29-10	26	GAS VALVE CHECK (TO GASING)	0	18.8	0	George Curry	27429
		Set 6					
3-29-10	33	GAS VALVE CHECK (TO GASING)	0	5.2	0	George Curry	27429
		Set 7					
3-29-10	38	GAS VALVE CHECK (TO GASING)	1.39	16.5	0	George Curry	27429
		Set 8					
3-29-10	43	GAS VALVE CHECK (TO GASING)	0	18.6	0	George Curry	27429
		Set 9					
3-29-10	44	GAS VALVE CHECK (TO GASING)	0	17.8	0	George Curry	27429
		Set 10					
3-29-10	47	GAS VALVE CHECK (TO GASING)	0	18.5	0	George Curry	27429
		Set 11					
3-29-10	50	GAS VALVE CHECK (TO GASING)	0	18.9	0	George Curry	27429
		Set 12					
3-29-10	53	GAS VALVE CHECK (TO GASING)	1.28	18.0	0	George Curry	27429
		Set 13					
3-29-10	56	GAS VALVE CHECK (TO GASING)	0	18.9	0	George Curry	27429
		Set 14					
3-29-10	62	GAS VALVE CHECK (TO GASING)	0	14.6	0	George Curry	27429
		Set 15					
3-29-10	63	GAS VALVE CHECK (TO GASING)	0	19.0	0	George Curry	27429
		BAROMETER READING 29.5					

Signature _____

Mine Foreman

Certificate No. 25736

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

MAR. 30, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-30-10	5	GAS VALVE CHECK (IN GASING)	0	4.1	0	Harley Taylor	37002
		Set 2					
3-30-10	10	GAS VALVE CHECK (IN GASING)	1	4.6	0	Harley Taylor	37002
		Set 3					
3-30-10	13	GAS VALVE CHECK (IN GASING)	2	19.4	0	Harley Taylor	37002
		Set 4					
3-30-10	21	GAS VALVE CHECK (IN GASING)	2	18.3	0	Harley Taylor	37002
		Set 5					
3-30-10	26	GAS VALVE CHECK (IN GASING)	2	18.9	0	Harley Taylor	37002
		Set 6					
3-30-10	33	GAS VALVE CHECK (IN GASING)	6	5.0	0	Harley Taylor	37002
		Set 7					
3-30-10	38	GAS VALVE CHECK (IN GASING)	1	18.2	0	Harley Taylor	37002
		Set 8					
3-30-10	43	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 9					
3-30-10	44	GAS VALVE CHECK (IN GASING)	0	18.3	0	Harley Taylor	37002
		Set 10					
3-30-10	47	GAS VALVE CHECK (IN GASING)	0	19.5	0	Harley Taylor	37002
		Set 11					
3-30-10	50	GAS VALVE CHECK (IN GASING)	0	20.6	0	Harley Taylor	37002
		Set 12					
3-30-10	53	GAS VALVE CHECK (IN GASING)	1	17.2	0	Harley Taylor	37002
		Set 13					
3-30-10	56	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 14					
3-30-10	62	GAS VALVE CHECK (IN GASING)	0	18.3	0	Harley Taylor	37002
		Set 15					
3-30-10	63	GAS VALVE CHECK (IN GASING)	0	18.6	0	Harley Taylor	37002
		BAROMETER READING 29.8					

Signature _____

Mine Foreman

Rick Zota

28734
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

MAR. 31, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
3-31-10	5	GAS VALVE CHECK (IN GASING)	0	4.4	0	Jim Bayner	32261
		Set 2					
3-31-10	10	GAS VALVE CHECK (IN GASING)	.14	5.6	0	Jim Bayner	32261
		Set 3					
3-31-10	13	GAS VALVE CHECK (IN GASING)	0	20.0	0	Jim Bayner	32261
		Set 4					
3-31-10	21	GAS VALVE CHECK (IN GASING)	0	18.9	0	Jim Bayner	32261
		Set 5					
3-31-10	26	GAS VALVE CHECK (IN GASING)	0	19.1	0	Harley Taylor	37002
		Set 6					
3-31-10	33	GAS VALVE CHECK (IN GASING)	6	4.7	0	Harley Taylor	37002
		Set 7					
3-31-10	38	GAS VALVE CHECK (IN GASING)	1	17.2	0	Harley Taylor	37002
		Set 8					
3-31-10	43	GAS VALVE CHECK (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 9					
3-31-10	44	GAS VALVE CHECK (IN GASING)	0	18.9	0	Harley Taylor	37002
		Set 10					
3-31-10	47	GAS VALVE CHECK (IN GASING)	0	19.9	0	Harley Taylor	37002
		Set 11					
3-31-10	50	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 12					
3-31-10	53	GAS VALVE CHECK (IN GASING)	1	17.8	0	Harley Taylor	37002
		Set 13					
3-31-10	56	GAS VALVE CHECK (IN GASING)	0	19.6	0	Harley Taylor	37002
		Set 14					
3-31-10	62	GAS VALVE CHECK (IN GASING)	0	15.5	0	Harley Taylor	37002
		Set 15					
3-31-10	63	GAS VALVE CHECK (IN GASING)	0	18.7	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature _____

Rick Foster
Mine Foreman

28731
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 1, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-1-10	5	GAS VALVE CHECK (IN GASING)	0	4.9	0	Jim Boyer	32261
		Set 2					
4-1-10	10	GAS VALVE CHECK (IN GASING)	.13	5.2	0	Jim Boyer	32261
		Set 3					
4-1-10	13	GAS VALVE CHECK (IN GASING)	0	20.2	0	Jim Boyer	32261
		Set 4					
4-1-10	21	GAS VALVE CHECK (IN GASING)	0	19	0	Jim Boyer	32261
		Set 5					
4-1-10	26	GAS VALVE CHECK (OUT GASING)	0	19.3	0	Harley Taylor	37002
		Set 6					
4-1-10	33	GAS VALVE CHECK (OUT GASING)	6	4.7	0	Harley Taylor	37002
		Set 7					
4-1-10	38	GAS VALVE CHECK (OUT GASING)	1	15.2	0	Harley Taylor	37002
		Set 8					
4-1-10	43	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 9					
4-1-10	44	GAS VALVE CHECK (IN GASING)	0	19.8	0	Harley Taylor	37002
		Set 10					
4-1-10	47	GAS VALVE CHECK (IN GASING)	0	20.4	0	Harley Taylor	37002
		Set 11					
4-1-10	50	GAS VALVE CHECK (IN GASING)	0	19.4	0	Harley Taylor	37002
		Set 12					
4-1-10	53	GAS VALVE CHECK (IN GASING)	1	20.7	0	Harley Taylor	37002
		Set 13					
4-1-10	56	GAS VALVE CHECK (IN GASING)	0	20.8	0	Harley Taylor	37002
		Set 14					
4-1-10	62	GAS VALVE CHECK (IN GASING)	.3	20.6	0	Harley Taylor	37002
		Set 15					
4-1-10	63	GAS VALVE CHECK (IN GASING)	0	20.4	0	Harley Taylor	37002
		BAROMETER READING 29.9					

Signature Rick Fort
Mine Foreman

28736
Certificate No.

Signature _____
Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 2, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-2-10	5	GAS VALVE CHECK (IN GASING)	0	4.5	0	Jacy Stewart	39199
		Set 2					
4-2-10	10	GAS VALVE CHECK (IN GASING)	1	4.5	0	Harley Taylor	37002
		Set 3					
4-2-10	13	GAS VALVE CHECK (IN GASING)	0	19.9	0	Jacy Stewart	39199
		Set 4					
4-2-10	21	GAS VALVE CHECK (IN GASING)	0	19.0	0	Harley Taylor	37002
		Set 5					
4-2-10	26	GAS VALVE CHECK (IN GASING)	0	19.3	0	Harley Taylor	37002
		Set 6					
4-2-10	33	GAS VALVE CHECK (IN GASING)	6	4.9	0	Harley Taylor	37002
		Set 7					
4-2-10	38	GAS VALVE CHECK (IN GASING)	0.1	20.5	0	Jacy Stewart	39199
		Set 8					
4-2-10	43	GAS VALVE CHECK (IN GASING)	0	20.2	0	Harley Taylor	37002
		Set 9					
4-2-10	44	GAS VALVE CHECK (IN GASING)	0	19.5	0	Jacy Stewart	39199
		Set 10					
4-2-10	47	GAS VALVE CHECK (IN GASING)	0	20.5	0	Harley Taylor	37002
		Set 11					
4-2-10	50	GAS VALVE CHECK (IN GASING)	0	19.4	0	Jacy Stewart	39199
		Set 12					
4-2-10	53	GAS VALVE CHECK (IN GASING)	0.1	20.5	0	Harley Taylor	37002
		Set 13					
4-2-10	56	GAS VALVE CHECK (IN GASING)	0	20.4	0	Jacy Stewart	39199
		Set 14					
4-2-10	62	GAS VALVE CHECK (IN GASING)	0.1	19.0	0	Harley Taylor	37002
		Set 15					
4-2-10	63	GAS VALVE CHECK (IN GASING)	0	20.5	0	Harley Taylor	37002
		Barometer Reading 29.9					

Signature _____

Rich Fort
Mine Foreman

28784
Certificate No.

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 3, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-3-10	5	GAS VALVE CHECK (IN GASING)	0	3.4	0	Joey Stewart	39199
		Set 2					
4-3-10	10	GAS VALVE CHECK (IN GASING)	1	3.6	0	Harley Taylor	37002
		Set 3					
4-3-10	13	GAS VALVE CHECK (IN GASING)	0	19.6	0	Joey Stewart	39199
		Set 4					
4-3-10	21	GAS VALVE CHECK (IN GASING)	0	19.1	0	Harley Taylor	37002
		Set 5					
4-3-10	26	GAS VALVE CHECK (IN GASING)	0	19.2	0	Harley Taylor	37002
		Set 6					
4-3-10	33	GAS VALVE CHECK (OUT GASING)	6	5.0	0	Harley Taylor	37002
		Set 7					
4-3-10	38	GAS VALVE CHECK (OUT GASING)	.30	15.7	0	Joey Stewart	39199
		Set 8					
4-3-10	43	GAS VALVE CHECK (IN GASING)	0	20.3	0	Harley Taylor	37002
		Set 9					
4-3-10	44	GAS VALVE CHECK (IN GASING)	0	19.7	0	Joey Stewart	39199
		Set 10					
4-3-10	47	GAS VALVE CHECK (IN GASING)	0	20.0	0	Harley Taylor	37002
		Set 11					
4-3-10	50	GAS VALVE CHECK (IN GASING)	0	19.2	0	Joey Stewart	39199
		Set 12					
4-3-10	53	GAS VALVE CHECK (IN GASING)	1	17.2	0	Harley Taylor	37002
		Set 13					
4-3-10	56	GAS VALVE CHECK (IN GASING)	0	20.4	0	Joey Stewart	39199
		Set 14					
4-3-10	62	GAS VALVE CHECK (IN GASING)	.2	17.4	0	Harley Taylor	37002
		Set 15					
4-3-10	63	GAS VALVE CHECK (IN GASING)	.1	19.3	0	Harley Taylor	37002
		BAROMETER READING 29.8					

Signature: Reik Zelen Certificate No. 28734 Signature: _____ Superintendent

Mine Foreman

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 5, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-5-10	5	GAS VALVE CHECK (IN GASING)	0	4.3	0	Jacq Stewart	39199
		Set 2					
4-5-10	10	GAS VALVE CHECK (IN GASING)	0	4.5	0	Jacq Stewart	39199
		Set 3					
4-5-10	13	GAS VALVE CHECK (IN GASING)	0	19.8	0	Jacq Stewart	39199
		Set 4					
4-5-10	21	GAS VALVE CHECK (IN GASING)	0	19.7	0	Jacq Stewart	39199
		Set 5					
4-5-10	26	GAS VALVE CHECK (NO GASING)	0	19.5	0	George Curry	27429
		Set 6					
4-5-10	33	GAS VALVE CHECK (OUT GASING)	0	5	0	George Curry	27429
		Set 7					
4-5-10	38	GAS VALVE CHECK (NO GASING)	0.26	19.7	0	George Curry	27429
		Set 8					
4-5-10	43	GAS VALVE CHECK (NO GASING)	0	19.9	0	George Curry	27429
		Set 9					
4-5-10	44	GAS VALVE CHECK (NO GASING)	0	19.0	0	George Curry	27429
		Set 10					
4-5-10	47	GAS VALVE CHECK (NO GASING)	0	19.9	0	George Curry	27429
		Set 11					
4-5-10	50	GAS VALVE CHECK (NO GASING)	0	18.5	0	George Curry	27429
		Set 12					
4-5-10	53	GAS VALVE CHECK (NO GASING)	1.17	17.6	0	George Curry	27429
		Set 13					
4-5-10	56	GAS VALVE CHECK (NO GASING)	0	20.2	0	George Curry	27429
		Set 14					
4-5-10	62	GAS VALVE CHECK (NO GASING)	0.2	17.6	0	George Curry	27429
		Set 15					
4-5-10	63	GAS VALVE CHECK (NO GASING)	0	19.4	0	George Curry	27429
		BAROMETER READING 29.9					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 6, 2010

Daily Examinations - Week Ending _____

ATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
6-10	5	GAS VALVE check					
		Set 2					
6-10	10	GAS VALVE check					
		Set 3					
6-10	13	GAS VALVE check					
		Set 4					
6-10	21	GAS VALVE check					
		Set 5					
6-10	26	GAS VALVE check					
		Set 6					
6-10	33	GAS VALVE check					
		Set 7					
6-10	38	GAS VALVE check					
		Set 8					
6-10	43	GAS VALVE check					
		Set 9					
6-10	44	GAS VALVE check					
		Set 10					
6-10	47	GAS VALVE check					
		Set 11					
6-10	50	GAS VALVE check					
		Set 12					
6-10	53	GAS VALVE check					
		Set 13					
1-6-10	56	GAS VALVE check					
		Set 14					
1-6-10	62	GAS VALVE check					
		Set 15					
1-6-10	63	GAS VALVE check					
		Barometer Reading					

nature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 7, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-7-10	5	GAS VALVE CHECK					
		Set 2					
4-7-10	10	GAS VALVE CHECK					
		Set 3					
4-7-10	13	GAS VALVE CHECK					
		Set 4					
4-7-10	21	GAS VALVE CHECK					
		Set 5					
4-7-10	26	GAS VALVE CHECK					
		Set 6					
4-7-10	33	GAS VALVE CHECK					
		Set 7					
4-7-10	38	GAS VALVE CHECK					
		Set 8					
4-7-10	43	GAS VALVE CHECK					
		Set 9					
4-7-10	44	GAS VALVE CHECK					
		Set 10					
4-7-10	47	GAS VALVE CHECK					
		Set 11					
4-7-10	50	GAS VALVE CHECK					
		Set 12					
4-7-10	53	GAS VALVE CHECK					
		Set 13					
4-7-10	56	GAS VALVE CHECK					
		Set 14					
4-7-10	62	GAS VALVE CHECK					
		Set 15					
4-7-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr 8, 2010

Daily

Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
1-8-10	5	GAS VALVE CHECK					
		Set 2					
1-8-10	10	GAS VALVE CHECK					
		Set 3					
1-8-10	13	GAS VALVE CHECK					
		Set 4					
1-8-10	21	GAS VALVE CHECK					
		Set 5					
1-8-10	26	GAS VALVE CHECK					
		Set 6					
1-8-10	33	GAS VALVE CHECK					
		Set 7					
1-8-10	38	GAS VALVE CHECK					
		Set 8					
1-8-10	43	GAS VALVE CHECK					
		Set 9					
1-8-10	44	GAS VALVE CHECK					
		Set 10					
1-8-10	47	GAS VALVE CHECK					
		Set 11					
1-8-10	50	GAS VALVE CHECK					
		Set 12					
1-8-10	53	GAS VALVE CHECK					
		Set 13					
1-8-10	56	GAS VALVE CHECK					
		Set 14					
1-8-10	62	GAS VALVE CHECK					
		Set 15					
1-8-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____ Mine Foreman Certificate No. _____ Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 9, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-9-10	5	GAS VALUE check (
		Set 2					
4-9-10	10	GAS VALUE check (
		Set 3					
4-9-10	13	GAS VALUE check (
		Set 4					
4-9-10	21	GAS VALUE check (
		Set 5					
4-9-10	26	GAS VALUE check (
		Set 6					
4-9-10	33	GAS VALUE check (
		Set 7					
4-9-10	38	GAS VALUE check (
		Set 8					
4-9-10	43	GAS VALUE check (
		Set 9					
4-9-10	44	GAS VALUE check (
		Set 10					
4-9-10	47	GAS VALUE check (
		Set 11					
4-9-10	50	GAS VALUE check (
		Set 12					
4-9-10	53	GAS VALUE check (
		Set 13					
4-9-10	56	GAS VALUE check (
		Set 14					
4-9-10	62	GAS VALUE check (
		Set 15					
4-9-10	63	GAS VALUE check (
		Barometer Pending					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

APR. 10, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-10-10	5	GAS VALVE check					
		Set 2					
4-10-10	10	GAS VALVE check					
		Set 3					
4-10-10	13	GAS VALVE check					
		Set 4					
4-10-10	21	GAS VALVE check					
		Set 5					
4-10-10	26	GAS VALVE check					
		Set 6					
4-10-10	33	GAS VALVE check					
		Set 7					
4-10-10	38	GAS VALVE check					
		Set 8					
4-10-10	43	GAS VALVE check					
		Set 9					
4-10-10	44	GAS VALVE check					
		Set 10					
4-10-10	47	GAS VALVE check					
		Set 11					
4-10-10	50	GAS VALVE check					
		Set 12					
4-10-10	53	GAS VALVE check					
		Set 13					
4-10-10	56	GAS VALVE check					
		Set 14					
4-10-10	62	GAS VALVE check					
		Set 15					
4-10-10	63	GAS VALVE check					
		BAROMETER READING					

Signature _____ Mine Foreman Certificate No. _____ Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 11, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-11-10	5	GAS VALVE CHECK					
		Set 2					
4-11-10	10	GAS VALVE CHECK					
		Set 3					
4-11-10	13	GAS VALVE CHECK					
		Set 4					
4-11-10	21	GAS VALVE CHECK					
		Set 5					
4-11-10	26	GAS VALVE CHECK					
		Set 6					
4-11-10	33	GAS VALVE CHECK					
		Set 7					
4-11-10	38	GAS VALVE CHECK					
		Set 8					
4-11-10	43	GAS VALVE CHECK					
		Set 9					
4-11-10	44	GAS VALVE CHECK					
		Set 10					
4-11-10	47	GAS VALVE CHECK					
		Set 11					
4-11-10	50	GAS VALVE CHECK					
		Set 12					
4-11-10	53	GAS VALVE CHECK					
		Set 13					
4-11-10	56	GAS VALVE CHECK					
		Set 14					
4-11-10	62	GAS VALVE CHECK					
		Set 15					
4-11-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Apr. 12, 2010

Rt. 4 + MRS Seals

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-12-10	5	GAS VALVE check (
		Set 2					
4-12-10	10	GAS VALVE check (
		Set 3					
4-12-10	13	GAS VALVE check (
		Set 4					
4-12-10	21	GAS VALVE check (
		Set 5					
4-12-10	26	GAS VALVE check (
		Set 6					
4-12-10	33	GAS VALVE check (
		Set 7					
4-12-10	38	GAS VALVE check (
		Set 8					
4-12-10	43	GAS VALVE check (
		Set 9					
4-12-10	44	GAS VALVE check (
		Set 10					
4-12-10	47	GAS VALVE check (
		Set 11					
4-12-10	50	GAS VALVE check (
		Set 12					
4-12-10	53	GAS VALVE check (
		Set 13					
4-12-10	56	GAS VALVE check (
		Set 14					
4-12-10	62	GAS VALVE check (
		Set 15					
4-12-10	63	GAS VALVE check (
		BAROMETER Reading					

Signature _____ Mine Foreman Certificate No. _____ Signature _____ Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

Apr. 13, 2010

Daily Examinations: - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-13-10	5	Gas Valve check					
		Set 2					
4-13-10	10	Gas Valve check					
		Set 3					
4-13-10	13	Gas Valve check					
		Set 4					
4-13-10	21	Gas Valve check					
		Set 5					
4-13-10	26	Gas Valve check					
		Set 6					
4-13-10	33	Gas Valve check					
		Set 7					
4-13-10	38	Gas Valve check					
		Set 8					
4-13-10	43	Gas Valve check					
		Set 9					
4-13-10	44	Gas Valve check					
		Set 10					
4-13-10	47	Gas Valve check					
		Set 11					
4-13-10	50	Gas Valve check					
		Set 12					
4-13-10	53	Gas Valve check					
		Set 13					
4-13-10	56	Gas Valve check					
		Set 14					
4-13-10	62	Gas Valve check					
		Set 15					
4-13-10	63	Gas Valve check					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 14, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-14-10	5	GAS VALVE CHECK					
		Set 2					
4-14-10	10	GAS VALVE CHECK					
		Set 3					
4-14-10	13	GAS VALVE CHECK					
		Set 4					
4-14-10	21	GAS VALVE CHECK					
		Set 5					
4-14-10	26	GAS VALVE CHECK					
		Set 6					
4-14-10	33	GAS VALVE CHECK					
		Set 7					
4-14-10	38	GAS VALVE CHECK					
		Set 8					
4-14-10	43	GAS VALVE CHECK					
		Set 9					
4-14-10	44	GAS VALVE CHECK					
		Set 10					
4-14-10	47	GAS VALVE CHECK					
		Set 11					
4-14-10	50	GAS VALVE CHECK					
		Set 12					
4-14-10	53	GAS VALVE CHECK					
		Set 13					
4-14-10	56	GAS VALVE CHECK					
		Set 14					
4-14-10	62	GAS VALVE CHECK					
		Set 15					
4-14-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

APR. 15, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-15-10	5	GAS VALVE CHECK					
		Set 2					
4-15-10	10	GAS VALVE CHECK					
		Set 3					
4-15-10	13	GAS VALVE CHECK					
		Set 4					
4-15-10	21	GAS VALVE CHECK					
		Set 5					
4-15-10	26	GAS VALVE CHECK					
		Set 6					
4-15-10	33	GAS VALVE CHECK					
		Set 7					
4-15-10	38	GAS VALVE CHECK					
		Set 8					
4-15-10	43	GAS VALVE CHECK					
		Set 9					
4-15-10	44	GAS VALVE CHECK					
		Set 10					
4-15-10	47	GAS VALVE CHECK					
		Set 11					
4-15-10	50	GAS VALVE CHECK					
		Set 12					
4-15-10	53	GAS VALVE CHECK					
		Set 13					
4-15-10	56	GAS VALVE CHECK					
		Set 14					
4-15-10	62	GAS VALVE CHECK					
		Set 15					
4-15-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 16, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4/16/10	5	GAS VALVE CHECK					
		Set 2					
4/16/10	10	GAS VALVE CHECK					
		Set 3					
4/16/10	13	GAS VALVE CHECK					
		Set 4					
4/16/10	21	GAS VALVE CHECK					
		Set 5					
4/16/10	26	GAS VALVE CHECK					
		Set 6					
4/16/10	33	GAS VALVE CHECK					
		Set 7					
4/16/10	38	GAS VALVE CHECK					
		Set 8					
4/16/10	43	GAS VALVE CHECK					
		Set 9					
4/16/10	44	GAS VALVE CHECK					
		Set 10					
4/16/10	47	GAS VALVE CHECK					
		Set 11					
4/16/10	50	GAS VALVE CHECK					
		Set 12					
4/16/10	53	GAS VALVE CHECK					
		Set 13					
4/16/10	56	GAS VALVE CHECK					
		Set 14					
4/16/10	62	GAS VALVE CHECK					
		Set 15					
4/16/10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____ Mine Foreman _____ Certificate No. _____ Signature _____ Superintendent _____

WEEKLY EXAMINATION OF SEALS

North West & North Mains Seals

APR. 17, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-17-10	5	GAS VALVE CHECK					
		Set 2					
4-17-10	10	GAS VALVE CHECK					
		Set 3					
4-17-10	13	GAS VALVE CHECK					
		Set 4					
4-17-10	21	GAS VALVE CHECK					
		Set 5					
4-17-10	26	GAS VALVE CHECK					
		Set 6					
4-17-10	33	GAS VALVE CHECK					
		Set 7					
4-17-10	38	GAS VALVE CHECK					
		Set 8					
4-17-10	43	GAS VALVE CHECK					
		Set 9					
4-17-10	44	GAS VALVE CHECK					
		Set 10					
4-17-10	47	GAS VALVE CHECK					
		Set 11					
4-17-10	50	GAS VALVE CHECK					
		Set 12					
4-17-10	53	GAS VALVE CHECK					
		Set 13					
4-17-10	56	GAS VALVE CHECK					
		Set 14					
4-17-10	62	GAS VALVE CHECK					
		Set 15					
4-17-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent

WEEKLY EXAMINATION OF SEALS

Rt. 4 + MRS Seals

Apr. 18, 2010

Daily Examinations - Week Ending _____

DATE	SEALS	HAZARDOUS CONDITIONS	CH ₄	O ₂	CO	SIGNATURE	CERTIFICATION #
		Set 1					
4-18-10	5	GAS VALVE CHECK					
		Set 2					
4-18-10	10	GAS VALVE CHECK					
		Set 3					
4-18-10	13	GAS VALVE CHECK					
		Set 4					
4-18-10	21	GAS VALVE CHECK					
		Set 5					
4-18-10	26	GAS VALVE CHECK					
		Set 6					
4-18-10	33	GAS VALVE CHECK					
		Set 7					
4-18-10	38	GAS VALVE CHECK					
		Set 8					
4-18-10	43	GAS VALVE CHECK					
		Set 9					
4-18-10	44	GAS VALVE CHECK					
		Set 10					
4-18-10	47	GAS VALVE CHECK					
		Set 11					
4-18-10	50	GAS VALVE CHECK					
		Set 12					
4-18-10	53	GAS VALVE CHECK					
		Set 13					
4-18-10	56	GAS VALVE CHECK					
		Set 14					
4-18-10	62	GAS VALVE CHECK					
		Set 15					
4-18-10	63	GAS VALVE CHECK					
		BAROMETER READING					

Signature _____

Mine Foreman

Certificate No. _____

Signature _____

Superintendent