

UBB #2 Section
Belts

1960

EXAMINATION OF ELECTRICAL EQUIPMENT

Company _____
Mine UBB
Location UBB #2 Section
Post Office _____ County _____ State _____

6/3/60
Rom Blundy

6
60

Re-order from
BJW Printing and
Office Supplies
P. O. Box 1309
Beckley, W. Va. 25801
Phone (304) 253-7361

Form 6—1492
(March 1970)

Budget Bureau No. 42-R1589
Approval expires 9-30-71

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. This book is approved by the Director of The West Virginia Department of Mines and The U. S. Bureau of Mines.

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-25-08	#1 Belt 2 Section	None observed at Time of Exam			DT
	Take-up OK				
	Fire Deluge OK				
	P. Center	Needs Cleaned		Cleaned	
				D. Duffy NR2681	

Weekly tests of grounding devices (diodes)

7-31-08	#1 Belt 2 Section	None observed at Time of Exam			DT
	Take-up OK				
	Fire deluge OK				
	P. Center OK				
					D. Duffy NR2681

Monthly examinations of methane monitors

8-7-08	#1 Belt 2 Section	Guard loose walkside		repaired	DT
	Take-up OK				
	Fire deluge OK				
	P. Center OK				
					D. Duffy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-14-08	#1 Head 2 Section	None observed at Time of Exam			
	Take-up OK Fire deluge OK P. Center OK				
					D Murphy NR2681
8-21-08	#1 Head 2 Section	None observed at Time of Exam			DT
	Take-up OK Fire deluge OK P. Center OK				
8-21-08	#2 Head 2 Section	Need a guard off side at D rollers Put Guard up			
	Take up OK Fire deluge not working P. Center OK			Replaced water Valve OK	
					D Murphy NR2681
Examinations of low- medium-voltage power circuit breakers (monthly)					
8-27-08	#1 Head 2 Section	None observed at Time of Exam			
	Take-up OK Fire deluge OK P. Center OK				
					D Murphy NR2681
8-27-08	#2 Head 2 Section	None observed at Time of Exam			
	Take-up OK Fire deluge OK P. Center OK				
					D Murphy NR2681

9
9

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-4-08	#1 Head 2 Section	None observed at Time of Exam			DT
	Take-up OK				DT
	Fire deluge OK				DT
	P Center OK				DT

Weekly tests of grounding devices (diodes)

9-4-08	#2 Head 2 Section	None observed at Time of Exam			DT
	Take-up OK				DT
	Fire Supp. OK				DT
	P Center OK				DT

D Campbell NR2681

9-11-08	#1 Head 2 Section	None observed at Time of Exam			DT
	Take-up OK				
	Fire deluge OK				
	P Center OK				

Monthly examinations of methane monitors

9-11-08	#2 Head 2 Section	None observed at Time of Exam			DT
	Take-up OK				
	Fire deluge OK				
	P Center OK				

D Campbell NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-18-08	#1 Head 2 Section	None observed at Time of Exam			DT
	Take-up	Chained Back Jack leaking			
	Fire deluge	OK			
	P Center	OK			

9-18-08	#2 Head 2 Section	None observed at Time of Exam			DT
	Take-up	OK			
	Fire deluge	OK			
	P Center	OK			

D Murphy NR2681

Examinations of low- medium-voltage power circuit breakers (monthly)

9-25-08	#1 Head 2 Section	None observed at Time of Exam			DT	10
	Take-up	Chained Back Jack Leaking				
	Fire-deluge	OK				
	P Center	OK				

9-25-08	#2 Head 2 Section	None observed at Time of Exam			DT	10
	Take-up	OK				
	Fire-deluge	OK				
	P Center	OK				

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10.2.08	#1 Belt 2 Section	None observed at Time of Exam.			DT
		Take-up Chain back Jack leaking			
		Fire deluge OK			
		P. Center OK			

Weekly tests of grounding devices (diodes)

10.2.08	#2 Belt 2 Section	None observed at Time of Exam.			DT
		Take-up OK			
		Fire deluge OK			
		P Center OK			

D. Murray NR2681

10.9.08	#1 Belt 2 Section	None observed at Time of Exam.			DT
		Take-up OK			
		Fire deluge OK			
		P Center OK			

Monthly examinations of methane monitors

10.9.08	#2 Belt 2 Section	None observed at Time of Exam.			DT
		Take-up OK			
		Fire deluge OK			
		P Center OK			

D. Murray NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-16-08	#1 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up OK			
	↓	Fire Deluge OK			
	↓	P Center OK			
10-16-08	#2 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up OK			
	↓	Fire deluge OK			
	↓	P Center OK			
			D Taraszkowy NR2681		
10-23-08	#1 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up OK			
	↓	Fire deluge OK			
	↓	P Center OK			

Examinations of low- medium-voltage power circuit breakers (monthly)

10-23-08	#2 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up OK			
	↓	Fire deluge OK			
	↓	P Center OK			
			D Gungler NR2651		

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-30-08	#1 Head 2 Section	None observed at Time of Exam			DT
↓		Take-up Ok Fire deluge Ok P Center Ok			
Weekly tests of grounding devices (diodes)					
10-30-08	#2 Head 2 Section	None observed at Time of Exam			DT
↓		Take-up Ok Fire deluge Ok P Center Ok			
D Murphy NR2681					
11-6-08	#1 Head 2 Section	None observed at Time of Exam			DT
↓		Take-up Ok Fire deluge Ok P Center Ok			
Monthly examinations of methane monitors					
11-6-08	#2 Head 2 Section	None observed at Time of Exam			DT
↓		Take-up Ok Fire deluge Ok P Center Ok			
D Murphy NR2681					

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11-13-08	#1 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK Fire deluge OK P Center OK			
11-13-08	#2 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK Fire deluge OK P Center OK			

D. L. Murphy NR2081

Examinations of low- medium-voltage power circuit breakers (monthly)

11-20-08	#1 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK Fire deluge OK P Center OK			
11-20-08	#2 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK Fire deluge OK P Center OK			

D. L. Murphy NR2081

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
Belts Idle 11.23.08 thru 11.30.08					
12-5-08	#1 Belt #2 Section	None observed at Time of Exam.			DT
	Take-up OK Fire deluge OK P Center OK				
Weekly tests of grounding devices (diodes)					
12-5-08	#2 Belt #2 Section	None observed at Time of Exam			DT
	Take-up OK Fire deluge will not stop Belt P Center OK				
			Changed Fire Supp. Sol.		DT
			D Murphy RA2681		
12-12-08	#1 Belt 2 Section	None observed at Time of Exam.			DT
	Take-up OK Fire deluge OK P Center OK				
Monthly examinations of methane monitors					
12-12-08	#2 Belt 2 Section	None observed at Time of Exam			DT
	Take-up OK Fire deluge OK P Center OK				
			D Murphy RA2681		

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-19-08	#2 Head #2 section	Take up ok Fire suppression ok Power center ok	None observed	D Lamy NR 268 VB	1
12-19-08	#2 belt head #2 section	Take up ok Fire suppression ok Power center ok	None observed	D Taraskey NR 268 VB	1
#1 Belt + #2 Belt Idle 12-20-08 thru 12-28-08					

Examinations of low- medium-voltage power circuit breakers (monthly)

1-2-09	#1 Head 2 Section	Take-up ok Fire Suppression ok Power Center ok	None observed at Time of Exam DI		
1-2-09	#2 Head 2 Section	Take-up ok Fire Suppression ok Power Center ok	None observed at Time of Exam		
D Lamy NR 268					

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-8-09	#1 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

Weekly tests of grounding devices (diodes)

1-8-09	#2 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

1-8-09	#3 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

D. Murphy WR2681

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-15-09	#1 Belt 2 Section	None observed at Time of Exam			
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
1-15-09	#2 Belt	None observed at Time of Exam			
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
1-15-09	#3 Belt	None observed at Time of Exam			
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

R. Clapp NR2681

Examinations of low- medium-voltage power circuit breakers (monthly)

1-22-09	#1 Belt 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
1-22-09	#2 Belt 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
1-22-09	#3 Belt 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

R. [Signature] NA2681

Weekly tests of grounding devices (diodes)

1-29-09	#1 Head 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

1-29-09	#2 Head 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

Monthly examinations of methane monitors

1-29-09	#3 Head 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

R. [Signature] NA2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2-5-09	#1 Belt 2 Section	None observed at Time of Exam			DT
↓		Take-up OK Fire Suppression OK P Center OK			
2-5-09	#2 Belt 2 Section	None observed at Time of Exam			DT
↓		Take-up OK Fire Suppression OK P Center OK			
2-5-09	#3 Belt 2 Section	Cross needs welded		Welded crossover	DT
↓		Take-up on/off Switch Brake		removed switch Plugged hole	
↓		Fire Suppression OK P Center OK			
		Track Charger 3 Spur	needs ground clamp	Installed Clamp	
					D. [Signature] NR 2681
Examinations of low- medium-voltage power circuit breakers (monthly)					
2-12-09	#1 Belt 2 Section	None observed at Time of Exam			DT
↓		Take-up OK Fire Suppression OK P Center OK			
2-12-09	#2 Bolt 2 Section	None observed at Time of Exam			DT
↓		Take-up OK Fire Suppression OK P Center OK			

D. [Signature] NR 2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2.12.09	#3 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok Fire Suppression Ok P Center Ok			

D Murphy NR2681

Weekly tests of grounding devices (diodes)

2.20.09	#1 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok Fire suppression Ok P Center Ok			
2.20.09	#2 Head 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok Fire Suppression Ok P Center Ok			

Monthly examinations of methane monitors

2.20.09	3 Head 2 Section	Tail roller Gobbled out		Cleaned	DT
	↓	Take-up Ok Fire Suppression Ok P Center Ok			

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
2.26.09	#1 Belt 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok			
	↓	Fire Suppression Ok			
	↓	P Center Ok			
2.26.09	#2 Belt 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok			
	↓	Fire Suppression Ok			
	↓	P Center Ok			
2.26.09	#3 Belt 2 Section	None observed at Time of Exam			DT
	↓	Take-up Ok			
	↓	Fire Suppression Ok			
	↓	P Center Ok			

D Murphy NR2681

Examinations of low- medium-voltage power circuit breakers (monthly)

3.5.09	#1 Belt 2 Section	None observed at Time of Exam			DT
		Take-up Ok			
		Fire Suppression Ok			
		P Center Ok			
3.5.09	#2 Belt 2 Section	None observed at Time of Exam			DT
		Take-up			
		Fire Suppression Ok			
		P Center Ok			

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-5-09	#3 Belt 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
					D Parughoggy NR2681

Weekly tests of grounding devices (diodes)

3-12-09	#1 Head 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
3-12-09	#2 Head 2 Section	None observed Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

Monthly examinations of methane monitors

3-12-09	#3 Head 2 Section	None observed at Time of Exam		DT	
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
					D Parughoggy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3-12-09	Put #4	Belt in Service			
		Checked Fire Suppression		OK	
		Checked Slip		OK	
	"	Seq		OK	
	"	Gov Switches		OK	
					D Murphy NR2681

3-19-09	#1 Belt 2 Section	None observed at Time of Exam. DT			
		Take-up		OK	
		Fire Suppression		OK	
		P Center		OK	

Examinations of low- medium-voltage power circuit breakers (monthly)

3-19-09	#2 Belt 2 Section	None observed at Time of Exam DT			
		Take-up		OK	
		Fire Suppression		OK	
		P Center		OK	

3-19-09	#3 Belt 2 Section	None observed at Time of Exam DT			
		Take-up	Jack needs changed	Change Jack	
		Fire Suppression		OK	
		P Center		OK	
		Spur Track Changer		OK	

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3.19.09	#4 Head 2 Section	None observed at Time of Exam			DT
		Fire Suppression OK			
		P Center OK			
					D. Murphy WA2681

Weekly tests of grounding devices (diodes)

3.26.09	#1 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		Power Center OK			

3.26.09	#2 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			

Monthly examinations of methane monitors

3.26.09	#3 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
					D. Murphy

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
3.26.09	#4 Head 2 Section	None observed at Time of Exam			
		Fire Suppression ok			
		P Center OK			
					D. Murphy W2601

4.2.09	#1 Belt 2 Section	None observed at Time of Exam		DT	
		Fire Suppression ok			
		Take-up ok			
		P Center ok			

4.2.09	#2 Belt 2 Section	None observed at Time of Exam		DT	
		Fire Suppression ok			
		Take-up ok			
		P Center ok			

Examinations of low- medium-voltage power circuit breakers (monthly)

4.2.09	#3 Belt 2 Section	None observed at Time of Exam		DT	
		Fire Suppression ok			
		Take-up	Power Pac needs replaced	replaced PowerPac DT	
		P Center ok			

4.2.09	#4 Head 2 Section	Put Head in Service			
		Check Fire Suppression			
		Slip, Seq + gob Switches			

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4.9.08	1 Belt	None observed at Time of Exam			
		Fire Supp. OK			
		P Center OK			
		Take-up OK			
4.9.08	2 Belt	None observed at Time of Exam			
		Fire Supp. OK			
		P Center OK			
		Take-up OK			

Weekly tests of grounding devices (diodes)

4.9.08	3 Belt	None observed at Time of Exam			
		Fire Supp. OK			
		P Center OK			
		Take-up OK	Tack leaking	reported	
		3 Spur Charger OK			
4.9.08	4 Belt	Bearing getting hot		Changed Bearing	
		Fire Supp. OK			
		P Center OK			

D. Murphy 12/2/08

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4-16-09	#1 Belt 2 Section	None observed at Time of Exam			DT
		Fire Suppression OK			
		Take-up OK			
		P Center OK			
4-16-09	#2 Belt 2 Section	None observed at Time of Exam			
		Fire Suppression OK			
		Take-up OK			
		P Center OK			
4-16-09	#3 Belt 2 Section	None observed at Time of Exam			DT
		Fire Suppression OK			
		Take-up OK			
		P Center OK			
		3 Spur Changer OK			

Examinations of low- medium-voltage power circuit breakers (monthly)

H Belt 2 Section None observed at Time of Exam DT
Fire Suppression OK
P Center OK

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
4.23.09	#1 Belt 2 Section	None observed at Time of Exam		Fire Suppression OK Take-up OK P Center OK	DT
4.23.09	#2 Belt 2 Section	None observed at Time of Exam		Fire Suppression OK Take-up OK P Center OK	DT
Weekly tests of grounding devices (diodes)					
4.23.09	#3 Belt 2 Section	None observed at Time of Exam		Fire Suppression OK Take-up OK P Center OK 3 Spur Track Charger OK	DT
Monthly examinations of methane monitors					
4.23.09	#4 Belt 2 Section	Starter Box needs Cleaned		Fire Suppression OK P Center OK	reported DT Cleaned

D. Murphy 4/23/09

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-1-09	#1 Head 2 Section	None observed at Time of Exam.			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
5-1-09	#2 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
5-1-09	#3 Head 2 Section	None observed at Time of Exam			DT
		Take-up OK			
		Fire Suppression OK			
		P Center OK			
		3 Spur Charger OK			
Examinations of low- medium-voltage power circuit breakers (monthly)					
5-1-09	#4 Head 2 Section	Needs a guard in front of Dr Roller reported			
		Fire Suppression OK			
		P Center OK			
					D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5.4.09	#1 Belt 2 Section	Locked + Tagged out of Service			DT
5.4.09	#2 Belt "	locked + Tagged out of Service			DT
5.4.09	#3 Belt "	Locked + Tagged out of Service			DT
5.4.09	#4 Belt "	locked + Tagged out of Service			DT

David Taraskey NRR 681

Weekly tests of grounding devices (diodes)

5.18.09	#1 Head Power Center	none observed
	#2 Head Power Center	none observed
	#3 Head Power Center	None observed
	#4 Head Power Center	none observed
	#3 Spur Track Charger	none observed

D. Taraskey NRR 681

Monthly examinations of methane monitors

5.29.09	H2 section #1	Power center ground faulted all breakers	B Farley 4-138
5.29.09	H2 section #1	Head Power center #2 circuit out of service	4-138
5.29.09	H2 section #1	head Power center Ground Resistor 18.9 Ω	4-138
5.29.09	H2 section #1	head Power center checked for stray current, checked monitor system	4-138
5.29.09	H2 section #2	head Power center ground faulted all breakers	4-138
5.29.09	H2 section #2	head checked stray current, checked monitor system	4-138
5.29.09	H2 section #2	head checked ground Resistor 23.0 Ω	4-138

Brian Farley

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
5-29-09	#2	section #3 power center	ground faulted all breakers	4-138	B Farley
5-29-09	#2	section #3 power center	checked grounding resistor	19.6 Ω	4-138
5-29-09	#2	section #3 power center	checked for stray current	monitor system	
5-29-09	#2	section #4 belt head power center	ground faulted all breakers	4-138	
5-29-09	#2	section #4 belt head	grounding resistor	19.6 Ω	4-138 B Farley
5-29-09	#2	section #4 belt head circuit #2 #4	does not work	Breaker will not	
5-29-09	#2	section #4 belt head power center		B Farley 4-138	set up.
			checked for stray current	monitor system	4-138 B Farley

5-30-09 #1 Head P Center OK
 #2 Head P Center OK
 #3 Head P Center OK
 #4 Head P Center OK

B Farley

Examinations of low- medium-voltage power circuit breakers (monthly)

6-5-09	#2	section #1 section power center	None observed	4-138	B Farley
6-5-09	#2	section #2 power center	Replaced 3 busted bulbs	4-138	
6-5-09	#2	section #2 power center	Repacked missing mat		B Farley
6-5-09	#2	section #3 power center	None observed		B Farley 4-138
6-5-09	#2	section #4 power center	Rubber mat missing	Repacked	4-138
6-5-09	#2	section #4 power center	Replaced light bulbs		B Farley 4-138

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-12-09	#2	Section #1 Power center	None	observed	4-138 B Farley
6-12-09	#2	Section #2 Power center	None	observed	4-138 B Farley
6-12-09	#2	Section #3 Power center	None	observed	4-138 B Farley
6-12-09	#2	Section #4 Power center	None	observed	4-138 B Farley

Weekly tests of grounding devices (diodes)

6-16-09	#2	Section #1 Belt P. Center	None	observed	DT
	#2	Section #2 Belt P. Center	None	observed	
	#2	Section #3 Belt P. Center	None	observed	
	#2	Section #4 Belt P. Center	None	observed	

R Murphy NR2681

6-19-09	#2	Section #4 Bolt Power center	out of service		4-138 Brian Farley
6-24-09	#2	Section #1 Head	completed	weekly Exam	Brian Farley 4-138
6-24-09	#2	Section #1 Head	None	observed	Brian Farley 4-138
6-24-09	#2	Section #1 Head	completed	monthly exam	Brian Farley 4-138
6-24-09	#2	Section #1 Head	checked monitor system and ground fault		Brooks 4-138
6-24-09	#2	Section #2 Head	completed	weekly exam	Brian Farley 4-138

Monthly examinations of methane monitors

6-24-09	#2	Section #2 Head	None	observed	Brian Farley 4-138
6-24-09	#2	Section #2 Head	completed	weekly monthly exam	Brian Farley 4-138
6-24-09	#2	Section #2 Head	checked	monitor system and ground fault	Brooks
6-24-09	#2	Section #2 Head	completed	monthly exam	Brian Farley 4-138

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
6-24-09	#2 Section	#3 Head	Completed weekly	Exam	None observed 4-132
6-24-09	#2 Section	#3 Head	Completed monthly	Exam	B. M. J. Kelly
6-24-09	#2 Section	#3 Head	ground faulted	all breakers checked	none observed 4-132 S. S. S.

Examinations of low- medium-voltage power circuit breakers (monthly)

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-10-09	#2 section 1 Head 3 BK Belt	transformer	None observed	Reported	Brian J. Kelly 4-138
7-10-09	#2 section 1 Head 3 BK Belt	transformer	serial # 9187 - 1000 - 496		Brian J. Kelly 4-138
7-10-09	#2 section 2 Head 4 BK	Belt transformer/starter	None observed	Reported	Brian J. Kelly 4-138
7-10-09	#2 section 2 Head 4 BK Break	27479 - 500 - 608	serial #		Brian J. Kelly 4-138
7-10-09	#3 section 3 Head 6 BK	Transformer and starter	None observed	Reported	Brian J. Kelly 4-138
7-10-09	#3 section 3 Head 6 BK	Transformer and starter	serial # 27480 - 500 - 1008		4-138

Weekly tests of grounding devices (diodes)

Monthly examinations of methane monitors

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner

Examinations of low- medium-voltage power circuit breakers (monthly)

7-10-09 #1	Head 2 section	Power center	ground faulted all breakers, checked monitors, E.S.P.		
7-10-09 #2	Head 2 section	Power center	ground faulted breakers, checked monitors, E.S.P.		
7-10-09 #2	Head 3 section	Power center	ground faulted breakers, checked monitors, E.S.P.		
7-10-09 #1	Belt transformer	serial # 9/87-1000-496	3 Break	Brim Jubey 4-138	
7-10-09 #2	Belt transformer and starter	serial # 27479-500-608	46 Break	4-138	
7-10-09 #3	Belt transformer and starter	serial # 27480-500-1008	69 Break	Brim Jubey 4-138	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
7-13-09	#1 Break	1000 KVA Box/# 9187-1000-496	None Observed	Reported	William J. Smith 3-152
7-13-09	#46 Break	500 KVA Box/# 27479-500-608	None Observed	Reported	William J. Smith 3-152
7-13-09	#69 Break	500 KVA Box/# 27480-500-1008	None Observed	Reported	William J. Smith 3-152
7-20-09	#1 Break	1000 KVA Box/# 9187-1000-496	None Observed	Reported	William J. Smith 3-152
7-20-09	#46 Break	500 KVA Box/# 27479-500-608	None Observed	Reported	William J. Smith 3-152
7-20-09	#69 Break	500 KVA Box/# 27480-500-1008	None Observed	Reported	William J. Smith 3-152

Weekly tests of grounding devices (diodes)

7-27-09	#1 Break	1000 KVA Box/# 9187-1000-496	None observed	reported	Bob Will 4-535
7-27-09	#46 Break	500 KVA Box/# 27479-500-608	None observed	reported	Bob Will 4-535
7-27-09	#69 Break	500 KVA Box/# 27480-500-1008	None observed	reported	Bob Will 4-535

#1 Belt 2 Section. None observed
 Fire Suppression ok
 Take-up Guard missing walk side Put new guard on OT
 P. Center ok
 D. Murphy WA 2681

Monthly examinations of methane monitors

8-3-09	#1 Break	1000 KVA Box/# 9187-1000-496	None observed	Bob Will 4-535
8-3-09	#46 Break	500 KVA Box/# 27479-500-608	None observed	Bob Will 4-535
8-3-09	#69 Break	500 KVA Box/# 27480-500-1008	None observed	Bob Will 4-535

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-10-09	#1 Bk.	1000 KVA Box / 9187-1000-496	None Obs	But Well	4-535
8-10-09	#46 Bk.	500 KVA Box / 27479-500-608	None Obs	But Well	4-535
8-10-09	#109 Bk.	500 KVA Box / 27480-500-1008	None Obs	But Well	4-535

8-8-09 #2 Belt New Setup 2 Section


Checked Fire Suppression OK
 Checked Slip OK
 Checked Seq OK

D Murphy NR2681

Examinations of low- medium-voltage power circuit breakers (monthly)

8-12-09 #1 Head 2 Section

None observed



Fire Supp OK
 Take up OK
 P Center OK

D Murphy NR2681

8-12-09 #2 Bolt 2 Section

None observed

Fire Supp OK
~~Take up OK~~
 P Center OK

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
8-19-09	#1 Head 2 Section	Guard off of Head		Replaced Guard	DT
	Fire Supp OK				
	Take-up OK				
	P Center OK				
					NR2681

Weekly tests of grounding devices (diodes)

8-19-09	2 Head 2 Section	Slip Sensor need remounted			corrected DT
	Fire Supp OK				
	P Center OK				
					D Muff NR2681

8-25-09	#1 Head 2 Section	None observed			
	Fire Supp OK				
	Take-up OK				
	P Center OK				

Monthly examinations of methane monitors

8-25-09	#2 Head 2 Section	Guard loose on off side			repaired DT
	Fire Supp OK				
	XXXXXXXXXX				
	P Center OK				
					D Muff NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9-1-09 Thru 9-4-09	Mine Idle	Inspectors Red Tagged Mine	None		
9-8-09 #1 Head 2 Section		Fire Supp OK Take-up OK P Center OK	None		D. L. Wynn NR2681

Examinations of low- medium-voltage power circuit breakers (monthly)

9-8-09 #2 Head 2 Section		Fire Supp OK Take-up OK P Center OK	None		D. L. Wynn NR2681
--------------------------	--	--	------	--	-------------------

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9/16/09	#1 Head 2 Section	Starter Box 3 Packing Glands CaT Head 2 IDs Belthead + D Box		corrected corrected	DT DT

↓
Take-up OK
P Center OK
✓ Fire Supp OK

D Murphy NR2681

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9.16.09	# #2 Head 2 Section		Weekly tests of grounding devices (diodes) Guard lose on head	corrected	

↓
Fire Supp OK
P Center OK

D Murphy NR2681

9.24.09	#1 Head 2 Section		None observed at Time of Exam.		
---------	-------------------	--	--------------------------------	--	--

Take-up OK
P Center OK
Fire Supp OK

D Murphy NR2681

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
9.24.09	#2 Head		Monthly examinations of methane monitors Guard lose on off side	corrected	DT

Fire Supp OK
P Center OK

D Murphy NR2681

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-1-09	#1 Belthead 2 section #1 KVA Box Fire Suppression	No Fire Ext. at power puc none observed O.K.	reported reported	Bl Will 4-535	
10-1-09	#2 Belthead 2 section #2 KVA Box Fire suppression	none observed none observed O.K.	reported reported	Bl Will 4-535	
10-8-09	#1 Belthead 2 section #1 KVA Box Fire Suppression	none observed at time of exam none observed O.K.	reported reported	Bl Will 4-535	
10-8-09	#2 Belthead 2 Section #2 KVA Box Fire Suppression	none observed at time of exam missing mat O.K.	reported replaced mat	Bl Will 4-535	
Examinations of low- medium-voltage-power circuit breakers (monthly)					
10-15-09	#1 Belthead 2 Section #1 KVA Box Fire suppression	none observed at time of exam none observed at time of exam O.K.	reported reported	Bl Will 4-535	
10-15-09	#2 Belthead 2 section #2 KVA Box Fire suppression	Guarding needs raised up Dirty need cleaned off O.K.	reported reported	Bl Will 4-535	
10-15-09	#3 KVA Box	none observed at time of exam	reported	Bl Will	

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
10-23-09	#1 Belthead	None observed at time of exam		Bl well 4-535	
	#1 KVA Box	OK.			
	Fire Suppression	OK.			
10-23-09	#2 Belthead	Guard loose	Tighten up guard	Bl well 4-535	
	#2 KVA Box	None observed			
	Fire Suppression	OK.			
Weekly tests of grounding devices (diodes)					
10-23-09	#3 Belthead	None observed at time of exam		cleaned off Bl well 4-535	
	#3 KVA Box	Dirty			
	Fire suppression	OK.			
10-29-09	#1 Belthead	None observed at time of exam		Bl well 4-535	
	#1 KVA Box	OK.			
	Fire Suppression	OK.			
10-29-09	#2 Belthead	Guard loose	reported	Bl well 4-535	
	#2 KVA Box	None observed OK.			
	Fire suppression	OK.			
Monthly examinations of methane monitors					
10-29-09	#3 Belthead	None observed at time of exam		Bl well 4-535	
	#3 KVA Box	OK.			
	Fire suppression	OK.			

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

B.W.	Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11-5-09		#1 Belthead #1 KVA Box	none observed at time of exam none observed at time of exam			Bl-Will 4-535
		Fire Suppression O.K.				
11-5-09		#2 Belthead #2 KVA Box	Guard too low none observed at time of exam	raised guard up		Bl-Will 4-535
		Fire suppression O.K.				
11-5-09		#3 Belthead #3 KVA Box	none observed at time of exam none observed observed at time of exam			Bl-Will 4-535
		Fire suppression O.K.				
Examinations of low- medium-voltage power circuit breakers (monthly)						
11-12-09		#1 Belthead #1 KVA Box	none observed at time of exam none observed at time of exam			Bl-Will 4-535
		Fire suppression O.K.				
11-12-09		#2 Belthead #2 KVA Box	none observed at time of exam none observed at time of exam			Bl-Will 4-535
		Fire suppression O.K.				
11-12-09		#3 Belthead #3 KVA Box	none observed at time exam none observed at time exam			Bl-Will 4-535
		Fire suppression	Bad Flow switch	changed out flow switch		

EXAMINATION OF ELECTRICAL EQUIPMENT

Examination of electrical equipment (weekly)

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
11-19-09	#1 Belthead	none observed at time of exam			Bl Well 4-535
	#1 KVA Box	none observed at time of exam			
	Fire suppression	OK.			
11-19-09	#2 Belthead	none observed at time of exam			Bl Well 4-535
	#2 KVA BOX	none observed at time of exam			
	Fire suppression	OK.			
Weekly tests of grounding devices (diodes)					
11-19-09	#3 Belthead	none observed at time of exam			Bl Well 4-535
	#3 KVA BOX	none observed at time of exam			
	Fire suppression	OK.			
12-4-09	#1 KVA Box	OK. none observed at time of exam			Bl- Well 4-535
12-4-09	#2 KVA Box	OK. none observed at time of exam			
12-4-09	#3 KVA Box	OK. none observed at time of exam			
Monthly examinations of methane monitors					
12-9-09	#1 Belthead	none observed at time of exam			Bl- Well 4-535
	# Fire suppression	OK.			
12-9-09	#2 Belthead	none observed at time of exam			Bl- Well 4-535
	Fire suppression	OK.			
12-9-09	#3 Belthead	none observed at time of exam			Bl- Well 4-535
	Fire suppression	OK.			

EXAMINATION OF ELECTRICAL EQUIPMENT

Power centers and transformers prior to movement

Date	Location	Equipment examined and/or tested	Dangerous conditions	Action taken	Examiner
12-9-09	# 1 KVA BOX	none observed at time of exam			Bl. Wadell 4-535
12-9-09	# 2 KVA BOX	Dirty	Cleaned off		Bl. Wadell 4-535
12-9-09	# 3 KVA BOX	none observed at time of exam			Bl. Wadell 4-535
12-17-09	# 1 Belthead	none observed at time of exam			
	# 1 KVA BOX	none observed at time of exam			Bl. Wadell 4-535
	Fire suppression	O.K.			
12-17-09	# 2 Belthead	none observed at time of exam			
	# 2 KVA BOX	none observed at time of exam			Bl. Wadell 4-535
	Fire suppression	O.K.			
12-17-09	# 3 Belthead	none observed at time of exam			
	# 3 KVA BOX	none observed at time of exam			Bl. Wadell 4-535
	Fire suppression	O.K.			

Examinations of low- medium-voltage power circuit breakers (monthly)