

⑩
5-18-10-20

Smoke Search

Started 3-05-09

PRESHIFT - ONSHIFT and DAILY REPORT

Company Performance Coal

Mine UBB

SECTION Long wall Setup - Motherdrive Work Area

LOCATION Ngoma Raleigh W.V
Post Office County State

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. 3-05-09	Smoke Search Motherdrive work area	None observed Michael A. Fenell 37942
2. 3-10-09	Smoke Search motherdrive work area	None observed Michael A. Fenell 37942
3. 3-17-09	Smoke Search motherdrive work area	None observed Michael A. Fenell 37942
4. 3-24-09	Smoke Search Motherdrive work area	None observed Michael A. Fenell 37942
5. 3-30-09	Smoke Search outside	None observed Michael A. Fenell 37942
6. 4-4-09	Smoke Search motherdrive	None observed Michael A. Fenell 37942
7. 4-7-09	Smoke Search outside	None observed Michael A. Fenell 37942
8. 4-16-09	Smoke Search motherdrive	None observed Michael A. Fenell 37942

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. 4-20-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
2. 4-29-09	Smoke Search	motherdrive	None observed	Michael A. Fenell	37942
3. 5-6-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
4. 5-13-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
5. 5-18-09	Smoke Search	motherdrive	None observed	Michael A. Fenell	37942
6. 5-29-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
7. 6-5-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
8. 6-5-09	Smoke Search	Setup face	None obs	Richard Kane	1357-A
9. 6-9-09	Smoke Search	motherdrive	None observed	Michael A. Fenell	37942
10. 6-10-09	Smoke Search	Setup face	None observed	Richard Kane	1357-A

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. 6-12-09	Smoke Search	Setup face	None observed	Hyellie	37010
2. 6-16-09	Smoke Search	motherdrive	None observed	Michael A. Fenell	37942
3. 6-19-09	Smoke Search	786k section	None observed	Richard Kane	1357-A
4. 6-23-09	Smoke Search	day shift setup crew	None found	Tommy Estep	1131-A
5. 6-23-09	Smoke Search	outside	None observed	Michael A. Fenell	37942
6. 6-26-09	Smoke Search	outside setup crew	None observed	Tommy Estep	1131-A

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination 6 20. Section or Area Examined
Time of Examination: from a.m. or p.m. to a.m. or p.m.
Was this report phoned to outside: Yes no
By whom Time A.M. P.M.
Report received by (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location

Violation or Hazardous Condition

Action Taken

- 1. 6-29-09 Smoke Search Setup crew outside None observed Jim Dai 38322
2. 6-30-09 smoke Search Motherdrive outside None observed Mike Ferrell 37942
3. 6-30-09 n.k. Search on setup Hazardous 9700
4. 7-1-09 smoke search at mantrip st. 4 wall setup, None Observed Lully 2909
5. 7-6-09 smoke Search outside None observed Mike Ferrell 37942
6. 7-7-09 smoke search setup crew on section None observed Tommy Ealy 1139-A
7. 7-14-9 smoke search Setup crew LW face None obs Richard Rame 1357-A
8. 7-15-09 smoke Search motherdrive crew outside None observed Mike Ferrell 37942
9. 7-20-09 smoke Search motherdrive crew outside None observed Mike Ferrell 37942
10. 7-23-09 Smoke Search LW setup Section None observed Richard Rame 1357-A

Air Measurements

Location

CFM

Location

CFM 37942

- 7-30-09 Smoke Search motherdrive crew outside None observed Michaela Fenell
8-03-09 smoke Search motherdrive crew outside None observed Michaela Fenell 37942
8-7-9 Smoke Search Head side Prop crew outside None observed Richard Rame 1357-A
8-7-09 Smoke Search 2nd shift 4 wall Lenzwell 1100 None observed
8-7-08 Smoke Search outside at mantrip station None found
8-10-09 Smoke search outside none none
8-10-09 smoke Search motherdrive crew at motherdrive None observed Michaela Fenell 37942
8-13-9 Smoke Search 2bk 1 section Prop Setters None observed R. Rame 1357-A
Remarks: 8-17-09 smoke Search outside motherdrive crew None observed Michaela Fenell 37942
8-21-09 smoke Search outside motherdrive crew None observed Michael Fenell 37942
8-27-09 smoke Search outside Head Prop + Setup Crew None obs R. Rame 1357-A
8-31-09 smoke Search outside motherdrive crew None observed Michaela Fenell 37942
9-8-09 smoke Search outside motherdrive crew None observed Michaela Fenell 37942

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.
Countersigned Mine Manager-Mine Foreman
Assistant Foreman
Superintendent or Assistant

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. 9-3-09 L wall	K. Medley, R. Hale, R. Scarbro, G. Skeens, Di Ross, J. Price, G. Quarley, R. Mullins, K. Brown, S. Suckles.	Searched crew at LWB L wall. (None found) Had tully 2805
4. 9-3-09 L wall	J. Martin, S. Dickers, L. Ford, G. Meadows, K. Cozart, M. Medley, S. McPherson, R. Ara, T. Dillon, J. Staley, R. Brown.	None found LWB 38922
7. 9-11-09	search at face end of track C crew	None observed Kevin W. Medley 38810
8. 9-11-09	search at mouth of section B crew	None observed R. Lane 1357A

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. 9-15-09	smoke search outside mother drive crew	11. None observed	Michael A Ford		37942
2. 9-18-09	search at face end of track C crew	None observed	Kevin W. Medley		38810
3. 9-22-09	searched outside in barn Owl I long wall crew	No articles found	Samuel K. Staley		39218
4. 9-22-09	searched LWB crew B end of track L/W	None obs	R. Lane		1357A
5. 9-23-09	smoke search mother drive at 102 break	15. None observed	Michael A Ford		37942
6. 9-26-09	search at Mule Train C crew	16. None observed	Kevin W. Medley		38810
7. 9-28-09	smoke search at 4 North Head mother drive crew	None observed	Michael A Ford		37942
8. 9-30-09	Smoke search at mule train Owl A & B long wall	None found	Samuel K. Staley		39218
9. 9-30-09	Smoke search at mule train C crew	None observed	Kevin W. Medley		38810
10. 9-30-09	Smoke search Ellis Switch B crew	None obs	Richard Lane		1357A

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. 10-3-09	Smoke search at Mantrip st. A crew	None found	7:20am	CTDaw	38322
2. 10-6-09	Smoke search at mantrip mother drive crew	None observed	Michael A Ford		37942
3. 10-6-09	Smoke search Long wall outly	8. None	Mont Parker		37004
4. 10-7-09	Smoke search Long wall C crew	None observed	Kevin W. Medley		38810
5. 10-8-09	Smoke search Long wall "Owl"	10. None observed	L. R.		38922
10-11-09	Smoke search Long wall B crew	None observed	Richard Lane		1357A

Number of Bolts Tested _____
 Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Use Indelible Pencil or Ink

Date of Examination _____ 20____ Section or Area Examined _____
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M _____ P.M.
 Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
10-11-09 LW A Crew	Smoker Search None observed	J. Davis 38,322
10-14-09 LW C Crew	Smoker Search at Mule Train	None Observed Kevin W. Medley 38810
10-16-09 LW Owl	Both crews Smoker Search at Mule Train	None Observed Daniel K. Staley 39218
10-19-09 LW B Crew	Smoke Search muletrain	None Observed Richard Ham 1357
10-15-09	out by crew Smoke Search outside	None Observed Richard Ham 37064
10-22-09 LW C Crew	Smoke Search at Mule Train	None Observed Kevin W. Medley 38810
10-24-09 LW Owl I & II	Smoke Search at matrip at end of track	None found Daniel K. Staley 39218
10-27-09 LW C Crew	Smoker Search at Mule Train	None Observed Kevin W. Medley 38810
10-28-09 LW Owl I & II	smoke search at drift mtd	None Observed J. Davis 38322
10-30-09 LW B crew	Smoke Search End of track	None Observed Richard Ham 1357-A

Air Measurements

Location	CFM	Location	CFM
11-3-09 LW C Crew	Smoker Search at Mule Train	None Observed Kevin W. Medley	38810
11-3-09 LW B crew	Smoke Search Ellis Switch	None Observed Richard Ham	1357-B
11-11-09 LW A Crew	Smoke Search Mule Train	None Observed J. Davis	38,322
11-11-09 LW Crib Crew	Smoke Search Mule Train	None Observed Kevin W. Medley	38810
11-12-09 LW C Crew	Smoke Search mule Train	None Observed James Staley	39117
11-13-09 LW Owl crews	Smoke Search at Mule Train	None Observed Daniel K. Staley	39218
11-18-09 LW C Crew	Smoke Search at mule Train	None Observed James Staley	39117
11-19-09 LW C crew	Smoke Search at Mouth of Section	None Observed James Staley	39117

Remarks: 11-19-09 LW Crib Crew Smoke Search end of track None Observed Kevin W. Medley 38810
 11-26-09 LW Crib Crew Smoke Search end of track None Observed Kevin W. Medley 38810
 11-27-09 LW Face Crew Smoke Search AT Mule Train None observed J. Davis 38,322
 11-29-09 LW Owl I & II crews smoke search at mule train None observed Daniel K. Staley 39218
 11-29-09 LW C crew Smoke Search at mule train None observed James Staley 39117
 11-29-09 LW B crew Smoke Search mule train None Observed Richard Ham 1357-A
 11-30-09 LW T Davis Smoker Search AT Matrip None Observed J. Davis 38,322

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No. _____
 Countersigned _____ Mine Manager—Mine Foreman
 _____ Assistant Foreman
 _____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken	
1. 11-30-09 Belt construction crew	Smoke Search Gloryhole	None observed	Michael Fenell 37942
2. 11-30-09 L/w C Crew	Smoke Search at the end of track	None observed	Jimmie Stith 5917
3. 12-3-09 Crib Crew	Smoke Search at end of the track	None observed	Kevin W. Medley 38810
4. 12-7-09 L/w C Crew	Smoke Search at the end of track	None obs	Jimmie Stith 3917
5. 12-8-09 Belt construction crew	Smoke Search Glory hole	None observed	Michael Fenell 37942
6. 12-10-09 Crib Crew	Smoke Search crib line	None Observed	Kevin W. Medley 38810
7. 12-12-09 AT Mule Train	Smoke Search	None obs	Jimmie Stith
8. 12-12-09 Mule Train	Smoke Search	None obs	Richard Lam 1357-A

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. 12-12-09 Section	Smoke Search	None obs	Z R		38928
2. 12-17-09 Belt construction crew	Smoke Search outside	None observed	Michael Fenell		37942
3. 12-17-09 L/w Dry	Mule Train Smoke Search	None observed	Jimmie Stith		38322
4. 12-21-09 L/w	Smoke Search Mule Train	None observed	Jimmie Stith		38322
5. 12-26-09 L/w	Smoke Search Mule Train	None observed	Jimmie Stith		5917
6. 12-28-09 Longwall Owl	Smoke Search End of Face	None obs	Z R		38928
7. 12-30-09 Longwall B Crew	Smoke Search Mule Train	None obs	Richard Lam		1357-A
8. 1-1-10 Longwall Owl I	Smoke Search Mule Train	None found	Dwight K. Stealy		39218
9. 1-4-10 Belt construction crew	outside	none observed	Michael Fenell		37942
10. 1-13-10 Longwall H Crew	Mule Train	None observed	Jimmie Stith		38322
1-13-10 Belt construction crew	mother drive	None observed	Michael Fenell		37942

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. 1-17-10 Longwall B Crew	Mule Train	None obs	Richard Lam		1357-A
2. 1-20-10 Longwall Owl 1+2	Partial	None obs	Z R		38928
3. 1-20-10 Longwall C Crew	Smoke Search Mule Train	None Observed	Kevin W. Medley		38810
4. 1-20-10 Belt construction crew	52 bck	None observed	Michael Fenell		37942
5. 1-25-10 Belt construction crew	outside	none observed	Michael Fenell		37942

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No

Mine Foreman - Mine Manager

Certificate No

Superintendent or Assistant

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____

Examinations for Methane in Working Places

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	11. _____	_____	_____
2. _____	_____	_____	12. _____	_____	_____
3. _____	_____	_____	13. _____	_____	_____
4. _____	_____	_____	14. _____	_____	_____
5. _____	_____	_____	15. _____	_____	_____
6. _____	_____	_____	16. _____	_____	_____
7. _____	_____	_____	17. _____	_____	_____
8. _____	_____	_____	18. _____	_____	_____
9. _____	_____	_____	19. _____	_____	_____
10. _____	_____	_____	20. _____	_____	_____

Examinations for Methane in Return Aircourses

Location	Time	Methane Content	Location	Time	Methane Content
1. _____	_____	_____	6. _____	_____	_____
2. _____	_____	_____	7. _____	_____	_____
3. _____	_____	_____	8. _____	_____	_____
4. _____	_____	_____	9. _____	_____	_____
5. _____	_____	_____	10. _____	_____	_____

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination _____ 20____ Section or Area Examined _____
 Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.
 Was this report phoned to outside: Yes _____ no _____
 By whom _____ Time _____ A.M _____ P.M.
 Report received by _____
 (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. _____	_____	_____
2. _____	_____	_____
3. _____	_____	_____
4. _____	_____	_____
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

Air Measurements

Location	CFM	Location	CFM
----------	-----	----------	-----

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Remarks: _____

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____	Preshift-Mine Examiner	Certificate No. _____	Assistant Foreman	Certificate No. _____
Countersigned _____	Mine Manager—Mine Foreman	_____	_____	_____
_____	Assistant Foreman	_____	_____	_____
_____	_____	_____	Superintendent or Assistant	_____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date Shift Area or Section

Violations and other Hazardous Conditions Observed and Reported

Table with 3 columns: Location, Violation or Hazardous Condition, Action taken. Rows 1-8.

Examinations for Methane in Working Places

Table with 6 columns: Location, Time, Methane Content. Rows 1-20.

Examinations for Methane in Return Aircourses

Table with 6 columns: Location, Time, Methane Content. Rows 1-10.

Number of Bolts Tested Number of Bolts Torqued Above Range Below Range

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken

Remarks (Statement as to General Conditions of Mine or Area of Mine)

Assistant Mine

Certificate No.

Mine Foreman-Mine Manager

Certificate No.

Superintendent or Assistant