

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4110078
 Company Name Performance Coal Company
 Mine Name Upper Big Branch mine - South
 Mine I.D. Number 4608436

Date(s) of Mine File Review 1-9-06

D Status _____ Citation/Order No. _____ Date _____

Dates of Inspection: began 3-20-06 completed 3-20-06

Pre-Inspection Conference Date 3-20-06

Company Representative(s) [REDACTED]

Miners Representative(s) None by Chas

Post-Inspection Conference Date 3-22-06

Company Representative(s) [REDACTED]

Miners Representative(s) None by Chas

Comments: _____

Inspector's Initials [REDACTED] Supervisor's Initials and Date RR3-20-06

DAILY COVER SHEET

Date 3-20-06 Event No. 4110078

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Permit & OSHA

Accompanied By: Company Representative [REDACTED]

Miners Representative None

AREAS OF INSPECTION ACTIVITY:

Upon arrival at the mine site I informed [REDACTED] that I would be traveling to the North ~~side~~ ^{main} where the water induction occurred. We traveled the track to the North ~~side~~ ^{main} section. Methane from outcrop to section 070 20.8

Inspector's Initials [REDACTED]

Supervisor's Initials and Date _____ Page No. 1

Date 3-20-06

Oxygen. I traveled all faces for instrument danger. 2.30 CH₄ all across the face. 4 locations between 2.90 .190 20.870 oxygen air reading 1987 = 133

212
133
28,196 CFM. 20.8.
We traveled to the Mary Hale. 0.70 CH₄ 20.9 Oxygen
Mary Hale 0.70 CH₄ 20.9.
We traveled back to the surface.

Inspector's Initials [REDACTED]

Supervisor's Initials and Date _____ Page No. 2