MSHA Form 7000-10H, June 93 (revised)

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4110675

Company Name Performance Coal Co.

Mine Name U B B

Mine I.D. Number 46-08476

Date(s) of Mine File Review 10/10/05

D Status _____ Citation/Order No. _____ Date _____

Dates of Inspection: began 12/19/05 completed 12/19/05

Pre-Inspection Conference Date 12/19/05

Company Representative(s) W. Wells, Supv

Miners Representative(s) NONE

Post-Inspection Conference Date 12/19/05

Company Representative(s) D. Petry, Mike Fahrnger

Miners Representative(s) NONE

Comments:

Inspector's Initial [redacted] Supervisor's Initials and Date RR 12-26-05

*U.S. GPO: 1993-0-509-093

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 12/19/05 Event No. 4110675

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked All per Ron Shift

Accompanied By: Company Representative

[redacted]

Miners Representative NONE

AREAS OF INSPECTION ACTIVITY:

North Mains

Inspector's Initials [redacted]

Supervisor's Initials and Date RR 12-26-05 Page No. 1

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

North Mains

Date 12/19/05 Inspector's Initial [redacted]

Supervisor's D&I RR 12-26-05 Page No. 2

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Long Wall 1415

Travled to Mains

Reviewed all pre & shift books & maps

Travled Track to HO 20

Checked HO 20 Belt & Mining Equip. 100% off-shift work where has been cleaned up.

Travled to HO 10

Checked CM

Date 12/19/05 Inspector's Initial [redacted]

Supervisor's D&I RR 12-26-05 Page No. 3

U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10J, June 93 (revised)

Blocking Pillars OK

Travled Track to North Mains

No CMV or food or drinks

No Hazards observed

Made Face to Face Tests & air reading

Pillars Reopen Rib OK

No CMV or violations

Travled back to HO 20

MSHA Form 7000-10J, June 93 (revised)

LO 13

5 to 1848 = 1444

1444 A 198 V

20.5 12 CFM

Time 1030

20.0 O2 0.0 CH4

observed Mining & Bolting cycle.

Travled back to Surface

checked Fire Valve and North Mains belt OK

Debriefed report with P. Petry Mike Fahrnger

Date 12/19/05 Inspector's Initial [redacted]

Supervisor's D&I RR 12-26-05 Page No. 5

*U.S. Government Printing Office: 1997 - 508-470