MSHA Form 7000-10H, June 93 (revised)

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4111139

Company Name Performance Coal Co.

Mine Name Upper Big Branch South

Mine I.D. Number 46-08436

Date(s) of Mine File Review 7-7-06

D Status Y Citation/Order No. 7254895 Date 6/3/06

Dates of Inspection: began 9/5 completed 9/5

Pre-Inspection Conference Date 9/5

Company Representative(s)

[redacted]

Miners Representative(s)

None

Post-Inspection Conference Date 9/5

Company Representative(s)

[redacted]

Miners Representative(s)

None

Comments:

Inspector's Initials [redacted] Supervisor's Initials and Date RR 9-5-06

*U.S. Government Printing Office: 1995 — 609-287

MSHA Form 7000-10I, June 93 (revised) 4111139

DAILY COVER SHEET 103-I

Date 9-5-06 Event No. ~~4111139~~

Arrived at the Mine — Departed from the Mine —

List Records Books Checked

Accompanied By: Company Representative

[redacted]

Miners Representative

None

AREAS OF INSPECTION ACTIVITY:

030- Section LBB

73 X 19.5 X 161

142.35 X 161

22,918 LOB

2nd lift 0% CH4 - 20.8 O2

Chnk all 5 faces

0% CH4 20.9 O2

Inspector's Initials

Supervisor's Initials and Date RR 9-5-06 Page No.

*U.S. Government Printing Office: 1997 - 508-470

MSHA Form 7000-10K, June 93 (revised)

Date 9-5-06 4111139

Section was rock dusted Except about 1/3 of the Section was Saturated with Water when a Water line had broken.

Inspector's Initials [redacted]

Supervisor's Initials and Date RR 9-5-06 Page No. 2

*U.S.GPO: 2004 - 642 - 912