MSHA Form 7000-10H, June 93 (revised)

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 4117129

Company Name Performance Coal

Mine Name Upper Big Branch

Mine I.D. Number 46-08436

Date(s) of Mine File Review 7-11-07

D Status _____ Citation/Order No. _____ Date _____

Dates of Inspection: began 7-12-07 completed 7-12-07

Pre-Inspection Conference Date 7-12-07

Company Representative(s) Rick Hodge

Miners Representative(s) [redacted]

Post-Inspection Conference Date 7-12-07 ~~Rick Hodge~~

Company Representative(s) Rick Hodge

Miners Representative(s) [redacted]

Comments: No comments from either party

Inspector's Initi[redacted] pervisor's Initials and Date MS 7227

(7)(C)

*U.S. Government Printing Office: 1995 — 609-287

E02

MSHA Form 7000-10I, June 93 (revised)

DAILY COVER SHEET

Date 7-12-07 Event No. 4117129

Arrived at the Mine _____ Departed from the Mine _____

List Records Books Checked Belts, Pocket No. 1 & 2

Accompanied By: Company Representative [redacted]

Miners Representative _____

AREAS OF INSPECTION ACTIVITY:

Informed Rick Hodge (Super) of [redacted] of Inspection purpose

Inspector's Initial [redacted]

Supervisor's Initials and Date MS 7227 Page No. 1

*U.S. Government Printing Office: 1997 - 503-470

E02

MSHA Form 7000-10K, June 93 (revised)

Date 7-12-07

Traveled No. 1 North Mains belt from head to tail (53 breaks) 20.8 0.0 DT & present

No. 47 break 20.8 0.0
No. 5 head
No. 79 break 20.8
0.0 No. 6 head
No. 105 break 20.8
0.0 No. 7 head
No. 126 break 20.8
0.0 Glory Hole head

Traveled track from portal to No. 1 North Mains belt head to North Mains section

Inspector's Initials [redacted]

Supervisor's Initials and Date MS 7227 Page No. 2

(7)(C)

GPO U.S. GPO: 2006-640-217

MSHA Form 7000-10K, June 93 (revised)

Date 7-12-07

LOA 5-6 North Mains section

20 W	20.8
81 H	0.05 CH4
160A	12.49
60V	52561
9600 fpm	~~52571~~

Inspector's Initial [redacted]

Supervisor's Initials and Date MS 7227 Page No. 3

GPO U.S. GPO: 2006-640-217