

GENERAL INFORMATION COVER SHEET

Inspection Code E02 Event No. 6285119Company Name performance COAL COMine Name Upper Big Branch mineMine I.D. Number 46-08436Date(s) of Mine File Review 12-15-9D Status ☒ Citation/Order No. _____ Date _____Dates of Inspection: began 12-15-9 completed 12-15-9Pre-Inspection Conference Date 12-15-9

Company Representative(s) _____

Miners Representative(s) _____

NONEPost-Inspection Conference Date 12-15-9

Company Representative(s) _____

Miners Representative(s) _____

NONE

Comments: _____

Inspector's Initials _____'s Initials and Date _____

DAILY COVER SHEET

Date 12-15-9 Event No. 6285119Arrived at the Mine 0800 Departed from the Mine _____List Records Books Checked gr-sift / onShift, Weekly Air Way book

Accompanied By: Company Representative _____

Miners Representative NONE

AREAS OF INSPECTION ACTIVITY:

- TRACK FROM RESURFACE TO THE LONG WALL.
- LONG WALL 050
- RETURN for 029 FROM

Inspector's Initials _____

Supervisor's Initials and Date _____

Date 12-15-9

_____ and I met
 WITH _____
 INFORMED HIM THAT
 WE WAS GOING TO CONDUCT
 A 108 I METHANE
 INSPECTION.

TRAVEL FROM THE
 SURFACE OF THE TRACK
 TO THE LW. 050
 OCH⁴, THE AREA IS
 WELL ROCK DUSTED,
 THE MINER ROUTE APPEARS
 SOLID. TRAVEL FROM
 THE END OF TRACK
 TO THE HEADGATE
 END OF THE LW.

TOOK AIR READING
 ON THE END TAIL

Inspector's Initials _____

Supervisor's Initials and Date _____

Date 12-15-9

end of the LW, ocht
The mine roof appears
solid,

Travel to the #9
shield, the LW.
Face looks good

The walkway is clear
in front of the face.
All movements ~~are~~ ^{across}

The wall is very
good ocht, 20,802

Travel from the
LW. over into the
return for 029

section, travel
to BR 72, ocht
The roof is broken,
but cribs and rock

Inspector's Initials [redacted]Supervisor's Initials and Date [redacted]Page No. 2Date 12-15-9

have been installed.
Water was blocking
travel, but a
citation has been
issued.

Travel from BR
in the return to
the end of the face
then to the surface
discussed the finding
with [redacted] no
comment was given

Inspector's Initials [redacted]Supervisor's Initials and Date 12-15-9Page No. 3

AIR READINGS

Date 12-15-9Location Return off of 029Width 19 Bottle Sample No. 1Height 6 CH4 Detected 0Area 114 Mean Entry 1220Velocity 480 Time 1220Quantity 54, 720Location Width Bottle Sample No. Height CH4 Detected Area Mean Entry Velocity Time Quantity Inspector's Initials [redacted]Supervisor's Initials and Date 12-15-9Page No. 4

AIR READINGS

Date 12-15-9

Location _____

INTAKE end of L4

Width 12 Bottle Sample No. _____

Height 8 CH4 Detected 0

Area 153 Mean Entry _____

Velocity 490 Time 1105

Quantity 74,450

Location TACH 9

Width _____ Bottle Sample No. _____

Height _____ CH4 Detected _____

Area _____ Mean Entry 0

Velocity 490 Time 1115

Quantity _____

Inspector's Initials _____ 12-15-9

Supervisor's Initials and _____ Page No. 5