



Mine Activity Data

1. Action: a. New Entry b. Update 2. Activity Code: E02 3. Event Number: 6288671
 4. Date Event Started: 2/17/2010 5. Date Event Finished: 2/17/2010 6. Mine ID: 46-08436
 7a. Organization Code (Mine Assignment) 20401 b. Work Group Identifier 02 9. Company Name PERFORMANCE COAL COMPANY
 8a. Organization Code (AR Assignment) 20401 b. Work Group 02 10. Mine Name UPPER BIG BRANCH MINE-SOUTH
 11. Report Type (check) a. First b. Interim c. Last d. Not Applicable 12. Area of Inspections a. Active Sections b. Idle Sections
 c. Outby Areas d. Shafts/Slopes e. Surface Areas (UG) f. Surface Workings g. Company Records h. ATF i. Impoundments j. Refuse Piles
 k. Major Construction (1) Shaft/Slope Sinking (2) Impoundment Construction (3) Buildings (4) Dragline/Shovel: (5) Other I. Miscellaneous
 m. MMU/Pit Number

13. Number of Samples Collected a. Air Samples b. Rock Dust Spot c. Rock Dust Survey d. Respirable Dust e. Noise f. Other

14. Impoundments/Refuse Piles:
 a. Number b. FHC c. Configuration

15. Prime Independent Contractor Codes (Major Construction)

16. Inspection Results

	Citations		Orders		Safeguards		Other	
	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con	Coal Opr	Ind Con
a. This Inspection								
(1) New Issuances		0						
(2) Terminations/Vacations		0/0						
(3) Modifications/Extensions		0/0						
(4) Left Pending		0						
b. Previously Issued								
(1) Modifications/Extensions		0/0						
(2) Terminations/Vacations		4/0						

18. Signature and Card Number of Authorized Representative/
 Right of Entry Person(s) Responsible for Activity

a.  Card Number
 b. _____
 c. _____
 d. _____

17. Remarks:

19. Key Entered By _____ Date _____

Shift	Sun			Mon			Tue			Wed			Thur			Fri			Sat		
	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3	1	2	3
Week 1 2/14/2010	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																		

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 02/16/2010	3. Citation/ Order Number 8087729 - 01
4. Served To Superintendent	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

The forklift has been cleaned.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 6288671		
11. Signature	AR Number	12. Date Mo Da Yr 02/17/2010	13. Time (24 Hr. Clock) 1015

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/> <input type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 02/16/2010	3. Citation/ Order Number 8087727 - 01
4. Served To Superintendent	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II--Justification for Action

The intake air is now going into the return at the #1 and #2 scoop chargers.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E02	10. Event Number 6288671		
11. Signature	AR Number	12. Date Mo Da Yr 02/17/2010	13. Time (24 Hr. Clock) 1030

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I-Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 02/08/2010	3. Citation/ Order Number 8090274 - 01
4. Served To [Redacted] Superintendent	5. Operator PERFORMANCE COAL COMPANY	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)

Section II-Justification for Action

The areas where the 2 samples were taken has been rock dusted.

See Continuation Form

Section III-Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV-Inspection Data

9. Type of Inspection E02	10. Event Number 6288671		
11. Signature [Redacted]	AR Number [Redacted]	12. Date Mo Da Yr 02/17/2010	13. Time (24 Hr. Clock) 1050

Mine Citation/Order
Continuation

Previously issued

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input checked="" type="checkbox"/>	2. Dated (Original Issue)	Mo Da Yr 02/16/2010	3. Citation/ Order Number	8087728 - 01
--	------------------------------	------------------------	------------------------------	--------------

4. Served To Superintendent	5. Operator PERFORMANCE COAL COMPANY
--------------------------------	---

6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)
--	------------------------	--------------

Section II--Justification for Action

The hole in the stopping has been repaired.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input checked="" type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	---	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection	E02	10. Event Number	6288671
-----------------------	-----	------------------	---------

11. Signature		AR Number		12. Date Mo Da Yr	02/17/2010	13. Time (24 Hr. Clock)	1105
---------------	--	-----------	--	-------------------	------------	-------------------------	------