

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 02/01/2014 05:50 PM		4. Date/Time of Death 02/01/2014 05:50 PM		5. Fatal Case No 1		
6. Mine Information :										
a) Mining Company Name GILBERT DEVELOPMENT CORP.			b) Mine Name Comstock / Mountain Lion			c) Parent of Mining Company Dale Gilbert				
7. Mine Location :		a) City Cedar City		b) County Iron		c) State UT		8. Mine ID Number: 42-01927		9. Union: NO
10. Primary Mineral Mined: IRON ORE MINING, N.E.C.			11. Number of Mine Employees:		a) Total 123	b) Underground	c) Open Pit/Quarry 115		d) Mill/Prep Plant	e) Other 8
12. Contractor Name:						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:										
a) City		b) County			c) State			d) Zip Code		
16. Number of Contractor Employees:										
a) Total 70		b) Underground		c) Open Pit/Quarry 63		d) Mill/Prep Plant 7		e) Other		
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:				
a) Mine Employees: 15		b) Contractor Employees: 14		a) Mine Employees: 0		b) Contractor Employees: 0				
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches				
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Mark F. Rowley				b) Age 56						
c) Regular Job Title: Rocho Belt Operator				d) Activity at Time of Accident: Cleaning return roller				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total: 48		b) at the mine: 48		c) at activity (23d) 20		d) with Contractor 48				
25. Autopsy Performed: If Yes, Location YES Salt Lake City, UT						26. Mine Telephone No.: (435) 586-5360				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was cleaning a return idler inside the frame of a belt conveyor when he became entangled between the return idler and the belt.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Rahco			29. Model: M30x1500		
30. District: M6000 Rocky Mountain		32. Field Office: Salt Lake City UT			33. Event Number: 6619972
34. Accident Investigator: Michael Treloar			35. MSHA Person Notified: Melvin Lapin		Date 02/01/2014
					Time 05:57 P
36. Type of Report: Amended		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>			Date 02/03/2014
38. Reason For Amendment: Items, 6(a), 12, 14, 15,					