

# Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 04/24/2014 05:35 PM		4. Date/Time of Death 04/24/2014 06:10 PM		5. Fatal Case No 8		
6. Mine Information :										
a) Mining Company Name Big River Industries			b) Mine Name Gravelite Division			c) Parent of Mining Company CRH PLC				
7. Mine Location :		a) City Erwinville		b) County Pointe Coupee		c) State LA		8. Mine ID Number: 16-00033		9. Union: NO
10. Primary Mineral Mined: FIRE CLAY MINING			11. Number of Mine Employees: 40		a) Total 40		b) Underground 40		c) Open Pit/Quarry 40	
12. Contractor Name: Craig Neal & Sons					13. Union NO		14. Contractor ID Number: H869			
15. Contractor Address:		a) City Morganza		b) County Pointe Coupee		c) State LA		d) Zip Code 70759		
16. Number of Contractor Employees:		a) Total 10		b) Underground 10		c) Open Pit/Quarry 10		d) Mill/Prep Plant 10		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 40		b) Contractor Employees: 10			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name James Gibson III				b) Age 50						
c) Regular Job Title: Dozer Operator										
d) Activity at Time of Accident: Dozer Operator <input checked="" type="checkbox"/> Contractor Employee										
24. Experience :										
a) Total:	Years		Weeks		Days		b) at the mine:	c) at activity (23d)		
23	0	1	0	0	1	23	0	1	d) with Contractor	
	0	0	1							
25. Autopsy Performed: YES					If Yes, Location Pointe Coupee Parish LA					
					26. Mine Telephone No.: (225) 627-4242					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
A contract dozer operator was found by co-workers lying on the ground behind the dozer he had been operating.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: John Deere			29. Model: 750C		
30. District: M5000 South Central		32. Field Office: Denham Springs LA			33. Event Number: 6653044
34. Accident Investigator: Michael R. VanDorn			35. MSHA Person Notified: Brad Peay		Date 04/24/2014
					Time 05:48 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>			Date 04/30/2014
38. Reason For Amendment:					