

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Fall of Face, Rib, Pillar or Highwall		3. Date/Time of Accident 07/25/2016 08:45 AM		4. Date/Time of Death 07/25/2016 08:45 AM		5. Fatal Case No 10		
6. Mine Information :										
a) Mining Company Name Vulcan Construction Materials, LLC			b) Mine Name Savannah Quarry			c) Parent of Mining Company Vulcan Materials Company				
7. Mine Location :		a) City Savannah		b) County Hardin		c) State TN		8. Mine ID Number: 40-00108		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 10	b) Underground	c) Open Pit/Quarry 4	d) Mill/Prep Plant 4	e) Other 2	
12. Contractor Name:						13. Union NO		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 10		b) Contractor Employees: 0			a) Mine Employees: 0		b) Contractor Employees:			
19) Location of Accident									20. Mining Height:	
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet	Inches
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility					
21. Nonfatal Injuries:			22. Fatal Injuries: 1							
23. Victim Information :				a) Name James Lynn		b) Age 59				
c) Regular Job Title: Excavator Operator			d) Activity at Time of Accident: Excavating			<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days		
a) Total:	17	36	b) at the mine:	8	c) at activity (23d)	5	d) with Contractor			
25. Autopsy Performed: If Yes, Location NO						26. Mine Telephone No.: (731) 925-9091				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

Employee was operating caterpillar 345B in pit area when he was struck by falling rock from nearby high wall. Employee had been loading rip rap material into haul trucks.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 345D		
30. District: M3000 Southeastern		32. Field Office: Franklin TN			33. Event Number: 6672955
34. Accident Investigator: Rory Smith			35. MSHA Person Notified: David Allen		Date 07/25/2016
					Time 09:16 AM
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Ed Jewell			Date 07/27/2016
38. Reason For Amendment:					