

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Explosives and Breaking Agents		3. Date/Time of Accident 03/22/2016 06:45 PM		4. Date/Time of Death 03/22/2016 07:06 PM		5. Fatal Case No 3		
6. Mine Information :										
a) Mining Company Name Martin Marietta Materials			b) Mine Name PLANT 862			c) Parent of Mining Company Martin Marietta Materials Inc				
7. Mine Location :		a) City Des Moines		b) County Polk		c) State IA		8. Mine ID Number: 13-02123		9. Union: NO
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 14	b) Underground 14	c) Open Pit/Quarry 14		d) Mill/Prep Plant 14	e) Other 14
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:			a) Total 2	b) Underground 2	c) Open Pit/Quarry 2	d) Mill/Prep Plant 2	e) Other 2			
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 2		b) Contractor Employees: 2			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident									20. Mining Height: Feet Inches	
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)						
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Tracy Hockemeier					b) Age 42					
c) Regular Job Title: Leadman			d) Activity at Time of Accident: Guarding a Blast				<input checked="" type="checkbox"/> Mine Employee			
24. Experience :										
Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total:	6	43	b) at the mine:	29	c) at activity (23d)	29	d) with Contractor			
25. Autopsy Performed: If Yes, Location YES Ankney, IA						26. Mine Telephone No.:				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The lead man was parked in his pickup truck approximately 1200 feet from blast area. The blast was initiated. Fly rock came through the roof of the lead man's truck, striking the lead man.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:					
30. District: M4000 North Central		32. Field Office: Hibbing MN				33. Event Number: 6706850			
34. Accident Investigator: Thaddeus Sichmeller				35. MSHA Person Notified: David Schwab		Date 03/22/2016		Time 07:56 PM	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Thaddeus Sichmeller				Date 03/28/2016			
38. Reason For Amendment:									