



14-Jun-16

|   |  |  |  |  |
|---|--|--|--|--|
| 1. Accident Type:<br>Fatal Injury   | 2. Accident Classification<br>Inundation | 3. Date/Time of Accident<br>06/03/2016 12:00 PM        | 4. Date/Time of Death<br>06/03/2016 12:00 PM | 5. Fatal Case No<br>7                          |
| 6. Mine Information :   |  |  |  |  |
| a) Mining Company Name<br>Green Brothers Gravel Company, Inc.   |  | b) Mine Name<br>Harmony Mine & Mill                    |  | c) Parent of Mining Company<br>Heyward C Green |
| 7. Mine Location :  |  |  | 8. Mine ID Number:                           | 9. Union:                                      |
| a) City<br>Crystal Springs  |  | b) County<br>Copolah                                   |  | c) State<br>MS                                 |
|   |  |  | 22-00650                                     | NO   |
| 10. Primary Mineral Mined:<br>CONSTRUCTION SAND & GRAVEL M  |  | 11. Number of Mine Employees:                          | a) Total<br>20                               | b) Underground<br>5                            |
|   |  | c) Open Pit/Quarry<br>15                               | d) Mill/Prep Plant<br>15                     | e) Other                                       |
| 12. Contractor Name:  |  |  | 13. Union                                    | 14. Contractor ID Number:                      |
| 15. Contractor Address:   |  |  |  |  |
| a) City   |  | b) County  |  | c) State                                       |
| d) Zip Code   |  |  |  |  |
| 16. Number of Contractor Employees:   |  |  |  |  |
| a) Total  |  | b) Underground   |  | c) Open Pit/Quarry                             |
|   |  | d) Mill/Prep Plant                                     |  | e) Other                                       |
| 17. Number of Persons in Mine at Time of Accident:  |  |  | 18. Number of Persons Unaccounted For:       |  |
| a) Mine Employees: 19   |  | b) Contractor Employees:                               |  | a) Mine Employees: 2                           |
|   |  |  |  | b) Contractor Employees:                       |
| 19) Location of Accident  |  |  |  | 20. Mining Height:                             |
| <input type="checkbox"/> 01-Underground <input checked="" type="checkbox"/> 03-Open Pit <input type="checkbox"/> 07-Advance Mining <input type="checkbox"/> 30-Mill/Prep Plant <input type="checkbox"/> Other (specify) |  |  |  | Feet    Inches                                 |
| <input type="checkbox"/> 02-Surface at Underground <input type="checkbox"/> 06-Dredge Mining <input type="checkbox"/> 08-Retreat Mining <input type="checkbox"/> 99-Office Facility                                     |  |  |  |  |
| 21. Nonfatal Injuries:  |  | 22. Fatal Injuries: 2                                  |  |  |
| 23. Victim Information :  |  |  |  |  |
| a) Name<br>Emmit Shorter  |  |  | b) Age<br>24                                 |  |
| c) Regular Job Title:<br>Haul Truck Driver  |  | d) Activity at Time of Accident:<br>Driving Haul Truck |  |  |
| <input checked="" type="checkbox"/> Mine Employee   |  |  |  |  |
| 24. Experience :  |  |  |  |  |
| Years Weeks Days  |  | Years Weeks Days                                       |  | Years Weeks Days                               |
| a) Total: 39 5  |  | b) at the mine: 39 5                                   |  | c) at activity (23d) 39 5                      |
|   |  |  |  | d) with Contractor                             |
| 25. Autopsy Performed: If Yes, Location<br>YES MS Corner's office   |  |  |  | 26. Mine Telephone No.:                        |

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

A haul truck operator and a hydraulic excavator operator were working below a pond when the pond's embankment broke engulfing both miners. Miners were recovered several days later.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

|   |  |  |  |                    |
|---|--|--|--|--------------------|
| 28. Equipment Manufacturer:<br>Caterpillar  |  | 29. Model:   |  |                    |
| 30. District:<br>M5000 South Central        |  | 32. Field Office:<br>Denham Springs LA                 |  | 33. Event Number:  |
| 34. Accident Investigator:<br>Joseph Oliver |  | 35. MSHA Person Notified:<br>Elwood M. Burriss         |  | Date<br>06/03/2016 |
|   |  |  |  | Time<br>12:00 PM   |
| 36. Type of Report:<br>Initial              |  | 37. Name of Preparer and Date Prepared:<br>Mac Burriss |  |                    |
|   |  | Date<br>06/04/2016                                     |  |                    |
| 38. Reason For Amendment:                   |  |  |  |                    |

# Preliminary Report of Accident



|                                   |  |   |  |                       |
|-----------------------------------|--|---|--|-----------------------|
| 1. Accident Type:<br>Fatal Injury | 2. Accident Classification<br>Inundation | 3. Date/Time of Accident<br>06/03/2016 12:00 PM | 4. Date/Time of Death<br>06/03/2016 12:00 PM | 5. Fatal Case No<br>8 |
|-----------------------------------|--|---|--|-----------------------|

6. Mine Information :

|   |                                     |  |
|---|-------------------------------------|--|
| a) Mining Company Name<br>Green Brothers Gravel Company, Inc. | b) Mine Name<br>Harmony Mine & Mill | c) Parent of Mining Company<br>Heyward C Green |
|---|-------------------------------------|--|

|                    |                            |                      |                |                                |                 |
|--------------------|----------------------------|----------------------|----------------|--------------------------------|-----------------|
| 7. Mine Location : | a) City<br>Crystal Springs | b) County<br>Copolah | c) State<br>MS | 8. Mine ID Number:<br>22-00650 | 9. Union:<br>NO |
|--------------------|----------------------------|----------------------|----------------|--------------------------------|-----------------|

|  |                               |                |                |                         |                          |          |
|--|-------------------------------|----------------|----------------|-------------------------|--------------------------|----------|
| 10. Primary Mineral Mined:<br>CONSTRUCTION SAND & GRAVEL M | 11. Number of Mine Employees: | a) Total<br>20 | b) Underground | c) Open Pit/Quarry<br>5 | d) Mill/Prep Plant<br>15 | e) Other |
|--|-------------------------------|----------------|----------------|-------------------------|--------------------------|----------|

|                      |           |                           |
|----------------------|-----------|---------------------------|
| 12. Contractor Name: | 13. Union | 14. Contractor ID Number: |
|----------------------|-----------|---------------------------|

|                         |         |           |          |             |
|-------------------------|---------|-----------|----------|-------------|
| 15. Contractor Address: | a) City | b) County | c) State | d) Zip Code |
|-------------------------|---------|-----------|----------|-------------|

|                                     |          |                |                    |                    |          |
|-------------------------------------|----------|----------------|--------------------|--------------------|----------|
| 16. Number of Contractor Employees: | a) Total | b) Underground | c) Open Pit/Quarry | d) Mill/Prep Plant | e) Other |
|-------------------------------------|----------|----------------|--------------------|--------------------|----------|

|  |  |
|--|--|
| 17. Number of Persons in Mine at Time of Accident: | 18. Number of Persons Unaccounted For: |
| a) Mine Employees: 19                              | a) Mine Employees: 2                   |
| b) Contractor Employees:                           | b) Contractor Employees:               |

|   |                                      |
|---|--------------------------------------|
| 19) Location of Accident  | 20. Mining Height:<br>Feet    Inches |
| <input type="checkbox"/> 01-Underground <input checked="" type="checkbox"/> 03-Open Pit <input type="checkbox"/> 07-Advance Mining <input type="checkbox"/> 30-Mill/Prep Plant <input type="checkbox"/> Other (specify) |                                      |
| <input type="checkbox"/> 02-Surface at Underground <input type="checkbox"/> 06-Dredge Mining <input type="checkbox"/> 08-Retreat Mining <input type="checkbox"/> 99-Office Facility                                     |                                      |

|                        |                          |
|------------------------|--------------------------|
| 21. Nonfatal Injuries: | 22. Fatal Injuries:<br>2 |
|------------------------|--------------------------|

|                          |                              |              |
|--------------------------|------------------------------|--------------|
| 23. Victim Information : | a) Name<br>James D. Hemphill | b) Age<br>56 |
|--------------------------|------------------------------|--------------|

|   |  |   |
|---|--|---|
| c) Regular Job Title:<br>Excavator Operator | d) Activity at Time of Accident:<br>Running Trackhoe | <input checked="" type="checkbox"/> Mine Employee |
|---|--|---|

|                  |       |       |      |                 |       |      |       |                      |      |       |       |                    |
|------------------|-------|-------|------|-----------------|-------|------|-------|----------------------|------|-------|-------|--------------------|
| 24. Experience : | Years | Weeks | Days | Years           | Weeks | Days | Years | Weeks                | Days | Years | Weeks | Days               |
| a) Total:        | 6     | 51    | 5    | b) at the mine: | 6     | 51   | 5     | c) at activity (23d) | 6    | 51    | 5     | d) with Contractor |

|   |                         |
|---|-------------------------|
| 25. Autopsy Performed:    If Yes, Location<br>YES    MS State Corner's Office | 26. Mine Telephone No.: |
|---|-------------------------|

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):  
A haul truck operator and a hydraulic excavator operator were working below a pond when the pond's embankment broke engulfing both miners. Miners were recovered several days later.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

|  |            |
|--|------------|
| 28. Equipment Manufacturer:<br>Caterpillar | 29. Model: |
|--|------------|

|   |  |                   |
|---|--|-------------------|
| 30. District:<br>M5000    South Central | 32. Field Office:<br>Denham Springs LA | 33. Event Number: |
|---|--|-------------------|

|   |  |                    |                  |
|---|--|--------------------|------------------|
| 34. Accident Investigator:<br>Joseph Oliver | 35. MSHA Person Notified:<br>Elwood M. Burriss | Date<br>06/03/2016 | Time<br>12:00 PM |
|---|--|--------------------|------------------|

|                                |  |                    |
|--------------------------------|--|--------------------|
| 36. Type of Report:<br>Initial | 37. Name of Preparer and Date Prepared:<br>Mac Burriss | Date<br>06/04/2016 |
|--------------------------------|--|--------------------|

38. Reason For Amendment: